

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "firstName": "r. Mohanty",
    "type": "CREDITOFFICER",
    "_id": "646dc536b05e530fb6c47b3d",
    "lastName": " Sir",
    "mobileNo": "",
    "workMobileNo": "8411020137",
    "email": "rlf.nasik@bankofbaroda.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "2500",
    "discussWithPerson": "r. Mohanty",
    "expectedFees": 1.25,
    "quotedAmount": "2950"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nashik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSN Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "643a91f233d16f6b1237a4ee",
    "role": "SITEENGINEER",
```

```
"firstName": "Pankaj",
"email": "pankajpachore510@gmail.com",
"lastName": "Pachore",
"mobileNo": "7709956078",
"shortName": "PA",
"workWithDocumentMaker": "",
"profilePhoto": "users/643a91f233d16f6b1237a4ee/
profilePhoto_1717744018409_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a29b64d42487767af43ea",
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"designation": "Site Engg",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": ""
```

```
    "shortName": "RV",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
  },
  "checker": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "shortName": "BS",
    "email": "binu@vastukala.org",
    "designation": "Back Office Team Leader",
    "mobileNo": "9930252906",
    "role": "FRONTDESK",
    "type": "EMPLOYEE",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453"
  },
  "valuers": []
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.966613745460794",
  "longitude": "73.75356874322124"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.75356874322124,
    19.966613745460794
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
```

```
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
}
```

```
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "02",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Amiratan Co - Op. Housing Society Ltd",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
```

```
"value": "Near Burkule Hall, Uttam Nagar",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Ambad - Trimurti Chowk Link Road, At - Cidco",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Neighborhood Shraavan Sector - 5",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
```

```
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "08",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
```



```
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422 0010",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    }
  },
}
```

```
"taxies": {
  "title": "Taxies"
},
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
"label": "Flooring, Tilling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```

```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66752ff349110344ffd311cc",
"invoices": [],
"ownerName": "Prathmesh Patil",
"ownerPhoneNo": "8975733189",
"appAddress": "flat no.8 Nebarhud shraavan sector E5 uttam nagar nashik",
"remark": "",
"documents": [
```



```
{
  "documentType": {
    "label": "Any Other Document",
    "value": "60ae124aaa6d152c1801b2f7"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66752ff349110344ffd311cc/
document_1718955959458_1718955821821_Prathamesh_patil_.pdf",
  "fileName": "document_1718955959458_1718955821821_Prathamesh_patil_.pdf",
  "id": "159917",
  "uploadedBy": "643a91f233d16f6b1237a4ee",
  "createdAt": "Fri Jun 21 2024 13:16:59 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "009436",
"createdBy": "643a91f233d16f6b1237a4ee",
"caseHistory": [
  {
    "id": "482329",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jun 21 2024 13:16:59 GMT+0530 (India Standard Time)"
  }
]
],
"owners": [
  {
    "name": "Prathmesh Patil",
    "phone": "8975733189",
    "ownershipShare": "",
    "email": "",
    "id": "993701"
  }
]
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
  }
]
```

```
    "_id": "667d43f8e6c0ca194e24fbeat",
    "name":
"externallmg_1719485428535_WhatsApp_Image_20240624_at_142235_1.jpeg",
    "path": "cases/66752ff349110344ffd311cc/"
externallmg_1719485428535_WhatsApp_Image_20240624_at_142235_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d43f8e6c0ca194e24fbeb",
    "name":
"externallmg_1719485428641_WhatsApp_Image_20240624_at_142235.jpeg",
    "path": "cases/66752ff349110344ffd311cc/"
externallmg_1719485428641_WhatsApp_Image_20240624_at_142235.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d43f8e6c0ca194e24fbec",
    "name":
"externallmg_1719485428818_WhatsApp_Image_20240624_at_142236_1.jpeg",
    "path": "cases/66752ff349110344ffd311cc/"
externallmg_1719485428818_WhatsApp_Image_20240624_at_142236_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d43f8e6c0ca194e24fbed",
    "name":
"externallmg_1719485428964_WhatsApp_Image_20240624_at_142236_2.jpeg",
    "path": "cases/66752ff349110344ffd311cc/"
externallmg_1719485428964_WhatsApp_Image_20240624_at_142236_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d43f8e6c0ca194e24fbee",
    "name":
"externallmg_1719485429049_WhatsApp_Image_20240624_at_142236.jpeg",
    "path": "cases/66752ff349110344ffd311cc/"
externallmg_1719485429049_WhatsApp_Image_20240624_at_142236.jpeg",
    "orientation": "portrait"
  }
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "667d43f8e6c0ca194e24fbef",
      "name":
"externallmg_1719485429118_WhatsApp_Image_20240624_at_142237_1.jpeg",
      "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485429118_WhatsApp_Image_20240624_at_142237_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "667d43f8e6c0ca194e24fbf0",
      "name":
"externallmg_1719485429179_WhatsApp_Image_20240624_at_142237_2.jpeg",
      "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485429179_WhatsApp_Image_20240624_at_142237_2.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "667d43f8e6c0ca194e24fbf1",
      "name":
"externallmg_1719485429351_WhatsApp_Image_20240624_at_142237.jpeg",
      "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485429351_WhatsApp_Image_20240624_at_142237.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "667d43f8e6c0ca194e24fbf2",
      "name":
"externallmg_1719485429392_WhatsApp_Image_20240624_at_142238_1.jpeg",
      "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485429392_WhatsApp_Image_20240624_at_142238_1.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "667d43f8e6c0ca194e24fbf3",
      "name":
"externallmg_1719485429782_WhatsApp_Image_20240624_at_142238_2.jpeg",
```

```
    "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485429782_WhatsApp_Image_20240624_at_142238_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d43f8e6c0ca194e24bf4",
    "name":
"externallmg_1719485430224_WhatsApp_Image_20240624_at_142239_1.jpeg",
    "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485430224_WhatsApp_Image_20240624_at_142239_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d43f8e6c0ca194e24bf5",
    "name":
"externallmg_1719485430281_WhatsApp_Image_20240624_at_142239_2.jpeg",
    "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485430281_WhatsApp_Image_20240624_at_142239_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d43f8e6c0ca194e24bf6",
    "name":
"externallmg_1719485430326_WhatsApp_Image_20240624_at_142239_3.jpeg",
    "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485430326_WhatsApp_Image_20240624_at_142239_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d43f8e6c0ca194e24bf7",
    "name":
"externallmg_1719485431172_WhatsApp_Image_20240624_at_142240_1.jpeg",
    "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485431172_WhatsApp_Image_20240624_at_142240_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "667d43f8e6c0ca194e24fbf8",
    "name":
"externallmg_1719485431442_WhatsApp_Image_20240624_at_142240_2.jpeg",
    "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485431442_WhatsApp_Image_20240624_at_142240_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d43f8e6c0ca194e24fbf9",
    "name":
"externallmg_1719485431471_WhatsApp_Image_20240624_at_142240.jpeg",
    "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485431471_WhatsApp_Image_20240624_at_142240.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d43f8e6c0ca194e24fbfa",
    "name":
"externallmg_1719485431523_WhatsApp_Image_20240624_at_142241_1.jpeg",
    "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485431523_WhatsApp_Image_20240624_at_142241_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d43f8e6c0ca194e24fbfb",
    "name":
"externallmg_1719485431765_WhatsApp_Image_20240624_at_142241_2.jpeg",
    "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485431765_WhatsApp_Image_20240624_at_142241_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d43f8e6c0ca194e24fbfc",
    "name":
"externallmg_r_1719485430079_WhatsApp_Image_20240624_at_142238.jpeg",
    "path": "cases/66752ff349110344ffd311cc/
externallmg_r_1719485430079_WhatsApp_Image_20240624_at_142238.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d43f8e6c0ca194e24fbfd",
    "name":
"externallmg_r_1719485430642_WhatsApp_Image_20240624_at_142239.jpeg",
    "path": "cases/66752ff349110344ffd311cc/
externallmg_r_1719485430642_WhatsApp_Image_20240624_at_142239.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d4405fe581f19554714d9",
    "name":
"externallmg_1719485443507_WhatsApp_Image_20240624_at_142241.jpeg",
    "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485443507_WhatsApp_Image_20240624_at_142241.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d4405fe581f19554714da",
    "name":
"externallmg_1719485443916_WhatsApp_Image_20240624_at_142242_1.jpeg",
    "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485443916_WhatsApp_Image_20240624_at_142242_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d4405fe581f19554714db",
    "name":
"externallmg_1719485443997_WhatsApp_Image_20240624_at_142242_2.jpeg",
    "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485443997_WhatsApp_Image_20240624_at_142242_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667d4405fe581f19554714dc",
```

```
    "name":
"externallmg_1719485444060_WhatsApp_Image_20240624_at_142242.jpeg",
  "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485444060_WhatsApp_Image_20240624_at_142242.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667d4405fe581f19554714dd",
  "name":
"externallmg_1719485444157_WhatsApp_Image_20240624_at_142243_1.jpeg",
  "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485444157_WhatsApp_Image_20240624_at_142243_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667d4405fe581f19554714de",
  "name":
"externallmg_1719485444228_WhatsApp_Image_20240624_at_142243_2.jpeg",
  "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485444228_WhatsApp_Image_20240624_at_142243_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667d4405fe581f19554714df",
  "name":
"externallmg_1719485444357_WhatsApp_Image_20240624_at_142243.jpeg",
  "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485444357_WhatsApp_Image_20240624_at_142243.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667d4405fe581f19554714e0",
  "name":
"externallmg_1719485444436_WhatsApp_Image_20240624_at_142244_1.jpeg",
  "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485444436_WhatsApp_Image_20240624_at_142244_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667d4405fe581f19554714e1",
  "name":
"externallmg_1719485444628_WhatsApp_Image_20240624_at_142244_2.jpeg",
  "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485444628_WhatsApp_Image_20240624_at_142244_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667d4405fe581f19554714e2",
  "name":
"externallmg_1719485444734_WhatsApp_Image_20240624_at_142244_3.jpeg",
  "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485444734_WhatsApp_Image_20240624_at_142244_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667d4405fe581f19554714e3",
  "name":
"externallmg_1719485444836_WhatsApp_Image_20240624_at_142244.jpeg",
  "path": "cases/66752ff349110344ffd311cc/
externallmg_1719485444836_WhatsApp_Image_20240624_at_142244.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "mane Cal.xlsx",
    "filename": "1719485389490_mane_Cal.xlsx",
    "path": "cases/66752ff349110344ffd311cc/
processingDocuments/1719485389490_mane_Cal.xlsx",
    "size": "585521",
    "createdAt": "Thu Jun 27 2024 16:19:50 GMT+0530 (India Standard Time)",
    "uploadedBy": "647ed1960ab64c23c9fcf71d"
  },
  {
    "originalname": "Shri. PrathmeshNana Patil.doc",
    "filename": "1719485417249_Shri_PrathmeshNana_Patil.doc",
    "path": "cases/66752ff349110344ffd311cc/
processingDocuments/1719485417249_Shri_PrathmeshNana_Patil.doc",
```



```

    "size": "7915520",
    "createdAt": "Thu Jun 27 2024 16:20:26 GMT+0530 (India Standard Time)",
    "uploadedBy": "647ed1960ab64c23c9fcf71d"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-21T07:46:59.944Z",
"updatedAt": "2024-06-27T10:50:45.348Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Flat No. 08, 2nd Floor, Amiratan Co - Op. Housing Society
Ltd, Neighborhood Shravan Sector - 5, Plot No. 02, Near Burkule Hall, Uttam Nagar,
Ambad - Trimurti Chowk Link Road, At - Cidco, Taluka - Nashik, Nashik, 422 0010",
"updatedAt": "636a29b64d42487767af43ea",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Prathmesh Patil",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8975733189"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			