

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64645e68ee6a9735bf790e6f"
    },
    "firstName": "Rajnessh ",
    "type": "CREDITOFFICER",
    "_id": "64645e68ee6a9735bf790e71",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "9167940785",
    "email": "bmmsro0618@centralbank.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "8000000",
    "discussWithPerson": "Rajnessh ",
    "expectedFees": 4000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17fa",
  "type": "BANK",
  "name": "Central Bank of India",
  "displayName": "Central Bank of India",
  "initial": "CBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64645e68ee6a9735bf790e6f",
  "name": "Malad West Branch\t",
  "branchCode": "",
  "mobileNo": "0222891551\t02228821375",
  "alternateMobileNo": "",
  "email": "bmmsro0618@centralbank.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Vishnu Bhawan,Anand Road, Opp, Malad Railway Station, Malad west
Mumbai-400064\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f917e0f3dd69653a592221",
  "zoneName": "South Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "64c777a8a5c3051014f4dd1f",
"role": "SITEENGINEER",
"firstName": "Pratik",
"email": "pratikjain2277@gmail.com",
"lastName": "Jain",
"mobileNo": "9619286285",
"designation": "",
"shortName": "Pratik",
"workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
}
]
```

```
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
```

```
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.308411338148854",
  "longitude": "72.8691553760064"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8691553760064,
    19.308411338148854
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "24/06/2024 04:21 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
```

```
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "3",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Bhaynder",
  "label": false
},
"tahsilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahsilNo",
  "value": "",
```

```
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Prasad CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "60 Feet Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Mandvi Bank",
  "label": false
},
"landmark": {
  "status": false,
```

```
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
}
```



```
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "304",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
```

```
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Bhaynder West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
},
"landAndBuildingDetails": {
```

```
"actualBuildingBoundaries": [],
"documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
}
```

```
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```



```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "667947cc4c08775ede708352",
"ownerName": "CHAMPABEN FUTERMAL KHUTER PROPOSED PURCHASER
VIKRAM JAIN",
"ownerPhoneNo": "9833098531",
"appAddress": "FLAT NO 304 PRASAD CHS LTD 3 RD FLOOR 60 FEET ROAD
NEAR JAIN MANDIR BHAYNDER EAST THANE 401101",
"remark": "URGENT VISIT BANKER KEY ARRANGE AUCTION FLAT Rohit Dhaval
9833098531\n\n",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/667947cc4c08775ede708352/document_1719223999471_17192238
66461_Agreement_for_sale__Builder__Champaben.pdf",
    "fileName": "document_1719223999471_1719223866461_Agreement_for_sale__Bu
ilder__Champaben.pdf",
    "id": "668068",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Mon Jun 24 2024 15:47:48 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Supplementary Agreement",
      "value": "60ae1261aa6d152c1801b364"
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/667947cc4c08775ede708352/
document_1719224113222_1719223980136_Supplemental_deed_of_mortgage.pdf",
    "fileName":
"document_1719224113222_1719223980136_Supplemental_deed_of_mortgage.pdf",
    "id": "335738",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Mon Jun 24 2024 15:47:48 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Other",
      "value": "60ae124eaa6d152c1801b30b"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/667947cc4c08775ede708352/
document_1719224154864_1719224021888_2505FPPFPJ24_compressed.pdf",
    "fileName":
"document_1719224154864_1719224021888_2505FPPFPJ24_compressed.pdf",
    "id": "555416",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Mon Jun 24 2024 15:47:48 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Other",
      "value": "60ae124eaa6d152c1801b30b"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/667947cc4c08775ede708352/
document_1719224170143_1719224037249_2505FPPNS22_compressed.pdf",
    "fileName":
"document_1719224170143_1719224037249_2505FPPNS22_compressed.pdf",
    "id": "240073",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Mon Jun 24 2024 15:47:48 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Other",
      "value": "60ae124eaa6d152c1801b30b"
    }
  },
}
```

```
"isHardCopy": false,
"displayStatus": false,
"path": "cases/667947cc4c08775ede708352/document_1719224188110_1719224055202_1834IBSAMBFSNFeAllEdi25052024_MUM.pdf",
"fileName": "document_1719224188110_1719224055202_1834IBSAMBFSNFeAllEdi25052024_MUM.pdf",
"id": "179724",
"uploadedBy": "659ccce98f39506e83489828",
"createdAt": "Mon Jun 24 2024 15:47:48 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/667947cc4c08775ede708352/document_1719224201661_1719224067961_display_pdf__20231204T170354532.pdf",
  "fileName": "document_1719224201661_1719224067961_display_pdf__20231204T170354532.pdf",
  "id": "236235",
  "uploadedBy": "659ccce98f39506e83489828",
  "createdAt": "Mon Jun 24 2024 15:47:48 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/667947cc4c08775ede708352/document_1719224216217_1719224082758_PAPER_PUBLICATION.pdf",
  "fileName": "document_1719224216217_1719224082758_PAPER_PUBLICATION.pdf",
  "id": "464278",
  "uploadedBy": "659ccce98f39506e83489828",
  "createdAt": "Mon Jun 24 2024 15:47:48 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
```

```
    "displayStatus": false,
    "path": "cases/667947cc4c08775ede708352/
document_1719224233800_1719224100486_Registered_mortgage_Deed_1.pdf",
    "fileName":
"document_1719224233800_1719224100486_Registered_mortgage_Deed_1.pdf",
    "id": "396021",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Mon Jun 24 2024 15:47:48 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Other",
      "value": "60ae124eaa6d152c1801b30b"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/667947cc4c08775ede708352/document_1719224252938_17192241
20125_Gmail__SALE_CONFIRMATION_LETTER_PropertyIDIB30147420639A.pdf",
    "fileName": "document_1719224252938_1719224120125_Gmail__SALE_CONFIR
MATION_LETTER_PropertyIDIB30147420639A.pdf",
    "id": "837857",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Mon Jun 24 2024 15:47:48 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Other",
      "value": "60ae124eaa6d152c1801b30b"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/667947cc4c08775ede708352/document_1719224265436_17192241
30785_Gmail__SALE_INTIMATION_LETTER_PropertyIDIB30147420639A.pdf",
    "fileName": "document_1719224265436_1719224130785_Gmail__SALE_INTIMATI
ON_LETTER_PropertyIDIB30147420639A.pdf",
    "id": "566875",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Mon Jun 24 2024 15:47:48 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "009477",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "646092",
    "title": "Create Lead",
```

```
    "description": "Create Lead",
    "datetime": "Mon Jun 24 2024 15:47:48 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "CHAMPABEN FUTERMAL KHUTER PROPOSED PURCHASER VIKRAM
JAIN",
    "phone": "9833098531",
    "ownershipShare": "",
    "email": "",
    "id": "462752"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77b7f891a97c54939017",
    "name":
"externalImg_1719302070818_WhatsApp_Image_20240625_at_130327_2.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externalImg_1719302070818_WhatsApp_Image_20240625_at_130327_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77b7f891a97c54939018",
    "name":
"externalImg_1719302070821_WhatsApp_Image_20240625_at_130328_1.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externalImg_1719302070821_WhatsApp_Image_20240625_at_130328_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "667a77b7f891a97c54939019",
    "name":
"externallmg_1719302070825_WhatsApp_Image_20240625_at_130328_2.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070825_WhatsApp_Image_20240625_at_130328_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77b7f891a97c5493901a",
    "name":
"externallmg_1719302070828_WhatsApp_Image_20240625_at_130328.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070828_WhatsApp_Image_20240625_at_130328.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77b7f891a97c5493901b",
    "name":
"externallmg_1719302070832_WhatsApp_Image_20240625_at_130310.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070832_WhatsApp_Image_20240625_at_130310.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77b7f891a97c5493901c",
    "name":
"externallmg_1719302070837_WhatsApp_Image_20240625_at_130311.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070837_WhatsApp_Image_20240625_at_130311.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77b7f891a97c5493901d",
    "name":
"externallmg_1719302070840_WhatsApp_Image_20240625_at_130312.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070840_WhatsApp_Image_20240625_at_130312.jpeg",
    "orientation": "portrait"
  }
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "667a77b7f891a97c5493901e",
      "name":
"externallmg_1719302070844_WhatsApp_Image_20240625_at_130315_1.jpeg",
      "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070844_WhatsApp_Image_20240625_at_130315_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "667a77b7f891a97c5493901f",
      "name":
"externallmg_1719302070849_WhatsApp_Image_20240625_at_130315.jpeg",
      "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070849_WhatsApp_Image_20240625_at_130315.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "667a77b7f891a97c54939020",
      "name":
"externallmg_1719302070853_WhatsApp_Image_20240625_at_130316.jpeg",
      "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070853_WhatsApp_Image_20240625_at_130316.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "667a77b7f891a97c54939021",
      "name":
"externallmg_1719302070857_WhatsApp_Image_20240625_at_130318_1.jpeg",
      "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070857_WhatsApp_Image_20240625_at_130318_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "667a77b7f891a97c54939022",
      "name":
"externallmg_1719302070861_WhatsApp_Image_20240625_at_130318_2.jpeg",
```

```
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070861_WhatsApp_Image_20240625_at_130318_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77b7f891a97c54939023",
    "name":
"externallmg_1719302070864_WhatsApp_Image_20240625_at_130318.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070864_WhatsApp_Image_20240625_at_130318.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77b7f891a97c54939024",
    "name":
"externallmg_1719302070868_WhatsApp_Image_20240625_at_130319_1.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070868_WhatsApp_Image_20240625_at_130319_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77b7f891a97c54939025",
    "name":
"externallmg_1719302070871_WhatsApp_Image_20240625_at_130319_2.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070871_WhatsApp_Image_20240625_at_130319_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77b7f891a97c54939026",
    "name":
"externallmg_1719302070873_WhatsApp_Image_20240625_at_130319.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070873_WhatsApp_Image_20240625_at_130319.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "667a77b7f891a97c54939027",
  "name":
"externallmg_1719302070876_WhatsApp_Image_20240625_at_130320_1.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070876_WhatsApp_Image_20240625_at_130320_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77b7f891a97c54939028",
  "name":
"externallmg_1719302070877_WhatsApp_Image_20240625_at_130320_2.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070877_WhatsApp_Image_20240625_at_130320_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77b7f891a97c54939029",
  "name":
"externallmg_1719302070880_WhatsApp_Image_20240625_at_130320.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302070880_WhatsApp_Image_20240625_at_130320.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77caf891a97c54939073",
  "name":
"externallmg_1719302090747_WhatsApp_Image_20240625_at_130320.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090747_WhatsApp_Image_20240625_at_130320.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77caf891a97c54939074",
  "name":
"externallmg_1719302090749_WhatsApp_Image_20240625_at_130321_1.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090749_WhatsApp_Image_20240625_at_130321_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77caf891a97c54939075",
    "name":
"externallmg_1719302090752_WhatsApp_Image_20240625_at_130321_2.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090752_WhatsApp_Image_20240625_at_130321_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77caf891a97c54939076",
    "name":
"externallmg_1719302090755_WhatsApp_Image_20240625_at_130321_3.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090755_WhatsApp_Image_20240625_at_130321_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77caf891a97c54939077",
    "name":
"externallmg_1719302090758_WhatsApp_Image_20240625_at_130321.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090758_WhatsApp_Image_20240625_at_130321.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77caf891a97c54939078",
    "name":
"externallmg_1719302090761_WhatsApp_Image_20240625_at_130322_1.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090761_WhatsApp_Image_20240625_at_130322_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77caf891a97c54939079",
```

```
    "name":
"externallmg_1719302090765_WhatsApp_Image_20240625_at_130322_2.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090765_WhatsApp_Image_20240625_at_130322_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77caf891a97c5493907a",
  "name":
"externallmg_1719302090769_WhatsApp_Image_20240625_at_130322.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090769_WhatsApp_Image_20240625_at_130322.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77caf891a97c5493907b",
  "name":
"externallmg_1719302090773_WhatsApp_Image_20240625_at_130323_1.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090773_WhatsApp_Image_20240625_at_130323_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77caf891a97c5493907c",
  "name":
"externallmg_1719302090775_WhatsApp_Image_20240625_at_130323_2.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090775_WhatsApp_Image_20240625_at_130323_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77caf891a97c5493907d",
  "name":
"externallmg_1719302090778_WhatsApp_Image_20240625_at_130323.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090778_WhatsApp_Image_20240625_at_130323.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77caf891a97c5493907e",
  "name":
"externallmg_1719302090781_WhatsApp_Image_20240625_at_130324_1.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090781_WhatsApp_Image_20240625_at_130324_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77caf891a97c5493907f",
  "name":
"externallmg_1719302090782_WhatsApp_Image_20240625_at_130324_2.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090782_WhatsApp_Image_20240625_at_130324_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77caf891a97c54939080",
  "name":
"externallmg_1719302090785_WhatsApp_Image_20240625_at_130324_3.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090785_WhatsApp_Image_20240625_at_130324_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77caf891a97c54939081",
  "name":
"externallmg_1719302090787_WhatsApp_Image_20240625_at_130324.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090787_WhatsApp_Image_20240625_at_130324.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77caf891a97c54939082",
  "name":
"externallmg_1719302090789_WhatsApp_Image_20240625_at_130325_1.jpeg",
```

```
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090789_WhatsApp_Image_20240625_at_130325_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77caf891a97c54939083",
    "name":
"externallmg_1719302090791_WhatsApp_Image_20240625_at_130325_2.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090791_WhatsApp_Image_20240625_at_130325_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77caf891a97c54939084",
    "name":
"externallmg_1719302090793_WhatsApp_Image_20240625_at_130325.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090793_WhatsApp_Image_20240625_at_130325.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77caf891a97c54939085",
    "name":
"externallmg_1719302090795_WhatsApp_Image_20240625_at_130326_1.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302090795_WhatsApp_Image_20240625_at_130326_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77d791e9187c1a923881",
    "name":
"externallmg_1719302103155_WhatsApp_Image_20240625_at_130326_1.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302103155_WhatsApp_Image_20240625_at_130326_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "667a77d791e9187c1a923882",
  "name":
"externallmg_1719302103158_WhatsApp_Image_20240625_at_130326_2.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302103158_WhatsApp_Image_20240625_at_130326_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77d791e9187c1a923883",
  "name":
"externallmg_1719302103161_WhatsApp_Image_20240625_at_130326.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302103161_WhatsApp_Image_20240625_at_130326.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77d791e9187c1a923884",
  "name":
"externallmg_1719302103163_WhatsApp_Image_20240625_at_130327_1.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302103163_WhatsApp_Image_20240625_at_130327_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77d791e9187c1a923885",
  "name":
"externallmg_1719302103165_WhatsApp_Image_20240625_at_130327.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302103165_WhatsApp_Image_20240625_at_130327.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a77d791e9187c1a923886",
  "name":
"externallmg_1719302103167_WhatsApp_Image_20240625_at_130305.jpeg",
  "path": "cases/667947cc4c08775ede708352/
externallmg_1719302103167_WhatsApp_Image_20240625_at_130305.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77d791e9187c1a923887",
    "name":
"externallmg_1719302103171_WhatsApp_Image_20240625_at_130306.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302103171_WhatsApp_Image_20240625_at_130306.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a77d791e9187c1a923888",
    "name":
"externallmg_1719302103174_WhatsApp_Image_20240625_at_130307.jpeg",
    "path": "cases/667947cc4c08775ede708352/
externallmg_1719302103174_WhatsApp_Image_20240625_at_130307.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-24T10:17:48.809Z",
"updatedAt": "2024-06-25T07:55:03.331Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 304, 3rd Floor, Prasad CHSL, 60 Feet Road, Near
Mandvi Bank , Bhaynder West, Bhaynder",
"updatedBy": "6006d4ce5080a310ac1fd2",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "CHAMPABEN FUTERMAL KHUTER PROPOSED
PURCHASER VIKRAM JAIN",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": ""
```

"proposePurchaserName": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"siteVisitContactNo": "9833098531"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			