

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9b2"
    },
    "firstName": "gaurav",
    "type": "CREDITOFFICER",
    "_id": "65f130a2857bdc098a9c101c",
    "lastName": "Rai",
    "mobileNo": "",
    "workMobileNo": "9768047284",
    "email": "gaurav.raai@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "10000000",
    "discussWithPerson": "gaurav",
    "expectedFees": 5000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9b2",
  "branchCode": "000012",
  "type": "BRANCH",
  "name": "Bandra (West) Branch",
  "email": "pratibha.bhatia@cosmosbank.in",
  "mobileNo": "02226402884",
  "alternateMobileNo": "",
  "address": "16, Lubina Turner Road, Opp. Tava Restaurant Bandra (West), Mumbai -
400 050, State - Maharashtra, Country - India.",
  "ledgerName": "COSMOS BANK- BANDRA WEST BRANCH",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "640c34384dda382753e651f2",
  "role": "SITEENGINEER",
  "firstName": "Prashant ",
  "email": "kasarprashant121@gmail.com",
  "lastName": "Kasar",
  "mobileNo": "9892524464",
  "designation": "",
  "shortName": "PK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/640c34384dda382753e651f2/
profilePhoto_1678521400647_WhatsApp_Image_20230311_at_12047_PM.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
```

```
{
  "title": {
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
```

```
"latitude": "19.19409575099775",
"longitude": "73.19693713743352"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.19693713743352,
    19.19409575099775
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "25/06/2024 03:40 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Morivali",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "D3",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Ambernath",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Royal Park Wings D1 to D6 CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "Type D",
```

```
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```



```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "501",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Ambernath",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
}
```

```
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
```

```
"title": "Showcases",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
```



```
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "667a559ff891a97c5493693d",
"ownerName": "Prashant Baban Sadafule ",
"ownerPhoneNo": "8369613749",
"appAddress": "Flat no 501, 5th floor, Bldg no D 3, building type - D, Royal park, D1 to
D3, co op hsg Ltd, Morivali,Ambarnath East ",
"remark": "p Bayer case - Mukesh Gajbhiye & Mangla Gajbhiye \n",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/667a559ff891a97c5493693d/
document_1719297095534_.1719296962858_Sadafule_",
    "fileName": "document_1719297095534_.1719296962858_Sadafule_",
    "id": "452887",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Tue Jun 25 2024 12:02:24 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "009497",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "152745",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jun 25 2024 10:59:03 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Prashant Baban Sadafule ",
    "phone": "8369613749",
    "ownershipShare": "",
    "email": ""
  }
]
```

```
    "id": "872248"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a98cd4348955719e209f1",
    "name":
"externallmg_1719310540842_WhatsApp_Image_20240624_at_092231_1.jpeg",
    "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310540842_WhatsApp_Image_20240624_at_092231_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a98cd4348955719e209f2",
    "name":
"externallmg_1719310540846_WhatsApp_Image_20240624_at_092231_2.jpeg",
    "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310540846_WhatsApp_Image_20240624_at_092231_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a98cd4348955719e209f3",
    "name":
"externallmg_1719310540851_WhatsApp_Image_20240624_at_092232_1.jpeg",
    "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310540851_WhatsApp_Image_20240624_at_092232_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a98cd4348955719e209f4",
```

```
    "name":
"externallmg_1719310540854_WhatsApp_Image_20240624_at_092232_2.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310540854_WhatsApp_Image_20240624_at_092232_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98cd4348955719e209f5",
  "name":
"externallmg_1719310540858_WhatsApp_Image_20240624_at_092232.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310540858_WhatsApp_Image_20240624_at_092232.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98cd4348955719e209f6",
  "name":
"externallmg_1719310540861_WhatsApp_Image_20240624_at_092233_1.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310540861_WhatsApp_Image_20240624_at_092233_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98cd4348955719e209f7",
  "name":
"externallmg_1719310540864_WhatsApp_Image_20240624_at_092233_2.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310540864_WhatsApp_Image_20240624_at_092233_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98cd4348955719e209f8",
  "name":
"externallmg_1719310540868_WhatsApp_Image_20240624_at_092233.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310540868_WhatsApp_Image_20240624_at_092233.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98cd4348955719e209f9",
  "name":
"externallmg_1719310540870_WhatsApp_Image_20240624_at_092234_1.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310540870_WhatsApp_Image_20240624_at_092234_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98cd4348955719e209fa",
  "name":
"externallmg_1719310540873_WhatsApp_Image_20240624_at_092234.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310540873_WhatsApp_Image_20240624_at_092234.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98cd4348955719e209fb",
  "name":
"externallmg_1719310540875_WhatsApp_Image_20240624_at_092235_1.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310540875_WhatsApp_Image_20240624_at_092235_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98cd4348955719e209fc",
  "name":
"externallmg_1719310540877_WhatsApp_Image_20240624_at_092235_2.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310540877_WhatsApp_Image_20240624_at_092235_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98cd4348955719e209fd",
  "name":
"externallmg_1719310540880_WhatsApp_Image_20240624_at_092235.jpeg",
```

```
    "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310540880_WhatsApp_Image_20240624_at_092235.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a98cd4348955719e209fe",
    "name":
"externallmg_1719310540883_WhatsApp_Image_20240624_at_092236_1.jpeg",
    "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310540883_WhatsApp_Image_20240624_at_092236_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a98dd4348955719e20b0a",
    "name":
"externallmg_1719310555687_WhatsApp_Image_20240624_at_092236_1.jpeg",
    "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310555687_WhatsApp_Image_20240624_at_092236_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a98dd4348955719e20b0b",
    "name":
"externallmg_1719310555764_WhatsApp_Image_20240624_at_092236_2.jpeg",
    "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310555764_WhatsApp_Image_20240624_at_092236_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a98dd4348955719e20b0c",
    "name":
"externallmg_1719310555767_WhatsApp_Image_20240624_at_092236.jpeg",
    "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310555767_WhatsApp_Image_20240624_at_092236.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "667a98dd4348955719e20b0d",
  "name":
"externallmg_1719310555771_WhatsApp_Image_20240624_at_092237_1.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310555771_WhatsApp_Image_20240624_at_092237_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98dd4348955719e20b0e",
  "name":
"externallmg_1719310555786_WhatsApp_Image_20240624_at_092237_2.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310555786_WhatsApp_Image_20240624_at_092237_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98dd4348955719e20b0f",
  "name":
"externallmg_1719310555789_WhatsApp_Image_20240624_at_092237.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310555789_WhatsApp_Image_20240624_at_092237.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98dd4348955719e20b10",
  "name":
"externallmg_1719310555792_WhatsApp_Image_20240624_at_092238_1.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310555792_WhatsApp_Image_20240624_at_092238_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98dd4348955719e20b11",
  "name":
"externallmg_1719310555795_WhatsApp_Image_20240624_at_092238.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310555795_WhatsApp_Image_20240624_at_092238.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a98dd4348955719e20b12",
    "name":
"externallmg_1719310556157_WhatsApp_Image_20240624_at_092239_1.jpeg",
    "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310556157_WhatsApp_Image_20240624_at_092239_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a98dd4348955719e20b13",
    "name":
"externallmg_1719310556284_WhatsApp_Image_20240624_at_092239_2.jpeg",
    "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310556284_WhatsApp_Image_20240624_at_092239_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a98dd4348955719e20b14",
    "name":
"externallmg_1719310556288_WhatsApp_Image_20240624_at_092239.jpeg",
    "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310556288_WhatsApp_Image_20240624_at_092239.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a98dd4348955719e20b15",
    "name":
"externallmg_1719310556292_WhatsApp_Image_20240624_at_092221.jpeg",
    "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310556292_WhatsApp_Image_20240624_at_092221.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a98dd4348955719e20b16",
```

```
"name":
"externallmg_1719310556314_WhatsApp_Image_20240624_at_092222.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310556314_WhatsApp_Image_20240624_at_092222.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98dd4348955719e20b17",
  "name":
"externallmg_1719310556740_WhatsApp_Image_20240624_at_092224.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310556740_WhatsApp_Image_20240624_at_092224.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98dd4348955719e20b18",
  "name":
"externallmg_1719310556745_WhatsApp_Image_20240624_at_092230_1.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310556745_WhatsApp_Image_20240624_at_092230_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98dd4348955719e20b19",
  "name":
"externallmg_1719310556749_WhatsApp_Image_20240624_at_092230_2.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310556749_WhatsApp_Image_20240624_at_092230_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98dd4348955719e20b1a",
  "name":
"externallmg_1719310556766_WhatsApp_Image_20240624_at_092230.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310556766_WhatsApp_Image_20240624_at_092230.jpeg",
  "orientation": "portrait"
},
},
```



```

{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a98dd4348955719e20b1b",
  "name":
"externallmg_1719310556771_WhatsApp_Image_20240624_at_092231.jpeg",
  "path": "cases/667a559ff891a97c5493693d/
externallmg_1719310556771_WhatsApp_Image_20240624_at_092231.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-25T05:29:03.477Z",
"updatedAt": "2024-06-25T10:15:57.261Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 501, 5th Floor, Building No D3, Wing - Type D,
Royal Park Wings D1 to D6 CHSL, Village - Morivali, Ambernath, Ambernath",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Prashant Baban Sadafule ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8369613749"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
