

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "66752eda24f3ba1343e7b978"
    },
    "firstName": "Sing",
    "type": "CREDITOFFICER",
    "_id": "667a7321f891a97c54938ba9",
    "email": "bom214@mahabank.co.in",
    "lastName": "Sir",
    "mobileNo": "1800233452",
    "workMobileNo": "9175179869"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "10620"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "66752eda24f3ba1343e7b978",
  "name": "COLLEGE CAMPUS-NASIK",
  "branchCode": "000214",
  "mobileNo": "1800-102-2636",
  "alternateMobileNo": "18002334526",
  "email": "bom214@mahabank.co.in",
  "ledgerName": "Sir",
  "sendStructuralCertificate": "0",
  "address": "College Rd, Krishi Nagar COLLEGE CAMPUS, COLLEGE ROAD, NASIK
422005"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "65b75f26e1e7bf61f3d19e98",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9f4adce84bf289ba9956e",
    "role": "FRONTDESK + ENGINEER",
```

```
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1717656808118_image.jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1717656808118_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "647ed1960ab64c23c9fcf71d",
"role": "FRONTDESK",
"firstName": "Rishidatt",
"email": "rishiyadav44444@gamil.com",
"lastName": "Yadav",
"mobileNo": "9404341081",
"designation": ""
```

```
    "shortName": "RV",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.914976526751538",
  "longitude": "73.82536318377753"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
```

```
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Sansari",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "C-2",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
}
```

```
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
```

```
"value": " Red Colour Wash, ndrayani Society",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Off Anand Road, Deolal",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Behind Sant Rajinder Singh Ji Maharaj Satsang",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Vini Park - Phase III ",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
```

```
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "004",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
```



```
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422401",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    }
  },
}
```

```
"taxies": {
  "title": "Taxies"
},
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
```

```
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
```

```
"title": "Interior Decorations",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
```

```
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "667a9832968b1257131beae7",
"ownerName": "Sanjay Mhavel",
"ownerPhoneNo": "8308843496",
"fullAddress": "Residential Flat No. 004, Ground Floor, Building No C-2, Vini Park -
Phase III , Behind Sant Rajinder Singh Ji Maharaj Satsang, Red Colour Wash,
ndrayani Societyi, Off Anand Road, Deolal, Village - Sansari, Nashik, 422401",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1719310136424_20240508VINI_PARK_PHASE_3DECLAR
```



```
ATION_FORM_Z.pdf",
  "path": "cases/667a9832968b1257131beae7/document_1719310136424_20240508
VINI_PARK_PHASE_3DECLARATION_FORM_Z.pdf",
  "id": "356226",
  "uploadedBy": "63f9f4adce84bf289ba9956e",
  "createdAt": "Tue Jun 25 2024 15:43:05 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1719310149934_20240508VINI_PARK_PHASE_3FORM_Y.pdf",
  "path": "cases/667a9832968b1257131beae7/
document_1719310149934_20240508VINI_PARK_PHASE_3FORM_Y.pdf",
  "id": "382815",
  "uploadedBy": "63f9f4adce84bf289ba9956e",
  "createdAt": "Tue Jun 25 2024 15:43:05 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1719310165188_20240511VINI_PARK_PHASE_3Scheme_
Document_with_annexure.pdf",
  "path": "cases/667a9832968b1257131beae7/document_1719310165188_20240511
VINI_PARK_PHASE_3Scheme_Document_with_annexure.pdf",
  "id": "235765",
  "uploadedBy": "63f9f4adce84bf289ba9956e",
  "createdAt": "Tue Jun 25 2024 15:43:05 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b308",
    "label": "Building Plan"
  },
  "inputs": {
    "nameOfApprovingAuthority": {
      "value": "Nashik_Municipal_Corporation",
      "label": "Nashik Municipal Corporation"
    }
  }
}
```

```
    }
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1719310311484_DocScanner_21Jun2024_435_pm.pdf",
  "path": "cases/667a9832968b1257131beae7/
document_1719310311484_DocScanner_21Jun2024_435_pm.pdf",
  "id": "949126",
  "uploadedBy": "63f9f4adce84bf289ba9956e",
  "createdAt": "Tue Jun 25 2024 15:43:05 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1719310332567_Flat_no_04.pdf",
  "path": "cases/667a9832968b1257131beae7/
document_1719310332567_Flat_no_04.pdf",
  "id": "184253",
  "uploadedBy": "63f9f4adce84bf289ba9956e",
  "createdAt": "Tue Jun 25 2024 15:43:05 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1248aa6d152c1801b2ee",
    "label": "Previous Valuation Report"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1719310351161_MRSANJAY_DIGAMBAR_MALVE1201202
3_Valution_Report.pdf",
  "path": "cases/667a9832968b1257131beae7/document_1719310351161_MRSANJ
AY_DIGAMBAR_MALVE12012023_Valution_Report.pdf",
  "id": "263949",
  "uploadedBy": "63f9f4adce84bf289ba9956e",
  "createdAt": "Tue Jun 25 2024 15:43:05 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
```

```
    "displayStatus": false,
    "fileName": "document_1719310366703_VINI_PARK_PHASE_3_FORM_A_Statement_A__B_and_ANNEXUREVIISTATEMENT_C.pdf",
    "path": "cases/667a9832968b1257131beae7/document_1719310366703_VINI_PARK_PHASE_3_FORM_A_Statement_A__B_and_ANNEXUREVIISTATEMENT_C.pdf",
    "id": "238993",
    "uploadedBy": "63f9f4adce84bf289ba9956e",
    "createdAt": "Tue Jun 25 2024 15:43:05 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "009515",
"createdBy": "63f9f4adce84bf289ba9956e",
"caseHistory": [
  {
    "id": "443191",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jun 25 2024 15:43:06 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Sanjay Mhavel",
    "phone": "8308843496",
    "ownershipShare": "",
    "email": "",
    "id": "381539"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a988c968b1257131bec0e",
```

```
"name":
"externallmg_1719310471121_WhatsApp_Image_20240621_at_175305.jpeg",
  "path": "cases/667a9832968b1257131beae7/
externallmg_1719310471121_WhatsApp_Image_20240621_at_175305.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a988c968b1257131bec0f",
  "name":
"externallmg_1719310474269_WhatsApp_Image_20240621_at_175306_1.jpeg",
  "path": "cases/667a9832968b1257131beae7/
externallmg_1719310474269_WhatsApp_Image_20240621_at_175306_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a988c968b1257131bec10",
  "name":
"externallmg_1719310474420_WhatsApp_Image_20240621_at_175306.jpeg",
  "path": "cases/667a9832968b1257131beae7/
externallmg_1719310474420_WhatsApp_Image_20240621_at_175306.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a988c968b1257131bec11",
  "name":
"externallmg_1719310474542_WhatsApp_Image_20240621_at_175307_1.jpeg",
  "path": "cases/667a9832968b1257131beae7/
externallmg_1719310474542_WhatsApp_Image_20240621_at_175307_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a988c968b1257131bec12",
  "name":
"externallmg_1719310474596_WhatsApp_Image_20240621_at_175307.jpeg",
  "path": "cases/667a9832968b1257131beae7/
externallmg_1719310474596_WhatsApp_Image_20240621_at_175307.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a988c968b1257131bec13",
  "name":
"externallmg_1719310474707_WhatsApp_Image_20240621_at_175308_1.jpeg",
  "path": "cases/667a9832968b1257131beae7/
externallmg_1719310474707_WhatsApp_Image_20240621_at_175308_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a988c968b1257131bec14",
  "name":
"externallmg_1719310474772_WhatsApp_Image_20240621_at_175308.jpeg",
  "path": "cases/667a9832968b1257131beae7/
externallmg_1719310474772_WhatsApp_Image_20240621_at_175308.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a988c968b1257131bec15",
  "name":
"externallmg_1719310474829_WhatsApp_Image_20240621_at_175309_1.jpeg",
  "path": "cases/667a9832968b1257131beae7/
externallmg_1719310474829_WhatsApp_Image_20240621_at_175309_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a988c968b1257131bec16",
  "name":
"externallmg_1719310474898_WhatsApp_Image_20240621_at_175309.jpeg",
  "path": "cases/667a9832968b1257131beae7/
externallmg_1719310474898_WhatsApp_Image_20240621_at_175309.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667a988c968b1257131bec17",
  "name":
"externallmg_1719310474943_WhatsApp_Image_20240621_at_175310_1.jpeg",
```

```
    "path": "cases/667a9832968b1257131beae7/
externallmg_1719310474943_WhatsApp_Image_20240621_at_175310_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a988c968b1257131bec18",
    "name":
"externallmg_1719310474991_WhatsApp_Image_20240621_at_175310.jpeg",
    "path": "cases/667a9832968b1257131beae7/
externallmg_1719310474991_WhatsApp_Image_20240621_at_175310.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a988c968b1257131bec19",
    "name":
"externallmg_1719310475120_WhatsApp_Image_20240621_at_175311.jpeg",
    "path": "cases/667a9832968b1257131beae7/
externallmg_1719310475120_WhatsApp_Image_20240621_at_175311.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a988c968b1257131bec1a",
    "name":
"externallmg_1719310475189_WhatsApp_Image_20240621_at_175312_1.jpeg",
    "path": "cases/667a9832968b1257131beae7/
externallmg_1719310475189_WhatsApp_Image_20240621_at_175312_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a988c968b1257131bec1b",
    "name":
"externallmg_1719310475239_WhatsApp_Image_20240621_at_175313_1.jpeg",
    "path": "cases/667a9832968b1257131beae7/
externallmg_1719310475239_WhatsApp_Image_20240621_at_175313_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "667a988c968b1257131bec1c",
    "name":
"externallmg_1719310475383_WhatsApp_Image_20240621_at_175313.jpeg",
    "path": "cases/667a9832968b1257131beae7/
externallmg_1719310475383_WhatsApp_Image_20240621_at_175313.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a988c968b1257131bec1d",
    "name":
"externallmg_1719310475482_WhatsApp_Image_20240621_at_175314_1.jpeg",
    "path": "cases/667a9832968b1257131beae7/
externallmg_1719310475482_WhatsApp_Image_20240621_at_175314_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a988c968b1257131bec1e",
    "name":
"externallmg_1719310475608_WhatsApp_Image_20240621_at_175314.jpeg",
    "path": "cases/667a9832968b1257131beae7/
externallmg_1719310475608_WhatsApp_Image_20240621_at_175314.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a988c968b1257131bec1f",
    "name":
"externallmg_1719310475730_WhatsApp_Image_20240621_at_175315_1.jpeg",
    "path": "cases/667a9832968b1257131beae7/
externallmg_1719310475730_WhatsApp_Image_20240621_at_175315_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a988c968b1257131bec20",
    "name":
"externallmg_1719310475906_WhatsApp_Image_20240621_at_175315.jpeg",
    "path": "cases/667a9832968b1257131beae7/
externallmg_1719310475906_WhatsApp_Image_20240621_at_175315.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a988c968b1257131bec21",
    "name":
"externallmg_1719310476079_WhatsApp_Image_20240621_at_175316_1.jpeg",
    "path": "cases/667a9832968b1257131beae7/
externallmg_1719310476079_WhatsApp_Image_20240621_at_175316_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a989b4348955719e20935",
    "name":
"externallmg_1719310490831_WhatsApp_Image_20240621_at_175316.jpeg",
    "path": "cases/667a9832968b1257131beae7/
externallmg_1719310490831_WhatsApp_Image_20240621_at_175316.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a989b4348955719e20936",
    "name":
"externallmg_1719310491163_WhatsApp_Image_20240621_at_175317_1.jpeg",
    "path": "cases/667a9832968b1257131beae7/
externallmg_1719310491163_WhatsApp_Image_20240621_at_175317_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667a989b4348955719e20937",
    "name":
"externallmg_1719310491489_WhatsApp_Image_20240621_at_175317.jpeg",
    "path": "cases/667a9832968b1257131beae7/
externallmg_1719310491489_WhatsApp_Image_20240621_at_175317.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
```



```
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-25T10:13:06.083Z",
"updatedAt": "2024-06-25T10:14:51.897Z",
"__v": 0,
"updatedBy": "63f9f4adce84bf289ba9956e",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Sanjay Mhavel",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8308843496"
```

}

Name	Length	Width	Total
Composition :			
Other			
Composition :			