

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6414170d720a3b25a9f3ba43"
    },
    "firstName": "Kalpana Jadhav",
    "type": "CREDITOFFICER",
    "_id": "6408311c22e33423764693b2",
    "lastName": "Jadhav",
    "mobileNo": "",
    "workMobileNo": "7447429162",
    "email": "kalpana@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Kalpana Jadhav",
    "expectedFees": null,
    "quotedAmount": "4000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6414170d720a3b25a9f3ba43",
  "name": "Chembur East Branch\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "cosmos@cosmos.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Plot no 239. Ground floor. Central avenue road. Near ambedkar garden.
Chembur east . Mumbai 400071\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "60b7177d2ffdf65bcd65882a",
"role": "PICKUPPERSON",
"firstName": "Saurabh",
"email": "saurabhvelonde143@gmail.com",
"lastName": "Velonde",
"mobileNo": "8691048846",
"shortName": "SSV",
"workWithDocumentMaker": "",
"profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f9462345132d6a6bddb9d5",
"role": "SITEENGINEER",
"firstName": "Dashrath ",
"email": "dasrat.jaiswar1234@gmail.com",
"lastName": "Jaiswar",
"mobileNo": "9987305468",
"designation": "",
"shortName": "DFJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
}
]
```

```
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
```

```
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.0144560463429",
  "longitude": "72.82946870560026"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82946870560026,
    19.0144560463429
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "26/06/2024 09:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
```

```
"status": true,
"name": "Country",
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Sewari",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "22",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "B2",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
```

```
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Krypton CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "156 Jakaria Bunder ROad",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
```

```
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
}
```



```
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2201",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
```

```
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Sewari West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
},
"landAndBuildingDetails": {
```

```
"actualBuildingBoundaries": [],
"documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
}
```

```
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```



```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"invoices": [],
"paymentIds": [],
"_id": "667ac51c968b1257131c1c88",
"ownerName": "Shabir Rajkotvala",
"ownerPhoneNo": "9136465560",
"appAddress": "Flat no. 2201, 22nd Floor, Krypton Twin tower, Building no. B, Sewri
West",
"remark": "visit Tomorrow ",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/667ac51c968b1257131c1c88/
document_1719321838063_1719321705550_New_Doc_06122024_1504.pdf",
    "fileName":
"document_1719321838063_1719321705550_New_Doc_06122024_1504.pdf",
    "id": "803934",
    "uploadedBy": "60b7177d2ffdf65bcd65882a",
    "createdAt": "Tue Jun 25 2024 18:54:44 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Other",
      "value": "60ae124eaa6d152c1801b30b"
    },
    "isHardCopy": false,
```

```
    "displayStatus": false,
    "path": "cases/667ac51c968b1257131c1c88/
document_1719321882349_46874.pdf",
    "fileName": "document_1719321882349_46874.pdf",
    "id": "533245",
    "uploadedBy": "60b7177d2ffdf65bcd65882a",
    "createdAt": "Tue Jun 25 2024 18:54:44 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "009527",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "636638",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jun 25 2024 18:54:44 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Shabir Rajkotvala",
    "phone": "9136465560",
    "ownershipShare": "",
    "email": "",
    "id": "542059"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "667cf516c01ce75768835936",
    "name": "externalImg_1719465236570_1719465098160_image_0.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externalImg_1719465236570_1719465098160_image_0.jpeg",
    "orientation": "portrait"
  }
],
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "667cf516c01ce75768835937",
  "name": "externallmg_1719465236595_1719465098160_image_1.jpeg",
  "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465236595_1719465098160_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "667cf516c01ce75768835938",
  "name": "externallmg_1719465236778_1719465098160_image_2.jpeg",
  "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465236778_1719465098160_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "667cf516c01ce75768835939",
  "name": "externallmg_1719465236916_1719465098160_image_3.jpeg",
  "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465236916_1719465098160_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "667cf516c01ce7576883593a",
  "name": "externallmg_1719465237117_1719465098160_image_4.jpeg",
  "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465237117_1719465098160_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "667cf516c01ce7576883593b",
  "name": "externallmg_1719465237288_1719465098160_image_5.jpeg",
  "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465237288_1719465098160_image_5.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "667cf516c01ce7576883593c",
    "name": "externallmg_1719465237471_1719465098160_image_6.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465237471_1719465098160_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "667cf516c01ce7576883593d",
    "name": "externallmg_1719465237644_1719465098160_image_7.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465237644_1719465098160_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "667cf516c01ce7576883593e",
    "name": "externallmg_1719465237889_1719465098160_image_8.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465237889_1719465098160_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf541968b1257131cd7ba",
    "name": "externallmg_1719465278976_1719465143573_image_0.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465278976_1719465143573_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf541968b1257131cd7bb",
    "name": "externallmg_1719465279006_1719465143573_image_1.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465279006_1719465143573_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "667cf541968b1257131cd7bc",
  "name": "externallmg_1719465279135_1719465143573_image_2.jpeg",
  "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465279135_1719465143573_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667cf541968b1257131cd7bd",
  "name": "externallmg_1719465279362_1719465143573_image_3.jpeg",
  "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465279362_1719465143573_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667cf541968b1257131cd7be",
  "name": "externallmg_1719465279663_1719465143573_image_4.jpeg",
  "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465279663_1719465143573_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667cf541968b1257131cd7bf",
  "name": "externallmg_1719465279766_1719465143573_image_5.jpeg",
  "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465279766_1719465143573_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667cf541968b1257131cd7c0",
  "name": "externallmg_1719465279867_1719465143573_image_6.jpeg",
  "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465279867_1719465143573_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "667cf541968b1257131cd7c1",
    "name": "externallmg_1719465279972_1719465143573_image_7.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465279972_1719465143573_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf541968b1257131cd7c2",
    "name": "externallmg_1719465280029_1719465143573_image_8.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465280029_1719465143573_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf541968b1257131cd7c3",
    "name": "externallmg_1719465280090_1719465143573_image_9.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465280090_1719465143573_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf541968b1257131cd7c4",
    "name": "externallmg_1719465280143_1719465143573_image_10.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465280143_1719465143573_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf541968b1257131cd7c5",
    "name": "externallmg_1719465280200_1719465143573_image_11.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465280200_1719465143573_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf541968b1257131cd7c6",
```

```
    "name": "externallmg_1719465280251_1719465143573_image_12.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465280251_1719465143573_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf541968b1257131cd7c7",
    "name": "externallmg_1719465280308_1719465143573_image_13.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465280308_1719465143573_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf541968b1257131cd7c8",
    "name": "externallmg_1719465280495_1719465143573_image_14.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465280495_1719465143573_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf541968b1257131cd7c9",
    "name": "externallmg_1719465280591_1719465143573_image_15.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465280591_1719465143573_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf541968b1257131cd7ca",
    "name": "externallmg_1719465280698_1719465143573_image_16.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465280698_1719465143573_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf541968b1257131cd7cb",
    "name": "externallmg_1719465280787_1719465143573_image_17.jpeg",
```

```
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465280787_1719465143573_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf541968b1257131cd7cc",
    "name": "externallmg_1719465280938_1719465143573_image_18.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465280938_1719465143573_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf541968b1257131cd7cd",
    "name": "externallmg_1719465281061_1719465143573_image_19.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465281061_1719465143573_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf55fc01ce757688359b2",
    "name": "externallmg_1719465310416_1719465172917_image_0.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465310416_1719465172917_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf55fc01ce757688359b3",
    "name": "externallmg_1719465310519_1719465172917_image_1.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465310519_1719465172917_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667cf55fc01ce757688359b4",
    "name": "externallmg_1719465310643_1719465172917_image_2.jpeg",
    "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465310643_1719465172917_image_2.jpeg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667cf55fc01ce757688359b5",
  "name": "externallmg_1719465310827_1719465172917_image_3.jpeg",
  "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465310827_1719465172917_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667cf55fc01ce757688359b6",
  "name": "externallmg_1719465310957_1719465172917_image_4.jpeg",
  "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465310957_1719465172917_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667cf55fc01ce757688359b7",
  "name": "externallmg_1719465311078_1719465172917_image_5.jpeg",
  "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465311078_1719465172917_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667cf55fc01ce757688359b8",
  "name": "externallmg_1719465311206_1719465172917_image_6.jpeg",
  "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465311206_1719465172917_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667cf55fc01ce757688359b9",
  "name": "externallmg_1719465311308_1719465172917_image_7.jpeg",
  "path": "cases/667ac51c968b1257131c1c88/
externallmg_1719465311308_1719465172917_image_7.jpeg",
  "orientation": "portrait"
}
```

```
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "667c0fa9c01ce75768833999",
    "note": "Value Given For Confirmation ",
    "taskId": "667b8bc04348955719e251c7",
    "createdAt": "2024-06-26T12:55:05.076Z"
  }
],
"createdAt": "2024-06-25T13:24:44.947Z",
"updatedAt": "2024-06-27T05:15:11.658Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 2201, 22nd Floor, Building No B2, Krypton CHSL,
156 Jakaria Bunder ROad, Village - Sewari, Sewari West, Mumbai",
"updatedBy": "60f9462345132d6a6bddb9d5",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Shabir Rajkotvala",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9136465560"
```

}

Name

Length

Width

Total

Composition :

Other

Composition :
