

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6413f770e6a52007fbaadc8"
    },
    "firstName": "Vishakha ",
    "type": "CREDITOFFICER",
    "_id": "6413f770e6a52007fbaadcba",
    "lastName": "Mane",
    "mobileNo": "",
    "workMobileNo": "9833242472",
    "email": "vishakha.mane@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6413f770e6a52007fbaadcb8",
  "name": "Ambarnath Branch",
  "branchCode": "",
  "mobileNo": "02512990632\t",
  "alternateMobileNo": "",
  "email": "ambarnath@cosmosbank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Panvelkar Pride, Shop no 1 to 4, Plot no 63-64, C T S NO 4740, Near
Hutatma Chawk Ambarnath (East)\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "640c34384dda382753e651f2",
  "role": "SITEENGINEER",
  "firstName": "Prashant ",
  "email": "kasarprashant121@gmail.com",
  "lastName": "Kasar",
  "mobileNo": "9892524464",
  "designation": "",
  "shortName": "PK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/640c34384dda382753e651f2/
profilePhoto_1678521400647_WhatsApp_Image_20230311_at_12047_PM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "ACCOUNTANT",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.166368013356415",
  "longitude": "73.23240842865356"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kulgaon",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Badlapur West",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Ambarnath",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "3",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vaishnavi Krupa Co. - Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
}
```

```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Samarth Nagar Ramesh Wadi",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "73",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```



```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "401",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```

```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 421 503",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    }
  }
}
```

```
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
    },
    "builtUpRateRange": {
      "min": "0.00",
      "max": "0.00"
    },
    "saleableRateRange": {
      "min": "0.00",
      "max": "0.00"
    }
  },
  "detailsOfValuation": {
    "presentValueOfFlat": {
      "title": "Present value of the flat (incl. car parking, if provided)",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": false
    },
    "wardrobes": {
      "title": "Wardrobes",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "showcases": {
      "title": "Showcases",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "kitchenArrangements": {
      "title": "Kitchen arrangements",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "superfineFinish": {
      "title": "Superfine finish",
      "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```



```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "667d48abfe581f19554719ca",
"ownerName": "Mrs. Aparna Chandrakant Shinde ",
"ownerPhoneNo": "9370626192",
"fullAddress": "Residential Flat No. 401, 4th Floor, Vaishnavi Krupa Co. - Op. Hsg. Soc.
Ltd., Samarth Nagar Ramesh Wadi, Plot No. 3, Village - Kulgaon, Taluka - Ambarnath,
District - Thane, Badlapur West, PIN Code - 421 503, State - Maharashtra, India",
"remark": "",
"documents": [
```

```
{
  "documentType": {
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "inputs": {
    "documentDate": "24/06/2024",
    "from": {
      "value": "Vendor",
      "label": "Vendor"
    },
    "Vendor": "Mr. Sital Singh Pal ",
    "to": {
      "value": "purchaser",
      "label": "purchaser"
    },
    "purchaser": "Mrs. Aparna Chandrakant Shinde ",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "8709/2024"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1719486630334_Shinde_agr.pdf",
  "path": "cases/667d48abfe581f19554719ca/
document_1719486630334_Shinde_agr.pdf",
  "id": "127628",
  "uploadedBy": "656aa949cebbe1714411d21b",
  "createdAt": "Thu Jun 27 2024 16:40:35 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "27/07/2009",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  }
}
```

```
    },
    "No": "KBMC / BP / 532 - 119"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1719577519465_193566.pdf",
  "path": "cases/667d48abfe581f19554719ca/
document_1719577519465_193566.pdf",
  "id": "788318",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Fri Jun 28 2024 17:59:18 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "21/01/2012",
    "nameOfApprovingAuthority": {
      "value": "Kulgaon_Badlapur_Municipal_Council",
      "label": "Kulgaon Badlapur Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "KBMC / BP / 2415"
},
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1719577586425_104884.pdf",
  "path": "cases/667d48abfe581f19554719ca/
document_1719577586425_104884.pdf",
  "id": "509601",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Fri Jun 28 2024 17:59:18 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "6077c791395bc80714864a30",
    "label": "Electricity Bill"
  },
  "inputs": {
    "documentDate": "07/05/2024",
    "number": {
```

```
    "value": "Consumer_No",
    "label": "Consumer No"
  },
  "Consumer_No": "021540145412"
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1719577758739_129942.pdf",
"path": "cases/667d48abfe581f19554719ca/
document_1719577758739_129942.pdf",
"id": "799850",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Fri Jun 28 2024 17:59:18 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "009583",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "910705",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jun 27 2024 16:40:35 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Aparna Chandrakant Shinde ",
    "phone": "9370626192",
    "ownershipShare": "",
    "email": "",
    "id": "374725"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
```

```
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667e6b92af848d643f6b2788",
    "name":
"externalImg_1719561106252_WhatsApp_Image_20240628_at_123825_1.jpeg",
    "path": "cases/667d48abfe581f19554719ca/
externalImg_1719561106252_WhatsApp_Image_20240628_at_123825_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667e6b92af848d643f6b2789",
    "name":
"externalImg_1719561106258_WhatsApp_Image_20240628_at_123830_1.jpeg",
    "path": "cases/667d48abfe581f19554719ca/
externalImg_1719561106258_WhatsApp_Image_20240628_at_123830_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667e6b92af848d643f6b278a",
    "name":
"externalImg_1719561106262_WhatsApp_Image_20240628_at_123830_2.jpeg",
    "path": "cases/667d48abfe581f19554719ca/
externalImg_1719561106262_WhatsApp_Image_20240628_at_123830_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667e6b92af848d643f6b278b",
    "name":
"externalImg_1719561106270_WhatsApp_Image_20240628_at_123830.jpeg",
    "path": "cases/667d48abfe581f19554719ca/
externalImg_1719561106270_WhatsApp_Image_20240628_at_123830.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667e6b92af848d643f6b278c",
    "name":
"externalImg_1719561106276_WhatsApp_Image_20240628_at_123831_1.jpeg",
```

```
    "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561106276_WhatsApp_Image_20240628_at_123831_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667e6ba1871a6063fb0dcca",
    "name":
"externallmg_1719561121475_WhatsApp_Image_20240628_at_123831.jpeg",
    "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121475_WhatsApp_Image_20240628_at_123831.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667e6ba1871a6063fb0dccb",
    "name":
"externallmg_1719561121479_WhatsApp_Image_20240628_at_123832_1.jpeg",
    "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121479_WhatsApp_Image_20240628_at_123832_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667e6ba1871a6063fb0dccc",
    "name":
"externallmg_1719561121483_WhatsApp_Image_20240628_at_123832_2.jpeg",
    "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121483_WhatsApp_Image_20240628_at_123832_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667e6ba1871a6063fb0dccc",
    "name":
"externallmg_1719561121485_WhatsApp_Image_20240628_at_123832.jpeg",
    "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121485_WhatsApp_Image_20240628_at_123832.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "667e6ba1871a6063fb0dccde",
  "name":
"externallmg_1719561121488_WhatsApp_Image_20240628_at_123833_1.jpeg",
  "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121488_WhatsApp_Image_20240628_at_123833_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667e6ba1871a6063fb0dccdf",
  "name":
"externallmg_1719561121491_WhatsApp_Image_20240628_at_123833.jpeg",
  "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121491_WhatsApp_Image_20240628_at_123833.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667e6ba1871a6063fb0dcce0",
  "name":
"externallmg_1719561121494_WhatsApp_Image_20240628_at_123834_1.jpeg",
  "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121494_WhatsApp_Image_20240628_at_123834_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667e6ba1871a6063fb0dcce1",
  "name":
"externallmg_1719561121497_WhatsApp_Image_20240628_at_123834_2.jpeg",
  "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121497_WhatsApp_Image_20240628_at_123834_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667e6ba1871a6063fb0dcce2",
  "name":
"externallmg_1719561121500_WhatsApp_Image_20240628_at_123834.jpeg",
  "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121500_WhatsApp_Image_20240628_at_123834.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667e6ba1871a6063fb0dcce3",
    "name":
"externallmg_1719561121505_WhatsApp_Image_20240628_at_123835_1.jpeg",
    "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121505_WhatsApp_Image_20240628_at_123835_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667e6ba1871a6063fb0dcce4",
    "name":
"externallmg_1719561121508_WhatsApp_Image_20240628_at_123835_2.jpeg",
    "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121508_WhatsApp_Image_20240628_at_123835_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667e6ba1871a6063fb0dcce5",
    "name":
"externallmg_1719561121511_WhatsApp_Image_20240628_at_123835.jpeg",
    "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121511_WhatsApp_Image_20240628_at_123835.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667e6ba1871a6063fb0dcce6",
    "name":
"externallmg_1719561121517_WhatsApp_Image_20240628_at_123836_1.jpeg",
    "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121517_WhatsApp_Image_20240628_at_123836_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "667e6ba1871a6063fb0dcce7",
```



```
    "name":
"externallmg_1719561121521_WhatsApp_Image_20240628_at_123836.jpeg",
  "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121521_WhatsApp_Image_20240628_at_123836.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667e6ba1871a6063fb0dcce8",
  "name":
"externallmg_1719561121523_WhatsApp_Image_20240628_at_123837_1.jpeg",
  "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121523_WhatsApp_Image_20240628_at_123837_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667e6ba1871a6063fb0dcce9",
  "name":
"externallmg_1719561121528_WhatsApp_Image_20240628_at_123837.jpeg",
  "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121528_WhatsApp_Image_20240628_at_123837.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667e6ba1871a6063fb0dccea",
  "name":
"externallmg_1719561121536_WhatsApp_Image_20240628_at_123428.jpeg",
  "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121536_WhatsApp_Image_20240628_at_123428.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "667e6ba1871a6063fb0dcceb",
  "name":
"externallmg_1719561121540_WhatsApp_Image_20240628_at_123825.jpeg",
  "path": "cases/667d48abfe581f19554719ca/
externallmg_1719561121540_WhatsApp_Image_20240628_at_123825.jpeg",
  "orientation": "portrait"
}
}
```

```
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR.pdf",
    "filename": "1719576487739_AGR.pdf",
    "path": "cases/667d48abfe581f19554719ca/
processingDocuments/1719576487739_AGR.pdf",
    "size": "20932798",
    "createdAt": "Fri Jun 28 2024 17:38:11 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_1719561106276_WhatsApp_Image_20240628_at_123831_1.jpeg",
    "filename": "1719576490438_externallmg_1719561106276_WhatsApp_Image_202
40628_at_123831_1.jpeg",
    "path": "cases/667d48abfe581f19554719ca/processingDocuments/1719576490438
_externallmg_1719561106276_WhatsApp_Image_20240628_at_123831_1.jpeg",
    "size": "42829",
    "createdAt": "Fri Jun 28 2024 17:38:11 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_1719561121479_WhatsApp_Image_20240628_at_123832_1.jpeg",
    "filename": "1719576490482_externallmg_1719561121479_WhatsApp_Image_202
40628_at_123832_1.jpeg",
    "path": "cases/667d48abfe581f19554719ca/processingDocuments/1719576490482
_externallmg_1719561121479_WhatsApp_Image_20240628_at_123832_1.jpeg",
    "size": "52941",
    "createdAt": "Fri Jun 28 2024 17:38:11 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_1719561121483_WhatsApp_Image_20240628_at_123832_2.jpeg",
    "filename": "1719576490539_externallmg_1719561121483_WhatsApp_Image_202
40628_at_123832_2.jpeg",
    "path": "cases/667d48abfe581f19554719ca/processingDocuments/1719576490539
_externallmg_1719561121483_WhatsApp_Image_20240628_at_123832_2.jpeg",
    "size": "117437",
    "createdAt": "Fri Jun 28 2024 17:38:11 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {

```

```
"originalname":
"externallmg_1719561121491_WhatsApp_Image_20240628_at_123833.jpeg",
  "filename": "1719576490545_externallmg_1719561121491_WhatsApp_Image_202
40628_at_123833.jpeg",
  "path": "cases/667d48abfe581f19554719ca/processingDocuments/1719576490545
_externallmg_1719561121491_WhatsApp_Image_20240628_at_123833.jpeg",
  "size": "133132",
  "createdAt": "Fri Jun 28 2024 17:38:11 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname":
"externallmg_1719561121536_WhatsApp_Image_20240628_at_123428.jpeg",
  "filename": "1719576490549_externallmg_1719561121536_WhatsApp_Image_202
40628_at_123428.jpeg",
  "path": "cases/667d48abfe581f19554719ca/processingDocuments/1719576490549
_externallmg_1719561121536_WhatsApp_Image_20240628_at_123428.jpeg",
  "size": "117437",
  "createdAt": "Fri Jun 28 2024 17:38:11 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-01.pdf",
  "filename": "1719576490601_IGR01.pdf",
  "path": "cases/667d48abfe581f19554719ca/
processingDocuments/1719576490601_IGR01.pdf",
  "size": "157453",
  "createdAt": "Fri Jun 28 2024 17:38:11 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "IGR-02.pdf",
  "filename": "1719576490632_IGR02.pdf",
  "path": "cases/667d48abfe581f19554719ca/
processingDocuments/1719576490632_IGR02.pdf",
  "size": "155009",
  "createdAt": "Fri Jun 28 2024 17:38:11 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Summary New=APARNA.xlsx",
  "filename": "1719576490713_Summary_NewAPARNA.xlsx",
  "path": "cases/667d48abfe581f19554719ca/
processingDocuments/1719576490713_Summary_NewAPARNA.xlsx",
  "size": "3882917",
  "createdAt": "Fri Jun 28 2024 17:38:11 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-06-27T11:10:35.287Z",
"updatedAt": "2024-06-28T12:29:18.836Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mrs. Aparna Chandrakant Shinde ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9370626192"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			