

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64ddb919ccaf1e7b7f650a1e"
    },
    "firstName": "Nitin ",
    "type": "CREDITOFFICER",
    "_id": "64ddb919ccaf1e7b7f650a20",
    "lastName": "Gupta",
    "mobileNo": "",
    "workMobileNo": "8191099787",
    "email": "ubin0562335@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64ddb919ccaf1e7b7f650a1e",
  "name": "Vartak Nagar Branch",
  "branchCode": "",
  "mobileNo": "022 25855050",
  "alternateMobileNo": "",
  "email": "ubin0562335@unionbankofindia.bank",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Ground Floor, Jagdale Amizra, Kores Road, Near Aai Mata Temple,
Vartak Nagar, Thane West - 400606"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
  "shortName": "PS",
  "workWithDocumentMaker": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "65829f7c65d49d78457ec7be",
  "role": "SITEENGINEER",
  "firstName": "Vaibhav",
  "email": "vaib1234b@gmail.com",
  "lastName": "Bhagat",
  "mobileNo": "8779534609",
  "designation": "Bachlore Of Engireeing",
  "shortName": "Vaibhav",
  "workWithDocumentMaker": "62691c48afd7d55eddecfda3"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvantha",
  "mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.20602439909676",
  "longitude": "72.96100077305317"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Panchpakhadi",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "7",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "D-3",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Thane",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Thane (West)",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Vedant Phase - IV Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Pokhran Road No. 1",
  "label": false
}
```

```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Vedant Residential Complex, Vartak Nagar",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "143A/1(Part), 4 (Part), 5 (Part), 144A/1(Part), 2 (Part), 145(Part),
146/1(Part),2,3,4,5(Part), 6(Part), 147(Part), 148/1(Part), 2(Part), 4, 5, 6, 8 (Part),
149/1(Part), 2(Part), 3(Part)",
  "label": true
},
"hissaNo": {
```



```
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "703 & 703A",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
```

```
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 606",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    }
  },
}
```

```
"taxies": {
  "title": "Taxies"
},
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
"label": "Flooring, Tilling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```

```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "668b7963e61b5802e8d90199",
"ownerName": "Ms. Vaishnavi Keshav Mathkar & Mr. Abhishek Pramod Patke",
"ownerPhoneNo": "9920040912",
"fullAddress": "Residential Flat No. 703 & 703A, 7th Floor, Building No D-3, Vedant Phase - IV Co-Op. Hsg. Soc. Ltd., Vedant Residential Complex, Vartak Nagar, Pokhran Road No. 1, Village - Panchpakhadi, Taluka - Thane, District - Thane, Thane (West),
```

```
PIN Code - 400 606, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mrs. Vineeta Manoj Kedare & Mrs. Manoj Amrut Kedare",
      "to": {
        "value": "transferee",
        "label": "transferee"
      },
      "transferee": "Ms. Vaishnavi Keshav Mathkar & Mr. Abhishek Pramod Patke",
      "number": {
        "value": "property_no",
        "label": "property no"
      },
      "property_no": "7143 / 2014"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1720416464189_Agreement.pdf",
    "path": "cases/668b7963e61b5802e8d90199/
document_1720416464189_Agreement.pdf",
    "id": "687559",
    "uploadedBy": "627222afafd7d55eddeddd82",
    "createdAt": "Mon Jul 08 2024 11:00:11 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "009783",
"createdBy": "627222afafd7d55eddeddd82",
"caseHistory": [
  {
    "id": "698250",
    "title": "Create Lead",
    "description": "Create Lead",
```

```
    "datetime": "Mon Jul 08 2024 11:00:11 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Ms. Vaishnavi Keshav Mathkar & Mr. Abhishek Pramod Patke",
    "phone": "9920040912",
    "ownershipShare": "",
    "email": "",
    "id": "500388"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bc6e6e61b5802e8d95567",
    "name":
"externallmg_1720436453570_WhatsApp_Image_20240708_at_102744_AM_1.jpeg",
    "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436453570_WhatsApp_Image_20240708_at_102744_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bc6e6e61b5802e8d95568",
    "name":
"externallmg_1720436453606_WhatsApp_Image_20240708_at_102744_AM_2.jpeg",
    "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436453606_WhatsApp_Image_20240708_at_102744_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bc6e6e61b5802e8d95569",
    "name":
"externallmg_1720436453632_WhatsApp_Image_20240708_at_102744_AM.jpeg",
```

```
    "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436453632_WhatsApp_Image_20240708_at_102744_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bc6e6e61b5802e8d9556a",
    "name":
"externallmg_1720436453679_WhatsApp_Image_20240708_at_102745_AM_1.jpeg",
    "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436453679_WhatsApp_Image_20240708_at_102745_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bc6e6e61b5802e8d9556b",
    "name":
"externallmg_1720436453719_WhatsApp_Image_20240708_at_102745_AM_2.jpeg",
    "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436453719_WhatsApp_Image_20240708_at_102745_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bc6e6e61b5802e8d9556c",
    "name":
"externallmg_1720436453745_WhatsApp_Image_20240708_at_102745_AM_3.jpeg",
    "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436453745_WhatsApp_Image_20240708_at_102745_AM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bc6e6e61b5802e8d9556d",
    "name":
"externallmg_1720436453783_WhatsApp_Image_20240708_at_102745_AM.jpeg",
    "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436453783_WhatsApp_Image_20240708_at_102745_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "668bc6e6e61b5802e8d9556e",
  "name":
"externallmg_1720436453814_WhatsApp_Image_20240708_at_102746_AM_1.jpeg",
  "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436453814_WhatsApp_Image_20240708_at_102746_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bc6e6e61b5802e8d9556f",
  "name":
"externallmg_1720436453843_WhatsApp_Image_20240708_at_102746_AM_2.jpeg",
  "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436453843_WhatsApp_Image_20240708_at_102746_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bc6e6e61b5802e8d95570",
  "name":
"externallmg_1720436453874_WhatsApp_Image_20240708_at_102746_AM.jpeg",
  "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436453874_WhatsApp_Image_20240708_at_102746_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bc6e6e61b5802e8d95571",
  "name":
"externallmg_1720436453894_WhatsApp_Image_20240708_at_102747_AM_1.jpeg",
  "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436453894_WhatsApp_Image_20240708_at_102747_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bc6e6e61b5802e8d95572",
  "name":
"externallmg_1720436453920_WhatsApp_Image_20240708_at_102749_AM.jpeg",
  "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436453920_WhatsApp_Image_20240708_at_102749_AM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bc6e6e61b5802e8d95573",
    "name":
"externallmg_1720436453935_WhatsApp_Image_20240708_at_102750_AM_1.jpeg",
    "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436453935_WhatsApp_Image_20240708_at_102750_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bc6e6e61b5802e8d95574",
    "name":
"externallmg_1720436453983_WhatsApp_Image_20240708_at_102750_AM_2.jpeg",
    "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436453983_WhatsApp_Image_20240708_at_102750_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bc6e6e61b5802e8d95575",
    "name":
"externallmg_1720436454027_WhatsApp_Image_20240708_at_102750_AM.jpeg",
    "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436454027_WhatsApp_Image_20240708_at_102750_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bc6f311581202eccb3ced",
    "name":
"externallmg_1720436467172_WhatsApp_Image_20240708_at_102747_AM_2.jpeg",
    "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436467172_WhatsApp_Image_20240708_at_102747_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668bc6f311581202eccb3cee",
```

```
    "name":
"externallmg_1720436467174_WhatsApp_Image_20240708_at_102747_AM_3.jpeg",
  "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436467174_WhatsApp_Image_20240708_at_102747_AM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bc6f311581202eccb3cef",
  "name":
"externallmg_1720436467194_WhatsApp_Image_20240708_at_102747_AM.jpeg",
  "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436467194_WhatsApp_Image_20240708_at_102747_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bc6f311581202eccb3cf0",
  "name":
"externallmg_1720436467229_WhatsApp_Image_20240708_at_102748_AM_1.jpeg",
  "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436467229_WhatsApp_Image_20240708_at_102748_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bc6f311581202eccb3cf1",
  "name":
"externallmg_1720436467258_WhatsApp_Image_20240708_at_102748_AM_2.jpeg",
  "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436467258_WhatsApp_Image_20240708_at_102748_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bc6f311581202eccb3cf2",
  "name":
"externallmg_1720436467279_WhatsApp_Image_20240708_at_102748_AM_3.jpeg",
  "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436467279_WhatsApp_Image_20240708_at_102748_AM_3.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bc6f311581202eccb3cf3",
  "name":
"externallmg_1720436467299_WhatsApp_Image_20240708_at_102748_AM.jpeg",
  "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436467299_WhatsApp_Image_20240708_at_102748_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bc6f311581202eccb3cf4",
  "name":
"externallmg_1720436467335_WhatsApp_Image_20240708_at_102749_AM_1.jpeg",
  "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436467335_WhatsApp_Image_20240708_at_102749_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bc6f311581202eccb3cf5",
  "name":
"externallmg_1720436467364_WhatsApp_Image_20240708_at_102749_AM_2.jpeg",
  "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436467364_WhatsApp_Image_20240708_at_102749_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668bc6f311581202eccb3cf6",
  "name":
"externallmg_1720436467387_WhatsApp_Image_20240708_at_102749_AM_3.jpeg",
  "path": "cases/668b7963e61b5802e8d90199/
externallmg_1720436467387_WhatsApp_Image_20240708_at_102749_AM_3.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
```



```

{
  "createdBy": {
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "lastName": "Jadhav",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "668cebc6443ccd6cfd48deef",
  "note": "Pending for proper documents",
  "taskId": "668b7995e61b5802e8d901f3",
  "createdAt": "2024-07-09T07:50:30.917Z"
}
],
"createdAt": "2024-07-08T05:30:11.675Z",
"updatedAt": "2024-07-09T08:46:22.435Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddeddd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Ms. Vaishnavi Keshav Mathkar & Mr. Abhishek Pramod Patke",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9920040912"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			