

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "668d24fc8725c717d803c8f7"
    },
    "firstName": "Chandan",
    "type": "CREDITOFFICER",
    "_id": "668d25767f52501810a6c0af",
    "email": "bom14@mahabank.co.in",
    "lastName": "Mishra",
    "mobileNo": "25325063",
    "workMobileNo": "8856866501"
  },
  "fees": {
    "type": "quoted",
    "propertyValue": "0",
    "discussWithPerson": "Chintamani",
    "expectedFees": null,
    "quotedAmount": "0"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Mashusha Elite, Vrundavan Naka Link Road, Adgaon, ",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180e",
  "type": "BANK",
  "name": "Bank Of Maharashtra",
  "displayName": "Bank Of Maharashtra",
  "initial": "BOM",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "668d24fc8725c717d803c8f7",
  "name": "Nashik City Branch",
  "branchCode": "000014",
  "mobileNo": "+91 2532502951",
  "alternateMobileNo": "",
  "email": "bom14@mahabank.co.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Janmangal, Tilak Road, Nasik 422 001"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "65b75f26e1e7bf61f3d19e98",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "63f9ed37ce84bf289ba991ac",
    "role": "FRONTDESK",
    "firstName": "Rushikesh",
```

```
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "636a29b64d42487767af43ea",
"role": "NASHIK (LEAD + VISIT + RATE)",
"firstName": "Sachin",
"email": "sachinraundal9021@gmail.com",
"lastName": "Raundal",
"mobileNo": "9021337843",
"designation": "Site Engg",
"shortName": "Sachin",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "Chintamani",
```

```
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "email": "binu@vastukala.org",
    "lastName": "Moozhickal",
    "mobileNo": "9930252906",
    "designation": "Back Office Team Leader",
    "shortName": "BS",
    "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "valuers": [],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.992640373688925",
  "longitude": "73.76216604929333"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "9/07/2024 05:32 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "NAshik",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
```

```
"value": "Nashik",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "65",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ushakiran Co.Op.Hsg.Society.Ltd",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": true,
"name": "Street 1",
"key": "street1",
"value": "Mahatma Nagar Untwadi Road",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Opposite Ganpati Mandir, Forest Colony, Parijat Nagar, ",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "746/1/8",
```

```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```



```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422005",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
```

```
"buses": {
  "title": "Buses"
},
"taxies": {
  "title": "Taxies"
},
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
```

```
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
}
```

```
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "668d2746d9bf3d181108e782",
"ownerName": "Hiren Chaudhari ",
"ownerPhoneNo": "9604154626",
```


"fullAddress": "Residential Land and Building No. 2nd Floor, Ushakiran Co.Op.Hsg.Society.Ltd, Opposite Ganpati Mandir, Forest Colony, Parijat Nagar, , Plot No. 65, New/Current Survey No. 746/1/8, Mahatma Nagar Untwadi Road, Village - NASHIK, Taluka - Nashik, District - Nashik, Nashik, 422005",

"remark": "",

"documents": [

{

"documentType": {

"value": "60ae124aaa6d152c1801b2f7",

"label": "Any Other Document"

},

"isHardCopy": false,

"displayStatus": false,

"fileName": "document_1720526592444_7_12.pdf",

"path": "cases/668d2746d9bf3d181108e782/document_1720526592444_7_12.pdf",

"id": "615024",

"uploadedBy": "63f9ed37ce84bf289ba991ac",

"createdAt": "Tue Jul 09 2024 17:34:22 GMT+0530 (India Standard Time)"

},

{

"documentType": {

"value": "60ae124aaa6d152c1801b2f7",

"label": "Any Other Document"

},

"isHardCopy": false,

"displayStatus": false,

"fileName": "document_1720526601279_Agreement.pdf",

"path": "cases/668d2746d9bf3d181108e782/

document_1720526601279_Agreement.pdf",

"id": "994276",

"uploadedBy": "63f9ed37ce84bf289ba991ac",

"createdAt": "Tue Jul 09 2024 17:34:22 GMT+0530 (India Standard Time)"

},

{

"documentType": {

"value": "60ae124aaa6d152c1801b2f7",

"label": "Any Other Document"

},

"isHardCopy": false,

"displayStatus": false,

"fileName":

"document_1720526607861_Chauthari_Hiren__Ushakiran_CHS_Ltd_ATS.pdf",

"path": "cases/668d2746d9bf3d181108e782/

document_1720526607861_Chauthari_Hiren__Ushakiran_CHS_Ltd_ATS.pdf",

"id": "827674",

"uploadedBy": "63f9ed37ce84bf289ba991ac",

```
"createdAt": "Tue Jul 09 2024 17:34:22 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1720526613414_CC__OC.pdf",
  "path": "cases/668d2746d9bf3d181108e782/
document_1720526613414_CC__OC.pdf",
  "id": "341976",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Jul 09 2024 17:34:22 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1720526621461_Chauthari_layout_.pdf",
  "path": "cases/668d2746d9bf3d181108e782/
document_1720526621461_Chauthari_layout_.pdf",
  "id": "368559",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Jul 09 2024 17:34:22 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1720526628122_chauthari_Plan.pdf",
  "path": "cases/668d2746d9bf3d181108e782/
document_1720526628122_chauthari_Plan.pdf",
  "id": "153282",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Jul 09 2024 17:34:22 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
```

```
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1720526637159_Death_Cert.pdf",
  "path": "cases/668d2746d9bf3d181108e782/
document_1720526637159_Death_Cert.pdf",
  "id": "875736",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Jul 09 2024 17:34:22 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1720526643141_docs.pdf",
  "path": "cases/668d2746d9bf3d181108e782/document_1720526643141_docs.pdf",
  "id": "476793",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Jul 09 2024 17:34:22 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1720526649701_Docs.pdf",
  "path": "cases/668d2746d9bf3d181108e782/document_1720526649701_Docs.pdf",
  "id": "383019",
  "uploadedBy": "63f9ed37ce84bf289ba991ac",
  "createdAt": "Tue Jul 09 2024 17:34:22 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f7",
    "label": "Any Other Document"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1720526656902_House_Tax.pdf",
```

```
    "path": "cases/668d2746d9bf3d181108e782/
document_1720526656902_House_Tax.pdf",
    "id": "635336",
    "uploadedBy": "63f9ed37ce84bf289ba991ac",
    "createdAt": "Tue Jul 09 2024 17:34:22 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "009815",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "612666",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 09 2024 17:34:22 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Hiren Chaudhari ",
    "phone": "9604154626",
    "ownershipShare": "",
    "email": "",
    "id": "352530"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d2785851e9e2a03c73555",
    "name":
"externalImg_1720526722561_WhatsApp_Image_20230626_at_10049_PM_1.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externalImg_1720526722561_WhatsApp_Image_20230626_at_10049_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d2785851e9e2a03c73556",
    "name":
"externallmg_1720526722642_WhatsApp_Image_20230626_at_10049_PM.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526722642_WhatsApp_Image_20230626_at_10049_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d2785851e9e2a03c73557",
    "name":
"externallmg_1720526722706_WhatsApp_Image_20230626_at_10050_PM_1.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526722706_WhatsApp_Image_20230626_at_10050_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d2785851e9e2a03c73558",
    "name":
"externallmg_1720526722762_WhatsApp_Image_20230626_at_10050_PM_2.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526722762_WhatsApp_Image_20230626_at_10050_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d2785851e9e2a03c73559",
    "name":
"externallmg_1720526722830_WhatsApp_Image_20230626_at_10050_PM.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526722830_WhatsApp_Image_20230626_at_10050_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d2785851e9e2a03c7355a",
```

```
    "name":
"externallmg_1720526722869_WhatsApp_Image_20230626_at_10051_PM_1.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526722869_WhatsApp_Image_20230626_at_10051_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d2785851e9e2a03c7355b",
    "name":
"externallmg_1720526723046_WhatsApp_Image_20230626_at_10051_PM.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526723046_WhatsApp_Image_20230626_at_10051_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d2785851e9e2a03c7355c",
    "name":
"externallmg_1720526723167_WhatsApp_Image_20230626_at_10052_PM_1.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526723167_WhatsApp_Image_20230626_at_10052_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d2785851e9e2a03c7355d",
    "name":
"externallmg_1720526723345_WhatsApp_Image_20230626_at_10052_PM_2.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526723345_WhatsApp_Image_20230626_at_10052_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d2785851e9e2a03c7355e",
    "name":
"externallmg_1720526723510_WhatsApp_Image_20230626_at_10052_PM.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526723510_WhatsApp_Image_20230626_at_10052_PM.jpeg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668d2785851e9e2a03c7355f",
  "name":
"externallmg_1720526723677_WhatsApp_Image_20230626_at_10053_PM_1.jpeg",
  "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526723677_WhatsApp_Image_20230626_at_10053_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668d2785851e9e2a03c73560",
  "name":
"externallmg_1720526723754_WhatsApp_Image_20230626_at_10053_PM.jpeg",
  "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526723754_WhatsApp_Image_20230626_at_10053_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668d2785851e9e2a03c73561",
  "name":
"externallmg_1720526723846_WhatsApp_Image_20230626_at_10054_PM_1.jpeg",
  "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526723846_WhatsApp_Image_20230626_at_10054_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668d2785851e9e2a03c73562",
  "name":
"externallmg_1720526723976_WhatsApp_Image_20230626_at_10054_PM.jpeg",
  "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526723976_WhatsApp_Image_20230626_at_10054_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668d2785851e9e2a03c73563",
  "name":
"externallmg_1720526724131_WhatsApp_Image_20230626_at_10055_PM_1.jpeg",
```

```
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526724131_WhatsApp_Image_20230626_at_10055_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d2785851e9e2a03c73564",
    "name":
"externallmg_1720526724210_WhatsApp_Image_20230626_at_10055_PM_2.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526724210_WhatsApp_Image_20230626_at_10055_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d2785851e9e2a03c73565",
    "name":
"externallmg_1720526724306_WhatsApp_Image_20230626_at_10055_PM.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526724306_WhatsApp_Image_20230626_at_10055_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d2785851e9e2a03c73566",
    "name":
"externallmg_1720526724388_WhatsApp_Image_20230626_at_10056_PM.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526724388_WhatsApp_Image_20230626_at_10056_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d2785851e9e2a03c73567",
    "name":
"externallmg_1720526724455_WhatsApp_Image_20230626_at_10057_PM_1.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526724455_WhatsApp_Image_20230626_at_10057_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "668d2785851e9e2a03c73568",
  "name":
"externallmg_1720526724623_WhatsApp_Image_20230626_at_10057_PM.jpeg",
  "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526724623_WhatsApp_Image_20230626_at_10057_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668d278ed608b22a3ca7df28",
  "name":
"externallmg_1720526732436_WhatsApp_Image_20230626_at_10058_PM_1.jpeg",
  "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526732436_WhatsApp_Image_20230626_at_10058_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668d278ed608b22a3ca7df29",
  "name":
"externallmg_1720526732489_WhatsApp_Image_20230626_at_10058_PM.jpeg",
  "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526732489_WhatsApp_Image_20230626_at_10058_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668d278ed608b22a3ca7df2a",
  "name":
"externallmg_1720526732702_WhatsApp_Image_20230626_at_10059_PM_1.jpeg",
  "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526732702_WhatsApp_Image_20230626_at_10059_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "668d278ed608b22a3ca7df2b",
  "name":
"externallmg_1720526732809_WhatsApp_Image_20230626_at_10059_PM.jpeg",
  "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526732809_WhatsApp_Image_20230626_at_10059_PM.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d278ed608b22a3ca7df2c",
    "name":
"externallmg_1720526732911_WhatsApp_Image_20230626_at_10100_PM_1.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526732911_WhatsApp_Image_20230626_at_10100_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d278ed608b22a3ca7df2d",
    "name":
"externallmg_1720526732974_WhatsApp_Image_20230626_at_10100_PM_2.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526732974_WhatsApp_Image_20230626_at_10100_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d278ed608b22a3ca7df2e",
    "name":
"externallmg_1720526733053_WhatsApp_Image_20230626_at_10100_PM.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526733053_WhatsApp_Image_20230626_at_10100_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d278ed608b22a3ca7df2f",
    "name":
"externallmg_1720526733114_WhatsApp_Image_20230626_at_10101_PM_1.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externallmg_1720526733114_WhatsApp_Image_20230626_at_10101_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "668d278ed608b22a3ca7df30",
```

```

    "name":
    "externalImg_1720526733300_WhatsApp_Image_20230626_at_10101_PM.jpeg",
    "path": "cases/668d2746d9bf3d181108e782/
externalImg_1720526733300_WhatsApp_Image_20230626_at_10101_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-09T12:04:22.653Z",
"updatedAt": "2024-07-09T12:05:34.045Z",
"__v": 0,
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "636a1ad14d42487767af3f91",
"contactPersonName": "Hiren Chaudhari ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9604154626"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			