

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "firstName": "Tanuj",
    "type": "CREDITOFFICER",
    "_id": "669e3f93e4681c3f58248b19",
    "email": "tanuj.khare@sbi.co.in",
    "lastName": "Khare",
    "mobileNo": "",
    "workMobileNo": "8999272635"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Tanuj",
    "expectedFees": null,
    "quotedAmount": "1"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1686816492317_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60016f965256c07aec8e6dd6",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Akhilesh",
  "email": "akhilesh.yadav@vastukala.org",
  "lastName": "Yadav",
  "mobileNo": "9545753921",
  "designation": "Processing Officer",
  "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
  "profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
  "shortName": "AY"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60016f965256c07aec8e6dd6",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Akhilesh",
  "email": "akhilesh.yadav@vastukala.org",
  "lastName": "Yadav",
  "mobileNo": "9545753921",
```

```
    "designation": "Processing Officer",
    "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
    "profilePhoto": "users\\60016f965256c07aec8e6dd6\\
\\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
    "shortName": "AY"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60016f965256c07aec8e6dd6",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Akhilesh",
    "email": "akhilesh.yadav@vastukala.org",
    "lastName": "Yadav",
    "mobileNo": "9545753921",
    "designation": "Processing Officer",
    "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
    "profilePhoto": "users\\60016f965256c07aec8e6dd6\\
\\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
    "shortName": "AY"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
          "title": {
            "label": "IBBI"
          },
          "_id": "60af80072ffdf65bcd658651",
          "number": "IBBI/RV/07/2018/10366"
        }
      ],
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.072967889699303",
  "longitude": "73.13063270408027"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.13063270408027,
    19.072967889699303
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "23/07/2024 03:19 pm"
    },
    {
      "dateTime": "23/07/2024 12:00 am"
    },
    {
      "dateTime": "23/07/2024 12:00 am"
    },
    {
      "dateTime": "23/07/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Tondre",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
```

```
"status": true,
"name": "Plot No.",
"key": "plotNo",
"value": "L112-113-114-115",
"label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "M I D C Taloja Industrial Area",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
```



```
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
```

```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "410208",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Taloja",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
```

```
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
  }
}
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
```

```
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "669e41d5ac43b53f525c62b5",
"ownerName": "M/s Glasstech Industries I Pvt Ltd ",
"ownerPhoneNo": "9820200716",
"appAddress": "Industrial Land & Building Plot no. L-112, L-113, L-114, L-115, MIDC,
Taloja Industrial Area, Village - Tondare, Tal. Panvel",
"remark": "Vastukala & Vankar.. Please collect Plan Copy at visit ",
"documents": [
  {
    "documentType": {
      "label": "Previous Valuation Report",
      "value": "60ae1248aa6d152c1801b2ee"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/669e41d5ac43b53f525c62b5/
document_1721647513282_1721647407347_Valuation_Report_2.pdf",
    "fileName": "document_1721647513282_1721647407347_Valuation_Report_2.pdf",
    "id": "712530",
    "uploadedBy": "60b7177d2ffdf65bcd65882a",
    "createdAt": "Mon Jul 22 2024 16:56:13 GMT+0530 (India Standard Time)"
  },

```

```

{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1721796289172_L113_1.pdf",
  "path": "cases/669e41d5ac43b53f525c62b5/
document_1721796289172_L113_1.pdf",
  "id": "382538",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Wed Jul 24 2024 10:16:15 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1721796303956_L112_1.pdf",
  "path": "cases/669e41d5ac43b53f525c62b5/
document_1721796303956_L112_1.pdf",
  "id": "614553",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Wed Jul 24 2024 10:16:15 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1721796317764_L113.pdf",
  "path": "cases/669e41d5ac43b53f525c62b5/document_1721796317764_L113.pdf",
  "id": "199524",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Wed Jul 24 2024 10:16:15 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },

```

```
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1721796335321_L__114115.pdf",
"path": "cases/669e41d5ac43b53f525c62b5/
document_1721796335321_L__114115.pdf",
"id": "625529",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Wed Jul 24 2024 10:16:15 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1721796361348_L__114115.pdf",
  "path": "cases/669e41d5ac43b53f525c62b5/
document_1721796361348_L__114115.pdf",
  "id": "330828",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Wed Jul 24 2024 10:16:15 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1721796373683_Oc_6.pdf",
  "path": "cases/669e41d5ac43b53f525c62b5/document_1721796373683_Oc_6.pdf",
  "id": "475360",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Wed Jul 24 2024 10:16:15 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2eb",
    "label": "Lease Deed"
  },
  "inputs": {
    "from": {
      "value": "Licensor",
      "label": "Licensor"
    }
  }
},
```

```
"Licensor": "Maharashtra Industrial Development Corporation ",
"to": {
  "value": "Lessee",
  "label": "Lessee"
},
"Lessee": "M/s. Glasstech Industries (India) Pvt. Ltd."
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1722408690958_document_1721796303956_L112.pdf",
"path": "cases/669e41d5ac43b53f525c62b5/
document_1722408690958_document_1721796303956_L112.pdf",
"id": "978097",
"uploadedBy": "60016f965256c07aec8e6dd6",
"createdAt": "Wed Jul 31 2024 12:21:38 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "010077",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "626907",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jul 22 2024 16:56:13 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s Glasstech Industries I Pvt Ltd ",
    "phone": "9820200716",
    "ownershipShare": "",
    "email": "",
    "id": "971794"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9ddf27a0b656fbbdcf364",
    "name": "externallmg_1722408434348_IMG_20240723_144741.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_1722408434348_IMG_20240723_144741.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9ddf27a0b656fbbdcf365",
    "name": "externallmg_r_1722408434509_TimePhoto_20240723_133635.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408434509_TimePhoto_20240723_133635.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9ddf27a0b656fbbdcf366",
    "name": "externallmg_r_1722408434518_TimePhoto_20240723_133644.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408434518_TimePhoto_20240723_133644.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9ddf27a0b656fbbdcf367",
    "name": "externallmg_r_1722408434540_TimePhoto_20240723_133701.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408434540_TimePhoto_20240723_133701.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9ddf27a0b656fbbdcf368",
    "name": "externallmg_r_1722408434526_TimePhoto_20240723_133651.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408434526_TimePhoto_20240723_133651.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66a9ddf27a0b656fbbdcf369",
  "name": "externalimg_r_1722408434559_TimePhoto_20240723_133718.jpg",
  "path": "cases/669e41d5ac43b53f525c62b5/
externalimg_r_1722408434559_TimePhoto_20240723_133718.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a9ddf27a0b656fbbdcf36a",
  "name": "externalimg_r_1722408434547_TimePhoto_20240723_133716.jpg",
  "path": "cases/669e41d5ac43b53f525c62b5/
externalimg_r_1722408434547_TimePhoto_20240723_133716.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a9ddf27a0b656fbbdcf36b",
  "name": "externalimg_r_1722408434567_TimePhoto_20240723_133721.jpg",
  "path": "cases/669e41d5ac43b53f525c62b5/
externalimg_r_1722408434567_TimePhoto_20240723_133721.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a9ddf27a0b656fbbdcf36c",
  "name": "externalimg_r_1722408434582_TimePhoto_20240723_133723.jpg",
  "path": "cases/669e41d5ac43b53f525c62b5/
externalimg_r_1722408434582_TimePhoto_20240723_133723.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a9ddf27a0b656fbbdcf36d",
  "name": "externalimg_r_1722408434598_TimePhoto_20240723_133728.jpg",
  "path": "cases/669e41d5ac43b53f525c62b5/
externalimg_r_1722408434598_TimePhoto_20240723_133728.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "66a9ddf27a0b656fbbdcf36e",
    "name": "externallmg_r_1722408434609_TimePhoto_20240723_133735.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408434609_TimePhoto_20240723_133735.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9ddf27a0b656fbbdcf36f",
    "name": "externallmg_r_1722408434617_TimePhoto_20240723_133749.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408434617_TimePhoto_20240723_133749.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9ddf27a0b656fbbdcf370",
    "name": "externallmg_r_1722408434625_TimePhoto_20240723_133753.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408434625_TimePhoto_20240723_133753.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9ddf27a0b656fbbdcf371",
    "name": "externallmg_r_1722408434636_TimePhoto_20240723_133801.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408434636_TimePhoto_20240723_133801.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9de186ade5c6fb59b99fb",
    "name": "externallmg_r_1722408472330_TimePhoto_20240723_133808.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408472330_TimePhoto_20240723_133808.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9de186ade5c6fb59b99fc",
```



```
    "name": "externallmg_r_1722408472327_TimePhoto_20240723_133803.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408472327_TimePhoto_20240723_133803.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9de186ade5c6fb59b99fd",
    "name": "externallmg_r_1722408472349_TimePhoto_20240723_133826.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408472349_TimePhoto_20240723_133826.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9de186ade5c6fb59b99fe",
    "name": "externallmg_r_1722408472340_TimePhoto_20240723_133822.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408472340_TimePhoto_20240723_133822.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9de186ade5c6fb59b99ff",
    "name": "externallmg_r_1722408472383_TimePhoto_20240723_134654.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408472383_TimePhoto_20240723_134654.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9de186ade5c6fb59b9a00",
    "name": "externallmg_r_1722408472366_TimePhoto_20240723_134437.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408472366_TimePhoto_20240723_134437.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9de186ade5c6fb59b9a01",
    "name": "externallmg_r_1722408472375_TimePhoto_20240723_134621.jpg",
```

```
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408472375_TimePhoto_20240723_134621.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9de287a0b656fbbdcf396",
    "name": "externallmg_r_1722408488629_TimePhoto_20240723_135243.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408488629_TimePhoto_20240723_135243.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9de287a0b656fbbdcf397",
    "name": "externallmg_r_1722408488610_TimePhoto_20240723_134841.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408488610_TimePhoto_20240723_134841.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9de287a0b656fbbdcf398",
    "name": "externallmg_r_1722408488643_TimePhoto_20240723_135246.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408488643_TimePhoto_20240723_135246.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9de287a0b656fbbdcf399",
    "name": "externallmg_r_1722408488612_TimePhoto_20240723_135241.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408488612_TimePhoto_20240723_135241.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a9de287a0b656fbbdcf39a",
    "name": "externallmg_r_1722408488648_TimePhoto_20240723_135253.jpg",
    "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408488648_TimePhoto_20240723_135253.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a9de287a0b656fbbdcf39b",
  "name": "externallmg_r_1722408488659_TimePhoto_20240723_135341.jpg",
  "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408488659_TimePhoto_20240723_135341.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a9de287a0b656fbbdcf39c",
  "name": "externallmg_r_1722408488667_TimePhoto_20240723_135345.jpg",
  "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408488667_TimePhoto_20240723_135345.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a9de676ade5c6fb59b9a45",
  "name": "externallmg_r_1722408550951_TimePhoto_20240723_135454.jpg",
  "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408550951_TimePhoto_20240723_135454.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a9de676ade5c6fb59b9a46",
  "name": "externallmg_r_1722408550943_TimePhoto_20240723_135440.jpg",
  "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408550943_TimePhoto_20240723_135440.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a9de676ade5c6fb59b9a47",
  "name": "externallmg_r_1722408550972_TimePhoto_20240723_135509.jpg",
  "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408550972_TimePhoto_20240723_135509.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66a9de676ade5c6fb59b9a48",
      "name": "externallmg_r_1722408550965_TimePhoto_20240723_135459.jpg",
      "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408550965_TimePhoto_20240723_135459.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66a9de676ade5c6fb59b9a49",
      "name": "externallmg_r_1722408550992_TimePhoto_20240723_135538.jpg",
      "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408550992_TimePhoto_20240723_135538.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66a9de676ade5c6fb59b9a4a",
      "name": "externallmg_r_1722408551006_TimePhoto_20240723_135710.jpg",
      "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408551006_TimePhoto_20240723_135710.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66a9de676ade5c6fb59b9a4b",
      "name": "externallmg_r_1722408550984_TimePhoto_20240723_135525.jpg",
      "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408550984_TimePhoto_20240723_135525.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66a9de676ade5c6fb59b9a4c",
      "name": "externallmg_r_1722408551017_TimePhoto_20240723_135743.jpg",
      "path": "cases/669e41d5ac43b53f525c62b5/
externallmg_r_1722408551017_TimePhoto_20240723_135743.jpg",
      "orientation": "portrait"
    },
  ],
```

```

{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a9de676ade5c6fb59b9a4d",
  "name": "externalImg_r_1722408551027_TimePhoto_20240723_135755.jpg",
  "path": "cases/669e41d5ac43b53f525c62b5/
externalImg_r_1722408551027_TimePhoto_20240723_135755.jpg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-22T11:26:13.583Z",
"updatedAt": "2024-07-31T06:51:38.584Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Land and Building No. Basement Floor, Plot No.
L112-113-114-115, M I D C Talaja Industrial Area, Village - Tondre, Talaja, Navi
Mumbai, 410208, State - Maharashtra, India",
"updatedBy": "60016f965256c07aec8e6dd6",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "M/s Glasstech Industries I Pvt Ltd ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9820200716"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
