

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856baa0"
    },
    "firstName": "Rajesh",
    "type": "CREDITOFFICER",
    "_id": "653de381d6fbd83553d3f51a",
    "lastName": "KUMAR",
    "mobileNo": "",
    "workMobileNo": "7892953881",
    "email": "1coorddesk.rasmecbhy@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4400000",
    "discussWithPerson": "Rajesh",
    "expectedFees": 2200,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856baa0",
  "branchCode": "000286",
  "type": "BRANCH",
  "name": "RASMECCC Bhayandar",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "RASMECCC Bhayandar Branch Unit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, Opp. Maxus Mall, Bhayander
(West), Thane – 401 101, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720a36afd7d55eddedc4a7",
  "role": "SITEENGINEER",
  "firstName": "Anwar",
  "email": "anwar21786@gmail.com",
  "lastName": "Shaikh",
  "mobileNo": "8552884500",
  "designation": "",
  "shortName": "AS",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91b6f344e052188ffd1fc",
  "role": "MAKER",
  "firstName": "Jayaraja",
```

```
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
  "lastName": "Khedekar",
  "mobileNo": "8369040652",
  "designation": "",
  "shortName": "NK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.419557068430844",
  "longitude": "72.80761456658216"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
72.80761456658216,
19.419557068430844
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "22/07/2024 06:09 pm"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-07-22",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
```

```
"value": "Sopara",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "15",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Palghar",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vasai",
  "label": true
},
"plotNo": {
```

```
"status": true,
"name": "Plot No.",
"key": "plotNo",
"value": "1, 2, 3, & 22",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Imperial Paramount ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Lodha Park",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Station Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
```



```
"label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Heera Panna Sharma Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "34/1, 34/4",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
```

```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "1503",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401 203",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Nalasopara (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
},
"general": {
  "ownership": {
```

```
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Semi_Urban",
  "label": "Semi Urban"
},
"townplanApprovedByList": {
  "value": "Vasai_Virar_City_Municipal_Corporation",
  "label": "Vasai Virar City Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Station Road",
  "west": "Internal Road & Shurparak Cricket Ground",
  "south": "Proposed Karari Heights",
  "east": "Ganga Tower"
},
"asPerDocumentAgreement": {
  "north": "Information not available",
  "west": "Information not available",
  "south": "Information not available",
  "east": "Information not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
```

```
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per Approved Building Plan, the composition of residential flat is Living / Dining + Kitchen +2 Bedrooms + 2 Toilets + Passage (i.e. 2 BHK with 2 Toilets)",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan No. VVCMC/TP/AMEND/VP-6461/381/2022-23 Dated 17.10.2022 issued by Vasai-Virar City Municipal Corporation.",
"approvePlanVerified": "Yes",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "As building is under construction, Internal site visit and photographs not allowed. The details about the work progress status has been provided by Sales Person Mr. Manish Jadhav (Contact No. 8698340022)",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "10000.00",
  "depreciatedBuildingRate": "3000",
  "buildingServicesDepreciatedRate": "0"
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "55100",
  "landRate": "16900",
```

```
"igrImage": "cases/669e44ea2abbb93f33eacb7c/igr_1721814096429_Image.png",
"squareMeterGuideLineRate": "60610.00",
"squareFeetGuideLineRate": "5631.00"
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "0",
  "rate": "55100.00",
  "squareMeterGuideLineRate": "60610.00",
  "squareFeetGuideLineRate": "5631.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_cum_Commercial_Purpose_",
    "label": "Proposed Residential cum Commercial Purpose "
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Building Under Construction",
  "taxPaidHolderName": "Building Under Construction",
  "taxAmount": "Building Under Construction",
  "electricityServiceConnectionNo": "Building Under Construction",
  "meterCardHolderName": "Building Under Construction",
  "undividedAreaOfLandAsPerSaleDeed": "Information not available",
  "floorSpaceIndex": "As per VVCMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
```

```
"label": "Proposed R.C.C. Slab"
},
"partitions": {
  "value": "Proposed_6" _Thk._Brick_Masonry",
  "label": "Proposed 6" Thk. Brick Masonery"
},
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed Bike Parking No. 33",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Proposed_Plain_Looking",
  "label": "Proposed Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2025",
  "fullDate": "1/1/2025"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"materialUsedList": {
```

```
"value": "Information_Not_Available",
"label": "Information Not Available"
},
"buildingSpecification": {
"value": "Proposed_Standard",
"label": "Proposed Standard"
},
"structuralSafety": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"protAgainstNatDis": {
"value": "Information_not_available",
"label": "Information not available"
},
"sewerageSystem": {
"value": "Proposed_Connected_to_Municipal_Sewerage_System_",
"label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"maintenanceIssues": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"visibleDamageInBuilding": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"systemOfAirConditioning": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"provisionOfFirefighting": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
}
```



```
},
"groundStilt": {
  "value": "Proposed_Ground",
  "label": "Proposed Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "17",
"flatFloorNo": "15",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "647.90",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/669e44ea2abbb93f33eachb7c/
routeMap_1721731081554_Image.png",
    "routeLat": "19.419294",
    "routeLng": "72.806977",
    "stationName": "Nalasopara",
    "routeDistance": "1.4 km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    null,
    null
  ],
  "type": "Point"
}
```

```
},
"showLocation": {
  "latlng": true,
  "finallatlng": true
},
"locationMapImg": [
  {
    "id": "sdn7ws",
    "name": "sdn7ws",
    "image": "cases/669e44ea2abbb93f33eacb7c/
routeMap_1721817783277_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
```

```
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "5890000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "5890000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "13",
    "percentage": "27.36842105263158",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "11",
    "percentage": "4.05",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
```

```
"floorsCompleted": "11",
"percentage": "4.05",
"isHideFloor": false,
"status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "10",
  "percentage": "1.84",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "3",
  "percentage": "0.55",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "3",
  "percentage": "0.39",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "3",
  "percentage": "0.39",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "3",
  "percentage": "1.58",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "3",
  "percentage": "0.24",
  "isHideFloor": false,
  "status": true
}
```

```
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "3",
  "percentage": "0.24",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "3",
  "percentage": "0.79",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "51.49",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3648325.00",
```

```
"selectedBuildUpValue": "647.90",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "669f86c190b89875ae9e8bba",
      "name": "externallmg_1721730752740_externallmg_1721705277321_WhatsApp_I
mage_20240722_at_185727_1.jpeg",
      "path": "cases/669e44ea2abbb93f33eacb7c/externallmg_1721730752740_externa
lmg_1721705277321_WhatsApp_Image_20240722_at_185727_1.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "669f86c190b89875ae9e8bbd",
      "name": "externallmg_1721730752751_externallmg_1721705277336_WhatsApp_I
mage_20240722_at_185728_1.jpeg",
      "path": "cases/669e44ea2abbb93f33eacb7c/externallmg_1721730752751_externa
lmg_1721705277336_WhatsApp_Image_20240722_at_185728_1.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "669f86c190b89875ae9e8bb9",
      "name": "externallmg_1721730752734_externallmg_1721705277315_WhatsApp_I
mage_20240722_at_185723.jpeg",
      "path": "cases/669e44ea2abbb93f33eacb7c/externallmg_1721730752734_externa
lmg_1721705277315_WhatsApp_Image_20240722_at_185723.jpeg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "669f86c190b89875ae9e8bbb",
      "name": "externallmg_1721730752744_externallmg_1721705277327_WhatsApp_I
mage_20240722_at_185727_2.jpeg",
      "path": "cases/669e44ea2abbb93f33eacb7c/externallmg_1721730752744_externa
lmg_1721705277327_WhatsApp_Image_20240722_at_185727_2.jpeg",
      "orientation": "portrait"
    }
  ],
  {

```

```
    "status": false,
    "_id": "669f86c190b89875ae9e8bc1",
    "name": "externallmg_1721730752762_externallmg_1721705277357_WhatsApp_I
mage_20240722_at_185730_1.jpeg",
    "path": "cases/669e44ea2abbb93f33eacb7c/externallmg_1721730752762_external
lmg_1721705277357_WhatsApp_Image_20240722_at_185730_1.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "9109.00",
    "max": "10339.00"
  },
  "builtUpRateRange": {
    "min": "8281.00",
    "max": "9399.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
```

```
"isSiteMeasurementAllowed": false,
"finalValuationArea": "589.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "669e44ea2abbb93f33eacb7c",
"ownerName": "Mr. Munna Ali Nasaruddin",
"ownerPhoneNo": "9323515061",
"appAddress": "FLAT NO 1503 A WING 15TH FLOOR IMPERIAL PARAMOUNT HIRA
PANNA SHARMA CHS LTD SOPARA VILLAGE NALASOPARA WEST PALGHAR
401203",
"remark": "ANY QUERY DEEPAK YADAV 8976230267",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "28/06/2024",
      "from": {
        "value": "Builder",
        "label": "Builder"
      },
      "Builder": "M/s. Shivganga Construction & Redevelopers",
      "to": {
        "value": "Allottee",
        "label": "Allottee"
      },
      "Allottee": "Mr. Munna Ali Nasaruddin & Mrs. Afreen Munna Ali",
      "number": {
        "value": "Registration_No",
        "label": "Registration No"
      },
      "Registration_No": "14233/2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "790737",
    "path": "cases/669e44ea2abbb93f33eacb7c/document_1721648163687_17216480
```

```
55884_MUNNA_NASABUDDIN__AGREEMENT.pdf",
  "fileName": "document_1721648163687_1721648055884_MUNNA_NASABUDDIN
__AGREEMENT.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "19/08/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " P99000046574"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "502861",
  "path": "cases/669e44ea2abbb93f33each7c/
document_1721735718215_P99000046574.pdf",
  "fileName": "document_1721735718215_P99000046574.pdf"
},
{
  "documentType": {
    "value": "60ae1268aa6d152c1801b383",
    "label": "Revised Development Permission"
  },
  "inputs": {
    "documentDate": "22/06/2023",
    "nameOfApprovingAuthority": {
      "value": "Vasai_Virar_City_Municipal_Corporation",
      "label": "Vasai Virar City Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": " VVCMC/TP/RDP/VP-6461/19/2023-24"
  },
  "isHardCopy": false,
```

```
    "displayStatus": false,
    "id": "834821",
    "path": "cases/669e44ea2abbb93f33eacb7c/document_1721735872375_3_Comme
ncement_Certificates__NA_Order_for_plotted_development.pdf",
    "fileName": "document_1721735872375_3_Commencement_Certificates__NA_Or
der_for_plotted_development.pdf"
  },
  {
    "documentType": {
      "value": "60ae1277aa6d152c1801b3cc",
      "label": "Approved Building Plan"
    },
    "inputs": {
      "documentDate": "17/10/2022",
      "nameOfApprovingAuthority": {
        "value": "Vasai_Virar_City_Municipal_Corporation",
        "label": "Vasai Virar City Municipal Corporation"
      },
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": " VVCMC/TP/AMEND/VP-6461/381/2022-23 "
    },
    "isHardCopy": false,
    "displayStatus": false,
    "id": "943090",
    "path": "cases/669e44ea2abbb93f33eacb7c/document_1721736875769_18_Buildin
g_Plan_Approval__NA_Order_for_plotted_development.pdf",
    "fileName": "document_1721736875769_18_Building_Plan_Approval__NA_Order_
for_plotted_development.pdf"
  }
],
"caseNumber": "010078",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "625509",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jul 22 2024 17:09:22 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Munna Ali Nasaruddin",
```

```
"phone": "9323515061",
"ownershipShare": "",
"email": "",
"id": "306131"
},
{
  "name": "Mrs. Afreen Munna Ali",
  "phone": "",
  "email": "",
  "ownershipShare": "",
  "id": "346017"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "845342",
    "selectAreaTypeDocument": "Carpet",
    "totalAreaDocument": "589",
    "squareMeterArea": "54.72",
    "docFinalBuiltUp": "647.9",
    "docFinalBuiltUpSquareMeter": "60.192",
    "docBuiltupPercentage": "10",
    "docSaleablePercentage": "0",
    "docFinalSaleable": "0",
    "docFinalSaleableSquareMeter": "0"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "601.49",
      "squareMeterArea": "55.88",
```

```
"expectedRate": "10228.77",
"percentage": ""
},
"builtUpArea": {
  "area": "661.64",
  "squareMeterArea": "61.47",
  "expectedRate": "9298.86",
  "percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "66a0cc78935bbf721bf579ee",
"property": "Imperial Paramount Nalasopara West",
"area": "601.49",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "6152500.00",
"expectedRate": "10228.77",
"builtUpExpectedRate": "9298.86",
"image": "cases/669e44ea2abbb93f33eacb7c/
indicator_1721813451846_Image.png",
"squareMeter": "55.88",
"id": "673854"
},
{
  "carpetArea": {
    "area": "428.19",
    "squareMeterArea": "39.78",
    "expectedRate": "9108.11",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "471.01",
    "squareMeterArea": "43.76",
    "expectedRate": "8280.08",
    "percentage": "10"
  },
}
```

```
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "66a0cc78935bbf721bf579ef",
"property": "Imperial Paramount Nalasopara West",
"area": "428.19",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "3900000.00",
"expectedRate": "9108.11",
"builtUpExpectedRate": "8280.08",
"image": "cases/669e44ea2abbb93f33each7c/
indicator_1721813489743_Image.png",
"squareMeter": "39.78",
"id": "499444"
},
{
  "carpetArea": {
    "area": "460.00",
    "squareMeterArea": "42.74",
    "expectedRate": "9782.61",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "506.00",
    "squareMeterArea": "47.01",
    "expectedRate": "8893.28",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66a0cc78935bbf721bf579f0",
  "property": "Imperial Paramount Shortlist-Button Nalasopara West",
```

```
"area": "460.00",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "4500000.00",
"expectedRate": "9782.61",
"builtUpExpectedRate": "8893.28",
"image": "cases/669e44ea2abbb93f33eacb7c/
indicator_1721813546698_Image.png",
"squareMeter": "42.74",
"id": "517703"
},
{
"carpetArea": {
"area": "665.00",
"squareMeterArea": "61.78",
"expectedRate": "10338.35",
"percentage": ""
},
"builtUpArea": {
"area": "731.50",
"squareMeterArea": "67.96",
"expectedRate": "9398.50",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66a0cc78935bbf721bf579f1",
"property": "Imperial Paramount Nalasopara West",
"area": "665.00",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "",
"source": "square_yards",
"expectedPrice": "6875000.00",
"expectedRate": "10338.35",
```



```
    "builtUpExpectedRate": "9398.50",
    "image": "cases/669e44ea2abbb93f33eacb7c/
indicator_1721813678500_Image.png",
    "squareMeter": "61.78",
    "id": "594876"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669f233d35f7d73f393679e7",
    "name":
"externallmg_1721705277305_WhatsApp_Image_20240722_at_185715.jpeg",
    "path": "cases/669e44ea2abbb93f33eacb7c/
externallmg_1721705277305_WhatsApp_Image_20240722_at_185715.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669f233d35f7d73f393679e8",
    "name":
"externallmg_1721705277311_WhatsApp_Image_20240722_at_185720.jpeg",
    "path": "cases/669e44ea2abbb93f33eacb7c/
externallmg_1721705277311_WhatsApp_Image_20240722_at_185720.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669f233d35f7d73f393679f4",
    "name":
"externallmg_1721705277366_WhatsApp_Image_20240722_at_185731_1.jpeg",
    "path": "cases/669e44ea2abbb93f33eacb7c/
externallmg_1721705277366_WhatsApp_Image_20240722_at_185731_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669f233d35f7d73f393679f5",
    "name":
"externallmg_1721705277368_WhatsApp_Image_20240722_at_185731_2.jpeg",
    "path": "cases/669e44ea2abbb93f33eacb7c/
externallmg_1721705277368_WhatsApp_Image_20240722_at_185731_2.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f233d35f7d73f393679f6",
  "name":
  "externallmg_1721705277371_WhatsApp_Image_20240722_at_185731.jpeg",
  "path": "cases/669e44ea2abbb93f33eacb7c/
externallmg_1721705277371_WhatsApp_Image_20240722_at_185731.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f233d35f7d73f393679f7",
  "name":
  "externallmg_1721705277374_WhatsApp_Image_20240722_at_185733.jpeg",
  "path": "cases/669e44ea2abbb93f33eacb7c/
externallmg_1721705277374_WhatsApp_Image_20240722_at_185733.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f233d35f7d73f393679f8",
  "name":
  "externallmg_1721705277377_WhatsApp_Image_20240722_at_185734.jpeg",
  "path": "cases/669e44ea2abbb93f33eacb7c/
externallmg_1721705277377_WhatsApp_Image_20240722_at_185734.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f233d35f7d73f393679f9",
  "name":
  "externallmg_1721705277380_WhatsApp_Image_20240722_at_185959.jpeg",
  "path": "cases/669e44ea2abbb93f33eacb7c/
externallmg_1721705277380_WhatsApp_Image_20240722_at_185959.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f86b290b89875ae9e8b7a",
```

```
    "name": "externallmg_1721730737497_Sale_Plan_6.jpeg",
    "path": "cases/669e44ea2abbb93f33each7c/
externallmg_1721730737497_Sale_Plan_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669f86c190b89875ae9e8bb9",
    "name": "externallmg_1721730752734_externallmg_1721705277315_WhatsApp_I
mage_20240722_at_185723.jpeg",
    "path": "cases/669e44ea2abbb93f33each7c/externallmg_1721730752734_externall
mg_1721705277315_WhatsApp_Image_20240722_at_185723.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669f86c190b89875ae9e8bba",
    "name": "externallmg_1721730752740_externallmg_1721705277321_WhatsApp_I
mage_20240722_at_185727_1.jpeg",
    "path": "cases/669e44ea2abbb93f33each7c/externallmg_1721730752740_externall
mg_1721705277321_WhatsApp_Image_20240722_at_185727_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669f86c190b89875ae9e8bbb",
    "name": "externallmg_1721730752744_externallmg_1721705277327_WhatsApp_I
mage_20240722_at_185727_2.jpeg",
    "path": "cases/669e44ea2abbb93f33each7c/externallmg_1721730752744_externall
mg_1721705277327_WhatsApp_Image_20240722_at_185727_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669f86c190b89875ae9e8bbc",
    "name": "externallmg_1721730752748_externallmg_1721705277332_WhatsApp_I
mage_20240722_at_185727.jpeg",
    "path": "cases/669e44ea2abbb93f33each7c/externallmg_1721730752748_externall
mg_1721705277332_WhatsApp_Image_20240722_at_185727.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669f86c190b89875ae9e8bbd",
    "name": "externallmg_1721730752751_externallmg_1721705277336_WhatsApp_I
mage_20240722_at_185728_1.jpeg",
    "path": "cases/669e44ea2abbb93f33eacb7c/externallmg_1721730752751_externall
mg_1721705277336_WhatsApp_Image_20240722_at_185728_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669f86c190b89875ae9e8bbe",
    "name": "externallmg_1721730752754_externallmg_1721705277339_WhatsApp_I
mage_20240722_at_185728.jpeg",
    "path": "cases/669e44ea2abbb93f33eacb7c/externallmg_1721730752754_externall
mg_1721705277339_WhatsApp_Image_20240722_at_185728.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669f86c190b89875ae9e8bbf",
    "name": "externallmg_1721730752756_externallmg_1721705277343_WhatsApp_I
mage_20240722_at_185729_1.jpeg",
    "path": "cases/669e44ea2abbb93f33eacb7c/externallmg_1721730752756_externall
mg_1721705277343_WhatsApp_Image_20240722_at_185729_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669f86c190b89875ae9e8bc0",
    "name": "externallmg_1721730752759_externallmg_1721705277347_WhatsApp_I
mage_20240722_at_185729_2.jpeg",
    "path": "cases/669e44ea2abbb93f33eacb7c/externallmg_1721730752759_externall
mg_1721705277347_WhatsApp_Image_20240722_at_185729_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669f86c190b89875ae9e8bc1",
    "name": "externallmg_1721730752762_externallmg_1721705277357_WhatsApp_I
mage_20240722_at_185730_1.jpeg",
    "path": "cases/669e44ea2abbb93f33eacb7c/externallmg_1721730752762_externall
```

```
mg_1721705277357_WhatsApp_Image_20240722_at_185730_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "669f86c190b89875ae9e8bc2",
  "name": "externalImg_1721730752765_externalImg_1721705277361_WhatsApp_I
mage_20240722_at_185730.jpeg",
  "path": "cases/669e44ea2abbb93f33each7c/externalImg_1721730752765_externalI
mg_1721705277361_WhatsApp_Image_20240722_at_185730.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "3 Commencement Certificates _ NA Order for plotted
development.pdf",
    "filename": "1721737873489_3_Commencement_Certificates__NA_Order_for_plot
ted_development.pdf",
    "path": "cases/669e44ea2abbb93f33each7c/processingDocuments/1721737873489
_3_Commencement_Certificates__NA_Order_for_plotted_development.pdf",
    "size": "1165765",
    "createdAt": "Tue Jul 23 2024 18:01:13 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "18 Building Plan Approval _ NA Order for plotted development.pdf",
    "filename": "1721737873515_18_Building_Plan_Approval__NA_Order_for_plotted
_development.pdf",
    "path": "cases/669e44ea2abbb93f33each7c/processingDocuments/1721737873515
_18_Building_Plan_Approval__NA_Order_for_plotted_development.pdf",
    "size": "1893833",
    "createdAt": "Tue Jul 23 2024 18:01:13 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Google Loction.jpeg",
    "filename": "1721737873556_Google_Loction.jpeg",
    "path": "cases/669e44ea2abbb93f33each7c/
processingDocuments/1721737873556_Google_Loction.jpeg",
    "size": "196875",
    "createdAt": "Tue Jul 23 2024 18:01:13 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
}
```

```
{
  "originalname": "Sale Deed - 2024.pdf",
  "filename": "1721737873560_Sale_Deed__2024.pdf",
  "path": "cases/669e44ea2abbb93f33each7c/
processingDocuments/1721737873560_Sale_Deed__2024.pdf",
  "size": "5708121",
  "createdAt": "Tue Jul 23 2024 18:01:13 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sale Plan (1).jpeg",
  "filename": "1721737873648_Sale_Plan_1.jpeg",
  "path": "cases/669e44ea2abbb93f33each7c/
processingDocuments/1721737873648_Sale_Plan_1.jpeg",
  "size": "187413",
  "createdAt": "Tue Jul 23 2024 18:01:13 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sale Plan (2).jpeg",
  "filename": "1721737882703_Sale_Plan_2.jpeg",
  "path": "cases/669e44ea2abbb93f33each7c/
processingDocuments/1721737882703_Sale_Plan_2.jpeg",
  "size": "170411",
  "createdAt": "Tue Jul 23 2024 18:01:22 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sale Plan (3).jpeg",
  "filename": "1721737882709_Sale_Plan_3.jpeg",
  "path": "cases/669e44ea2abbb93f33each7c/
processingDocuments/1721737882709_Sale_Plan_3.jpeg",
  "size": "198955",
  "createdAt": "Tue Jul 23 2024 18:01:22 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
  "originalname": "Sale Plan (4).jpeg",
  "filename": "1721737882718_Sale_Plan_4.jpeg",
  "path": "cases/669e44ea2abbb93f33each7c/
processingDocuments/1721737882718_Sale_Plan_4.jpeg",
  "size": "151499",
  "createdAt": "Tue Jul 23 2024 18:01:22 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91b6f344e052188ffd1fc"
},
{
```

```
    "originalname": "Sale Plan (5).jpeg",
    "filename": "1721737882722_Sale_Plan_5.jpeg",
    "path": "cases/669e44ea2abbb93f33each7c/
processingDocuments/1721737882722_Sale_Plan_5.jpeg",
    "size": "184471",
    "createdAt": "Tue Jul 23 2024 18:01:22 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Sale Plan (6).jpeg",
    "filename": "1721737882727_Sale_Plan_6.jpeg",
    "path": "cases/669e44ea2abbb93f33each7c/
processingDocuments/1721737882727_Sale_Plan_6.jpeg",
    "size": "371282",
    "createdAt": "Tue Jul 23 2024 18:01:22 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Site Details 1.jpeg",
    "filename": "1721737882734_Site_Details_1.jpeg",
    "path": "cases/669e44ea2abbb93f33each7c/
processingDocuments/1721737882734_Site_Details_1.jpeg",
    "size": "122573",
    "createdAt": "Tue Jul 23 2024 18:01:22 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  },
  {
    "originalname": "Site Details.jpeg",
    "filename": "1721737882738_Site_Details.jpeg",
    "path": "cases/669e44ea2abbb93f33each7c/
processingDocuments/1721737882738_Site_Details.jpeg",
    "size": "126703",
    "createdAt": "Tue Jul 23 2024 18:01:22 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91b6f344e052188ffd1fc"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-22T11:39:22.111Z",
"updatedAt": "2024-07-25T11:03:31.116Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
}
```

```
"fullAddress": "Residential Flat No. 1503, 15th Floor, Wing - A, Imperial Paramount ,
Heera Panna Sharma Co-op. Hsg. Soc. Ltd., Plot No. 1, 2, 3, & 22, Lodha Park, Station
Road, Village - Sopara, Nalasopara (West), Taluka - Vasai, District - Palghar, PIN - 401
203, State - Maharashtra, India",
"updatedBy": "60092304a16fab0f2af9b0c2",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mr. Manish Jadhav",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person",
"siteVisitContactNo": "8698340022",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 589.00",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"buildingServicesRate": "3000",
"flatRate": "10000.00",
"landOtherRate": "7000",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"reportGeneratedDate": "Wed Jul 24 2024 15:30:33 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-07-22",
"landDetails": {
  "holdType": {
```



```
"label": "Free Hold",
"value": "Free_Hold"
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			