

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b953"
    },
    "firstName": "Rajivkumar",
    "type": "CREDITOFFICER",
    "_id": "665eedb7b33b3015bdcf64f8",
    "lastName": "Shrivastav",
    "mobileNo": "",
    "workMobileNo": "8779795142",
    "email": "borivali_east@jansevabank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "29000000",
    "discussWithPerson": "Rajivkumar",
    "expectedFees": 14500,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank",
  "displayName": "Janaseva Sahakari Bank",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b953",
  "branchCode": "000003",
  "type": "BRANCH",
  "name": "Borivali (East) Branch",
  "email": "borivali_east@jansevabank.in",
  "mobileNo": "022 - 28705312",
  "alternateMobileNo": "",
  "address": "Shiv Hara Co-operative Society, Road No. 2, Borivali, Opposite Shatabdi
Municipal Hospital, Borivali (East), Mumbai - 400066, State - Maharashtra, Country -
India",
  "ledgerName": "JANSEVA SAHAKARI BANK BORIVALI (E)",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"deliveryPerson": {
  "type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "ADMIN",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60092304a16fab0f2af9b0c2",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Nitesh",
  "email": "nitesh.khedekar@vastukala.org",
```

```
"lastName": "Khedekar",
"mobileNo": "8369040652",
"designation": "",
"shortName": "NK",
"workWithDocumentMaker": "",
"profilePhoto": "users/60092304a16fab0f2af9b0c2/
profilePhoto_1681212511436_IMG3094.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60eeaeddf3dd69653a581316",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shyam",
  "email": "shyam@vastukala.org",
  "lastName": "Kajvilkar",
  "mobileNo": "9765074720",
  "designation": "",
  "shortName": "SK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
```

```
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
```

```
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.186368532100442",
  "longitude": "72.85429093041874"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85429093041874,
    19.186368532100442
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-07-23",
      "remark": "visit Bhavika madam monday"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-07-23",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-07-22",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-07-22",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
}
```

```
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Malad East",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "3",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
```

```
"status": true,
"name": "District",
"key": "district",
"value": "Mumbai Suburban District",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Pethenagar Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
```



```
"label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Kedarmal Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
```

```
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "302, Hissa No. 1, 2 & 3",
"label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "404",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B-34",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "P Ward",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
}
```

```
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 097",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Malad (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
```

```
"value": "rcc_Slab",
"label": "R. C. C. Slab"
},
"flooring": {
"value": "VerifiedTileFlooring",
"label": "Vitrified Tile Flooring"
},
"doors": {
"value": "Teak_Wood_Door_frame_with_Solid_flush_door",
"label": "Teak Wood Door frame with Solid flush door"
},
"windows": {
"value": "Powder_coated_Aluminum_sliding_windows",
"label": "Powder coated Aluminum sliding windows"
},
"fittings": {
"value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
"label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
"value": "Cement_Plastering",
"label": "Cement Plastering"
}
},
"general": {
"ownership": {
"value": "Joint_Ownership",
"label": "Joint Ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Urban",
"label": "Urban"
},
"townplanApprovedByList": {
"value": "MCGM",
"label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
}
},
```

```
"asPerActualAgreement": {
  "north": "Apnadesh CHSL",
  "west": "Internal Road & Bhavana Kunj CHSL",
  "south": "Road",
  "east": "Ashmi Apartment"
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of Approved Plan were not provided and not verified",
"approvePlanVerified": "N.A.",
```

```
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "27800",
  "depreciatedBuildingRate": "2700"
},
"igrRate": {
  "propertyName": "Village - Malad East",
  "rate": "132420",
  "landRate": "62930",
  "igrImage": "cases/669f7c5f8be38171f22b63f3/igr_1721798314845_Image.png",
  "squareMeterGuideLineRate": "112557.00",
  "squareFeetGuideLineRate": "10457.00"
},
"igrFinalRate": {
  "floorRatePercentage": "85",
  "depreciationPercentage": "46",
  "rate": "7967.00",
  "squareMeterGuideLineRate": "85758.00",
  "squareFeetGuideLineRate": "7967.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
```

```
"value": "Tenant_Occupied",
"label": "Tenant Occupied"
},
"monthlyRent": "16,500/- Present rental income per month",
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "Mrs. Priya Nemade",
"maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
```

```
"label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "1971",
  "fullDate": "1/1/1971"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
```



```
"label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "as_per_agreement",
  "label": "As per agreement"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "7",
"ageOfBuilding": "53",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "4",
"flatFloorNo": "3",
"noOfLifts": "",
"noOfDwellingUnitsInBuilding": "4"
},
```

```
"finalPlinthArea": {
  "area": "426.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/669f7c5f8be38171f22b63f3/
routeMap_1721798073611_Image.png",
    "routeLat": "19.186155",
    "routeLng": "72.853692",
    "stationName": "Malad",
    "routeDistance": "650 Mt.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      null,
      null
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": true,
    "finallatLng": true
  },
  "locationMapImg": [
    {
      "id": "rfzi4g",
      "name": "rfzi4g",
      "image": "cases/669f7c5f8be38171f22b63f3/
routeMap_1721798035428_Image.png"
    }
  ]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
}
```

```
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "9869000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "0",
"finalValue": "9869000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Thu Jul 25 2024 11:08:51 GMT+0530 (India Standard Time)",
  "number": "2307392",
  "dayCount": "3",
  "monthCount": "396",
  "generatedBy": "60092304a16fab0f2af9b0c2"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
```

```
"rccFootingFoundation": {
  "label": "RCC Footing/Foundation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
```

```
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "3393942.00",
"selectedBuildUpValue": "426.00",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "669f7e5b522e015687d40fdb",
"name": "externalImg_1721728599137_1721728477575_image_3.jpeg",
"path": "cases/669f7c5f8be38171f22b63f3/
externalImg_1721728599137_1721728477575_image_3.jpeg",
"orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [
{
```

```
    "status": false,
    "_id": "669f7e5b522e015687d40fe4",
    "name": "externallmg_1721728602144_1721728477575_image_12.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728602144_1721728477575_image_12.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "669f7e5b522e015687d40fda",
    "name": "externallmg_1721728598543_1721728477575_image_2.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728598543_1721728477575_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "669f7e5b522e015687d40fdc",
    "name": "externallmg_1721728599718_1721728477575_image_4.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728599718_1721728477575_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "669f7e5b522e015687d40fe7",
    "name": "externallmg_1721728602808_1721728477575_image_15.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728602808_1721728477575_image_15.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [
  {
    "status": false,
    "_id": "669f7e5b522e015687d40fdd",
    "name": "externallmg_1721728600556_1721728477575_image_5.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728600556_1721728477575_image_5.jpeg",
    "orientation": "portrait"
  }
],
"compositionImages": [
```

```
{
  "status": false,
  "_id": "669f7e5b522e015687d40fde",
  "name": "Living Room",
  "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728600924_1721728477575_image_6.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "669f7e5b522e015687d40fe0",
  "name": "Living Room",
  "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728601295_1721728477575_image_8.jpeg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "669f7e5b522e015687d40fe1",
  "name": "Living Room",
  "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728601638_1721728477575_image_9.jpeg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "24743.00",
    "max": "27739.00"
  },
  "builtUpRateRange": {
    "min": "20619.00",
    "max": "23116.00"
  },
  "saleableRateRange": {
    "min": "19264.00",
    "max": "19264.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
```

```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "355.00",
"empanelmentNo": [
  "36/ LOAN H.O./2016-17/232"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORDELIVERY",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "669f7c5f8be38171f22b63f3",
"ownerName": "Mrs. Swapnal Mukul Shrotri & Mr. Mukul Arvind Shrotri ",
"ownerPhoneNo": "9869408280",
"appAddress": "FLAT NO B-33/ B-34 B WING 3RD FLOOR PETHE NAGAR CHS LTD
KEDARMAL ROAD MALAD EAST MUMBAI 400097",
"remark": "visit Bhavika madam monday",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "15/03/2014",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Smt. Shubhada Suresh Bhadbhade @ Mrs. Shubhada Dhananjay
Dhawde",
      "to": {
        "value": "transferee",
```

```
    "label": "transferee"
  },
  "transferee": "Mrs. Swapnal Mukul Shrotri & Mr. Mukul Arvind Shrotri",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "2300/2014"
},
"isHardCopy": false,
"displayStatus": true,
"id": "976948",
"path": "cases/669f7c5f8be38171f22b63f3/
document_1721458127583_1721458017289_B_34.pdf",
"fileName": "document_1721458127583_1721458017289_B_34.pdf"
}
],
"caseNumber": "010104",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "739176",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Jul 20 2024 12:21:48 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Swapnal Mukul Shrotri & Mr. Mukul Arvind Shrotri ",
    "phone": "9869408280",
    "ownershipShare": "",
    "email": "",
    "id": "525501"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "806797",
    "name": "Living Room",
```

```
"length": "20.25",
"length1": "20",
"length2": "3",
"width": "9.33",
"width1": "9",
"width2": "4",
"totalArea": "189.00",
"images": [],
"extraAreas": [],
"finalArea": "189.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "8.92",
  "width1": "8",
  "width2": "11",
  "totalArea": "69.10",
  "images": [],
  "extraAreas": [],
  "finalArea": "69.10"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bathroom",
  "length": "4.50",
  "length1": "4",
  "length2": "6",
  "width": "3.25",
  "width1": "3",
  "width2": "3",
  "totalArea": "14.62",
  "images": [],
  "extraAreas": [],
  "finalArea": "14.62"
}
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "4.33",
  "length1": "4",
  "length2": "4",
  "width": "3.00",
  "width1": "3",
  "width2": "00",
  "totalArea": "13.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "13.00"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "4",
  "name": "Passage",
  "length": "7.42",
  "length1": "7",
  "length2": "5",
  "width": "2.58",
  "width1": "2",
  "width2": "7",
  "totalArea": "19.16",
  "images": [],
  "extraAreas": [],
  "finalArea": "19.16"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
  },

```

```
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "592048",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "355",
"squareMeterArea": "32.98",
"docFinalBuiltUp": "426",
"docFinalBuiltUpSquareMeter": "39.57599999999999",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "291.00",
    "squareMeterArea": "27.03",
    "expectedRate": "24742.27",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "349.20",
    "squareMeterArea": "32.44",
    "expectedRate": "20618.56",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "66a08e69b178c60d94836132",
  "property": "1 BHK Flat In Shiv Ashish Chs For Sale In Malad East",
  "area": "291",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": ""
}
```

```
"source": "Nobroker.com",
"expectedPrice": "7200000",
"expectedRate": "24742.27",
"builtUpExpectedRate": "20618.56",
"image": "cases/669f7c5f8be38171f22b63f3/indicator_1721798176498_Image.png",
"squareMeter": "27.03",
"id": "791820"
},
{
  "carpetArea": {
    "area": "429.00",
    "squareMeterArea": "39.86",
    "expectedRate": "27738.93",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "514.80",
    "squareMeterArea": "47.83",
    "expectedRate": "23115.77",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "617.76",
    "squareMeterArea": "57.39",
    "expectedRate": "19263.14",
    "percentage": "20"
  },
  "printlnReport": true,
  "_id": "66ffeaaa554d3e0d4630e5bc",
  "property": "Flat",
  "area": "429",
  "builtUpPercentage": "20",
  "saleablePercentage": "20",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "11900000",
  "expectedRate": "27738.93",
  "builtUpExpectedRate": "23115.77",
  "image": "cases/669f7c5f8be38171f22b63f3/indicator_1728047786819_Image.png",
  "squareMeter": "39.86",
  "id": "391870"
},
{
  "carpetArea": {
```



```
    "area": "350.00",
    "squareMeterArea": "32.52",
    "expectedRate": "28571.43",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "420.00",
    "squareMeterArea": "39.02",
    "expectedRate": "23809.52",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": false,
  "_id": "674b049fe077c54e532d83fa",
  "property": "Residential Flat",
  "area": "350",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "10000000",
  "expectedRate": "28571.43",
  "builtUpExpectedRate": "23809.52",
  "image": "cases/669f7c5f8be38171f22b63f3/indicator_1732969631605_Image.png",
  "squareMeter": "32.52",
  "id": "810085"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "669f7e59522e015687d40faa",
    "name": "externalImg_1721728599784_1721728494579_image_0.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externalImg_1721728599784_1721728494579_image_0.jpeg",
    "orientation": "portrait"
  },
  {
```

```
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "669f7e5b522e015687d40fd8",
    "name": "externallmg_1721728598189_1721728477572_image_0.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728598189_1721728477572_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "669f7e5b522e015687d40fd9",
    "name": "externallmg_1721728598357_1721728477575_image_1.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728598357_1721728477575_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "669f7e5b522e015687d40fda",
    "name": "externallmg_1721728598543_1721728477575_image_2.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728598543_1721728477575_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "669f7e5b522e015687d40fdb",
    "name": "externallmg_1721728599137_1721728477575_image_3.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728599137_1721728477575_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "669f7e5b522e015687d40fdc",
    "name": "externallmg_1721728599718_1721728477575_image_4.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728599718_1721728477575_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
```

```
"status": false,
  "_id": "669f7e5b522e015687d40fdd",
  "name": "externallmg_1721728600556_1721728477575_image_5.jpeg",
  "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728600556_1721728477575_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "669f7e5b522e015687d40fde",
  "name": "externallmg_1721728600924_1721728477575_image_6.jpeg",
  "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728600924_1721728477575_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "669f7e5b522e015687d40fdf",
  "name": "externallmg_1721728601172_1721728477575_image_7.jpeg",
  "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728601172_1721728477575_image_7.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "669f7e5b522e015687d40fe0",
  "name": "externallmg_1721728601295_1721728477575_image_8.jpeg",
  "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728601295_1721728477575_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "669f7e5b522e015687d40fe1",
  "name": "externallmg_1721728601638_1721728477575_image_9.jpeg",
  "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728601638_1721728477575_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "669f7e5b522e015687d40fe2",
    "name": "externallmg_1721728601711_1721728477575_image_10.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728601711_1721728477575_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "669f7e5b522e015687d40fe3",
    "name": "externallmg_1721728601981_1721728477575_image_11.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728601981_1721728477575_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "669f7e5b522e015687d40fe4",
    "name": "externallmg_1721728602144_1721728477575_image_12.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728602144_1721728477575_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "669f7e5b522e015687d40fe5",
    "name": "externallmg_1721728602165_1721728477575_image_13.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728602165_1721728477575_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "669f7e5b522e015687d40fe6",
    "name": "externallmg_1721728602648_1721728477575_image_14.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externallmg_1721728602648_1721728477575_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "669f7e5b522e015687d40fe7",
```

```
    "name": "externalImg_1721728602808_1721728477575_image_15.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externalImg_1721728602808_1721728477575_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "669f7e5b522e015687d40fe8",
    "name": "externalImg_1721728602956_1721728477575_image_16.jpeg",
    "path": "cases/669f7c5f8be38171f22b63f3/
externalImg_1721728602956_1721728477575_image_16.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [
  {
    "originalname": "Swapnal Mukul Shrotri & Mr. Mukul Arvind Shrotri.pdf",
    "filename":
"1721890793399_Swapnal_Mukul_Shrotri__Mr_Mukul_Arvind_Shrotri.pdf",
    "path": "cases/669f7c5f8be38171f22b63f3/externalDocuments/1721890793399_Sw
apnal_Mukul_Shrotri__Mr_Mukul_Arvind_Shrotri.pdf",
    "size": "1764263",
    "documentType": {
      "value": "640ece6024088f0f94ee4ea8",
      "label": "Final PDF Report"
    },
    "createdAt": "Thu Jul 25 2024 12:29:53 GMT+0530 (India Standard Time)",
    "uploadedBy": "63f31d626f9c2254a9b39144"
  },
  {
    "originalname": "Valuation_report_Swapnal Mukul Shrotri & Mr. Mukul Arvind
Shrotri.pdf",
    "filename": "1721890793440_Valuation_report_Swapnal_Mukul_Shrotri__Mr_Mukul
_Arvind_Shrotri.pdf",
    "path": "cases/669f7c5f8be38171f22b63f3/externalDocuments/1721890793440_Val
uation_report_Swapnal_Mukul_Shrotri__Mr_Mukul_Arvind_Shrotri.pdf",
    "size": "6086672",
    "documentType": {
      "value": "640ece6024088f0f94ee4ea8",
      "label": "Final PDF Report"
    },
    "createdAt": "Thu Jul 25 2024 12:29:53 GMT+0530 (India Standard Time)",
    "uploadedBy": "63f31d626f9c2254a9b39144"
  },
  {

```

```
"path": "../CDN/cases/669f7c5f8be38171f22b63f3/
externalDocuments/1722058761925_330371.pdf",
"filename": "1722058761925_330371.pdf",
"documentType": {
  "organization": {
    "status": true,
    "isdelete": false,
    "_id": "5f2bdee67813470eb443deb4",
    "name": "Vastukala Consultants India Pvt. Ltd.",
    "gstNo": "18AABCT3518Q1ZZ",
    "panNo": "ABCDE1234A",
    "email": "vastukalamumbai@vastukala.com",
    "phone": "9819670183",
    "address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E),
Mumbai - 400 093",
    "shortName": "VCIPL",
    "type": "ORGANIZATION",
    "city": "Mumbai",
    "ownerEmail": "umang@vastukala.org",
    "ownerName": "Umang Patel"
  },
  "_id": "60ae124daa6d152c1801b307",
  "document": {
    "documentType": "Office Copy",
    "documentDate": true,
    "to": false,
    "from": false,
    "amount": false,
    "nameOfApprovingAuthority": false,
    "number": false,
    "remarks": true,
    "caseStatus": {
      "value": "DELIVERED",
      "label": "Delivered"
    }
  },
  "createdAt": "2021-05-26T09:18:05.809Z",
  "updatedAt": "2023-06-20T10:17:50.158Z",
  "__v": 0,
  "label": "Office Copy",
  "value": "60ae124daa6d152c1801b307",
  "Name": "Office Copy",
  "Value": "60ae124daa6d152c1801b307",
  "caseStatus": {
    "value": "DELIVERED",
    "label": "Delivered"
  }
}
```

```
    }
  },
  "createdAt": "Sat Jul 27 2024 11:09:21 GMT+0530 (India Standard Time)",
  "uploadedBy": "659ccce98f39506e83489828"
},
{
  "originalname": "Swapnal Mukul Shrotri & Mr. Mukul Arvind Shrotri.pdf",
  "filename":
"1728106246628_Swapnal_Mukul_Shrotri__Mr_Mukul_Arvind_Shrotri.pdf",
  "path": "cases/669f7c5f8be38171f22b63f3/externalDocuments/1728106246628_Sw
apnal_Mukul_Shrotri__Mr_Mukul_Arvind_Shrotri.pdf",
  "size": "1761758",
  "documentType": {
    "value": "640ece6024088f0f94ee4ea8",
    "label": "Final PDF Report"
  },
  "createdAt": "Sat Oct 05 2024 11:00:46 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f9589345132d6a6bddcc3a"
},
{
  "originalname": "Valuation_report_Swapnal Mukul Shrotri & Mr. Mukul Arvind
Shrotri.pdf",
  "filename": "1728111896708_Valuation_report_Swapnal_Mukul_Shrotri__Mr_Mukul
_Arvind_Shrotri.pdf",
  "path": "cases/669f7c5f8be38171f22b63f3/externalDocuments/1728111896708_Val
uation_report_Swapnal_Mukul_Shrotri__Mr_Mukul_Arvind_Shrotri.pdf",
  "size": "4894037",
  "documentType": {
    "value": "640ece6024088f0f94ee4ea8",
    "label": "Final PDF Report"
  },
  "createdAt": "Sat Oct 05 2024 12:34:56 GMT+0530 (India Standard Time)",
  "uploadedBy": "63f31d626f9c2254a9b39144"
}
],
"processingDocuments": [
  {
    "originalname": "10104.xlsx",
    "filename": "1721800136719_10104.xlsx",
    "path": "cases/669f7c5f8be38171f22b63f3/
processingDocuments/1721800136719_10104.xlsx",
    "size": "10142",
    "createdAt": "Wed Jul 24 2024 11:18:57 GMT+0530 (India Standard Time)",
    "uploadedBy": "627221f4afd7d55eddeddcb4"
  }
],
```

```
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "CHECKER",
    "display": true,
    "status": true,
    "_id": "66ffea27de702a0d3957d946",
    "note": "value changed (Task Reopen)",
    "taskId": "66a095d46e8f430d9509045d",
    "createdAt": "2024-10-04T13:14:15.153Z"
  },
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "PRINT",
    "display": true,
    "status": true,
    "_id": "66ffea2fde702a0d3957d988",
    "note": "value changed (Task Reopen)",
    "taskId": "66a1ea8f1b03a77e0e1761ad",
    "createdAt": "2024-10-04T13:14:23.957Z"
  },
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
  },
}
```



```
"workType": "SIGNED_REPORT_UPLOAD",
"display": true,
"status": true,
"_id": "66ffea37554d3e0d4630e47c",
"note": "value changed (Task Reopen)",
"taskId": "66a1efcb6318787e5267ba95",
"createdAt": "2024-10-04T13:14:31.940Z"
},
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "CHECKER",
  "display": true,
  "status": true,
  "_id": "6700c7e2c514c90d38660c83",
  "note": "value change (Task Reopen)",
  "taskId": "66a095d46e8f430d9509045d",
  "createdAt": "2024-10-05T05:00:18.701Z"
},
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "CHECKER",
  "display": true,
  "status": true,
  "_id": "674af730e077c54e532d5eec",
  "note": "revision (Task Reopen)",
  "taskId": "66a095d46e8f430d9509045d",
  "createdAt": "2024-11-30T11:29:52.604Z"
}
],
"createdAt": "2024-07-23T09:48:15.466Z",
"updatedAt": "2024-11-30T12:28:39.847Z",
"__v": 0,
```

```
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. B-34, 3rd Floor, Wing - B, Pethenagar Co-op. Hsg.
Soc. Ltd., Kedarmal Road, Village - Malad East, Municipality Ward No. P Ward, Malad
(East), Taluka - Borivali, District - Mumbai Suburban District, Mumbai, PIN Code - 400
097, State - Maharashtra, India",
"updatedBy": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mr. Mukul Arvind Shrotri",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "9869408280",
"invoiceId": null,
"siteVisitDate": "2024-07-22",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"buildingServicesRate": "2700",
"flatRate": "27800",
"landOtherRate": "25100",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
```

```

"finalMeasurementType": "Sq. Ft.",
"finalSaleablePercentage": "0",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 355.00",
"briefDescOfProperty": "Living Room + Kitchen + Bathroom + WC + Passage",
"carpetTotal": "291.88",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "365.86",
"finalCarpetArea": "304.88",
"finalSalableArea": "402.44",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"reportGeneratedDate": "Thu Jul 25 2024 10:40:27 GMT+0530 (India Standard Time)",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
}
}

```

| Name | Length | Width | Total |
|------------------------|---------------|--------------|--------------|
| Composition : | | | |
| Living Room | 20'3" | 9'4" | 189.00 |
| Kitchen | 7'9" | 8'11" | 69.10 |
| Bathroom | 4'6" | 3'3" | 14.62 |
| WC | 4'4" | 3'00" | 13.00 |
| Passage | 7'5" | 2'7" | 19.16 |
| Other Composition : | | | |