

```
{
  "typeOfReport": {
    "value": "Unit",
    "label": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Capital_Gain",
    "label": "Capital Gain"
  },
  "masterTypeOfPurpose": {
    "value": "Capital_Gain",
    "label": "Capital Gain"
  },
  "toAssess": {
    "value": "Capital_Gain_2001",
    "label": "Capital Gain 2001"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "12000"
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "66a1fb05f702e07e145ae4b9",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "Rajender Mohan Bector ",
"displayName": "Rajender Mohan Bector ",
"initial": "R"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "60f949ce45132d6a6bddbcc3",
    "role": "SITEENGINEER",
    "firstName": "Tushar ",
    "email": "tusharbhuwad90@gmail.com",
    "lastName": "Bhuwad",
    "mobileNo": "9082053889",
    "designation": "",
    "shortName": "TSB",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60f9147bf3dd69653a591e8c",
    "role": "MAKER + RATE VERFIER + CHEAKER",
```

```
"firstName": "Vinita",
"email": "vinita.surve@vastukala.org",
"lastName": "Surve",
"mobileNo": "9820652818",
"designation": "",
"shortName": "V",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f9147bf3dd69653a591e8c",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Vinita",
  "email": "vinita.surve@vastukala.org",
  "lastName": "Surve",
  "mobileNo": "9820652818",
  "designation": "",
  "shortName": "V",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f9147bf3dd69653a591e8c/
profilePhoto_1668058171670_WhatsApp_Image_20221110_at_105714_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  }
],
```

```
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.1042303102221",
  "longitude": "72.88147434834492"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
```

```
    "dateTime": "25/07/2024 12:30 pm"
  },
  {
    "dateTime": "25/07/2024 12:00 am"
  },
  {
    "dateTime": "25/07/2024 12:00 am"
  }
],
"visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Marol",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "Akshay Mittal Industrial Estate",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Mittal Industrial Estate",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```

```
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "5/B/39",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```



```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
}
```

```
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri East",
  "label": false
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
```

```
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```

```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```



```
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66a1fb06f702e07e145ae4bf",
"ownerName": "Rajender Mohan Bector ",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9819158397",
"contactPersonName": "Kinjal Malavia",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Rajender Mohan Bector ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "504219"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "Contact Person",
"fullAddress": "Commercial Unit No. 5/B/39, Ground Floor, Akshay Mittal Industrial Estate, Mittal Industrial Estate, Village - Marol, Andheri East, Mumbai, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    }
  }
],
```

```
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1721891044600_1984_agreement.pdf",
"path": "cases/66a1fb06f702e07e145ae4bf/
document_1721891044600_1984_agreement.pdf",
"id": "846724",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Thu Jul 25 2024 12:43:09 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1721891054798_DEED_CONFIRMATION.pdf",
  "path": "cases/66a1fb06f702e07e145ae4bf/
document_1721891054798_DEED_CONFIRMATION.pdf",
  "id": "898444",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Thu Jul 25 2024 12:43:09 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1721891064412_Draft_of_Sale_Deed__Unti_No_B_39_Akshay_Mittal.pdf",
  "path": "cases/66a1fb06f702e07e145ae4bf/
document_1721891064412_Draft_of_Sale_Deed__Unti_No_B_39_Akshay_Mittal.pdf",
  "id": "120109",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Thu Jul 25 2024 12:43:09 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1721891077738_gala_no39_mittal.pdf",
```

```
    "path": "cases/66a1fb06f702e07e145ae4bf/
document_1721891077738_gala_no39_mittal.pdf",
    "id": "327111",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Thu Jul 25 2024 12:43:09 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1721891089775_SHARE_CERT.pdf",
    "path": "cases/66a1fb06f702e07e145ae4bf/
document_1721891089775_SHARE_CERT.pdf",
    "id": "711403",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Thu Jul 25 2024 12:43:09 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1721891099718_gala_no39_mittal__new.pdf",
    "path": "cases/66a1fb06f702e07e145ae4bf/
document_1721891099718_gala_no39_mittal__new.pdf",
    "id": "716304",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Thu Jul 25 2024 12:43:09 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1721891110991_111569.pdf",
    "path": "cases/66a1fb06f702e07e145ae4bf/
document_1721891110991_111569.pdf",
    "id": "711323",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
```

```
"createdAt": "Thu Jul 25 2024 12:43:09 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1721891126705_127811.pdf",
  "path": "cases/66a1fb06f702e07e145ae4bf/
document_1721891126705_127811.pdf",
  "id": "232674",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Thu Jul 25 2024 12:43:09 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1721891144727_125995.pdf",
  "path": "cases/66a1fb06f702e07e145ae4bf/
document_1721891144727_125995.pdf",
  "id": "908087",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Thu Jul 25 2024 12:43:09 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "010151",
"createdBy": "6006d4ce5080a310ac1fd2",
"caseHistory": [
  {
    "id": "766773",
    "title": "Create Case",
    "description": "Create Case",
```

```
    "datetime": "Thu Jul 25 2024 12:43:10 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d5cbc6e5d340a0b3e43",
    "name": "externalimg_r_1722051931666_TimePhoto_20240726_163048.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/externalimg_r_1722051931666_TimePhoto_20240726_163048.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d5cbc6e5d340a0b3e44",
    "name": "externalimg_r_1722051931655_TimePhoto_20240726_162341.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/externalimg_r_1722051931655_TimePhoto_20240726_162341.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d5cbc6e5d340a0b3e45",
    "name": "externalimg_r_1722051931662_TimePhoto_20240726_162456.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/externalimg_r_1722051931662_TimePhoto_20240726_162456.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d5cbc6e5d340a0b3e46",
    "name": "externalimg_r_1722051931651_TimePhoto_20240726_161530.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/externalimg_r_1722051931651_TimePhoto_20240726_161530.jpg",
  }
]
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a46d5cbc6e5d340a0b3e47",
  "name": "externallmg_r_1722051931670_TimePhoto_20240726_163140.jpg",
  "path": "cases/66a1fb06f702e07e145ae4bf/
externallmg_r_1722051931670_TimePhoto_20240726_163140.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a46d5cbc6e5d340a0b3e48",
  "name": "externallmg_r_1722051931676_IMG20240726163021.jpg",
  "path": "cases/66a1fb06f702e07e145ae4bf/
externallmg_r_1722051931676_IMG20240726163021.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a46d5cbc6e5d340a0b3e49",
  "name": "externallmg_r_1722051931672_IMG20240726163019.jpg",
  "path": "cases/66a1fb06f702e07e145ae4bf/
externallmg_r_1722051931672_IMG20240726163019.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a46d5cbc6e5d340a0b3e4a",
  "name": "externallmg_r_1722051931678_IMG20240726163026.jpg",
  "path": "cases/66a1fb06f702e07e145ae4bf/
externallmg_r_1722051931678_IMG20240726163026.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a46d5cbc6e5d340a0b3e4b",
  "name": "externallmg_r_1722051931681_TimePhoto_20240726_161517.jpg",
  "path": "cases/66a1fb06f702e07e145ae4bf/
externallmg_r_1722051931681_TimePhoto_20240726_161517.jpg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d5cbc6e5d340a0b3e4c",
    "name": "externallmg_r_1722051931684_TimePhoto_20240726_161522.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externallmg_r_1722051931684_TimePhoto_20240726_161522.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d5cbc6e5d340a0b3e4d",
    "name": "externallmg_r_1722051931687_TimePhoto_20240726_161525.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externallmg_r_1722051931687_TimePhoto_20240726_161525.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d5cbc6e5d340a0b3e4e",
    "name": "externallmg_r_1722051931689_TimePhoto_20240726_161544.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externallmg_r_1722051931689_TimePhoto_20240726_161544.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d5cbc6e5d340a0b3e4f",
    "name": "externallmg_r_1722051931692_TimePhoto_20240726_161546.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externallmg_r_1722051931692_TimePhoto_20240726_161546.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d5cbc6e5d340a0b3e50",
    "name": "externallmg_r_1722051931697_TimePhoto_20240726_161606.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externallmg_r_1722051931697_TimePhoto_20240726_161606.jpg",
    "orientation": "landscape"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a46d5cbc6e5d340a0b3e51",
  "name": "externallmg_r_1722051931700_TimePhoto_20240726_161607.jpg",
  "path": "cases/66a1fb06f702e07e145ae4bf/
externallmg_r_1722051931700_TimePhoto_20240726_161607.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a46d5cbc6e5d340a0b3e52",
  "name": "externallmg_r_1722051931695_TimePhoto_20240726_161558.jpg",
  "path": "cases/66a1fb06f702e07e145ae4bf/
externallmg_r_1722051931695_TimePhoto_20240726_161558.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a46d5cbc6e5d340a0b3e53",
  "name": "externallmg_r_1722051931703_TimePhoto_20240726_161642.jpg",
  "path": "cases/66a1fb06f702e07e145ae4bf/
externallmg_r_1722051931703_TimePhoto_20240726_161642.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a46d5cbc6e5d340a0b3e54",
  "name": "externallmg_r_1722051931707_TimePhoto_20240726_162259.jpg",
  "path": "cases/66a1fb06f702e07e145ae4bf/
externallmg_r_1722051931707_TimePhoto_20240726_162259.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a46d5cbc6e5d340a0b3e55",
  "name": "externallmg_r_1722051931705_TimePhoto_20240726_161719.jpg",
  "path": "cases/66a1fb06f702e07e145ae4bf/
externallmg_r_1722051931705_TimePhoto_20240726_161719.jpg",
  "orientation": "portrait"
},
{
```



```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d5cbc6e5d340a0b3e56",
    "name": "externalimg_r_1722051931709_TimePhoto_20240726_162307.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externalimg_r_1722051931709_TimePhoto_20240726_162307.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d6cbc6e5d340a0b3e75",
    "name": "externalimg_r_1722051948371_TimePhoto_20240726_162339.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externalimg_r_1722051948371_TimePhoto_20240726_162339.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d6cbc6e5d340a0b3e76",
    "name": "externalimg_r_1722051948361_TimePhoto_20240726_162309.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externalimg_r_1722051948361_TimePhoto_20240726_162309.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d6cbc6e5d340a0b3e77",
    "name": "externalimg_r_1722051948358_TimePhoto_20240726_162307.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externalimg_r_1722051948358_TimePhoto_20240726_162307.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d6cbc6e5d340a0b3e78",
    "name": "externalimg_r_1722051948365_TimePhoto_20240726_162318.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externalimg_r_1722051948365_TimePhoto_20240726_162318.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66a46d6cbc6e5d340a0b3e79",
  "name": "externalimg_r_1722051948375_TimePhoto_20240726_162348.jpg",
  "path": "cases/66a1fb06f702e07e145ae4bf/
externalimg_r_1722051948375_TimePhoto_20240726_162348.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a46d6cbc6e5d340a0b3e7a",
  "name": "externalimg_r_1722051948379_TimePhoto_20240726_162352.jpg",
  "path": "cases/66a1fb06f702e07e145ae4bf/
externalimg_r_1722051948379_TimePhoto_20240726_162352.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a46d6cbc6e5d340a0b3e7b",
  "name": "externalimg_r_1722051948383_TimePhoto_20240726_162424.jpg",
  "path": "cases/66a1fb06f702e07e145ae4bf/
externalimg_r_1722051948383_TimePhoto_20240726_162424.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a46d6cbc6e5d340a0b3e7c",
  "name": "externalimg_r_1722051948386_TimePhoto_20240726_162504.jpg",
  "path": "cases/66a1fb06f702e07e145ae4bf/
externalimg_r_1722051948386_TimePhoto_20240726_162504.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66a46d6cbc6e5d340a0b3e7d",
  "name": "externalimg_r_1722051948389_TimePhoto_20240726_162604.jpg",
  "path": "cases/66a1fb06f702e07e145ae4bf/
externalimg_r_1722051948389_TimePhoto_20240726_162604.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "66a46d6cbc6e5d340a0b3e7e",
    "name": "externalimg_r_1722051948392_TimePhoto_20240726_162622.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externalimg_r_1722051948392_TimePhoto_20240726_162622.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d6cbc6e5d340a0b3e7f",
    "name": "externalimg_r_1722051948394_TimePhoto_20240726_162626.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externalimg_r_1722051948394_TimePhoto_20240726_162626.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d6cbc6e5d340a0b3e80",
    "name": "externalimg_r_1722051948397_TimePhoto_20240726_162627.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externalimg_r_1722051948397_TimePhoto_20240726_162627.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d6cbc6e5d340a0b3e81",
    "name": "externalimg_r_1722051948400_TimePhoto_20240726_163045.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externalimg_r_1722051948400_TimePhoto_20240726_163045.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d6cbc6e5d340a0b3e82",
    "name": "externalimg_r_1722051948403_TimePhoto_20240726_163126.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externalimg_r_1722051948403_TimePhoto_20240726_163126.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46d6cbc6e5d340a0b3e83",
```

```

    "name": "externalImg_r_1722051948405_TimePhoto_20240726_163129.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externalImg_r_1722051948405_TimePhoto_20240726_163129.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46dbcbc6e5d340a0b3eb1",
    "name": "externalImg_r_1722052028147_IMG20240727055126.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externalImg_r_1722052028147_IMG20240727055126.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66a46dbcbc6e5d340a0b3eb2",
    "name": "externalImg_r_1722052028128_IMG20240727055541.jpg",
    "path": "cases/66a1fb06f702e07e145ae4bf/
externalImg_r_1722052028128_IMG20240727055541.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-07-25T07:13:10.075Z",
"updatedAt": "2024-07-27T03:47:08.497Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "6006d4ce5080a310ac1fdcf2"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			