

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63b263d9191f7b344b008894"
    },
    "firstName": "Ravi Ratnaparikhi",
    "type": "CREDITOFFICER",
    "_id": "64c7602105efe8082a8c9b43",
    "lastName": "Ratnaparikhi",
    "mobileNo": "",
    "workMobileNo": "9970694920",
    "email": "ravi.ratnaparikhi@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63b263d9191f7b344b008894",
  "name": "SME Fort Branch",
  "branchCode": "",
  "mobileNo": "022-22624308",
  "alternateMobileNo": "",
  "email": "sbi.60113@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Gresham House, Sir P. M. Road Branch, Fort, \nMumbai - 400 001, State
- Maharashtra, Country - India."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62550ed0aba01e0af98f2f75",
    "role": "SITEENGINEER",
    "firstName": "Chandan",
    "email": "ck06806@gmail.com",
    "lastName": "Singh",
    "mobileNo": "8454863607",
    "designation": "",
    "shortName": "CH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
  },
  "rateVerifier": null,
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
          "label": "Registered Valuer"
        }
      ]
    },
    {
      "type": "EMPLOYEE",
      "_id": "5ffe92d27737ca4d986b6453",
      "role": "VALUER",
      "firstName": "Manoj",
      "email": "manoj@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9819597579",
      "designation": "Registered Valuer",
      "registrationNo": [
        {
```

```
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "18.954271610893123",
```

```
"longitude": "72.82435877693645"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82435877693645,
    18.954271610893123
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "1/08/2024 12:59 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Girgaon",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "19",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shreepati Jewelles Ruby ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Near C P tank Circle ",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
}
```

```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
```



```
"key": "selectNo",
"value": "1903 and 1904",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400004",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Girgaon",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```

```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
```



```
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66a898e424c0566f86156699",
"ownerName": "Bhavik Arvindkumar Shah ",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat no 3 &4 (1903&1904) A-wing,19Floor, Shreepati Tower,
(Shreepati Jewels Ruby) Near CP Thank Circle & Shree Pimpleshwar Mahadev
&Hanuman Mandir, Taty Gharpure Marg,Pimpalwadi Girgaon Charni Road East ",
"remark": "Contact Person Mr Paresh Bhai 9819870330",
"documents": [
  {
    "documentType": {
      "label": "Old Valuation Report ",
      "value": "60ae1296aa6d152c1801b455"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66a898e424c0566f86156699/
document_1722325192222_391133.pdf",
    "fileName": "document_1722325192222_391133.pdf",
    "id": "740320",
    "uploadedBy": "60af3d172ffdf65bcd6585cd",
    "createdAt": "Tue Jul 30 2024 13:10:20 GMT+0530 (India Standard Time)"
  },

```

```
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66a898e424c0566f86156699/document_1722326978393_1722326877179_Bhavik_Shah_Flat_no_19031904_SBI_SME_Fort.pdf",
  "fileName": "document_1722326978393_1722326877179_Bhavik_Shah_Flat_no_19031904_SBI_SME_Fort.pdf",
  "id": "703864",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Tue Jul 30 2024 13:41:45 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Old Valution Report ",
    "value": "60ae1296aa6d152c1801b455"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66a898e424c0566f86156699/document_1722327102611_1722326941106_Bhavik_Arivindkumar_ShahFkat_no_1319031904_Old_Valuation_Report.pdf",
  "fileName": "document_1722327102611_1722326941106_Bhavik_Arivindkumar_ShahFkat_no_1319031904_Old_Valuation_Report.pdf",
  "id": "281902",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Tue Jul 30 2024 13:41:45 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Approved Building Plan",
    "value": "60ae1277aa6d152c1801b3cc"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66a898e424c0566f86156699/document_1722327236861_1722327138207_Flat_no_1903_1904_Plan_Copy.pdf",
  "fileName": "document_1722327236861_1722327138207_Flat_no_1903_1904_Plan_Copy.pdf",
  "id": "570656",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Tue Jul 30 2024 13:44:00 GMT+0530 (India Standard Time)"
}
],
```

```
"caseNumber": "010246",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
    "id": "144533",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jul 30 2024 13:10:20 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Bhavik Arvindkumar Shah ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "453355"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e3fc884d1123342377d",
    "name":
"externallmg_1722916415383_WhatsApp_Image_20240806_at_091839.jpeg",
    "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415383_WhatsApp_Image_20240806_at_091839.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e3fc884d1123342377e",
    "name":
"externallmg_1722916415384_WhatsApp_Image_20240806_at_091840_1.jpeg",
    "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415384_WhatsApp_Image_20240806_at_091840_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e3fc884d1123342377f",
    "name":
"externallmg_1722916415387_WhatsApp_Image_20240806_at_091840_2.jpeg",
    "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415387_WhatsApp_Image_20240806_at_091840_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e3fc884d11233423780",
    "name":
"externallmg_1722916415389_WhatsApp_Image_20240806_at_091840.jpeg",
    "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415389_WhatsApp_Image_20240806_at_091840.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e3fc884d11233423781",
    "name":
"externallmg_1722916415390_WhatsApp_Image_20240806_at_091841_1.jpeg",
    "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415390_WhatsApp_Image_20240806_at_091841_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e3fc884d11233423782",
    "name":
"externallmg_1722916415391_WhatsApp_Image_20240806_at_091841_2.jpeg",
    "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415391_WhatsApp_Image_20240806_at_091841_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e3fc884d11233423783",
```

```
"name":
"externallmg_1722916415392_WhatsApp_Image_20240806_at_091841.jpeg",
  "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415392_WhatsApp_Image_20240806_at_091841.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b19e3fc884d11233423784",
  "name":
"externallmg_1722916415394_WhatsApp_Image_20240806_at_091842_1.jpeg",
  "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415394_WhatsApp_Image_20240806_at_091842_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b19e3fc884d11233423785",
  "name":
"externallmg_1722916415396_WhatsApp_Image_20240806_at_091842_2.jpeg",
  "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415396_WhatsApp_Image_20240806_at_091842_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b19e3fc884d11233423786",
  "name":
"externallmg_1722916415397_WhatsApp_Image_20240806_at_091842.jpeg",
  "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415397_WhatsApp_Image_20240806_at_091842.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b19e3fc884d11233423787",
  "name":
"externallmg_1722916415399_WhatsApp_Image_20240806_at_091843_1.jpeg",
  "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415399_WhatsApp_Image_20240806_at_091843_1.jpeg",
  "orientation": "portrait"
},
},
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b19e3fc884d11233423788",
  "name":
"externallmg_1722916415400_WhatsApp_Image_20240806_at_091843_2.jpeg",
  "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415400_WhatsApp_Image_20240806_at_091843_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b19e3fc884d11233423789",
  "name":
"externallmg_1722916415400_WhatsApp_Image_20240806_at_091843.jpeg",
  "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415400_WhatsApp_Image_20240806_at_091843.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b19e3fc884d1123342378a",
  "name":
"externallmg_1722916415403_WhatsApp_Image_20240806_at_091844_1.jpeg",
  "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415403_WhatsApp_Image_20240806_at_091844_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b19e3fc884d1123342378b",
  "name":
"externallmg_1722916415404_WhatsApp_Image_20240806_at_091844_2.jpeg",
  "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415404_WhatsApp_Image_20240806_at_091844_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b19e3fc884d1123342378c",
  "name":
"externallmg_1722916415405_WhatsApp_Image_20240806_at_091844.jpeg",
```

```
    "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415405_WhatsApp_Image_20240806_at_091844.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b19e3fc884d1123342378d",
    "name":
"externallmg_1722916415406_WhatsApp_Image_20240806_at_091845.jpeg",
    "path": "cases/66a898e424c0566f86156699/
externallmg_1722916415406_WhatsApp_Image_20240806_at_091845.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "ACCOUNTANT",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "66aa28b92282636f80b3a4d6",
    "note": "Given approx. value",
    "taskId": "66a898e424c0566f861566aa",
    "createdAt": "2024-07-31T12:06:17.656Z"
  }
],
"createdAt": "2024-07-30T07:40:20.176Z",
"updatedAt": "2024-08-06T03:53:35.441Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
}
```

```
},
"fullAddress": "Residential Flat No. 1903 and 1904, 19th Floor, Wing - A, Shreepati Jewelles Ruby , Near C P tank Circle , Village - Girgaon, Girgaon, Mumbai, 400004",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Bhavik Arvindkumar Shah ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "0000000000"
}
```

Name	Length	Width	Total
Composition :			
Other Composition :			