

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b99c"
    },
    "firstName": "Vivek",
    "type": "CREDITOFFICER",
    "_id": "65d84551cf7ad63a0afd023e",
    "lastName": "Kulkarni",
    "mobileNo": "",
    "workMobileNo": "9922278899",
    "email": "vivek.kulkarni@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "46451645",
    "discussWithPerson": "Vivek",
    "expectedFees": 23225.822500000002,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b99c",
  "branchCode": "000011",
  "type": "BRANCH",
  "name": "Dadar Branch ",
  "email": "dadar@cosmosbank.in",
  "mobileNo": "02224476018",
  "alternateMobileNo": "8369167372",
  "address": "Horizon Bldg.,1st Floor, Ranade Road & Gokhale Road, Dadar (West),
Mumbai - 400 028, State - Maharashtra, Country - India.",
  "ledgerName": "COSMOS BANK - DADAR",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1720806809901_image.jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60016f965256c07aec8e6dd6",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Akhilesh",
  "email": "akhilesh.yadav@vastukala.org",
  "lastName": "Yadav",
  "mobileNo": "9545753921",
  "designation": "Processing Officer",
  "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
  "profilePhoto": "users\\60016f965256c07aec8e6dd6\\
\\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
  "shortName": "AY"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60016f965256c07aec8e6dd6",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Akhilesh",
  "email": "akhilesh.yadav@vastukala.org",
```

```
"lastName": "Yadav",
"mobileNo": "9545753921",
"designation": "Processing Officer",
"workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
"profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
"shortName": "AY"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60016f965256c07aec8e6dd6",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Akhilesh",
"email": "akhilesh.yadav@vastukala.org",
"lastName": "Yadav",
"mobileNo": "9545753921",
"designation": "Processing Officer",
"workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
"profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
"shortName": "AY"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
}
```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.25395063735534",
  "longitude": "73.10191165034004"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.10191165034004,
```

```
19.25395063735534
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "9/08/2024 01:54 pm"
    },
    {
      "dateTime": "9/08/2024 12:00 am"
    },
    {
      "dateTime": "9/08/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "KON",
  }
}
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "B/21",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Asmeeta Textile Park",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "MIDC",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Additional Kalyan Bhiwandi Industrial Area",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```



```
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```



```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
```

```
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66b5c8a2da840b1214c43dbe",
"ownerName": "Focus Jeans India Pvt Ltd ",
"ownerPhoneNo": "9819200442",
"appAddress": "Textile Bldg. No B-2/1, Asmeeta Textile park, MIDC plot no 1, Kalyan
Bhiwandi, industrial area, kon , Bhiwandi Thane ",
"remark": "urgent basis \nvisit schedule tomorrow - 1st half ",
"documents": [
  {
    "documentType": {
      "label": "Any Other Document",
      "value": "60ae124aaa6d152c1801b2f7"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66b5c8a2da840b1214c43dbe/
document_1723189372748_.1723189369971_Focus_-_CB_Dadar_",
    "fileName": "document_1723189372748_.1723189369971_Focus_-_CB_Dadar_",
    "id": "908317",
    "uploadedBy": "62723addafd7d55eddeddfe4",
    "createdAt": "Fri Aug 09 2024 13:13:30 GMT+0530 (India Standard Time)"
  },
  {
```

```
"documentType": {
  "value": "60ae124eaa6d152c1801b30b",
  "label": "Other"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1723274503998_GRFIRST_FLOOR_PLAN_1.pdf",
"path": "cases/66b5c8a2da840b1214c43dbe/
document_1723274503998_GRFIRST_FLOOR_PLAN_1.pdf",
"id": "213252",
"uploadedBy": "6006d4ce5080a310ac1fd2",
"createdAt": "Sat Aug 10 2024 12:54:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1723274512808_GRFIRST_FLOOR_PLAN.pdf",
  "path": "cases/66b5c8a2da840b1214c43dbe/
document_1723274512808_GRFIRST_FLOOR_PLAN.pdf",
  "id": "635971",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Sat Aug 10 2024 12:54:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1723274523341_MASTER_PLAN_LAYOUT_1.pdf",
  "path": "cases/66b5c8a2da840b1214c43dbe/
document_1723274523341_MASTER_PLAN_LAYOUT_1.pdf",
  "id": "927965",
  "uploadedBy": "6006d4ce5080a310ac1fd2",
  "createdAt": "Sat Aug 10 2024 12:54:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
}
```

```
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1723274534020_MASTER_PLAN_LAYOUT.pdf",
"path": "cases/66b5c8a2da840b1214c43dbe/
document_1723274534020_MASTER_PLAN_LAYOUT.pdf",
"id": "479291",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Sat Aug 10 2024 12:54:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1723274549360_MASTER_PLANPARKING_LAYOUT_1.pdf",
  "path": "cases/66b5c8a2da840b1214c43dbe/
document_1723274549360_MASTER_PLANPARKING_LAYOUT_1.pdf",
  "id": "244761",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Sat Aug 10 2024 12:54:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1723274562230_MASTER_PLANPARKING_LAYOUT.pdf",
  "path": "cases/66b5c8a2da840b1214c43dbe/
document_1723274562230_MASTER_PLANPARKING_LAYOUT.pdf",
  "id": "878808",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Sat Aug 10 2024 12:54:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1723274571966_Revised_Plan_approval_B2_Building_Drg
```

```
_Digi_Sign_1.pdf",
  "path": "cases/66b5c8a2da840b1214c43dbe/document_1723274571966_Revised_Plan_approval_B2_Building_Drg_Digi_Sign_1.pdf",
  "id": "453785",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Sat Aug 10 2024 12:54:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1723274583711_Revised_Plan_approval_B2_Building_Drg_Digi_Sign.pdf",
  "path": "cases/66b5c8a2da840b1214c43dbe/
document_1723274583711_Revised_Plan_approval_B2_Building_Drg_Digi_Sign.pdf",
  "id": "947411",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Sat Aug 10 2024 12:54:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1723274593382_electric_bill_asmeeta.pdf",
  "path": "cases/66b5c8a2da840b1214c43dbe/
document_1723274593382_electric_bill_asmeeta.pdf",
  "id": "396624",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Sat Aug 10 2024 12:54:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1723274604108_maitenance_bill.pdf",
  "path": "cases/66b5c8a2da840b1214c43dbe/
document_1723274604108_maitenance_bill.pdf",
```

```
"id": "676591",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Sat Aug 10 2024 12:54:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1723274616540_property_tax_challan__asmeeta.pdf",
  "path": "cases/66b5c8a2da840b1214c43dbe/
document_1723274616540_property_tax_challan__asmeeta.pdf",
  "id": "423734",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Sat Aug 10 2024 12:54:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1723274629795_Revised_additional_plan_approval_1.pdf",
  "path": "cases/66b5c8a2da840b1214c43dbe/
document_1723274629795_Revised_additional_plan_approval_1.pdf",
  "id": "823930",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Sat Aug 10 2024 12:54:14 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1723274640408_Revised_additional_plan_approval.pdf",
  "path": "cases/66b5c8a2da840b1214c43dbe/
document_1723274640408_Revised_additional_plan_approval.pdf",
  "id": "996368",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Sat Aug 10 2024 12:54:14 GMT+0530 (India Standard Time)"
},
}
```

```
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1723274652080_TERRACE_CLOOR.pdf",
  "path": "cases/66b5c8a2da840b1214c43dbe/
document_1723274652080_TERRACE_CLOOR.pdf",
  "id": "866371",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Sat Aug 10 2024 12:54:14 GMT+0530 (India Standard Time)"
},
"caseNumber": "010501",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "862297",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Aug 09 2024 13:13:30 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Focus Jeans India Pvt Ltd ",
    "phone": "9819200442",
    "ownershipShare": "",
    "email": "",
    "id": "302116"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
  }
]
```

```
    "_id": "66b753bc4388d81213f5cce3",
    "name": "externalimg_r_172329055530_1723290552026_image_0.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_172329055530_1723290552026_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b753e9c884d1123346c292",
    "name": "externalimg_1723290579795_1723290576224_image_1.png",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_1723290579795_1723290576224_image_1.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b753e9c884d1123346c293",
    "name": "externalimg_r_1723290581687_1723290576224_image_3.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290581687_1723290576224_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b753e9c884d1123346c294",
    "name": "externalimg_r_1723290582714_1723290576224_image_4.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290582714_1723290576224_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b753e9c884d1123346c295",
    "name": "externalimg_r_1723290580558_1723290576224_image_2.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290580558_1723290576224_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b753e9c884d1123346c296",
```



```
    "name": "externalimg_r_1723290578715_1723290576224_image_0.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290578715_1723290576224_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b753e9c884d1123346c297",
    "name": "externalimg_r_1723290584981_1723290576224_image_6.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290584981_1723290576224_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b753e9c884d1123346c298",
    "name": "externalimg_r_1723290586352_1723290576224_image_7.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290586352_1723290576224_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b753e9c884d1123346c299",
    "name": "externalimg_r_1723290583745_1723290576224_image_5.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290583745_1723290576224_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b753e9c884d1123346c29a",
    "name": "externalimg_r_1723290587681_1723290576224_image_8.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290587681_1723290576224_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b753e9c884d1123346c29b",
    "name": "externalimg_r_1723290590212_1723290576224_image_10.jpg",
```

```
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290590212_1723290576224_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b753e9c884d1123346c29c",
    "name": "externallmg_r_1723290592139_1723290576224_image_12.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290592139_1723290576224_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b753e9c884d1123346c29d",
    "name": "externallmg_r_1723290588870_1723290576224_image_9.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290588870_1723290576224_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b753e9c884d1123346c29e",
    "name": "externallmg_r_1723290591266_1723290576224_image_11.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290591266_1723290576224_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b753e9c884d1123346c29f",
    "name": "externallmg_r_1723290594088_1723290576224_image_14.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290594088_1723290576224_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b753e9c884d1123346c2a0",
    "name": "externallmg_r_1723290592887_1723290576224_image_13.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290592887_1723290576224_image_13.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b753e9c884d1123346c2a1",
  "name": "externallmg_r_1723290595957_1723290576224_image_16.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290595957_1723290576224_image_16.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b753e9c884d1123346c2a2",
  "name": "externallmg_r_1723290594846_1723290576224_image_15.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290594846_1723290576224_image_15.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b753e9c884d1123346c2a3",
  "name": "externallmg_r_1723290597085_1723290576224_image_17.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290597085_1723290576224_image_17.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b753e9c884d1123346c2a4",
  "name": "externallmg_r_1723290598178_1723290576224_image_18.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290598178_1723290576224_image_18.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b753e9c884d1123346c2a5",
  "name": "externallmg_r_1723290598916_1723290576224_image_19.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290598916_1723290576224_image_19.jpg",
  "orientation": "portrait"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b7541b4388d81213f5cd83",
  "name": "externallmg_r_1723290635592_1723290631200_image_2.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290635592_1723290631200_image_2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b7541b4388d81213f5cd84",
  "name": "externallmg_r_1723290636436_1723290631200_image_3.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290636436_1723290631200_image_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b7541b4388d81213f5cd85",
  "name": "externallmg_r_1723290634652_1723290631200_image_1.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290634652_1723290631200_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b7541b4388d81213f5cd86",
  "name": "externallmg_r_1723290633668_1723290631200_image_0.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290633668_1723290631200_image_0.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b7541b4388d81213f5cd87",
  "name": "externallmg_r_1723290637365_1723290631200_image_4.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290637365_1723290631200_image_4.jpg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b7541b4388d81213f5cd88",
  "name": "externallmg_r_1723290639155_1723290631200_image_6.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290639155_1723290631200_image_6.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b7541b4388d81213f5cd89",
  "name": "externallmg_r_1723290639982_1723290631200_image_7.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290639982_1723290631200_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b7541b4388d81213f5cd8a",
  "name": "externallmg_r_1723290638121_1723290631200_image_5.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290638121_1723290631200_image_5.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b7541b4388d81213f5cd8b",
  "name": "externallmg_r_1723290640823_1723290631200_image_8.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290640823_1723290631200_image_8.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b7541b4388d81213f5cd8c",
  "name": "externallmg_r_1723290641567_1723290631200_image_9.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290641567_1723290631200_image_9.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b7541b4388d81213f5cd8d",
    "name": "externallmg_r_1723290642283_1723290631200_image_10.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290642283_1723290631200_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b7541b4388d81213f5cd8e",
    "name": "externallmg_r_1723290643239_1723290631200_image_11.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290643239_1723290631200_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b7541b4388d81213f5cd8f",
    "name": "externallmg_r_1723290643913_1723290631200_image_12.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290643913_1723290631200_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b7541b4388d81213f5cd90",
    "name": "externallmg_r_1723290645450_1723290631200_image_14.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290645450_1723290631200_image_14.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b7541b4388d81213f5cd91",
    "name": "externallmg_r_1723290644783_1723290631200_image_13.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290644783_1723290631200_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66b7541b4388d81213f5cd92",
  "name": "externalimg_r_1723290646334_1723290631200_image_15.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290646334_1723290631200_image_15.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b7541b4388d81213f5cd93",
  "name": "externalimg_r_1723290647329_1723290631200_image_16.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290647329_1723290631200_image_16.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b7541b4388d81213f5cd94",
  "name": "externalimg_r_1723290648464_1723290631200_image_17.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290648464_1723290631200_image_17.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b7541b4388d81213f5cd95",
  "name": "externalimg_r_1723290649380_1723290631200_image_18.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290649380_1723290631200_image_18.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66b7541b4388d81213f5cd96",
  "name": "externalimg_r_1723290650246_1723290631200_image_19.jpg",
  "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290650246_1723290631200_image_19.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "66b7543ec884d1123346c3d0",
    "name": "externallmg_r_1723290675128_1723290669448_image_0.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290675128_1723290669448_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b7543ec884d1123346c3d1",
    "name": "externallmg_r_1723290677128_1723290669448_image_2.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290677128_1723290669448_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b7543ec884d1123346c3d2",
    "name": "externallmg_r_1723290677983_1723290669448_image_3.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290677983_1723290669448_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b7543ec884d1123346c3d3",
    "name": "externallmg_r_1723290676125_1723290669448_image_1.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290676125_1723290669448_image_1.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b7543ec884d1123346c3d4",
    "name": "externallmg_r_1723290678865_1723290669448_image_4.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externallmg_r_1723290678865_1723290669448_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b7543ec884d1123346c3d5",
```



```
    "name": "externalimg_r_1723290679722_1723290669448_image_5.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290679722_1723290669448_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b7543ec884d1123346c3d6",
    "name": "externalimg_r_1723290680625_1723290669448_image_6.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290680625_1723290669448_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b7543ec884d1123346c3d7",
    "name": "externalimg_r_1723290681536_1723290669448_image_7.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290681536_1723290669448_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b7543ec884d1123346c3d8",
    "name": "externalimg_r_1723290683535_1723290669448_image_9.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290683535_1723290669448_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b7543ec884d1123346c3d9",
    "name": "externalimg_r_1723290684592_1723290669448_image_10.jpg",
    "path": "cases/66b5c8a2da840b1214c43dbe/
externalimg_r_1723290684592_1723290669448_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66b7543ec884d1123346c3da",
    "name": "externalimg_r_1723290682611_1723290669448_image_8.jpg",
```

```

    "path": "cases/66b5c8a2da840b1214c43dbe/
externalImg_r_1723290682611_1723290669448_image_8.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-08-09T07:43:30.157Z",
"updatedAt": "2024-08-10T11:51:26.835Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Industrial Land and Building No. Basement Floor, Building No B/21,
Asmeeta Textile Park, MIDC, Additional Kalyan Bhiwandi Industrial Area, Village - KON,
State - Maharashtra, India",
"updatedBy": "63fc4680ce84bf289ba9c7fc",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Focus Jeans India Pvt Ltd ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9819200442"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			