

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b979"
    },
    "firstName": "Niraj",
    "type": "CREDITOFFICER",
    "_id": "66bede53da840b1214c79a4a",
    "email": "bo9867@pnb.co.in",
    "lastName": "KUmar",
    "mobileNo": "",
    "workMobileNo": "9869447424"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4100000",
    "discussWithPerson": "Niraj",
    "expectedFees": 2050,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b979",
  "branchCode": "000037",
  "type": "BRANCH",
  "name": "Charkop Branch P F Office",
  "email": "bo9867@pnb.co.in",
  "mobileNo": "02228679180",
  "alternateMobileNo": "",
  "address": "PNB Complex, Plot No. 202, RDP 6, Sector No. 3, Near P.F. Sadan,
Charkop, Kandivali (West), Mumbai - 400 067, State - Maharashtra, Country - India.",
  "ledgerName": "",
  "fax": null,
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "MAKER",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
```

```
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
          "label": "Wealth Tax"
        },
        "_id": "6084131a13f01f158c6ea1f4",
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "label": "Bank",
```

```
"value": "BANK"
},
"location": {
  "latitude": "19.17937303434126",
  "longitude": "72.81458191717182"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.81458191717182,
    19.17937303434126
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-08-18",
      "remark": "other Contact no - 7977206718"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1RK",
  "label": "1 RK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
```

```
"name": "Country",
"key": "country",
"value": "Country - India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Malwani ",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "43",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
}
```

```
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Malwani Sadgurukrupa Co-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Chhatrapati Shivaji Raje Complex, MHADA",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Opp. Ekta Nagar, Charkop Link Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
```

```
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "6-A(Part)",
  "label": true
},
}
```



```
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "004",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
```

```
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 067",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali (West)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "VerifiedTileFlooring",
    "label": "Vitrified Tile Flooring"
  },
  "doors": {
    "value": "Teak_Wood_Door_frame_with_Solid_flush_door",
    "label": "Teak Wood Door frame with Solid flush door"
  },
  "windows": {
    "value": "Aluminium_Sliding_Windows_with_window_grills",
    "label": "Aluminium Sliding Windows with window grills"
  },
  "fittings": {
    "value": "Open-Conduit_plumbing_with_Casing_Capping_Electrical_wiring_",
    "label": "Open-Conduit plumbing with Casing Capping Electrical wiring "
  },
}
```

```
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Shiv Sadan Society",
    "west": "Internal Road ",
    "south": "Open Plot",
    "east": "Building No. 44"
  },
  "asPerDocumentAgreement": {
    "north": "Details not available ",
    "west": "Details not available ",
    "south": "Details not available ",
    "east": "Details not available "
  },
  "unitBoundaries": {
    "asPerActual": {
      "north": "Marginal Space",
      "east": "Lobby",
      "south": "Flat No. 001",
      "west": "Lobby & Flat No. 003"
    },
    "asPerDocument": {
```

```
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "As Occupancy Certificate is received may be assumed
that the construction is as per sanctioned plan. ",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "N.A.",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "The loading between Measured Carpet Area to Built Up Area mentioned
in agreement is 39% for the purpose of valuation we have considering loading factor. ",
  "depreciationPercentage": "31.499999999999996",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "13118",
  "depreciatedBuildingRate": "1918"
},
"igrRate": {
  "propertyName": "Flat",
```

```
"rate": "99270",
"landRate": "53960",
"igrImage": "cases/66bee113da840b1214c79dcd/igr_1724060706112_Image.png",
"squareMeterGuideLineRate": "99270.00",
"squareFeetGuideLineRate": "9222.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "79",
  "rate": "8339.00",
  "squareMeterGuideLineRate": "89755.00",
  "squareFeetGuideLineRate": "8339.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Residential_Purpose",
    "label": "Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Vacant",
    "label": "Vacant"
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MCGM norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Average",
    "label": "Average"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
```

```
"roof": {
  "value": "rcc_Slab",
  "label": "R. C. C. Slab"
},
"partitions": {
  "value": "6\"_Thk._Brick_Masonry",
  "label": "6\" Thk. Brick Masonery"
},
"waterTank": {
  "value": "MunicipalWaterSupply",
  "label": "Municipal Water Supply"
},
"pavementLaid": {
  "value": "Yes",
  "label": "Yes"
},
"carParking": "Open Car Parking Space",
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2003",
  "fullDate": "1/1/2003"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
}
```

```
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Good",
  "label": "Good"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
```

```
"value": "1",
"label": "Yes"
},
"groundStilt": {
"value": "ground",
"label": "Ground"
},
"yearOfConstructionAsPer": {
"value": "as_per_occupancy_certificate",
"label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "39",
"ageOfBuilding": "21",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "7",
"flatFloorNo": "Ground",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
"area": "340.00",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Area as per Agreement For Sale"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "cases/66bee113da840b1214c79dcd/
routeMap_1724156462725_Image.png",
"routeLat": "19.203056",
"routeLng": "72.825028",
"stationName": "Dahanukarwadi",
"routeDistance": "2.1 Km. ",
"routeStation": {
"value": "Metro_Station",
"label": "Metro Station"
}
}
},
"finalLatLng": {
"coordinates": [
0,
0
```



```
],
  "type": "Point"
},
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "nrvxwv",
    "name": "nrvxwv",
    "image": "cases/66bee113da840b1214c79dcd/
routeMap_1724156329435_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
```

```
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "4460120.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "4376000",
"finalValue": "4460120.00",
"purchaseValueDocument": {
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "704208",
  "path": "cases/66bee113da840b1214c79dcd/document_1723785358755_17237853
55772_PNB_Charkop_pf_Office__Ashok_Kumar_Thakai_Sahu__Alok_kumar_Ashok_
Sahu.pdf",
  "fileName": "document_1723785358755_1723785355772_PNB_Charkop_pf_Office
__Ashok_Kumar_Thakai_Sahu__Alok_kumar_Ashok_Sahu.pdf",
  "documentDate": "13/08/2024",
  "amount": "4100000",
  "from": {
    "value": "Transferor",
    "label": "Transferor"
  },
  "Transferor": "Mrs. Shubhangee Sanjay Mengane alias Mrs. Shubhangi Sanjay
Mengane & Mr. Sanjay Ganpat Mengane",
  "to": {
    "value": "Transferee",
    "label": "Transferee"
  },
  "Transferee": "Mr. Ashokkumar Thakai Sahu & Mr. Alok Kumar Ashok Sahu ",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "12329 / 2024"
}
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
}
```

```
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2835260.00",
  "selectedBuildUpValue": "340.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66c20ac5da840b1214c8d1aa",
      "name": "externallmg_1723992761471_1723992752038_image_1.jpeg",
      "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992761471_1723992752038_image_1.jpeg",
      "orientation": "portrait"
    }
  ]
}
```

```
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
  {
    "status": false,
    "_id": "66c20ac5da840b1214c8d1aa",
    "name": "externallmg_1723992761471_1723992752038_image_1.jpeg",
    "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992761471_1723992752038_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66c20abe0f117327db71c01c",
    "name": "externallmg_1723992751465_1723992704721_image_2.jpeg",
    "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992751465_1723992704721_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66c20abe0f117327db71c01d",
    "name": "externallmg_1723992752216_1723992704721_image_3.jpeg",
    "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992752216_1723992704721_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66c20abe0f117327db71c021",
    "name": "externallmg_1723992756008_1723992704721_image_7.jpeg",
    "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992756008_1723992704721_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66c20abe0f117327db71c022",
    "name": "externallmg_1723992756968_1723992704721_image_8.jpeg",
    "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992756968_1723992704721_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
```

```
    "_id": "66c20abe0f117327db71c023",
    "name": "externalimg_1723992759235_1723992704721_image_9.jpeg",
    "path": "cases/66bee113da840b1214c79dcd/
externalimg_1723992759235_1723992704721_image_9.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "10883.00",
    "max": "19112.00"
  },
  "builtUpRateRange": {
    "min": "9069.00",
    "max": "15926.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": true,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "PARTIAL",
isExternalReport": false,
isSiteMeasurementAllowed": true,
finalValuationArea": "340.00",
```

```
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66bee113da840b1214c79dcd",
"ownerName": "Mr. Ashokkumar Thakai Sahu & Mr. Alok Kumar Ashok Sahu ",
"ownerPhoneNo": "7506085363",
"appAddress": "Flat no 004 Ground floor Bldg no 43 Malwani Sadguru krupa Co-
operative HSG Soc Ltd Chhatrapati Shivaji Raje Complex Opp Ekta Nagar kandivali
West Mumbai 400067",
"remark": "other Contact no - 7977206718",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "inputs": {
      "documentDate": "13/08/2024",
      "amount": "4100000",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mrs. Shubhangee Sanjay Mengane alias Mrs. Shubhangi Sanjay
Mengane & Mr. Sanjay Ganpat Mengane",
      "to": {
        "value": "Transferee",
        "label": "Transferee"
      },
      "Transferee": "Mr. Ashokkumar Thakai Sahu & Mr. Alok Kumar Ashok Sahu ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "12329 / 2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "id": "704208",
    "path": "cases/66bee113da840b1214c79dcd/document_1723785358755_17237853
55772_PNB_Charkop_pf_Office__Ashok_Kumar_Thakai_Sahu__Alok_kumar_Ashok_
Sahu.pdf",
```

```
"fileName": "document_1723785358755_1723785355772_PNB_Charkop_pf_Office
__Ashok_Kumar_Thakai_Sahu__Alok_kumar_Ashok_Sahu.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "14/09/2003",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "CHE / 145 / BP(WS) / GOVT"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1724154117618_261748.pdf",
"path": "cases/66bee113da840b1214c79dcd/
document_1724154117618_261748.pdf",
"id": "979375",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Aug 20 2024 17:11:57 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1254aa6d152c1801b325",
    "label": "Society NOC Letter "
  },
  "inputs": {
    "documentDate": "11/08/2024",
    "remark": " in the name of Mr. Ashokkumar Thakai Sahu & Mr. Alok Kumar Ashok
Sahu issued by Sadgurukrupa Co-Op. Hsg. Soc. Ltd\n"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1724154329817_226794.pdf",
  "path": "cases/66bee113da840b1214c79dcd/
document_1724154329817_226794.pdf",
  "id": "330338",
  "uploadedBy": "62fe044a48a26047e6552796",
```

```
"createdAt": "Tue Aug 20 2024 17:15:29 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "010607",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "847043",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Aug 16 2024 10:48:11 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Ashokkumar Thakai Sahu & Mr. Alok Kumar Ashok Sahu ",
    "phone": "7506085363",
    "ownershipShare": "",
    "email": "",
    "id": "295989"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "id": "866532",
    "name": "Living Room",
    "length": "9.50",
    "length1": "9",
    "length2": "6",
    "width": "14.92",
    "width1": "14",
    "width2": "11",
    "totalArea": "141.71",
    "images": [],
    "extraAreas": [],
    "finalArea": "141.71"
  },
  {
    "measurementType": {
      "value": "Square_Feet",
```

```
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "7.75",
  "length1": "7",
  "length2": "9",
  "width": "6.92",
  "width1": "6",
  "width2": "11",
  "totalArea": "53.60",
  "images": [],
  "extraAreas": [],
  "finalArea": "53.60"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Bathroom",
  "length": "8.67",
  "length1": "8",
  "length2": "8",
  "width": "2.67",
  "width1": "2",
  "width2": "8",
  "totalArea": "23.11",
  "images": [],
  "extraAreas": [],
  "finalArea": "23.11"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "WC",
  "length": "4.67",
  "length1": "4",
  "length2": "8",
  "width": "4.75",
  "width1": "4",
  "width2": "9",
```

```
"totalArea": "22.17",
"images": [],
"extraAreas": [],
"finalArea": "22.17"
}
],
"otherComposition": [
{
  "toBeAdded": {
    "label": "Carpet",
    "value": "Carpet"
  },
  "name": {
    "label": "Cupboard",
    "value": "Cupboard"
  },
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "0",
  "length": "4.00",
  "length1": "4",
  "length2": "00",
  "width": "1.00",
  "width1": "1",
  "width2": "00",
  "totalArea": "4.00",
  "images": [],
  "extraAreas": [],
  "finalArea": "4",
  "percentageBeforeTotal": "4.00",
  "percentage": "100"
}
],
"externalReport": [],
"documentPerArea": [
{
  "typeOfDocument": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
}
```

```
"id": "168718",
"selectAreaTypeDocument": "Built_Up",
"totalAreaDocument": "340",
"squareMeterArea": "31.59",
"docFinalBuiltUp": "0.00",
"docFinalBuiltUpSquareMeter": "0.00",
"docBuiltupPercentage": "",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "334.17",
"squareMeterArea": "31.05",
"expectedRate": "12867.70",
"percentage": ""
},
"builtUpArea": {
"area": "401.00",
"squareMeterArea": "37.25",
"expectedRate": "10723.19",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66c3144f0f117327db72287e",
"property": "Flat",
"area": "401",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "4300000",
"expectedRate": "12867.70",
"builtUpExpectedRate": "4300000",
```

```
"image": "cases/66bee113da840b1214c79dcd/
indicator_1724060485303_Image.png",
"squareMeter": "37.25",
"id": "339724"
},
{
"carpetArea": {
"area": "225.00",
"squareMeterArea": "20.90",
"expectedRate": "19111.11",
"percentage": ""
},
"builtUpArea": {
"area": "270.00",
"squareMeterArea": "25.08",
"expectedRate": "15925.93",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
},
"printlnReport": true,
"_id": "66c3144f0f117327db72287f",
"property": "Flat",
"area": "270",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "Nobroker.com",
"expectedPrice": "4300000",
"expectedRate": "19111.11",
"builtUpExpectedRate": "4300000",
"image": "cases/66bee113da840b1214c79dcd/
indicator_1724060515250_Image.png",
"squareMeter": "25.08",
"id": "830308"
},
{
"carpetArea": {
"area": "283.33",
"squareMeterArea": "26.32",
```



```
    "expectedRate": "15529.59",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "340.00",
    "squareMeterArea": "31.59",
    "expectedRate": "12941.18",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66c3144f0f117327db722880",
  "property": "Flat",
  "area": "340",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "4400000",
  "expectedRate": "15529.59",
  "builtUpExpectedRate": "4400000",
  "image": "cases/66bee113da840b1214c79dcd/
indicator_1724060562061_Image.png",
  "squareMeter": "31.59",
  "id": "307843"
},
{
  "carpetArea": {
    "area": "340.00",
    "squareMeterArea": "31.59",
    "expectedRate": "10882.35",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "408.00",
    "squareMeterArea": "37.90",
    "expectedRate": "9068.63",
    "percentage": "20"
  },
}
```

```
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "66c3144f0f117327db722881",
"property": "Flat",
"area": "340",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "3700000",
"expectedRate": "10882.35",
"builtUpExpectedRate": "9068.63",
"image": "cases/66bee113da840b1214c79dcd/
indicator_1724060604307_Image.png",
"squareMeter": "31.59",
"id": "805927"
}
],
"externalImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c20ac5da840b1214c8d1a9",
  "name": "externalImg_1723992755433_1723992752038_image_0.jpeg",
  "path": "cases/66bee113da840b1214c79dcd/
externalImg_1723992755433_1723992752038_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66c20ac5da840b1214c8d1aa",
  "name": "externalImg_1723992761471_1723992752038_image_1.jpeg",
  "path": "cases/66bee113da840b1214c79dcd/
externalImg_1723992761471_1723992752038_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66c20ac5da840b1214c8d1ab",
  "name": "externallmg_1723992767007_1723992752038_image_2.jpeg",
  "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992767007_1723992752038_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66c20abe0f117327db71c01a",
  "name": "externallmg_1723992749177_1723992704720_image_0.jpeg",
  "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992749177_1723992704720_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66c20abe0f117327db71c01b",
  "name": "externallmg_1723992750811_1723992704721_image_1.jpeg",
  "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992750811_1723992704721_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66c20abe0f117327db71c01c",
  "name": "externallmg_1723992751465_1723992704721_image_2.jpeg",
  "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992751465_1723992704721_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "66c20abe0f117327db71c01d",
  "name": "externallmg_1723992752216_1723992704721_image_3.jpeg",
  "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992752216_1723992704721_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
```

```
    "_id": "66c20abe0f117327db71c01e",
    "name": "externallmg_1723992753458_1723992704721_image_4.jpeg",
    "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992753458_1723992704721_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66c20abe0f117327db71c01f",
    "name": "externallmg_1723992754623_1723992704721_image_5.jpeg",
    "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992754623_1723992704721_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66c20abe0f117327db71c020",
    "name": "externallmg_1723992755260_1723992704721_image_6.jpeg",
    "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992755260_1723992704721_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66c20abe0f117327db71c021",
    "name": "externallmg_1723992756008_1723992704721_image_7.jpeg",
    "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992756008_1723992704721_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66c20abe0f117327db71c022",
    "name": "externallmg_1723992756968_1723992704721_image_8.jpeg",
    "path": "cases/66bee113da840b1214c79dcd/
externallmg_1723992756968_1723992704721_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66c20abe0f117327db71c023",
```

```
    "name": "externalImg_1723992759235_1723992704721_image_9.jpeg",
    "path": "cases/66bee113da840b1214c79dcd/
externalImg_1723992759235_1723992704721_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66c20abe0f117327db71c024",
    "name": "externalImg_1723992759366_1723992704721_image_10.jpeg",
    "path": "cases/66bee113da840b1214c79dcd/
externalImg_1723992759366_1723992704721_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66c20abe0f117327db71c025",
    "name": "externalImg_1723992764384_1723992704721_image_11.jpeg",
    "path": "cases/66bee113da840b1214c79dcd/
externalImg_1723992764384_1723992704721_image_11.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Calculation (2) - sahu.xlsx",
    "filename": "1724060743281_Calculation_2__sahu.xlsx",
    "path": "cases/66bee113da840b1214c79dcd/
processingDocuments/1724060743281_Calculation_2__sahu.xlsx",
    "size": "16038",
    "createdAt": "Mon Aug 19 2024 15:15:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr1.pdf",
    "filename": "1724060743281_igr1.pdf",
    "path": "cases/66bee113da840b1214c79dcd/
processingDocuments/1724060743281_igr1.pdf",
    "size": "162572",
    "createdAt": "Mon Aug 19 2024 15:15:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr2.pdf",
```

```
    "filename": "1724060743293_igr2.pdf",
    "path": "cases/66bee113da840b1214c79dcd/
processingDocuments/1724060743293_igr2.pdf",
    "size": "147647",
    "createdAt": "Mon Aug 19 2024 15:15:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr3.pdf",
    "filename": "1724060743306_igr3.pdf",
    "path": "cases/66bee113da840b1214c79dcd/
processingDocuments/1724060743306_igr3.pdf",
    "size": "150834",
    "createdAt": "Mon Aug 19 2024 15:15:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "reference report.pdf",
    "filename": "1724060743319_reference_report.pdf",
    "path": "cases/66bee113da840b1214c79dcd/
processingDocuments/1724060743319_reference_report.pdf",
    "size": "1020858",
    "createdAt": "Mon Aug 19 2024 15:15:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "Summary - sahu.xlsx",
    "filename": "1724060743405_Summary__sahu.xlsx",
    "path": "cases/66bee113da840b1214c79dcd/
processingDocuments/1724060743405_Summary__sahu.xlsx",
    "size": "3593139",
    "createdAt": "Mon Aug 19 2024 15:15:44 GMT+0530 (India Standard Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "5fc78e26625ecd20ec1f88e9",
      "role": "MAKER+CHECKER",
      "firstName": "Vaishali",
      "lastName": "Sarmalkar",
      "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
```

```
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "66c085970f117327db719d15",
    "note": "value shared",
    "taskId": "66bee33eda840b1214c7a1e0",
    "createdAt": "2024-08-17T11:12:23.752Z"
  }
],
"createdAt": "2024-08-16T05:18:11.736Z",
"updatedAt": "2024-08-20T12:21:47.508Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 004, Ground Floor, Building No 43, Malwani Sadgurukrupa Co-Op. Hsg. Soc. Ltd., Chhatrapati Shivaji Raje Complex, MHADA, Opp. Ekta Nagar, Charkop Link Road, Village - Malwani , Kandivali (West), Taluka - Borivali, District - Mumbai Suburban , PIN - 400 067, State - Maharashtra, Country - India",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Mr. Ashokkumar Thakai Sahu",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner",
"siteVisitContactNo": "7506085363",
"buildingServicesRate": "2800",
"finalAreaType": "Built Up Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 340.00",
"flatRate": "14000",
"landOtherRate": "11200",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
}
```

```

},
"builtupPercentage": "10",
"carpetTotal": "240.59",
"extendOfSiteRemark": "",
"finalBuiltupArea": "269.05",
"finalCarpetArea": "244.59",
"finalSalableArea": "295.95",
"otherCarpetTotal": "4.00",
"salablePercentage": "10",
"siteMeasurementRemark": "Carpet Area in Sq. Ft. = 240.00\nCupboard Area in Sq.
Ft. = 04.00\n\n",
"toBeAdded": "",
"briefDescOfProperty": "Living Room + Kitchen + Bathroom + WC",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "4.00",
"otherCompositionSaleableTotal": "0.00",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
}
}

```

Name	Length	Width	Total
Composition :			
Living Room	9'6"	14'11"	141.71
Kitchen	7'9"	6'11"	53.60
Bathroom	8'8"	2'8"	23.11
WC	4'8"	4'9"	22.17

Other
Composition :

Cupboard	4'00"	1'00"	4.00
----------	-------	-------	------
