

```
{
  "typeOfReport": {
    "value": "Office",
    "label": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "65a2084302c44c777bb3079c"
    },
    "firstName": "Manish",
    "type": "CREDITOFFICER",
    "_id": "65a2084302c44c777bb3079e",
    "lastName": "Prasad",
    "mobileNo": "",
    "workMobileNo": "9473474007",
    "email": "manish.prasad@isarc.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": ""
  }
}
```

```
"discussWithPerson": "",
"expectedFees": null,
"quotedAmount": ""
},
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "65a0ef2102c44c777bb2191e",
  "type": "BANK",
  "name": "India SME Asset reconstruction Company Limited",
  "displayName": "India SME Asset reconstruction Company Limited",
  "initial": "ISARC"
},
"branch": {
  "_id": "65a2084302c44c777bb3079c",
  "name": "MIDC Andheri ",
  "branchCode": "",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "manish.prasad@isarc.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "India SME Asset Reconstruction Company Limited,\n\nArena House, 2nd
Floor, Gate no.3, Plot No.103,\n\nRoad No.12, MIDC, Andheri (East), Mumbai – 400
093."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "65a0f2e802c44c777bb2203e",
  "zoneName": "Pan India"
},
```

```
"staff": {
  "pickupPerson": null,
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62691c48afd7d55eddecfda3",
    "role": "MAKER",
    "firstName": "Bhavika",
    "email": "bhavikachavan0102@gmail.com",
    "lastName": "chavan",
    "mobileNo": "8390804382",
    "designation": "Site Engineer",
    "shortName": "BH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "ACCOUNTANT",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "ACCOUNTANT",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shym_Photo.jpg"
  },
  "checker": {
    "type": "EMPLOYEE",
```

```

    "_id": "60016f965256c07aec8e6dd6",
    "role": "MAKER + RATE VERFIER + CHEAKER",
    "firstName": "Akhilesh",
    "email": "akhilesh.yadav@vastukala.org",
    "lastName": "Yadav",
    "mobileNo": "9545753921",
    "designation": "Processing Officer",
    "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
    "profilePhoto": "users\\60016f965256c07aec8e6dd6\\
\\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
    "shortName": "AY"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "6084131a13f01f158c6ea1f3",
      "PANNo": "AEAPC7114Q",
      "role": "VALUER",
      "firstName": "Sharadkumar",
      "fatherName": "Baburao",
      "email": "cmd@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9422171100",
      "designation": "CMD",
      "registrationNo": [
        {
          "title": {
            "value": "Wealth_Tax",
            "label": "Wealth Tax"
          },
          "_id": "6084131a13f01f158c6ea1f4",
          "number": "[N]C.C.I.T/I -14/52/2008-09"
        }
      ],
      "shortName": "SBC",
      "workWithDocumentMaker": "",
      "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
    }
  ]

```

```
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "18.997028",
  "longitude": "72.816833"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.816833,
    18.997028
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-17",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-01-16",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false,
  "area": "185",
  "rate": "28000",
  "yearOfConstruction": "1965",
  "compositionOfBuilding": "Ground + 4 Upper Floors"
},
"address": {
  "state": {
```

```
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Worli",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
```

```
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ready Money Terrace",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
```

```
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
}
```



```
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "202",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
```

```
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    }
  }
}
```

```
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
```

```
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
```

```
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
}
```

```
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "CASE",
"paymentStatus": "PENDING",
"invoiceIds": [
  "65d5dee9cf7ad63a0af9b452"
],
"paymentIds": [],
"_id": "66bf1c28fa198fc44a7993df",
"invoices": [],
```

```
"paymentId": [],
"ownerName": "Shri. Bhagwan D. Rathod",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "8779750791",
"contactPersonName": "Ashok Keer",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Shri. Bhagwan D. Rathod",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "703147"
  }
],
"caseReferredBy": "5ff3ead28cda966090eachbbe",
"relationWithOwner": "Bank Staff",
"fullAddress": "Commercial Office No. 202, 2nd Floor, Ready Money Terrace, Village -
Worli, State - Maharashtra, India",
"remark": "",
"documents": [],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "010622",
"createdBy": "6006d4ce5080a310ac1fdfc2",
"caseHistory": [
  {
    "id": "122860",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Wed Jan 17 2024 09:28:50 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
```

```
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c57ce2da840b1214ca2f4c",
    "name":
"externalImg_1724218594203_WhatsApp_Image_20240821_at_092539_1.jpeg",
    "path": "cases/66bf1c28fa198fc44a7993df/
externalImg_1724218594203_WhatsApp_Image_20240821_at_092539_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c57ce2da840b1214ca2f4d",
    "name":
"externalImg_1724218594205_WhatsApp_Image_20240821_at_092539.jpeg",
    "path": "cases/66bf1c28fa198fc44a7993df/
externalImg_1724218594205_WhatsApp_Image_20240821_at_092539.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c57ce2da840b1214ca2f4e",
    "name":
"externalImg_1724218594207_WhatsApp_Image_20240821_at_092540_1.jpeg",
    "path": "cases/66bf1c28fa198fc44a7993df/
externalImg_1724218594207_WhatsApp_Image_20240821_at_092540_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c57ce2da840b1214ca2f4f",
    "name":
"externalImg_1724218594209_WhatsApp_Image_20240821_at_092540_2.jpeg",
    "path": "cases/66bf1c28fa198fc44a7993df/
externalImg_1724218594209_WhatsApp_Image_20240821_at_092540_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "66c57ce2da840b1214ca2f50",
    "name":
"externallmg_1724218594211_WhatsApp_Image_20240821_at_092540.jpeg",
    "path": "cases/66bf1c28fa198fc44a7993df/
externallmg_1724218594211_WhatsApp_Image_20240821_at_092540.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c57ce2da840b1214ca2f51",
    "name":
"externallmg_1724218594213_WhatsApp_Image_20240821_at_092541_1.jpeg",
    "path": "cases/66bf1c28fa198fc44a7993df/
externallmg_1724218594213_WhatsApp_Image_20240821_at_092541_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c57ce2da840b1214ca2f52",
    "name":
"externallmg_1724218594214_WhatsApp_Image_20240821_at_092541_2.jpeg",
    "path": "cases/66bf1c28fa198fc44a7993df/
externallmg_1724218594214_WhatsApp_Image_20240821_at_092541_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c57ce2da840b1214ca2f53",
    "name":
"externallmg_1724218594215_WhatsApp_Image_20240821_at_092541.jpeg",
    "path": "cases/66bf1c28fa198fc44a7993df/
externallmg_1724218594215_WhatsApp_Image_20240821_at_092541.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c57ce2da840b1214ca2f54",
    "name":
"externallmg_1724218594216_WhatsApp_Image_20240821_at_092542_1.jpeg",
    "path": "cases/66bf1c28fa198fc44a7993df/
externallmg_1724218594216_WhatsApp_Image_20240821_at_092542_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c57ce2da840b1214ca2f55",
    "name":
"externallmg_1724218594217_WhatsApp_Image_20240821_at_092542_2.jpeg",
    "path": "cases/66bf1c28fa198fc44a7993df/
externallmg_1724218594217_WhatsApp_Image_20240821_at_092542_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c57ce2da840b1214ca2f56",
    "name":
"externallmg_1724218594218_WhatsApp_Image_20240821_at_092542.jpeg",
    "path": "cases/66bf1c28fa198fc44a7993df/
externallmg_1724218594218_WhatsApp_Image_20240821_at_092542.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c57ce2da840b1214ca2f57",
    "name":
"externallmg_1724218594219_WhatsApp_Image_20240821_at_092543_1.jpeg",
    "path": "cases/66bf1c28fa198fc44a7993df/
externallmg_1724218594219_WhatsApp_Image_20240821_at_092543_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c57ce2da840b1214ca2f58",
    "name":
"externallmg_1724218594220_WhatsApp_Image_20240821_at_092543_2.jpeg",
    "path": "cases/66bf1c28fa198fc44a7993df/
externallmg_1724218594220_WhatsApp_Image_20240821_at_092543_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66c57ce2da840b1214ca2f59",
```

```
"name":
"externalImg_1724218594221_WhatsApp_Image_20240821_at_092543.jpeg",
  "path": "cases/66bf1c28fa198fc44a7993df/
externalImg_1724218594221_WhatsApp_Image_20240821_at_092543.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [
{
  "originalname": "Bhagwan Devji Rathod - Office No. 202 - Checked.doc",
  "filename":
"1708511126373_Bhagwan_Devji_Rathod__Office_No_202__Checked.doc",
  "path": "cases/66bf1c28fa198fc44a7993df/externalDocuments/1708511126373_Bha
gwan_Devji_Rathod__Office_No_202__Checked.doc",
  "size": "6152192",
  "documentType": {
    "value": "649998c6cab24d3d1a2cc577",
    "label": "Draft Word Report"
  },
  "createdAt": "Wed Feb 21 2024 15:55:26 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Bhagwan Devji Rathod - Office No. 202.doc",
  "filename": "1708515005274_Bhagwan_Devji_Rathod__Office_No_202.doc",
  "path": "cases/66bf1c28fa198fc44a7993df/
externalDocuments/1708515005274_Bhagwan_Devji_Rathod__Office_No_202.doc",
  "size": "6151680",
  "documentType": {
    "value": "64058cdff10de22571d01b37",
    "label": "Final Word Report"
  },
  "createdAt": "Wed Feb 21 2024 17:00:05 GMT+0530 (India Standard Time)",
  "uploadedBy": "60016f965256c07aec8e6dd6"
},
{
  "originalname": "Valuation_report_Bhagwan_Devji_Rathod__Office_No_202.pdf",
  "filename":
"1708670994018_Valuation_report_Bhagwan_Devji_Rathod__Office_No_202.pdf",
  "path": "cases/66bf1c28fa198fc44a7993df/externalDocuments/1708670994018_Val
uation_report_Bhagwan_Devji_Rathod__Office_No_202.pdf",
  "size": "724366",
  "documentType": {
    "value": "640ece6024088f0f94ee4ea8",
    "label": "Final PDF Report"
  },
}
```

```
"createdAt": "Fri Feb 23 2024 12:19:54 GMT+0530 (India Standard Time)",
"uploadedBy": "60f9589345132d6a6bddcc3a"
},
{
  "path": "../CDN/cases/66bf1c28fa198fc44a7993df/
externalDocuments/1708687385401_200027.pdf",
  "filename": "1708687385401_200027.pdf",
  "documentType": {
    "organization": {
      "status": true,
      "isdelete": false,
      "_id": "5f2bdee67813470eb443deb4",
      "name": "Vastukala Consultants India Pvt. Ltd.",
      "gstNo": "18AABCT3518Q1ZZ",
      "panNo": "ABCDE1234A",
      "email": "vastukalamumbai@vastukala.com",
      "phone": "9819670183",
      "address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E),
Mumbai - 400 093",
      "shortName": "VCIPL",
      "type": "ORGANIZATION",
      "city": "Mumbai",
      "ownerEmail": "umang@vastukala.org",
      "ownerName": "Umang Patel"
    },
    "_id": "60ae124daa6d152c1801b307",
    "document": {
      "documentType": "Office Copy",
      "documentDate": true,
      "to": false,
      "from": false,
      "amount": false,
      "nameOfApprovingAuthority": false,
      "number": false,
      "remarks": true,
      "caseStatus": {
        "value": "DELIVERED",
        "label": "Delivered"
      }
    }
  },
  "createdAt": "2021-05-26T09:18:05.809Z",
  "updatedAt": "2023-06-20T10:17:50.158Z",
  "__v": 0,
  "label": "Office Copy",
  "value": "60ae124daa6d152c1801b307",
  "Name": "Office Copy",
```

```
    "Value": "60ae124daa6d152c1801b307",
    "caseStatus": {
      "value": "DELIVERED",
      "label": "Delivered"
    }
  },
  "createdAt": "Fri Feb 23 2024 16:53:05 GMT+0530 (India Standard Time)",
  "uploadedBy": "60af6ae22ffdf65bcd65861d"
},
"processingDocuments": [
  {
    "originalname": "IGR-01.pdf",
    "filename": "1708511139275_IGR01.pdf",
    "path": "cases/66bf1c28fa198fc44a7993df/
processingDocuments/1708511139275_IGR01.pdf",
    "size": "145910",
    "createdAt": "Wed Feb 21 2024 15:55:39 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-02.pdf",
    "filename": "1708511139280_IGR02.pdf",
    "path": "cases/66bf1c28fa198fc44a7993df/
processingDocuments/1708511139280_IGR02.pdf",
    "size": "154085",
    "createdAt": "Wed Feb 21 2024 15:55:39 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-03.pdf",
    "filename": "1708511139284_IGR03.pdf",
    "path": "cases/66bf1c28fa198fc44a7993df/
processingDocuments/1708511139284_IGR03.pdf",
    "size": "153650",
    "createdAt": "Wed Feb 21 2024 15:55:39 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "IGR-04.pdf",
    "filename": "1708511139288_IGR04.pdf",
    "path": "cases/66bf1c28fa198fc44a7993df/
processingDocuments/1708511139288_IGR04.pdf",
    "size": "156200",
    "createdAt": "Wed Feb 21 2024 15:55:39 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  }
]
```



```
},
{
  "originalname": "Summary New=Office.xlsx",
  "filename": "1708511139291_Summary_NewOffice.xlsx",
  "path": "cases/66bf1c28fa198fc44a7993df/
processingDocuments/1708511139291_Summary_NewOffice.xlsx",
  "size": "3478938",
  "createdAt": "Wed Feb 21 2024 15:55:39 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "WhatsApp Image 2024-01-29 at 15.29.28 (1).jpeg",
  "filename": "1708511139373_WhatsApp_Image_20240129_at_152928_1.jpeg",
  "path": "cases/66bf1c28fa198fc44a7993df/processingDocuments/1708511139373_
WhatsApp_Image_20240129_at_152928_1.jpeg",
  "size": "135566",
  "createdAt": "Wed Feb 21 2024 15:55:39 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "WhatsApp Image 2024-01-29 at 15.29.28.jpeg",
  "filename": "1708511139378_WhatsApp_Image_20240129_at_152928.jpeg",
  "path": "cases/66bf1c28fa198fc44a7993df/
processingDocuments/1708511139378_WhatsApp_Image_20240129_at_152928.jpeg",
  "size": "120630",
  "createdAt": "Wed Feb 21 2024 15:55:39 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "AGR-OFFICE NO. 2.pdf",
  "filename": "1708511145762_AGROFFICE_NO_2.pdf",
  "path": "cases/66bf1c28fa198fc44a7993df/
processingDocuments/1708511145762_AGROFFICE_NO_2.pdf",
  "size": "2082458",
  "createdAt": "Wed Feb 21 2024 15:55:45 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "WhatsApp Image 2024-01-15 at 16.39.09.jpeg",
  "filename": "1708511145800_WhatsApp_Image_20240115_at_163909.jpeg",
  "path": "cases/66bf1c28fa198fc44a7993df/
processingDocuments/1708511145800_WhatsApp_Image_20240115_at_163909.jpeg",
  "size": "135500",
  "createdAt": "Wed Feb 21 2024 15:55:45 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
}
```

```
{
  "originalname": "WhatsApp Image 2024-01-29 at 15.29.28.jpeg",
  "filename": "1708511145804_WhatsApp_Image_20240129_at_152928.jpeg",
  "path": "cases/66bf1c28fa198fc44a7993df/
processingDocuments/1708511145804_WhatsApp_Image_20240129_at_152928.jpeg",
  "size": "120630",
  "createdAt": "Wed Feb 21 2024 15:55:45 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
},
{
  "originalname": "Annexure.xlsx",
  "filename": "1708511155813_Annexure.xlsx",
  "path": "cases/66bf1c28fa198fc44a7993df/
processingDocuments/1708511155813_Annexure.xlsx",
  "size": "11893",
  "createdAt": "Wed Feb 21 2024 15:55:55 GMT+0530 (India Standard Time)",
  "uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60eeaeddf3dd69653a581316",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shyam",
      "lastName": "Kajvilkar",
      "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "65c0c3da6635d840ef5e070e",
    "note": "Hold by bank",
    "taskId": "65a7507a9413402ebab6f2ad",
    "createdAt": "2024-02-05T11:17:46.504Z"
  }
],
"createdAt": "2024-08-16T09:30:16.166Z",
"updatedAt": "2024-08-21T05:36:34.254Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "6006d4ce5080a310ac1fd2",
"siteVisitDate": "2024-01-16",
```

"reportGeneratedDate": "Wed Feb 21 2024 16:59:47 GMT+0530 (India Standard Time)",

"invoiceId": null

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
-------------	---------------	--------------	--------------

---

Composition :

---

Other

Composition :

---