

```
{
  "typeOfReport": {
    "value": "Row_House",
    "label": "Row House"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bae3"
    },
    "firstName": "Amit",
    "type": "CREDITOFFICER",
    "_id": "64e45230ae896715ef8152d1",
    "lastName": "Kale",
    "mobileNo": "",
    "workMobileNo": "8286849874",
    "email": "amit@cosmosbank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1820",
  "type": "BANK",
  "name": "Cosmos Bank",
  "displayName": "Cosmos Bank",
  "initial": "CB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bae3",
  "branchCode": "000024",
  "type": "BRANCH",
  "name": "Zaveri Bazar Branch",
  "email": "zaveri@cosmosbank.in",
  "mobileNo": "02222400297",
  "alternateMobileNo": "",
  "address": "19/21, Cosmos Bank Bldg, Vithalwadi Zaveri Bazar, Mumbai-400002",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f919bff3dd69653a5926b8",
  "zoneName": "Mumbai & Aurangabad Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "62727444afd7d55eddee092c",
"role": "PICKUPPERSON",
"firstName": "Shantilal",
"email": "shantilal@vastukala.org",
"lastName": "Patel",
"mobileNo": "9969039853",
"shortName": "SHP",
"workWithDocumentMaker": "",
"profilePhoto": "users/62727444afd7d55eddee092c/
profilePhoto_1668057663775_WhatsApp_Image_20221110_at_104853_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.010043355572456",
  "longitude": "73.11480039295002"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    73.11480039295002,
    19.010043355572456
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "20/09/2024 11:44 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "New Panvel",
    "label": true
  },
}
```

```
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Navi Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
```

```
"value": "2",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Mayur CHSL",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "6",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
```

```
"status": false,
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "A-3",
```



```
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
```

```
"name": "Postal Code",
"key": "postalCode",
"value": "",
"label": false
},
"suburb": {
"status": true,
"name": "Suburb",
"key": "suburb",
"value": "New Pnavel",
"label": false
}
},
"general": {
"unitBoundaries": {
"isDisplay": false
},
"whichTheLocalityIsServed": {
"buses": {
"title": "Buses"
},
"taxies": {
"title": "Taxies"
},
"auto": {
"title": "Auto"
},
"privateCars": {
"title": "Private Cars"
}
}
},
"landAndBuildingDetails": {
"actualBuildingBoundaries": [],
"documentsBuildingBoundaries": []
},
"igrFinalRate": {
"floorRatePercentage": "0.00"
},
"outgoingDetail": {
"monthlyRent": ""
},
"siteMeasurement": {
"isSiteVisitAllowed": true
},
"finalPlinthArea": {
```

```
"area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
```

```
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
```



```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66c6d78dda840b1214caf2e3",
"ownerName": "Vilas J Katkar And Eknath D Chirke",
"ownerPhoneNo": "9987098609",
"appAddress": "A -3 sector no No 6\nMayur co op society Ltd \npanvel \npin 410206",
"remark": "Approx value \n\nMaximus ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66c6d78dda840b1214caf2e3/
document_1724307132919_1724307129662_ACE_Scanner_2024_08_081.pdf",
    "fileName":
"document_1724307132919_1724307129662_ACE_Scanner_2024_08_081.pdf",
    "id": "576195",
    "uploadedBy": "62727444afd7d55eddee092c",
    "createdAt": "Thu Aug 22 2024 11:45:41 GMT+0530 (India Standard Time)"
  }
],
"caseNumber": "010741",
"createdBy": "62727444afd7d55eddee092c",
```

```
"caseHistory": [
  {
    "id": "528946",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Aug 22 2024 11:45:41 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Vilas J Katkar And Eknath D Chirke",
    "phone": "9987098609",
    "ownershipShare": "",
    "email": "",
    "id": "426854"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee40e4ada7094de493f1c0",
    "name":
"externalImg_1726890212617_WhatsApp_Image_20240921_at_081427.jpeg",
    "path": "cases/66c6d78dda840b1214caf2e3/
externalImg_1726890212617_WhatsApp_Image_20240921_at_081427.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee40e4ada7094de493f1c1",
    "name":
"externalImg_1726890212617_WhatsApp_Image_20240921_at_081440.jpeg",
    "path": "cases/66c6d78dda840b1214caf2e3/
externalImg_1726890212617_WhatsApp_Image_20240921_at_081440.jpeg",
    "orientation": "portrait"
  },
],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40e4ada7094de493f1c2",
  "name":
"externallmg_1726890212620_WhatsApp_Image_20240921_at_081443_1.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212620_WhatsApp_Image_20240921_at_081443_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40e4ada7094de493f1c3",
  "name":
"externallmg_1726890212621_WhatsApp_Image_20240921_at_081443.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212621_WhatsApp_Image_20240921_at_081443.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40e4ada7094de493f1c4",
  "name":
"externallmg_1726890212622_WhatsApp_Image_20240921_at_081444_1.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212622_WhatsApp_Image_20240921_at_081444_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40e4ada7094de493f1c5",
  "name":
"externallmg_1726890212625_WhatsApp_Image_20240921_at_081444_2.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212625_WhatsApp_Image_20240921_at_081444_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40e4ada7094de493f1c6",
  "name":
"externallmg_1726890212626_WhatsApp_Image_20240921_at_081444.jpeg",
```

```
    "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212626_WhatsApp_Image_20240921_at_081444.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee40e4ada7094de493f1c7",
    "name":
"externallmg_1726890212630_WhatsApp_Image_20240921_at_081445_1.jpeg",
    "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212630_WhatsApp_Image_20240921_at_081445_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee40e4ada7094de493f1c8",
    "name":
"externallmg_1726890212630_WhatsApp_Image_20240921_at_081445.jpeg",
    "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212630_WhatsApp_Image_20240921_at_081445.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee40e4ada7094de493f1c9",
    "name":
"externallmg_1726890212631_WhatsApp_Image_20240921_at_081446_1.jpeg",
    "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212631_WhatsApp_Image_20240921_at_081446_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee40e4ada7094de493f1ca",
    "name":
"externallmg_1726890212631_WhatsApp_Image_20240921_at_081446_2.jpeg",
    "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212631_WhatsApp_Image_20240921_at_081446_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66ee40e4ada7094de493f1cb",
  "name":
"externallmg_1726890212632_WhatsApp_Image_20240921_at_081446.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212632_WhatsApp_Image_20240921_at_081446.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40e4ada7094de493f1cc",
  "name":
"externallmg_1726890212632_WhatsApp_Image_20240921_at_081447_1.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212632_WhatsApp_Image_20240921_at_081447_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40e4ada7094de493f1cd",
  "name":
"externallmg_1726890212633_WhatsApp_Image_20240921_at_081447_2.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212633_WhatsApp_Image_20240921_at_081447_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40e4ada7094de493f1ce",
  "name":
"externallmg_1726890212633_WhatsApp_Image_20240921_at_081447.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212633_WhatsApp_Image_20240921_at_081447.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40e4ada7094de493f1cf",
  "name":
"externallmg_1726890212634_WhatsApp_Image_20240921_at_081448_1.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212634_WhatsApp_Image_20240921_at_081448_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee40e4ada7094de493f1d0",
    "name":
"externallmg_1726890212634_WhatsApp_Image_20240921_at_081448_2.jpeg",
    "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212634_WhatsApp_Image_20240921_at_081448_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee40e4ada7094de493f1d1",
    "name":
"externallmg_1726890212635_WhatsApp_Image_20240921_at_081448.jpeg",
    "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212635_WhatsApp_Image_20240921_at_081448.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee40e4ada7094de493f1d2",
    "name":
"externallmg_1726890212635_WhatsApp_Image_20240921_at_081449_1.jpeg",
    "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212635_WhatsApp_Image_20240921_at_081449_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee40e4ada7094de493f1d3",
    "name":
"externallmg_1726890212636_WhatsApp_Image_20240921_at_081449_2.jpeg",
    "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890212636_WhatsApp_Image_20240921_at_081449_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee40f6ada7094de493f226",
```

```
    "name":
"externallmg_1726890230441_WhatsApp_Image_20240921_at_081449.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890230441_WhatsApp_Image_20240921_at_081449.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40f6ada7094de493f227",
  "name":
"externallmg_1726890230441_WhatsApp_Image_20240921_at_081450_1.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890230441_WhatsApp_Image_20240921_at_081450_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40f6ada7094de493f228",
  "name":
"externallmg_1726890230441_WhatsApp_Image_20240921_at_081450.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890230441_WhatsApp_Image_20240921_at_081450.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40f6ada7094de493f229",
  "name":
"externallmg_1726890230442_WhatsApp_Image_20240921_at_081451_1.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890230442_WhatsApp_Image_20240921_at_081451_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40f6ada7094de493f22a",
  "name":
"externallmg_1726890230442_WhatsApp_Image_20240921_at_081451.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890230442_WhatsApp_Image_20240921_at_081451.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40f6ada7094de493f22b",
  "name":
"externallmg_1726890230442_WhatsApp_Image_20240921_at_081452.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890230442_WhatsApp_Image_20240921_at_081452.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40f6ada7094de493f22c",
  "name":
"externallmg_1726890230443_WhatsApp_Image_20240921_at_081453.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890230443_WhatsApp_Image_20240921_at_081453.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40f6ada7094de493f22d",
  "name":
"externallmg_1726890230443_WhatsApp_Image_20240921_at_081454.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890230443_WhatsApp_Image_20240921_at_081454.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40f6ada7094de493f22e",
  "name":
"externallmg_1726890230444_WhatsApp_Image_20240921_at_081455_1.jpeg",
  "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890230444_WhatsApp_Image_20240921_at_081455_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ee40f6ada7094de493f22f",
  "name":
"externallmg_1726890230445_WhatsApp_Image_20240921_at_081455_2.jpeg",
```



```
    "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890230445_WhatsApp_Image_20240921_at_081455_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee40f6ada7094de493f230",
    "name":
"externallmg_1726890230446_WhatsApp_Image_20240921_at_081455.jpeg",
    "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890230446_WhatsApp_Image_20240921_at_081455.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee40f6ada7094de493f231",
    "name":
"externallmg_1726890230446_WhatsApp_Image_20240921_at_081456_1.jpeg",
    "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890230446_WhatsApp_Image_20240921_at_081456_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee40f6ada7094de493f232",
    "name":
"externallmg_1726890230447_WhatsApp_Image_20240921_at_081456_2.jpeg",
    "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890230447_WhatsApp_Image_20240921_at_081456_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ee40f6ada7094de493f233",
    "name":
"externallmg_1726890230447_WhatsApp_Image_20240921_at_081456.jpeg",
    "path": "cases/66c6d78dda840b1214caf2e3/
externallmg_1726890230447_WhatsApp_Image_20240921_at_081456.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```

```

"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-08-22T06:15:41.576Z",
"updatedAt": "2024-09-21T03:43:50.481Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. A-3, Ground Floor, Mayur CHSL, Plot No. 2, Sector
6, Village - New Panvel, New Pnavel, Navi Mumbai",
"updatedBy": "6006d4ce5080a310ac1fdcf2",
"addressForMap": "",
"caseReferredBy": "62727444afd7d55eddee092c",
"contactPersonName": "Vilas J Katkar And Eknath D Chirke",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9987098609"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			