

```
{
  "typeOfReport": {
    "label": "Gala",
    "value": "Gala"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64cb4e070faf29427aca4671"
    },
    "firstName": "Neha",
    "type": "CREDITOFFICER",
    "_id": "65d6e4d5cf7ad63a0afa958a",
    "lastName": "Khankal",
    "mobileNo": "",
    "workMobileNo": "7709307753",
    "email": "mcc813400@gmail.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4528700",
    "discussWithPerson": "Neha",
    "expectedFees": 2264.35,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "64cb4e070faf29427aca4671",
  "name": "MCC MW 2 Goregaon\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "mcc8134@pnb.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Rajnigandha Shopping Centre, 1st Floor, Krishna Vatika Marg, Opp.
Gokuldham Temple, Goregaon (E), Mumbai 400063"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62720a36afd7d55eddedc4a7",
    "role": "SITEENGINEER",
    "firstName": "Anwar",
    "email": "anwar21786@gmail.com",
    "lastName": "Shaikh",
    "mobileNo": "8552884500",
    "designation": "",
    "shortName": "AS",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62720a36afd7d55eddedc4a7/
profilePhoto_1668059819446_anwar_2.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
    "lastName": "Sarmalkar",
    "mobileNo": "9004437379",
    "shortName": "VS",
    "workWithDocumentMaker": "1",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
    "designation": ""
  },
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
```

```
    "label": "Wealth Tax"
  }
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.407953261632525",
  "longitude": "72.87291889801584"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87291889801584,
    19.407953261632525
  ]
}
},
"siteVisit": {
```

```
"siteVisitStatus": false,
"schedule": [
  {
    "dateTime": "30/08/2024 10:02 am"
  },
  {
    "dateTime": "30/08/2024 12:00 am"
  },
  {
    "dateTime": "30/08/2024 12:00 am"
  }
],
"visitedDate": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Sativali",
    "label": true
  },
  "floorNo": {
    "status": true,
```

```
"name": "Floor No",
"key": "floorNo",
"value": "Basement",
"label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "1",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vasai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
}
```

```
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Saatvik",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Tungarphata",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Nidhi Paradise",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
```

```
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "201",
  "label": false
},
}
```



```
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
```

```
"value": "401208",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Vasai East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
}
```

```
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  }
}
```

```
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
```



```
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66cc6f970f117327db76bc99",
"ownerName": "Manoj Budhia ",
"ownerPhoneNo": "9309918892",
"appAddress": "Gala no 202 Bldg no 1 Satvik Square industrial Park Sativali Vasai
East Plaghar 401208",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66cc6f970f117327db76bc99/
document_1724673631731_1724673630475_Gala_202_agreement_copy.pdf",
    "fileName":
"document_1724673631731_1724673630475_Gala_202_agreement_copy.pdf",
    "id": "699077",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Mon Aug 26 2024 17:35:43 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Maintenance Bill",
      "value": "60ae125eaa6d152c1801b353"
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66cc6f970f117327db76bc99/
document_1724673686401_1724673680949_202_Maintenance_bill.pdf",
    "fileName":
"document_1724673686401_1724673680949_202_Maintenance_bill.pdf",
    "id": "310233",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Mon Aug 26 2024 17:35:43 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Electricity Bill",
      "value": "60ae1249aa6d152c1801b2f3"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66cc6f970f117327db76bc99/
document_1724673704912_1724673702779_Electricity_Bill_Gala_No202.pdf",
    "fileName":
"document_1724673704912_1724673702779_Electricity_Bill_Gala_No202.pdf",
    "id": "112262",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Mon Aug 26 2024 17:35:43 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Property Tax",
      "value": "60ae124daa6d152c1801b306"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/66cc6f970f117327db76bc99/
document_1724673734206_1724673731793_202_Property_tax.pdf",
    "fileName": "document_1724673734206_1724673731793_202_Property_tax.pdf",
    "id": "361812",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Mon Aug 26 2024 17:35:43 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Occupancy Certificate",
      "value": "60ae124baa6d152c1801b2fd"
    },
    "isHardCopy": false,
```

```
"displayStatus": false,
"path": "cases/66cc6f970f117327db76bc99/
document_1724673854732_1724673853001_Occupation_certificate.pdf",
"fileName":
"document_1724673854732_1724673853001_Occupation_certificate.pdf",
"id": "926952",
"uploadedBy": "60af6ae22ffdf65bcd65861d",
"createdAt": "Mon Aug 26 2024 17:35:43 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"label": "Occupancy Certificate",
"value": "60ae124baa6d152c1801b2fd"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/66cc6f970f117327db76bc99/
document_1724673886928_1724673885226_OC_pege_2.pdf",
"fileName": "document_1724673886928_1724673885226_OC_pege_2.pdf",
"id": "904087",
"uploadedBy": "60af6ae22ffdf65bcd65861d",
"createdAt": "Mon Aug 26 2024 17:35:43 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"label": "Occupancy Certificate",
"value": "60ae124baa6d152c1801b2fd"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/66cc6f970f117327db76bc99/
document_1724673909231_1724673907481_OC_pege_3.pdf",
"fileName": "document_1724673909231_1724673907481_OC_pege_3.pdf",
"id": "136806",
"uploadedBy": "60af6ae22ffdf65bcd65861d",
"createdAt": "Mon Aug 26 2024 17:35:43 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"label": "Occupancy Certificate",
"value": "60ae124baa6d152c1801b2fd"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/66cc6f970f117327db76bc99/
document_1724673923965_1724673922230_Occupation.pdf",
```

```
"fileName": "document_1724673923965_1724673922230_Occupation.pdf",
"id": "506749",
"uploadedBy": "60af6ae22ffdf65bcd65861d",
"createdAt": "Mon Aug 26 2024 17:35:43 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Occupancy Certificate",
    "value": "60ae124baa6d152c1801b2fd"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66cc6f970f117327db76bc99/
document_1724673937886_1724673936523_OC_page_2.pdf",
"fileName": "document_1724673937886_1724673936523_OC_page_2.pdf",
"id": "697739",
"uploadedBy": "60af6ae22ffdf65bcd65861d",
"createdAt": "Mon Aug 26 2024 17:35:43 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Approved Building Plan",
    "value": "60ae1277aa6d152c1801b3cc"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66cc6f970f117327db76bc99/document_1724950037595_172495002
3634_OC_Blue_Print_B1_NI_approved_plan.pdf",
"fileName": "document_1724950037595_1724950023634_OC_Blue_Print_B1_NI_a
pproved_plan.pdf",
"id": "940418",
"uploadedBy": "60af6ae22ffdf65bcd65861d",
"createdAt": "Thu Aug 29 2024 22:17:41 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "010838",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "768394",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Aug 26 2024 17:35:43 GMT+0530 (India Standard Time)"
  }
],
"owners": [
```

```
{
  "name": "Manoj Budhia ",
  "phone": "9309918892",
  "ownershipShare": "",
  "email": "",
  "id": "770802"
},
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2909a0f117327db79d370",
    "name":
"externallmg_1725075610038_WhatsApp_Image_20240830_at_152314.jpeg",
    "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075610038_WhatsApp_Image_20240830_at_152314.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2909a0f117327db79d371",
    "name":
"externallmg_1725075610039_WhatsApp_Image_20240830_at_152315_1.jpeg",
    "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075610039_WhatsApp_Image_20240830_at_152315_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2909a0f117327db79d372",
    "name":
"externallmg_1725075610040_WhatsApp_Image_20240830_at_152315.jpeg",
    "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075610040_WhatsApp_Image_20240830_at_152315.jpeg",
    "orientation": "portrait"
  }
]
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66d2909a0f117327db79d373",
      "name":
"externallmg_1725075610042_WhatsApp_Image_20240830_at_152316_1.jpeg",
      "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075610042_WhatsApp_Image_20240830_at_152316_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66d2909a0f117327db79d374",
      "name":
"externallmg_1725075610043_WhatsApp_Image_20240830_at_152316.jpeg",
      "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075610043_WhatsApp_Image_20240830_at_152316.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66d2909a0f117327db79d375",
      "name":
"externallmg_1725075610044_WhatsApp_Image_20240830_at_152317_1.jpeg",
      "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075610044_WhatsApp_Image_20240830_at_152317_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66d2909a0f117327db79d376",
      "name":
"externallmg_1725075610044_WhatsApp_Image_20240830_at_152317_2.jpeg",
      "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075610044_WhatsApp_Image_20240830_at_152317_2.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66d2909a0f117327db79d377",
      "name":
"externallmg_1725075610047_WhatsApp_Image_20240830_at_152317.jpeg",
```

```
    "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075610047_WhatsApp_Image_20240830_at_152317.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2909a0f117327db79d378",
    "name":
"externallmg_1725075610049_WhatsApp_Image_20240830_at_152318_1.jpeg",
    "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075610049_WhatsApp_Image_20240830_at_152318_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2909a0f117327db79d379",
    "name":
"externallmg_1725075610050_WhatsApp_Image_20240830_at_152318_2.jpeg",
    "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075610050_WhatsApp_Image_20240830_at_152318_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2909a0f117327db79d37a",
    "name":
"externallmg_1725075610051_WhatsApp_Image_20240830_at_152318.jpeg",
    "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075610051_WhatsApp_Image_20240830_at_152318.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d290b20f117327db79d3ae",
    "name":
"externallmg_1725075634762_WhatsApp_Image_20240830_at_151146_1.jpeg",
    "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075634762_WhatsApp_Image_20240830_at_151146_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66d290b20f117327db79d3af",
  "name":
"externallmg_1725075634764_WhatsApp_Image_20240830_at_151146_2.jpeg",
  "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075634764_WhatsApp_Image_20240830_at_151146_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d290b20f117327db79d3b0",
  "name":
"externallmg_1725075634765_WhatsApp_Image_20240830_at_151146.jpeg",
  "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075634765_WhatsApp_Image_20240830_at_151146.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d290b20f117327db79d3b1",
  "name":
"externallmg_1725075634766_WhatsApp_Image_20240830_at_151147_1.jpeg",
  "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075634766_WhatsApp_Image_20240830_at_151147_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d290b20f117327db79d3b2",
  "name":
"externallmg_1725075634767_WhatsApp_Image_20240830_at_151147.jpeg",
  "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075634767_WhatsApp_Image_20240830_at_151147.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d290b20f117327db79d3b3",
  "name":
"externallmg_1725075634768_WhatsApp_Image_20240830_at_151148.jpeg",
  "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075634768_WhatsApp_Image_20240830_at_151148.jpeg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d290b20f117327db79d3b4",
    "name":
"externallmg_1725075634770_WhatsApp_Image_20240830_at_151149.jpeg",
    "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075634770_WhatsApp_Image_20240830_at_151149.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d290b20f117327db79d3b5",
    "name":
"externallmg_1725075634771_WhatsApp_Image_20240830_at_151151_1.jpeg",
    "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075634771_WhatsApp_Image_20240830_at_151151_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d290b20f117327db79d3b6",
    "name":
"externallmg_1725075634773_WhatsApp_Image_20240830_at_151151_2.jpeg",
    "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075634773_WhatsApp_Image_20240830_at_151151_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d290b20f117327db79d3b7",
    "name":
"externallmg_1725075634774_WhatsApp_Image_20240830_at_151151.jpeg",
    "path": "cases/66cc6f970f117327db76bc99/
externallmg_1725075634774_WhatsApp_Image_20240830_at_151151.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d290b20f117327db79d3b8",
```

```
    "name":
"externalImg_1725075634775_WhatsApp_Image_20240830_at_151152_1.jpeg",
  "path": "cases/66cc6f970f117327db76bc99/
externalImg_1725075634775_WhatsApp_Image_20240830_at_151152_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d290b20f117327db79d3b9",
  "name":
"externalImg_1725075634776_WhatsApp_Image_20240830_at_151152.jpeg",
  "path": "cases/66cc6f970f117327db76bc99/
externalImg_1725075634776_WhatsApp_Image_20240830_at_151152.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d290b20f117327db79d3ba",
  "name":
"externalImg_1725075634778_WhatsApp_Image_20240830_at_151153_1.jpeg",
  "path": "cases/66cc6f970f117327db76bc99/
externalImg_1725075634778_WhatsApp_Image_20240830_at_151153_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d290b20f117327db79d3bb",
  "name":
"externalImg_1725075634779_WhatsApp_Image_20240830_at_151153.jpeg",
  "path": "cases/66cc6f970f117327db76bc99/
externalImg_1725075634779_WhatsApp_Image_20240830_at_151153.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-08-26T12:05:43.639Z",
"updatedAt": "2024-08-31T03:40:34.816Z",
"__v": 0,
"uniqueNo": ""
```

```

"updatedBy": "6006d4ce5080a310ac1fdcf2",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Industrial Gala No. 201, Basement Floor, Building No 1, Saatvik,
Tungarphata, Near Nidhi Paradise, Village - Sativali, Vasai East, Vasai, 401208, State -
Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Manoj Budhia ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9309918892"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			