

```
{
  "typeOfReport": {
    "value": "Bungalow",
    "label": "Bungalow"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "masterTypeOfPurpose": {
    "value": "SARFAESI_Securitisation_And_Reconstruction_Of_Financial_Assets_And_Enforcement_Of_Security_Interest_Act,_2002",
    "label": "SARFAESI Securitisation And Reconstruction Of Financial Assets And Enforcement Of Security Interest Act, 2002"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "646dc536b05e530fb6c47b3b"
    },
    "firstName": "Sagar",
    "type": "CREDITOFFICER",
    "_id": "64d2280087258203eaae5058",
    "lastName": "Sir",
    "mobileNo": "",
    "workMobileNo": "8999588878",
    "email": "rlf.nasik@bankofbaroda.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": ""
  }
}
```

```
"discussWithPerson": "",
"expectedFees": null,
"quotedAmount": "2950"
},
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusha Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "646dc536b05e530fb6c47b3b",
  "name": "RO Nashik\t",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rlf.nasik@bankofbaroda.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "BSNL Building, Data Mandir Road, Nashik Road, Nashik 422101\n"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda060ce84bf289baace4c",
  "zoneName": "Nashik Zone"
},
```

```
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "647ed1960ab64c23c9fcf71d",
    "role": "FRONTDESK",
    "firstName": "Rishidatt",
    "email": "rishiyadav44444@gamil.com",
    "lastName": "Yadav",
    "mobileNo": "9404341081",
    "shortName": "RV",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "636a29b64d42487767af43ea",
    "role": "NASHIK (LEAD + VISIT + RATE)",
    "firstName": "Sachin",
    "email": "sachinraundal9021@gmail.com",
    "lastName": "Raundal",
    "mobileNo": "9021337843",
    "designation": "Site Engg",
    "shortName": "Sachin",
    "workWithDocumentMaker": "62724142afd7d55eddede405",
    "profilePhoto": "users/636a29b64d42487767af43ea/
profilePhoto_1688819202426_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "647ed1960ab64c23c9fcf71d",
    "role": "FRONTDESK",
    "firstName": "Rishidatt",
    "email": "rishiyadav44444@gamil.com",
    "lastName": "Yadav",
    "mobileNo": "9404341081",
    "designation": "",
    "shortName": "RV",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/647ed1960ab64c23c9fcf71d/
profilePhoto_1717659680447_WhatsApp_Image_20240601_at_74841_PM.jpeg"
  },
  "maker": {
    "type": "EMPLOYEE",
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
```

```
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
        "title": {
          "value": "Wealth_Tax",
```

```
    "label": "Wealth Tax"
  },
  "_id": "6084131a13f01f158c6ea1f4",
  "number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.981306",
  "longitude": "73.833917"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "31/08/2024 12:00 am"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
```

```
"state": {
  "status": true,
  "name": "State",
  "key": "state",
  "value": "Maharashtra",
  "label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Dasak",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
```

```
"value": "Nashik",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "2+3/ C",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Samarth Villa Row Bungalows ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
```

```
"status": false,
"name": "Street 2",
"key": "street2",
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Near Shree Hari Lawns & Mangal Karyalay, Shivram Nagar, Adhav Mala,
Jail Road",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "67/2",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
```



```
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "03",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
```

```
"status": false,
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422 101",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    }
  }
},
```

```
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
```

```
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
```

```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
```

```
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66d2f1b6807b2347dd58c011",
"ownerName": "Prabhu Maruti Zakane ",
```

```
"ownerPhoneNo": "9766669917",
"fullAddress": "Residential Bungalow No. 03, Ground Floor, Samarth Villa Row
Bungalows , Near Shree Hari Lawns & Mangal Karyalay, Shivram Nagar, Adhav Mala,
Jail Road, Plot No. 2+3/ C, New/Current Survey No. 67/2, Village - Dasak, Taluka -
Nashik, District - Nashik, Nashik, 422 101, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1725100393583_Prabhu_zhakne.pdf",
    "path": "cases/66d2f1b6807b2347dd58c011/
document_1725100393583_Prabhu_zhakne.pdf",
    "id": "710110",
    "uploadedBy": "647ed1960ab64c23c9fcf71d",
    "createdAt": "Sat Aug 31 2024 16:04:30 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1725100411792_Prabhu_Zhakne_building_plan_1.pdf",
    "path": "cases/66d2f1b6807b2347dd58c011/
document_1725100411792_Prabhu_Zhakne_building_plan_1.pdf",
    "id": "422425",
    "uploadedBy": "647ed1960ab64c23c9fcf71d",
    "createdAt": "Sat Aug 31 2024 16:04:30 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1725100444474_139396.pdf",
    "path": "cases/66d2f1b6807b2347dd58c011/
document_1725100444474_139396.pdf",
    "id": "791730",
```

```
    "uploadedBy": "647ed1960ab64c23c9fcf71d",
    "createdAt": "Sat Aug 31 2024 16:04:30 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "010983",
"createdBy": "647ed1960ab64c23c9fcf71d",
"caseHistory": [
  {
    "id": "857578",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Aug 31 2024 16:04:30 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Prabhu Maruti Zakane ",
    "phone": "9766669917",
    "ownershipShare": "",
    "email": "",
    "id": "935923"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f24400f75047be5f2eea",
    "name":
"externalImg_1725100607971_WhatsApp_Image_20240319_at_10448_PM.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externalImg_1725100607971_WhatsApp_Image_20240319_at_10448_PM.jpeg",
    "orientation": "landscape"
  }
],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d2f24400f75047be5f2eeb",
  "name":
"externallmg_1725100608285_WhatsApp_Image_20240319_at_10449_PM.jpeg",
  "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100608285_WhatsApp_Image_20240319_at_10449_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d2f24400f75047be5f2eec",
  "name":
"externallmg_1725100608599_WhatsApp_Image_20240319_at_10454_PM.jpeg",
  "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100608599_WhatsApp_Image_20240319_at_10454_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d2f24400f75047be5f2eed",
  "name":
"externallmg_1725100608874_WhatsApp_Image_20240319_at_10456_PM.jpeg",
  "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100608874_WhatsApp_Image_20240319_at_10456_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d2f24400f75047be5f2eee",
  "name":
"externallmg_1725100609207_WhatsApp_Image_20240319_at_10458_PM.jpeg",
  "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100609207_WhatsApp_Image_20240319_at_10458_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d2f24400f75047be5f2eef",
  "name":
"externallmg_1725100609522_WhatsApp_Image_20240319_at_10459_PM_1.jpeg",
```

```
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100609522_WhatsApp_Image_20240319_at_10459_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f24400f75047be5f2ef0",
    "name":
"externallmg_1725100609895_WhatsApp_Image_20240319_at_10459_PM_2.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100609895_WhatsApp_Image_20240319_at_10459_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f24400f75047be5f2ef1",
    "name":
"externallmg_1725100610014_WhatsApp_Image_20240319_at_10459_PM.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100610014_WhatsApp_Image_20240319_at_10459_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f24400f75047be5f2ef2",
    "name":
"externallmg_1725100610385_WhatsApp_Image_20240319_at_10500_PM_1.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100610385_WhatsApp_Image_20240319_at_10500_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f24400f75047be5f2ef3",
    "name":
"externallmg_1725100610501_WhatsApp_Image_20240319_at_10500_PM.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100610501_WhatsApp_Image_20240319_at_10500_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66d2f24400f75047be5f2ef4",
  "name":
"externallmg_1725100610681_WhatsApp_Image_20240319_at_10501_PM_1.jpeg",
  "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100610681_WhatsApp_Image_20240319_at_10501_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d2f24400f75047be5f2ef5",
  "name":
"externallmg_1725100610781_WhatsApp_Image_20240319_at_10501_PM.jpeg",
  "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100610781_WhatsApp_Image_20240319_at_10501_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d2f24400f75047be5f2ef6",
  "name":
"externallmg_1725100610939_WhatsApp_Image_20240319_at_10502_PM_1.jpeg",
  "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100610939_WhatsApp_Image_20240319_at_10502_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d2f24400f75047be5f2ef7",
  "name":
"externallmg_1725100611156_WhatsApp_Image_20240319_at_10502_PM.jpeg",
  "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100611156_WhatsApp_Image_20240319_at_10502_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d2f24400f75047be5f2ef8",
  "name":
"externallmg_1725100611376_WhatsApp_Image_20240319_at_10503_PM_1.jpeg",
  "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100611376_WhatsApp_Image_20240319_at_10503_PM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f24400f75047be5f2ef9",
    "name":
"externallmg_1725100611457_WhatsApp_Image_20240319_at_10503_PM_2.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100611457_WhatsApp_Image_20240319_at_10503_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f24400f75047be5f2efa",
    "name":
"externallmg_1725100611555_WhatsApp_Image_20240319_at_10503_PM.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100611555_WhatsApp_Image_20240319_at_10503_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f24400f75047be5f2efb",
    "name":
"externallmg_1725100611673_WhatsApp_Image_20240319_at_10504_PM_1.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100611673_WhatsApp_Image_20240319_at_10504_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f24400f75047be5f2efc",
    "name":
"externallmg_1725100611789_WhatsApp_Image_20240319_at_10504_PM.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100611789_WhatsApp_Image_20240319_at_10504_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f24400f75047be5f2efd",
```

```
    "name":
"externallmg_1725100611867_WhatsApp_Image_20240319_at_10505_PM_1.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100611867_WhatsApp_Image_20240319_at_10505_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f259807b2347dd58c212",
    "name":
"externallmg_1725100631256_WhatsApp_Image_20240319_at_10505_PM.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100631256_WhatsApp_Image_20240319_at_10505_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f259807b2347dd58c213",
    "name":
"externallmg_1725100631386_WhatsApp_Image_20240319_at_10506_PM_1.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100631386_WhatsApp_Image_20240319_at_10506_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f259807b2347dd58c214",
    "name":
"externallmg_1725100631496_WhatsApp_Image_20240319_at_10506_PM.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100631496_WhatsApp_Image_20240319_at_10506_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f259807b2347dd58c215",
    "name":
"externallmg_1725100631622_WhatsApp_Image_20240319_at_10507_PM_1.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100631622_WhatsApp_Image_20240319_at_10507_PM_1.jpeg",
    "orientation": "portrait"
  },
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d2f259807b2347dd58c216",
  "name":
"externallmg_1725100631950_WhatsApp_Image_20240319_at_10507_PM_2.jpeg",
  "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100631950_WhatsApp_Image_20240319_at_10507_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d2f259807b2347dd58c217",
  "name":
"externallmg_1725100632033_WhatsApp_Image_20240319_at_10507_PM.jpeg",
  "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100632033_WhatsApp_Image_20240319_at_10507_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d2f259807b2347dd58c218",
  "name":
"externallmg_1725100632277_WhatsApp_Image_20240319_at_10508_PM_1.jpeg",
  "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100632277_WhatsApp_Image_20240319_at_10508_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d2f259807b2347dd58c219",
  "name":
"externallmg_1725100632358_WhatsApp_Image_20240319_at_10508_PM.jpeg",
  "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100632358_WhatsApp_Image_20240319_at_10508_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d2f259807b2347dd58c21a",
  "name":
"externallmg_1725100632458_WhatsApp_Image_20240319_at_10509_PM_1.jpeg",
```

```
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100632458_WhatsApp_Image_20240319_at_10509_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f259807b2347dd58c21b",
    "name":
"externallmg_1725100632579_WhatsApp_Image_20240319_at_10509_PM.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100632579_WhatsApp_Image_20240319_at_10509_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f259807b2347dd58c21c",
    "name":
"externallmg_1725100632662_WhatsApp_Image_20240319_at_10510_PM_1.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100632662_WhatsApp_Image_20240319_at_10510_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f259807b2347dd58c21d",
    "name":
"externallmg_1725100632761_WhatsApp_Image_20240319_at_10510_PM_2.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100632761_WhatsApp_Image_20240319_at_10510_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f259807b2347dd58c21e",
    "name":
"externallmg_1725100632922_WhatsApp_Image_20240319_at_10510_PM.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externallmg_1725100632922_WhatsApp_Image_20240319_at_10510_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```

    "status": false,
    "_id": "66d2f259807b2347dd58c21f",
    "name":
"externalImg_1725100633062_WhatsApp_Image_20240319_at_10511_PM_1.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externalImg_1725100633062_WhatsApp_Image_20240319_at_10511_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d2f259807b2347dd58c220",
    "name":
"externalImg_1725100633246_WhatsApp_Image_20240319_at_10511_PM.jpeg",
    "path": "cases/66d2f1b6807b2347dd58c011/
externalImg_1725100633246_WhatsApp_Image_20240319_at_10511_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-08-31T10:34:30.598Z",
"updatedAt": "2024-08-31T10:37:13.465Z",
"__v": 0,
"updatedBy": "647ed1960ab64c23c9fcf71d",
"addressForMap": "",
"caseReferredBy": "643a91f233d16f6b1237a4ee",
"contactPersonName": "Prabhu Maruti Zakane ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9766669917"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
