

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "firstName": "Dheerendra",
    "type": "CREDITOFFICER",
    "_id": "662781af7f34894a8aa37859",
    "lastName": "Singh",
    "mobileNo": "",
    "workMobileNo": "9140957299",
    "email": "dheerendra.singh@gmail.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Dheerendra",
    "expectedFees": null,
    "quotedAmount": "2500"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1720806809901_image.jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
```

```
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
  "lastName": "Kuperkar",
  "mobileNo": "9004134140",
  "designation": "",
  "shortName": "SH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "FIIV",
        "label": "FIIV"
      },
      "_id": "60af80072ffdf65bcd658652",
      "number": "CAT-I-F-1763"
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.20410289108278",
  "longitude": "73.10620792644336"
},
"geo": {
  "type": "Point",
  "coordinates": [
```

```
73.10620792644336,
19.20410289108278
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-03",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-03",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "Country - India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
```

```
"key": "village",
"value": "Golavali",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "6",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan",
  "label": true
},
}
```

```
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "S B Tower",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
```



```
"value": "Type B",
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "70, Hissa No. 1",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
```

```
"status": true,
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "607",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
```

```
"label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 201",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dombivli (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Proposed_Cement_Plastering",
    "label": "Proposed Cement Plastering"
  }
}
},
"general": {
```

```
"ownership": {
  "value": "Joint_Ownership",
  "label": "Joint Ownership"
},
"populationClassList": {
  "value": "MiddleClass",
  "label": "Middle Class"
},
"populationGroupList": {
  "value": "Urban",
  "label": "Urban"
},
"townplanApprovedByList": {
  "value": "Kalyan_Dombivali_Municipal_Corporation",
  "label": "Kalyan Dombivali Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Road",
  "west": "Veer Savarkar Marg",
  "south": "Open Plot ",
  "east": "Open Plot "
},
"asPerDocumentAgreement": {
  "north": "Details not available ",
  "west": "Details not available ",
  "south": "Details not available ",
  "east": "Details not available "
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Building is under construction ",
    "east": "Building is under construction ",
    "south": "Building is under construction ",
    "west": "Building is under construction "
  },
  "asPerDocument": {
    "north": "Details not available ",
    "east": "Details not available ",
    "south": "Details not available ",
    "west": "Details not available "
  },
  "isDisplay": true,
```

```
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per site visit / Brochure Plan, the composition of Flat will
be 1 Bedroom + Living Room + Kitchen + 2 Toilets. (i.e. 1BHK)",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and
not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "Builders has not allowed for site inspection & Internal Photographs. The
details about the work progress status has been provided by sales office person Ms.
Kajal Pandya - Mob. No. 8828424882",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "52900",
  "landRate": "13200",
  "igrImage": "cases/66d5893c807b2347dd59b3be/igr_1725358240699_Image.png",
  "squareMeterGuideLineRate": "55545.00",
```

```
"squareFeetGuideLineRate": "5160.00"
},
"igrFinalRate": {
  "floorRatePercentage": "5",
  "depreciationPercentage": "0",
  "rate": "52900.00",
  "squareMeterGuideLineRate": "55545.00",
  "squareFeetGuideLineRate": "5160.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_is_under_construction_",
    "label": "Building is under construction "
  },
  "monthlyRent": "13,000/- (Expected rental income per month after completion of construction works)\n",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per KDMC norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Building is under construction "
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area ",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  }
}
```

```
},
"partitions": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"waterTank": {
  "value": "Proposed_Municipal_Water_Supply",
  "label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"carParking": "Proposed Stilt / Open Car Parking Space ",
"constructionWorkStatus": {
  "value": "InProgress",
  "label": "Under Construction"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "",
  "month": "1",
  "year": "2025",
  "fullDate": "1/1/2025"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "Proposed_R.C.C_Framed_Structure",
  "label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C_Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Building_Under_Construction",
```

```
"label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
}
```



```
"groundStilt": {
  "value": "Part_Ground_and_Part_Stilt",
  "label": "Part Ground + Part Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
  "label": "As per site information"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "28",
"flatFloorNo": "6",
"noOfLifts": "4",
"noOfDwellingUnitsInBuilding": "11"
},
"finalPlinthArea": {
  "area": "453.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66d5893c807b2347dd59b3be/
routeMap_1725363903041_Image.png",
    "routeLat": "19.261722",
    "routeLng": "73.120694",
    "stationName": "Kalyan ",
    "routeDistance": "4.2 Km. ",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
```

```
"showLocation": {
  "latlng": false,
  "finallatlng": false
},
"locationMapImg": [
  {
    "id": "v7grwp",
    "name": "v7grwp",
    "image": "cases/66d5893c807b2347dd59b3be/
routeMap_1725363730649_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
```

```
"totalOthersRate": "0",
"finalTotal": "4532000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "4532000.00"
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "14",
    "percentage": "18.666666666666664",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "10",
    "percentage": "2.33",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "10",
```

```
"percentage": "2.33",
"isHideFloor": false,
"status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "33.33",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "2338512.00",
  "selectedBuildUpValue": "453.20",
```

```
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66d6c651807b2347dd5a5a2d",
      "name": "externallmg_r_1725351501070_1725351493481_image_6.jpg",
      "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351501070_1725351493481_image_6.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66d6c651807b2347dd5a5a2e",
      "name": "externallmg_r_1725351501981_1725351493481_image_7.jpg",
      "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351501981_1725351493481_image_7.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66d6c651807b2347dd5a5a2d",
      "name": "externallmg_r_1725351501070_1725351493481_image_6.jpg",
      "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351501070_1725351493481_image_6.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66d6c651807b2347dd5a5a2f",
      "name": "externallmg_r_1725351504014_1725351493481_image_9.jpg",
      "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351504014_1725351493481_image_9.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66d6c651807b2347dd5a5a31",
      "name": "externallmg_r_1725351499092_1725351493481_image_4.jpg",
      "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351499092_1725351493481_image_4.jpg",
      "orientation": "portrait"
    }
  ]
}
```

```
    },
    {
      "status": false,
      "_id": "66d6c651807b2347dd5a5a30",
      "name": "externallmg_r_1725351503089_1725351493481_image_8.jpg",
      "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351503089_1725351493481_image_8.jpg",
      "orientation": "portrait"
    },
    {
      "status": false,
      "_id": "66d6c651807b2347dd5a5a2b",
      "name": "externallmg_r_1725351500045_1725351493481_image_5.jpg",
      "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351500045_1725351493481_image_5.jpg",
      "orientation": "portrait"
    }
  ],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "9780.00",
    "max": "11964.00"
  },
  "builtUpRateRange": {
    "min": "8891.00",
    "max": "10877.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```

```
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "412.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66d5893c807b2347dd59b3be",
"ownerName": "Mr. Suraj Ramawatar Vishwakarma & Mrs. Sindhu R. Vishwakarma",
"ownerPhoneNo": "8433576597",
"appAddress": "Flat no. 607, 6th Floor, Type B, SB Tower, Village - Golvali Kalyan ",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "26/08/2024",
      "remark": " (5 Pages from documents)",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Ekveera Enterprises ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Suraj Ramawatar Vishwakarma & Mrs. Sindhu R. Vishwakarma",
      "number": {
```

```
    "value": "No",
    "label": "No"
  },
  "No": "13747 / 2024"
},
"isHardCopy": false,
"displayStatus": true,
"id": "508631",
"path": "cases/66d5893c807b2347dd59b3be/
document_1725270202736_1725270200433_DocScanner_02Sept2024_300_pm.pdf",
"fileName":
"document_1725270202736_1725270200433_DocScanner_02Sept2024_300_pm.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "29/05/2023",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    }
  },
  "No": "P517000541089"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1725360500311_Agreement.pdf",
"path": "cases/66d5893c807b2347dd59b3be/
document_1725360500311_Agreement.pdf",
"id": "885773",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Sep 03 2024 16:18:20 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "21/02/2023",
```

```
"nameOfApprovingAuthority": {
  "value": "Kalyan_Dombivli_Municipal_Corporation",
  "label": "Kalyan Dombivli Municipal Corporation"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "KDMC / TPD / BP / 27 Village / 2022 - 23 / 33"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1725360570828_CC.pdf",
"path": "cases/66d5893c807b2347dd59b3be/document_1725360570828_CC.pdf",
"id": "732301",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Tue Sep 03 2024 16:19:30 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "011000",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "792590",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Sep 02 2024 15:15:32 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Suraj Ramawatar Vishwakarma & Mrs. Sindhu R. Vishwakarma",
    "phone": "8433576597",
    "ownershipShare": "",
    "email": "",
    "id": "572783"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
```

```
    "value": "60af48bf2ffdf65bcd6585fa",
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "593160",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "412",
  "squareMeterArea": "38.28",
  "docFinalBuiltUp": "453.2",
  "docFinalBuiltUpSquareMeter": "42.108000000000004",
  "docBuiltupPercentage": "10",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "415.00",
      "squareMeterArea": "38.55",
      "expectedRate": "10542.17",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "456.50",
      "squareMeterArea": "42.41",
      "expectedRate": "9583.79",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    }
  },
  "printlnReport": true,
  "_id": "66d6e1f500f75047be607efa",
  "property": "Ekveera SB Tower, Dombivali East",
  "area": "415",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
```

```
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "square_yards",
"expectedPrice": "4375000",
"expectedRate": "10542.17",
"builtUpExpectedRate": "9583.79",
"image": "cases/66d5893c807b2347dd59b3be/
indicator_1725358012129_Image.png",
"squareMeter": "38.55",
"id": "948253"
},
{
"carpetArea": {
"area": "407.00",
"squareMeterArea": "37.81",
"expectedRate": "11199.02",
"percentage": ""
},
"builtUpArea": {
"area": "447.70",
"squareMeterArea": "41.59",
"expectedRate": "10180.92",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printInReport": true,
"_id": "66d6e1f500f75047be607efb",
"property": "Ekveera SB Tower, Dombivali East",
"area": "407",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "Housing.Com",
"expectedPrice": "4558000",
"expectedRate": "11199.02",
"builtUpExpectedRate": "10180.92",
"image": "cases/66d5893c807b2347dd59b3be/
indicator_1725358049766_Image.png",
```

```
"squareMeter": "37.81",
"id": "159750"
},
{
  "carpetArea": {
    "area": "415.00",
    "squareMeterArea": "38.55",
    "expectedRate": "11963.86",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "456.50",
    "squareMeterArea": "42.41",
    "expectedRate": "10876.23",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66d6e1f500f75047be607efc",
  "property": "Ekveera SB Tower, Dombivali East T",
  "area": "415",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "Middle",
  "source": "Housing.Com",
  "expectedPrice": "4965000",
  "expectedRate": "11963.86",
  "builtUpExpectedRate": "10876.23",
  "image": "cases/66d5893c807b2347dd59b3be/
indicator_1725358093836_Image.png",
  "squareMeter": "38.55",
  "id": "180268"
},
{
  "carpetArea": {
    "area": "409.00",
    "squareMeterArea": "38.00",
    "expectedRate": "9779.95",
    "percentage": ""
  }
}
```

```
},
"builtUpArea": {
  "area": "449.90",
  "squareMeterArea": "41.80",
  "expectedRate": "8890.86",
  "percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printInReport": true,
"_id": "66d6e1f500f75047be607efd",
"property": "Ekveera SB Tower, Dombivali East",
"area": "409",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "10",
"source": "Index_no.2",
"expectedPrice": "4000000",
"expectedRate": "9779.95",
"builtUpExpectedRate": "8890.86",
"image": "cases/66d5893c807b2347dd59b3be/
indicator_1725358141765_Image.png",
"squareMeter": "38.00",
"id": "761617"
},
{
  "carpetArea": {
    "area": "409.00",
    "squareMeterArea": "38.00",
    "expectedRate": "11246.94",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "449.90",
    "squareMeterArea": "41.80",
    "expectedRate": "10224.49",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
```



```
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66d6e1f500f75047be607efe",
  "property": "Ekveera SB Tower, Dombivali East",
  "area": "409",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "2",
  "source": "Index_no.2",
  "expectedPrice": "4600000",
  "expectedRate": "11246.94",
  "builtUpExpectedRate": "10224.49",
  "image": "cases/66d5893c807b2347dd59b3be/
indicator_1725358191169_Image.png",
  "squareMeter": "38.00",
  "id": "632402"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d6c651807b2347dd5a5a28",
    "name": "externalImg_1725351496848_1725351493481_image_1.png",
    "path": "cases/66d5893c807b2347dd59b3be/
externalImg_1725351496848_1725351493481_image_1.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d6c651807b2347dd5a5a29",
    "name": "externalImg_r_1725351497666_1725351493481_image_2.jpg",
    "path": "cases/66d5893c807b2347dd59b3be/
externalImg_r_1725351497666_1725351493481_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d6c651807b2347dd5a5a2a",
```

```
    "name": "externallmg_r_1725351498354_1725351493481_image_3.jpg",
    "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351498354_1725351493481_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d6c651807b2347dd5a5a2b",
    "name": "externallmg_r_1725351500045_1725351493481_image_5.jpg",
    "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351500045_1725351493481_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d6c651807b2347dd5a5a2c",
    "name": "externallmg_r_1725351496028_1725351493481_image_0.jpg",
    "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351496028_1725351493481_image_0.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d6c651807b2347dd5a5a2d",
    "name": "externallmg_r_1725351501070_1725351493481_image_6.jpg",
    "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351501070_1725351493481_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d6c651807b2347dd5a5a2e",
    "name": "externallmg_r_1725351501981_1725351493481_image_7.jpg",
    "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351501981_1725351493481_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d6c651807b2347dd5a5a2f",
    "name": "externallmg_r_1725351504014_1725351493481_image_9.jpg",
```

```
    "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351504014_1725351493481_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d6c651807b2347dd5a5a30",
    "name": "externallmg_r_1725351503089_1725351493481_image_8.jpg",
    "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351503089_1725351493481_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d6c651807b2347dd5a5a31",
    "name": "externallmg_r_1725351499092_1725351493481_image_4.jpg",
    "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351499092_1725351493481_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66d6c63d00f75047be60656c",
    "name": "externallmg_r_1725351483860_1725351483076_image_0.jpg",
    "path": "cases/66d5893c807b2347dd59b3be/
externallmg_r_1725351483860_1725351483076_image_0.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "1718776194681_1716026508753_1715323634339_17116066606
30_1700891975573_1695465043548_1694516251783_1694241590859_Calculation_1
_2.xlsx",
    "filename": "1725358587906_1718776194681_1716026508753_1715323634339_1
711606660630_1700891975573_1695465043548_1694516251783_1694241590859_
Calculation_1_2.xlsx",
    "path": "cases/66d5893c807b2347dd59b3be/processingDocuments/172535858790
6_1718776194681_1716026508753_1715323634339_1711606660630_170089197557
3_1695465043548_1694516251783_1694241590859_Calculation_1_2.xlsx",
    "size": "1428384",
    "createdAt": "Tue Sep 03 2024 15:46:28 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "9700.pdf",
  "filename": "1725358588033_9700.pdf",
  "path": "cases/66d5893c807b2347dd59b3be/
processingDocuments/1725358588033_9700.pdf",
  "size": "153132",
  "createdAt": "Tue Sep 03 2024 15:46:28 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "11000.pdf",
  "filename": "1725358588045_11000.pdf",
  "path": "cases/66d5893c807b2347dd59b3be/
processingDocuments/1725358588045_11000.pdf",
  "size": "151390",
  "createdAt": "Tue Sep 03 2024 15:46:28 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "CC.pdf",
  "filename": "1725365227996_CC.pdf",
  "path": "cases/66d5893c807b2347dd59b3be/
processingDocuments/1725365227996_CC.pdf",
  "size": "1017927",
  "createdAt": "Tue Sep 03 2024 17:37:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-09-02T09:45:32.929Z",
"updatedAt": "2024-09-03T12:22:28.327Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 607, 6th Floor, Wing - Type B, S B Tower, Village -
Golavali, Dombivli (East), Taluka - Kalyan, District - Thane, PIN - 421 201, State -
Maharashtra, Country - India",
"updatedBy": "60f915d3f3dd69653a592199",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
```

```
"contactPersonName": "Miss. Kajal Pandya ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Sales Person ",
"siteVisitContactNo": "8828424842",
"buildingServicesRate": "2700",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 412.00",
"flatRate": "11000",
"landOtherRate": "8300",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "Carpet Area in Sq. Ft. = 332.00\nFlower Bed Area in Sq. Ft. =
80.00\n",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "\n",
"toBeAdded": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
```

```
"leaseFrom": "",
"leaseTo": "",
"remainingLeasePeriod": 0,
"leaseDate": ""
}
},
"reportGeneratedDate": "Tue Sep 03 2024 15:50:57 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-09-03"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			