

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": true,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "66cc7060c884d1123351cad2"
    },
    "firstName": "Chitra",
    "type": "CREDITOFFICER",
    "_id": "66cc7074da840b1214cdcdff",
    "email": "bo045510@pnb.co.in",
    "lastName": "Desai",
    "mobileNo": "",
    "workMobileNo": "9152731985"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Chitra",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "66cc7060c884d1123351cad2",
  "name": "Lokhandwala Branch",
  "branchCode": "045510",
  "mobileNo": "02226326281",
  "alternateMobileNo": "02226365099",
  "email": "bo045510@pnb.co.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "68, Kamal Apartment, Lokhandwala Comlex, Versova Andheri West
Mumbai 400053"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60af3d172ffdf65bcd6585cd",
```

```
"role": "PICKUPPERSON",
"firstName": "Sachin",
"email": "sachin.joshi@vastukala.org",
"lastName": "Joshi",
"mobileNo": "9167204063",
"shortName": "SJ",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af3d172ffdf65bcd6585cd\
\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63fc575ece84bf289ba9e82d",
"role": "SITEENGINEER",
"firstName": "Deepak ",
"email": "daksh7831@gmail.com",
"lastName": "Jain ",
"mobileNo": "9022815908",
"designation": "",
"shortName": "DJ",
"workWithDocumentMaker": ""
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60eeaeddf3dd69653a581316",
"role": "ACCOUNTANT",
"firstName": "Shyam",
"email": "shyam@vastukala.org",
"lastName": "Kajvilkar",
"mobileNo": "9765074720",
"designation": "",
"shortName": "SK",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60eeaeddf3dd69653a581316\
\profilePhoto_1626255068979_Shyan_Photo.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "60f91b6f344e052188ffd1fc",
"role": "MAKER",
"firstName": "Jayaraja",
"email": "jayaraja@vastukala.org",
"lastName": "Acharya",
"mobileNo": "9867664219",
"designation": "",
"shortName": "JA",
```

```

    "workWithDocumentMaker": "",
    "profilePhoto": "users/60f91b6f344e052188ffd1fc/
profilePhoto_1678780588416_Profile_Photo.jpeg"
  },
  "checker": {
    "type": "EMPLOYEE",
    "_id": "60eeaeddf3dd69653a581316",
    "role": "ACCOUNTANT",
    "firstName": "Shyam",
    "email": "shyam@vastukala.org",
    "lastName": "Kajvilkar",
    "mobileNo": "9765074720",
    "designation": "",
    "shortName": "SK",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60eeaeddf3dd69653a581316\\
\\profilePhoto_1626255068979_Sh Yam_Photo.jpg"
  },
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
          "label": "Wealth Tax"
        }
      ],
      "type": "EMPLOYEE",
      "_id": "6084131a13f01f158c6ea1f3",
      "PANNo": "AEAPC7114Q",
      "role": "VALUER",
      "firstName": "Sharadkumar",
      "fatherName": "Baburao",
      "email": "cmd@vastukala.org",
      "lastName": "Chalikwar",
      "mobileNo": "9422171100",
      "designation": "CMD",
      "registrationNo": [
        {
          "title": {
            "value": "Wealth_Tax",
            "label": "Wealth Tax"
          },
          "_id": "6084131a13f01f158c6ea1f4",
          "number": "[N]C.C.I.T/I -14/52/2008-09"
        }
      ],
    }
  ],

```

```
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\
\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.17260911403624",
  "longitude": "72.87046967314444"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87046967314444,
    19.17260911403624
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "3/09/2024 01:09 pm"
    },
    {
      "dateTime": "3/09/2024 12:00 am"
    }
  ],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-04",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "2BHK",
  "label": "2 BHK"
}
```

```
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Dindoshi",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "6",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
```

```
"value": "",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Goregaon (East), Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Boirivali",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Lakshachandi Apartment A B C D Co-op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
```

```
"status": true,
"name": "Street 1",
"key": "street1",
"value": "Gokuldhama",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Krishna Vatika Marg",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
```



```
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "156/A/9/C/1, 2 & 3",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "603A/B",
  "label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "P/S",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
```

```
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 400 063",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Goregaon East",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  }
},
```

```
"flooring": {
  "value": "Vitrified_tiles_flooring",
  "label": "Vitrified tiles flooring"
},
"doors": {
  "value": "Teak_wood_door_frame_with_flush_shutters",
  "label": "Teak wood door frame with flush shutters"
},
"windows": {
  "value": "Powder_coated_Aluminum_sliding_windows",
  "label": "Powder coated Aluminum sliding windows"
},
"fittings": {
  "value":
"Concealed_plumbing_with_C.P._fittings._Electrical_wiring_with_concealed_",
  "label": "Concealed plumbing with C.P. fittings. Electrical wiring with concealed "
},
"finishing": {
  "value": "Cement_Plastering",
  "label": "Cement Plastering"
}
},
"general": {
  "ownership": {
    "value": "Joint_Ownership",
    "label": "Joint Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  },
  "townplanApprovedByList": {
    "value": "MCGM",
    "label": "Municipal Corporation of Greater Mumbai (MCGM)"
  },
  "whetherCoveredUnderAnyState": {
    "value": "No",
    "label": "No"
  },
  "asPerActualAgreement": {
    "north": "Krishna Vatika Marg",
    "west": "Lakshachandi Height",
```

```
"south": "Residential Building",
"east": "Mohan Gokhale Road"
},
"asPerDocumentAgreement": {
  "north": "Information not available",
  "west": "Information not available",
  "south": "Information not available",
  "east": "Information not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Lift",
    "east": "Lobby",
    "south": "Staircase",
    "west": "Marginal Space"
  },
  "asPerDocument": {
    "north": "Information not available",
    "east": "Information not available",
    "south": "Information not available",
    "west": "Information not available"
  },
  "isDisplay": true,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "",
"dateOfIssusApprovePlan": "Copy of approved building plans were not provided and not verified",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "No",
"unauthorizedConstruction": "No",
"extraDetailOfBuilding": ""
```

```

    "compoundWall": ""
  },
  "landAndBuildingDetails": {
    "actualBuildingBoundaries": [],
    "documentsBuildingBoundaries": []
  },
  "compositeRate": {
    "remark": "1.\tAs per site inspection, Flat No. 603A/B & 604A/B in 'B' Wing of Lakshachandi Apartment are internally amalgamated to form a single unit having single entrance door from Flat No. 603A/B. Common Lobby & Balcony Area merged with flat.<br />\n2.\tFor the purpose of valuation, we have considered the carpet area as per Gift Deed of Flat No. 603A & 603B.<br />\n3.\tAs per Memorandum of Understanding dated 06/05/2024 between Mr. Rajnikant Sharwankumar Kedia Vendor) AND Mr. Arvind Agarwal & Mrs. Amala Arvinnd Agarwal (Proposed Purchasers), the vendor undertakes to erect partition / wall between 603A/B & 604A/B and provide separate door at his cost and expense on or before handing over the possession to the Purchasers.<br />\n4.\tCopy of approved building plans not provided for our verification. It is advisable to submit plan showing to 603A & 603B as a single unit and 604A & 604B as independent unit and the location of door also provide the partition wall and the net final area of each flat separately prior to disbursement of loan.<br />",
    "depreciationPercentage": "24",
    "depreciationRatioOfBuilding": "",
    "salvageValue": "10",
    "depreciatedCostOfConstruction": "31780",
    "depreciatedBuildingRate": "2280"
  },
  "igrRate": {
    "propertyName": "Residential Flat",
    "rate": "177060",
    "landRate": "88390",
    "igrImage": "cases/66d6a70600f75047be6048b1/igr_1725595907461_Image.png",
    "squareMeterGuideLineRate": "185913.00",
    "squareFeetGuideLineRate": "17272.00"
  },
  "igrFinalRate": {
    "floorRatePercentage": "5",
    "depreciationPercentage": "84",
    "rate": "15822.00",
    "squareFeetGuideLineRate": "15822.00",
    "squareMeterGuideLineRate": "170309.00"
  },
  "outgoingDetail": {
    "areaStatusList": {
      "value": "Medium",
      "label": "Medium"
    }
  },

```

```
"propertyTypeOfUseList": {
  "value": "Residential_Purpose",
  "label": "Residential Purpose"
},
"propertyOccupiedByList": {
  "value": "Owner_Occupied",
  "label": "Owner Occupied"
},
"monthlyRent": "N.A",
"assessmentNo": "As per Maintenance Bill No. 2024-25/125",
"taxPaidHolderName": "Mr. Rajnikant Kedia",
"taxAmount": "As per Maintenance Bill<br />\nRs. 2,279/- for Flat No. 603A<br />\nRs. 62148/- for Flat No. 603B\n",
"electricityServiceConnectionNo": "Information not available",
"meterCardHolderName": "Information not available",
"undividedAreaOfLandAsPerSaleDeed": "Information not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Good"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed area",
  "negativeFactorsOfAffectMarketValue": "NO"
},
"siteMeasurement": {
  "roof": {
    "value": "R.C.C._slab",
    "label": "R.C.C. slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Car Parking Sapce No. 10 for Flat No. 603A",
```

```
"constructionWorkStatus": {
  "value": "Completed",
  "label": "Completed"
},
"asthetikLook": {
  "value": "Plain_Looking",
  "label": "Plain Looking"
},
"dateOfConstruction": {
  "date": "1",
  "month": "1",
  "year": "2008",
  "fullDate": "1/1/2008"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C.",
  "label": "R.C.C. Framed"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Good",
  "label": "Good"
},
"materialUsedList": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Good",
  "label": "Good"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
```

```
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceOfTheBuilding": {
  "value": "Good",
  "label": "Good"
},
"maintenanceIssues": {
  "value": "0",
  "label": "No"
},
"visibleDamageInBuilding": {
  "value": "0",
  "label": "No"
},
"systemOfAirConditioning": {
  "value": "0",
  "label": "No"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_occupancy_certificate",
  "label": "As per occupancy certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "44",
"ageOfBuilding": "16",
"noOfBasement": "1",
"noOfPodium": ""
```



```
"noOfAmenityFloors": "",
"noOfFloors": "10",
"flatFloorNo": "6",
"noOfLifts": "2",
"noOfDwellingUnitsInBuilding": "4"
},
"finalPlinthArea": {
  "area": "937.20",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 20%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/66d6a70600f75047be6048b1/
routeMap_1725599205228_Image.png",
    "routeLat": "19.171790",
    "routeLng": "72.870998",
    "stationName": "Aarey",
    "routeDistance": "2.6 km.",
    "routeStation": {
      "value": "Metro_Station",
      "label": "Metro Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "g1sjbn",
    "name": "g1sjbn",
    "image": "cases/66d6a70600f75047be6048b1/
routeMap_1725598983982_Image.png"
  }
]
},
"valuation": {
```

```
"fairMarketValue": {
  "costOfConstruction": "",
  "depreciationPercentage": "",
  "depreciatedCostOfConstruction": "",
  "totalFairMarketValue": ""
},
"wardrobesRate": "0",
"totalwardrobesRate": "0",
"wardrobesQty": "0",
"showcasesQty": "0",
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "24820180.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValue": "00",
"finalValue": "24820180.00",
"purchaseValueDocument": {
  "documentType": {
    "value": "60ae1253aa6d152c1801b323",
    "label": "Deed Of Gift"
  },
},
"isHardCopy": false,
"displayStatus": false,
"id": "925849",
```

```
"path": "cases/66d6a70600f75047be6048b1/document_1725343315826_1725343313396_Gift_deed_to_Rajnikant_Kedia__A603_compressed.pdf",
"fileName": "document_1725343315826_1725343313396_Gift_deed_to_Rajnikant_Kedia__A603_compressed.pdf",
"documentDate": "28/05/2018",
"from": {
  "value": "Donor",
  "label": "Donor"
},
"Donor": "Mr. Mahesh Sharwankumar Kedia & Mr. Sharwankumar Kedia",
"to": {
  "value": "donee",
  "label": "donee"
},
"donee": "Mr. Rajnikant Sharwankumar Kedia"
}
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
```

```
    "label": "Work Completed (%)",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "14828378.00",
  "selectedBuildUpValue": "937.20",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "66da8c13f2721b47e8e316af",
      "name": "externallmg_r_1725598739031_externallmg_r_1725512052226_TimePhoto_20240904_134112.jpg",
      "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598739031_externallmg_r_1725512052226_TimePhoto_20240904_134112.jpg",
      "orientation": "portrait"
    }
  ],
  "selfieWithSiteVisitImages": [
    {
      "status": false,
      "_id": "66da8c0915784548070e6f99",
      "name": "externallmg_r_1725598729220_externallmg_r_1725512052223_TimePhoto_20240904_133852.jpg",
      "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598729220_externallmg_r_1725512052223_TimePhoto_20240904_133852.jpg",
      "orientation": "portrait"
    }
  ],
  "externalPhotos": [
    {
      "status": false,
      "_id": "66da8c0915784548070e6f96",
      "name": "externallmg_r_1725598729215_externallmg_r_1725512052217_TimePhoto_20240904_133847.jpg",
      "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598729215_externallmg_r_1725512052217_TimePhoto_20240904_133847.jpg",
      "orientation": "portrait"
    }
  ],
  {

```

```
    "status": false,
    "_id": "66da8c0915784548070e6f98",
    "name": "externallmg_r_1725598729219_externallmg_r_1725512052220_TimePhoto_20240904_133848.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598729219_externallmg_r_1725512052220_TimePhoto_20240904_133848.jpg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "66da8c13f2721b47e8e316b1",
    "name": "Living Room",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598739059_externallmg_r_1725512067716_TimePhoto_20240904_132202.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66da8c13f2721b47e8e316b4",
    "name": "Living Room",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598739075_externallmg_r_1725512067732_TimePhoto_20240904_132227.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66da8c13f2721b47e8e316b5",
    "name": "Living Room",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598739070_externallmg_r_1725512067730_TimePhoto_20240904_132211.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66da8c1ff2721b47e8e31717",
    "name": "Living Room",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751277_externallmg_r_1725512067740_TimePhoto_20240904_132644.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
```

```
    "_id": "66da8c1ff2721b47e8e3171b",
    "name": "Living Room",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751320_exter
nallmg_r_1725512067749_TimePhoto_20240904_132837.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66da8c1ff2721b47e8e3171f",
    "name": "Living Room",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751347_exter
nallmg_r_1725512067755_TimePhoto_20240904_133015.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66da8c1ff2721b47e8e31721",
    "name": "Living Room",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751349_exter
nallmg_r_1725512067760_TimePhoto_20240904_133108.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66da8c0915784548070e6f95",
    "name": "Living Room",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598729195_exter
nallmg_r_1725512052208_TimePhoto_20240904_133127.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66da8c1ff2721b47e8e31718",
    "name": "Living Room",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751275_exter
nallmg_r_1725512067738_TimePhoto_20240904_132242.jpg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "66da8c1ff2721b47e8e3171c",
    "name": "Living Room",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751306_exter
nallmg_r_1725512067745_TimePhoto_20240904_132651.jpg",
    "orientation": "portrait"
  },
}
```



```
{
  "status": false,
  "_id": "66da8c1ff2721b47e8e3171d",
  "name": "Living Room",
  "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751334_externallmg_r_1725512067752_TimePhoto_20240904_132842.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66da8c1ff2721b47e8e3171e",
  "name": "Living Room",
  "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751348_externallmg_r_1725512067757_TimePhoto_20240904_133024.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66da8c1ff2721b47e8e31720",
  "name": "Living Room",
  "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751351_externallmg_r_1725512067763_TimePhoto_20240904_133124.jpg",
  "orientation": "portrait"
}
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "29144.00",
    "max": "37648.00"
  },
  "builtUpRateRange": {
    "min": "24286.00",
    "max": "31373.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
```

```
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "781.00",
"empanelmentNo": [
  "REF:ZO: SAMD:1138"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66d6a70600f75047be6048b1",
"ownerName": "Mr. Rajnikant Sharwankumar Kedia",
"ownerPhoneNo": "9322234491",
"appAddress": "Flat no 603A/B& 604A/B, B-wing,Lakshachandi Apartment A&B
CHS,Krishna Vatika Marg,Gokuldharm Goregaon East ",
"remark": "9322234491",
"documents": [
  {
    "documentType": {
      "value": "60ae1253aa6d152c1801b323",
      "label": "Deed Of Gift"
    },
    "inputs": {
      "documentDate": "28/05/2018",
      "from": {
        "value": "Donor",
        "label": "Donor"
      },
      "Donor": "Mr. Mahesh Sharwankumar Kedia & Mr. Sharwankumar Kedia",
      "to": {
        "value": "donee",
        "label": "donee"
      }
    }
  }
]
```

```
    },
    "donee": "Mr. Rajnikant Sharwankumar Kedia"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "925849",
  "path": "cases/66d6a70600f75047be6048b1/document_1725343315826_1725343313396_Gift_deed_to_Rajnikant_Kedia__A603_compressed.pdf",
  "fileName": "document_1725343315826_1725343313396_Gift_deed_to_Rajnikant_Kedia__A603_compressed.pdf"
},
{
  "documentType": {
    "value": "60ae1253aa6d152c1801b323",
    "label": "Deed Of Gift"
  },
  "inputs": {
    "documentDate": "28/05/2018",
    "from": {
      "value": "Donor",
      "label": "Donor"
    },
    "Donor": "Mr. Mahesh Sharwankumar Kedia & Mr. Sharwankumar Kedia",
    "to": {
      "value": "donee",
      "label": "donee"
    },
    "donee": "Mr. Rajnikant Sharwankumar Kedia"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "991754",
  "path": "cases/66d6a70600f75047be6048b1/document_1725343357732_1725343352205_Gift_deed_to_Rajnikant_Kedia__B603_compressed.pdf",
  "fileName": "document_1725343357732_1725343352205_Gift_deed_to_Rajnikant_Kedia__B603_compressed.pdf"
},
{
  "documentType": {
    "value": "60ae124aaa6d152c1801b2f9",
    "label": "Memorandum of Understanding"
  },
  "inputs": {
    "documentDate": "06/05/2024",
    "from": {
      "value": "Vendor",
```

```
    "label": "Vendor"
  },
  "Vendor": "Mr. Rajnikant Sharwankumar Kedia",
  "to": {
    "value": "Purchasers",
    "label": "Purchasers"
  },
  "Purchasers": "Mr. Arvind Agrawal & Mrs. Amala Arvind Agrawal"
},
"isHardCopy": false,
"displayStatus": true,
"id": "624186",
"path": "cases/66d6a70600f75047be6048b1/document_1725343430372_17253434
27788_MOU_between_Rajnikant_Kedia_and_Arvind_and_Amala_Agarwal_compresse
d.pdf",
"fileName": "document_1725343430372_1725343427788_MOU_between_Rajnikan
t_Kedia_and_Arvind_and_Amala_Agarwal_compressed.pdf"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f1",
    "label": "Society Maintenance Bill"
  },
  "inputs": {
    "documentDate": "01/04/2024",
    "remark": "in the name of Mr. Rajnikant Kedia for Flat No. B0603A issued by
Lakshachandi Apartment ABDC Co-op. Hsg. Soc. Ltd.",
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " 2024-25/125"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "297156",
  "path": "cases/66d6a70600f75047be6048b1/document_1725343445602_17253434
43640_Maintainence_bill_and_share_certificate_compressed.pdf",
  "fileName": "document_1725343445602_1725343443640_Maintainence_bill_and_s
hare_certificate_compressed.pdf"
},
{
  "documentType": {
    "value": "60ae1249aa6d152c1801b2f1",
    "label": "Society Maintenance Bill"
  },
}
```

```
"inputs": {
  "documentDate": "01/04/2024",
  "remark": "in the name of Mr. Rajnikant Kedia for Flat No. B0603B issued by
Lakshachandi Apartment ABDC Co-op. Hsg. Soc. Ltd.",
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": " 2024-25/126"
},
"isHardCopy": false,
"displayStatus": false,
"id": "524537",
"path": "cases/66d6a70600f75047be6048b1/
document_1725601567108_Maintenance_Bill__Share_Certificate.pdf",
"fileName": "document_1725601567108_Maintenance_Bill__Share_Certificate.pdf"
},
{
  "documentType": {
    "value": "60ae124baa6d152c1801b2fd",
    "label": "Occupancy Certificate"
  },
  "inputs": {
    "documentDate": "08/01/2008",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": " CJHE/7423/BP(WS)/Ap"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "id": "725001",
  "path": "cases/66d6a70600f75047be6048b1/
document_1725601726124_Occupancy_Certificate.pdf",
  "fileName": "document_1725601726124_Occupancy_Certificate.pdf"
}
],
"caseNumber": "011012",
"createdBy": "60af3d172ffdf65bcd6585cd",
"caseHistory": [
  {
```

```
"id": "159146",
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Tue Sep 03 2024 11:34:54 GMT+0530 (India Standard Time)"
}
],
"owners": [
{
"name": "Mr. Rajnikant Sharwankumar Kedia",
"phone": "9322234491",
"ownershipShare": "",
"email": "",
"id": "579753"
}
],
"proposePurchasers": [
{
"name": "Mr. Arvind Agrawal",
"phone": "",
"email": "",
"ownershipShare": ""
},
{
"name": "Mrs. Amala Arvind Agrawal",
"phone": "",
"email": "",
"ownershipShare": ""
}
],
"siteInspection": [],
"composition": [
{
"measurementType": {
"value": "Square_Feet",
"label": "Square Feet"
},
"id": "595231",
"name": "Living Room",
"length": "18.08",
"length1": "18",
"length2": "1",
"width": "10.50",
"width1": "10",
"width2": "6",
"totalArea": "189.87",
"images": [],

```



```
"extraAreas": [],
"finalArea": "189.87"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "1",
  "name": "Kitchen",
  "length": "13.25",
  "length1": "13",
  "length2": "3",
  "width": "8.33",
  "width1": "8",
  "width2": "4",
  "totalArea": "110.42",
  "images": [],
  "extraAreas": [],
  "finalArea": "110.42"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "2",
  "name": "Dining",
  "length": "8.42",
  "length1": "8",
  "length2": "5",
  "width": "6.08",
  "width1": "6",
  "width2": "1",
  "totalArea": "51.20",
  "images": [],
  "extraAreas": [],
  "finalArea": "51.20"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "3",
  "name": "Bedroom",
```

```
"length": "14.83",
"length1": "14",
"length2": "10",
"width": "9.92",
"width1": "9",
"width2": "11",
"totalArea": "147.10",
"images": [],
"extraAreas": [],
"finalArea": "147.10"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "8",
  "name": "Toilet",
  "length": "4.83",
  "length1": "4",
  "length2": "10",
  "width": "9.67",
  "width1": "9",
  "width2": "8",
  "totalArea": "46.72",
  "images": [],
  "finalArea": "46.72",
  "extraAreas": []
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "5",
  "name": "Bedroom",
  "length": "16.42",
  "length1": "16",
  "length2": "5",
  "width": "10.08",
  "width1": "10",
  "width2": "1",
  "totalArea": "165.53",
  "images": [],
  "extraAreas": [],
  "finalArea": "165.53"
```

```
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "6",
  "name": "Toilet",
  "length": "6.67",
  "length1": "6",
  "length2": "8",
  "width": "9.25",
  "width1": "9",
  "width2": "3",
  "totalArea": "61.67",
  "images": [],
  "extraAreas": [],
  "finalArea": "61.67"
},
{
  "measurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7",
  "name": "Passage",
  "length": "6.83",
  "length1": "6",
  "length2": "10",
  "width": "9.67",
  "width1": "9",
  "width2": "8",
  "totalArea": "66.06",
  "images": [],
  "extraAreas": [],
  "finalArea": "66.06"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60ae1253aa6d152c1801b323",
      "label": "Deed Of Gift"
    },
  },

```

```
"docMeasurementType": {
  "value": "Square_Feet",
  "label": "Square Feet"
},
"id": "418661",
"selectAreaTypeDocument": "Carpet",
"totalAreaDocument": "781",
"squareMeterArea": "72.56",
"docFinalBuiltUp": "937.2",
"docFinalBuiltUpSquareMeter": "87.072",
"docBuiltupPercentage": "20",
"docSaleablePercentage": "0",
"docFinalSaleable": "0",
"docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
{
  "carpetArea": {
    "area": "743.00",
    "squareMeterArea": "69.03",
    "expectedRate": "31292.06",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "891.60",
    "squareMeterArea": "82.83",
    "expectedRate": "26076.72",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "66da810b2eeecd47e76f716c",
  "property": "Residential Flat",
  "area": "743",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": ""
}
```

```
"source": "Index_no.2",
"expectedPrice": "23250000",
"expectedRate": "31292.06",
"builtUpExpectedRate": "26076.72",
"image": "cases/66d6a70600f75047be6048b1/
indicator_1725595635512_Image.png",
"squareMeter": "69.03",
"id": "838638"
},
{
"carpetArea": {
"area": "583.33",
"squareMeterArea": "54.19",
"expectedRate": "29143.02",
"percentage": ""
},
"builtUpArea": {
"area": "700.00",
"squareMeterArea": "65.03",
"expectedRate": "24285.71",
"percentage": "20"
},
"saleableArea": {
"area": "0.00",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printlnReport": true,
"_id": "66da810b2eeecd47e76f716d",
"property": "Residential Flat",
"area": "700",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Built_Up",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "17000000",
"expectedRate": "29143.02",
"builtUpExpectedRate": "17000000",
"image": "cases/66d6a70600f75047be6048b1/
indicator_1725595677481_Image.png",
"squareMeter": "65.03",
"id": "698681"
},
```

```
{
  "carpetArea": {
    "area": "784.00",
    "squareMeterArea": "72.84",
    "expectedRate": "31887.76",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "940.80",
    "squareMeterArea": "87.40",
    "expectedRate": "26573.13",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "66da810b2eeecd47e76f716e",
  "property": "Residential Flat",
  "area": "784",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "https://www.99acres.com/",
  "expectedPrice": "25000000",
  "expectedRate": "31887.76",
  "builtUpExpectedRate": "26573.13",
  "image": "cases/66d6a70600f75047be6048b1/
indicator_1725595696869_Image.png",
  "squareMeter": "72.84",
  "id": "245751"
},
{
  "carpetArea": {
    "area": "850.00",
    "squareMeterArea": "78.97",
    "expectedRate": "37647.06",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1020.00",
```

```
    "squareMeterArea": "94.76",
    "expectedRate": "31372.55",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66da810b2eeecd47e76f716f",
  "property": "Residential Flat",
  "area": "850",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Carpet",
  "floor": "",
  "source": "Nobroker.com",
  "expectedPrice": "32000000",
  "expectedRate": "37647.06",
  "builtUpExpectedRate": "31372.55",
  "image": "cases/66d6a70600f75047be6048b1/
indicator_1725595720610_Image.png",
  "squareMeter": "78.97",
  "id": "642133"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d93974433b95fe09e334eb",
    "name": "externalImg_1725512052235_IMG_20240904_224307__01.jpg",
    "path": "cases/66d6a70600f75047be6048b1/
externalImg_1725512052235_IMG_20240904_224307__01.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66d93974433b95fe09e334f4",
    "name": "externalImg_r_1725512052237_TimePhoto_20240904_131351.jpg",
    "path": "cases/66d6a70600f75047be6048b1/
externalImg_r_1725512052237_TimePhoto_20240904_131351.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d93974433b95fe09e334f5",
  "name": "externallmg_r_1725512052240_TimePhoto_20240904_131403.jpg",
  "path": "cases/66d6a70600f75047be6048b1/
externallmg_r_1725512052240_TimePhoto_20240904_131403.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d93974433b95fe09e334f6",
  "name": "externallmg_r_1725512052239_TimePhoto_20240904_131356.jpg",
  "path": "cases/66d6a70600f75047be6048b1/
externallmg_r_1725512052239_TimePhoto_20240904_131356.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d93974433b95fe09e334f7",
  "name": "externallmg_r_1725512052243_TimePhoto_20240904_131642.jpg",
  "path": "cases/66d6a70600f75047be6048b1/
externallmg_r_1725512052243_TimePhoto_20240904_131642.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66d93974433b95fe09e334f8",
  "name": "externallmg_r_1725512052245_TimePhoto_20240904_131725.jpg",
  "path": "cases/66d6a70600f75047be6048b1/
externallmg_r_1725512052245_TimePhoto_20240904_131725.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66da8c0915784548070e6f94",
  "name": "externallmg_1725598729191_externallmg_1725512052233_IMG_202409
04_133458.jpg",
  "path": "cases/66d6a70600f75047be6048b1/externallmg_1725598729191_externall
mg_1725512052233_IMG_20240904_133458.jpg",
```



```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66da8c0915784548070e6f95",
  "name": "externallmg_r_1725598729195_externallmg_r_1725512052208_TimePhoto_20240904_133127.jpg",
  "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598729195_externallmg_r_1725512052208_TimePhoto_20240904_133127.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66da8c0915784548070e6f96",
  "name": "externallmg_r_1725598729215_externallmg_r_1725512052217_TimePhoto_20240904_133847.jpg",
  "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598729215_externallmg_r_1725512052217_TimePhoto_20240904_133847.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66da8c0915784548070e6f97",
  "name": "externallmg_r_1725598729212_externallmg_r_1725512052213_TimePhoto_20240904_133846.jpg",
  "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598729212_externallmg_r_1725512052213_TimePhoto_20240904_133846.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66da8c0915784548070e6f98",
  "name": "externallmg_r_1725598729219_externallmg_r_1725512052220_TimePhoto_20240904_133848.jpg",
  "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598729219_externallmg_r_1725512052220_TimePhoto_20240904_133848.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66da8c0915784548070e6f99",
```

```
    "name": "externalimg_r_1725598729220_externalimg_r_1725512052223_TimePhoto_20240904_133852.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externalimg_r_1725598729220_externalimg_r_1725512052223_TimePhoto_20240904_133852.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66da8c0915784548070e6f9a",
    "name": "externalimg_r_1725598729210_externalimg_r_1725512052210_TimePhoto_20240904_133844.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externalimg_r_1725598729210_externalimg_r_1725512052210_TimePhoto_20240904_133844.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66da8c13f2721b47e8e316af",
    "name": "externalimg_r_1725598739031_externalimg_r_1725512052226_TimePhoto_20240904_134112.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externalimg_r_1725598739031_externalimg_r_1725512052226_TimePhoto_20240904_134112.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66da8c13f2721b47e8e316b0",
    "name": "externalimg_r_1725598739062_externalimg_r_1725512067719_TimePhoto_20240904_132207.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externalimg_r_1725598739062_externalimg_r_1725512067719_TimePhoto_20240904_132207.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66da8c13f2721b47e8e316b1",
    "name": "externalimg_r_1725598739059_externalimg_r_1725512067716_TimePhoto_20240904_132202.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externalimg_r_1725598739059_externalimg_r_1725512067716_TimePhoto_20240904_132202.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66da8c13f2721b47e8e316b2",
  "name": "externallmg_r_1725598739046_externallmg_r_1725512052229_TimePhoto_20240904_134113.jpg",
  "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598739046_externallmg_r_1725512052229_TimePhoto_20240904_134113.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66da8c13f2721b47e8e316b3",
  "name": "externallmg_r_1725598739065_externallmg_r_1725512067726_TimePhoto_20240904_132208.jpg",
  "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598739065_externallmg_r_1725512067726_TimePhoto_20240904_132208.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66da8c13f2721b47e8e316b4",
  "name": "externallmg_r_1725598739075_externallmg_r_1725512067732_TimePhoto_20240904_132227.jpg",
  "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598739075_externallmg_r_1725512067732_TimePhoto_20240904_132227.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66da8c13f2721b47e8e316b5",
  "name": "externallmg_r_1725598739070_externallmg_r_1725512067730_TimePhoto_20240904_132211.jpg",
  "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598739070_externallmg_r_1725512067730_TimePhoto_20240904_132211.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66da8c1ff2721b47e8e31716",
  "name": "externallmg_r_1725598751272_externallmg_r_1725512067736_TimePhoto_20240904_132229.jpg",
```

```
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751272_extern
allmg_r_1725512067736_TimePhoto_20240904_132229.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66da8c1ff2721b47e8e31717",
    "name": "externallmg_r_1725598751277_externallmg_r_1725512067740_TimePhot
o_20240904_132644.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751277_extern
allmg_r_1725512067740_TimePhoto_20240904_132644.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66da8c1ff2721b47e8e31718",
    "name": "externallmg_r_1725598751275_externallmg_r_1725512067738_TimePhot
o_20240904_132242.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751275_extern
allmg_r_1725512067738_TimePhoto_20240904_132242.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66da8c1ff2721b47e8e31719",
    "name": "externallmg_r_1725598751282_externallmg_r_1725512067742_TimePhot
o_20240904_132645.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751282_extern
allmg_r_1725512067742_TimePhoto_20240904_132645.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66da8c1ff2721b47e8e3171a",
    "name": "externallmg_r_1725598751308_externallmg_r_1725512067747_TimePhot
o_20240904_132655.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751308_extern
allmg_r_1725512067747_TimePhoto_20240904_132655.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "66da8c1ff2721b47e8e3171b",
    "name": "externallmg_r_1725598751320_externallmg_r_1725512067749_TimePhoto_20240904_132837.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751320_externallmg_r_1725512067749_TimePhoto_20240904_132837.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66da8c1ff2721b47e8e3171c",
    "name": "externallmg_r_1725598751306_externallmg_r_1725512067745_TimePhoto_20240904_132651.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751306_externallmg_r_1725512067745_TimePhoto_20240904_132651.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66da8c1ff2721b47e8e3171d",
    "name": "externallmg_r_1725598751334_externallmg_r_1725512067752_TimePhoto_20240904_132842.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751334_externallmg_r_1725512067752_TimePhoto_20240904_132842.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66da8c1ff2721b47e8e3171e",
    "name": "externallmg_r_1725598751348_externallmg_r_1725512067757_TimePhoto_20240904_133024.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751348_externallmg_r_1725512067757_TimePhoto_20240904_133024.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66da8c1ff2721b47e8e3171f",
    "name": "externallmg_r_1725598751347_externallmg_r_1725512067755_TimePhoto_20240904_133015.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751347_externallmg_r_1725512067755_TimePhoto_20240904_133015.jpg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66da8c1ff2721b47e8e31720",
    "name": "externallmg_r_1725598751351_externallmg_r_1725512067763_TimePhoto_20240904_133124.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751351_externallmg_r_1725512067763_TimePhoto_20240904_133124.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66da8c1ff2721b47e8e31721",
    "name": "externallmg_r_1725598751349_externallmg_r_1725512067760_TimePhoto_20240904_133108.jpg",
    "path": "cases/66d6a70600f75047be6048b1/externallmg_r_1725598751349_externallmg_r_1725512067760_TimePhoto_20240904_133108.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "AGR-2003.pdf",
    "filename": "1725595943947_AGR2003.pdf",
    "path": "cases/66d6a70600f75047be6048b1/processingDocuments/1725595943947_AGR2003.pdf",
    "size": "4047629",
    "createdAt": "Fri Sep 06 2024 09:42:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_1725512052235_IMG_20240904_224307__01.jpg",
    "filename": "1725595944072_externallmg_1725512052235_IMG_20240904_224307__01.jpg",
    "path": "cases/66d6a70600f75047be6048b1/processingDocuments/1725595944072_externallmg_1725512052235_IMG_20240904_224307__01.jpg",
    "size": "215321",
    "createdAt": "Fri Sep 06 2024 09:42:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "externallmg_r_1725512052237_TimePhoto_20240904_131351.jpg",
```

```
    "filename":
"1725595944077_externallmg_r_1725512052237_TimePhoto_20240904_131351.jpg",
    "path": "cases/66d6a70600f75047be6048b1/processingDocuments/1725595944077_externallmg_r_1725512052237_TimePhoto_20240904_131351.jpg",
    "size": "155566",
    "createdAt": "Fri Sep 06 2024 09:42:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_r_1725512052239_TimePhoto_20240904_131356.jpg",
    "filename":
"1725595944079_externallmg_r_1725512052239_TimePhoto_20240904_131356.jpg",
    "path": "cases/66d6a70600f75047be6048b1/processingDocuments/1725595944079_externallmg_r_1725512052239_TimePhoto_20240904_131356.jpg",
    "size": "153323",
    "createdAt": "Fri Sep 06 2024 09:42:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_r_1725512052240_TimePhoto_20240904_131403.jpg",
    "filename":
"1725595944091_externallmg_r_1725512052240_TimePhoto_20240904_131403.jpg",
    "path": "cases/66d6a70600f75047be6048b1/processingDocuments/1725595944091_externallmg_r_1725512052240_TimePhoto_20240904_131403.jpg",
    "size": "147545",
    "createdAt": "Fri Sep 06 2024 09:42:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_r_1725512052243_TimePhoto_20240904_131642.jpg",
    "filename":
"1725595944094_externallmg_r_1725512052243_TimePhoto_20240904_131642.jpg",
    "path": "cases/66d6a70600f75047be6048b1/processingDocuments/1725595944094_externallmg_r_1725512052243_TimePhoto_20240904_131642.jpg",
    "size": "180162",
    "createdAt": "Fri Sep 06 2024 09:42:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname":
"externallmg_r_1725512052245_TimePhoto_20240904_131725.jpg",
    "filename":
"1725595944101_externallmg_r_1725512052245_TimePhoto_20240904_131725.jpg",
```

```
    "path": "cases/66d6a70600f75047be6048b1/processingDocuments/1725595944101_externallmg_r_1725512052245_TimePhoto_20240904_131725.jpg",
    "size": "115918",
    "createdAt": "Fri Sep 06 2024 09:42:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "GD-28.05.2018-603A.pdf",
    "filename": "1725595944103_GD28052018603A.pdf",
    "path": "cases/66d6a70600f75047be6048b1/processingDocuments/1725595944103_GD28052018603A.pdf",
    "size": "1636996",
    "createdAt": "Fri Sep 06 2024 09:42:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "GD-28.05.2018-603B.pdf",
    "filename": "1725595944127_GD28052018603B.pdf",
    "path": "cases/66d6a70600f75047be6048b1/processingDocuments/1725595944127_GD28052018603B.pdf",
    "size": "1306212",
    "createdAt": "Fri Sep 06 2024 09:42:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "MB & SHARE.pdf",
    "filename": "1725595952075_MB__SHARE.pdf",
    "path": "cases/66d6a70600f75047be6048b1/processingDocuments/1725595952075_MB__SHARE.pdf",
    "size": "736420",
    "createdAt": "Fri Sep 06 2024 09:42:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "MOU-2024.pdf",
    "filename": "1725595952083_MOU2024.pdf",
    "path": "cases/66d6a70600f75047be6048b1/processingDocuments/1725595952083_MOU2024.pdf",
    "size": "814299",
    "createdAt": "Fri Sep 06 2024 09:42:32 GMT+0530 (India Standard Time)",
    "uploadedBy": "60eeaeddf3dd69653a581316"
  },
  {
    "originalname": "OC.pdf",
    "filename": "1725595952090_OC.pdf",
    "path": "cases/66d6a70600f75047be6048b1/processingDocuments/1725595952090_OC.pdf",
```



```
"size": "1076902",
"createdAt": "Fri Sep 06 2024 09:42:32 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "SITE DETAILS.pdf",
"filename": "1725595952101_SITE_DETAILS.pdf",
"path": "cases/66d6a70600f75047be6048b1/
processingDocuments/1725595952101_SITE_DETAILS.pdf",
"size": "181818",
"createdAt": "Fri Sep 06 2024 09:42:32 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
},
{
"originalname": "Summary New=RAJANIKANT.xlsx",
"filename": "1725595952105_Summary_NewRAJANIKANT.xlsx",
"path": "cases/66d6a70600f75047be6048b1/
processingDocuments/1725595952105_Summary_NewRAJANIKANT.xlsx",
"size": "2137340",
"createdAt": "Fri Sep 06 2024 09:42:32 GMT+0530 (India Standard Time)",
"uploadedBy": "60eeaeddf3dd69653a581316"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-09-03T06:04:54.595Z",
"updatedAt": "2024-09-06T07:51:52.763Z",
"__v": 0,
"assignmentType": {
"value": "Retail",
"label": "Retail"
},
"fullAddress": "Residential Flat No. 603A/B, 6th Floor, Wing - B, Lakshachandi
Apartment A B C D Co-op. Hsg. Soc. Ltd., Gokuldham, Krishna Vatika Marg, Village -
Dindoshi, Municipality Ward No. P/S, Goregaon East, Taluka - Boirivali, Goregaon
(East), Mumbai, PIN - 400 063, State - Maharashtra, India",
"updatedAt": "60eeaeddf3dd69653a581316",
"addressForMap": "",
"caseReferredBy": "60af3d172ffdf65bcd6585cd",
"contactPersonName": "Mr. Rajnikant Kedia",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "Mr. Arvind Agrawal",
```

```
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Flat Seller",
"siteVisitContactNo": "9322234491",
"buildingServicesRate": "3000",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Deed Of Gift",
"finalBuiltUpPercentage": "20",
"finalCarpetConvertToBuiltUpPer": "20",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 781.00",
"flatRate": "32500",
"landOtherRate": "29500",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  },
  "roadFacing": false,
  "mall": false
},
"briefDescOfProperty": "2 Bedroom + Living Room + Kitchen + Dining + 2 Toilet +
Passage",
"carpetTotal": "838.5699999999999",
"otherCarpetTotal": "0.00",
"builtupPercentage": "20",
"finalBuiltupArea": "1006.28",
"finalCarpetArea": "838.57",
"finalSalableArea": "1006.28",
"salablePercentage": "0",
"toBeAdded": "",
"extendOfSiteRemark": "\nCarpet Area in Sq. Ft. = 402.00 for Flat No. 603A\nCarpet
Area in Sq. Ft. = 379.00 for Flat No. 603B\n",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"reportGeneratedDate": "Fri Sep 06 2024 10:18:20 GMT+0530 (India Standard Time)",
"siteVisitDate": "2024-09-04",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": ""
  }
}
```

```

    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Living Room	18'1"	10'6"	189.87
Kitchen	13'3"	8'4"	110.42
Dining	8'5"	6'1"	51.20
Bedroom	14'10"	9'11"	147.10
Toilet	4'10"	9'8"	46.72
Bedroom	16'5"	10'1"	165.53
Toilet	6'8"	9'3"	61.67
Passage	6'10"	9'8"	66.06
Other Composition :			