

```
{
  "typeOfReport": {
    "value": "Office",
    "label": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "firstName": "Anju",
    "type": "CREDITOFFICER",
    "_id": "655c87b25586e008158f7000",
    "lastName": "Rajdev",
    "mobileNo": "",
    "workMobileNo": "7291316555",
    "email": "anju.rajdev@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Anju",
    "expectedFees": null,
    "quotedAmount": "5000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Commercial",
  "value": "Commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f949ce45132d6a6bddbcc3",
  "role": "SITEENGINEER",
  "firstName": "Tushar ",
  "email": "tusharbhuwad90@gmail.com",
  "lastName": "Bhuwad",
  "mobileNo": "9082053889",
  "designation": "",
  "shortName": "TSB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f949ce45132d6a6bddbcc3/
profilePhoto_1668058314746_WhatsApp_Image_20221110_at_105931_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
```

```
    "value": "IBBI/RV/07/2018/10366",
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.11308679209247",
  "longitude": "72.84333355210809"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.84333355210809,
    19.11308679209247
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "5/09/2024 08:50 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Vile Parle",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahsilNo": {
  "status": false,
```

```
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Mesacon Jewel",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "L S road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
}
```

```
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "C",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```



```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "21",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```

```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400058",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Andheri West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
```

```
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
    },
    "builtUpRateRange": {
      "min": "0.00",
      "max": "0.00"
    },
    "saleableRateRange": {
      "min": "0.00",
      "max": "0.00"
    }
  },
  "detailsOfValuation": {
    "presentValueOfFlat": {
      "title": "Present value of the flat (incl. car parking, if provided)",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": false
    },
    "wardrobes": {
      "title": "Wardrobes",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "showcases": {
      "title": "Showcases",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "kitchenArrangements": {
      "title": "Kitchen arrangements",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "superfineFinish": {
      "title": "Superfine finish",
      "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```



```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66d85ebb807b2347dd5b6dc6",
"ownerName": "Vaishali Vikram Mehta And Vikram Rashmikant Mehta",
"ownerPhoneNo": "9920622118",
"appAddress": "Office no. 21, Mesacon Jewel, Wing - C, Andheri West ",
"remark": "Vastukala + Vankar ",
"documents": [
  {
    "documentType": {
```

```
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/66d85ebb807b2347dd5b6dc6/
document_1725455969858_1725455968440_Mesacon_Office_No_21.pdf",
  "fileName":
"document_1725455969858_1725455968440_Mesacon_Office_No_21.pdf",
  "id": "997244",
  "uploadedBy": "60b7177d2ffdf65bcd65882a",
  "createdAt": "Wed Sep 04 2024 18:50:59 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "011056",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "166166",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Sep 04 2024 18:50:59 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Vaishali Vikram Mehta And Vikram Rashmikant Mehta",
    "phone": "9920622118",
    "ownershipShare": "",
    "email": "",
    "id": "611782"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3bf2eeecd47e76f9ea5",
```

```
    "name": "externalImg_r_1725604799457_TimePhoto_20240905_124851.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externalImg_r_1725604799457_TimePhoto_20240905_124851.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3bf2eeecd47e76f9ea6",
    "name": "externalImg_r_1725604799458_TimePhoto_20240905_125127.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externalImg_r_1725604799458_TimePhoto_20240905_125127.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3bf2eeecd47e76f9ea7",
    "name": "externalImg_r_1725604799461_TimePhoto_20240905_130319.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externalImg_r_1725604799461_TimePhoto_20240905_130319.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3bf2eeecd47e76f9ea8",
    "name": "externalImg_r_1725604799464_TimePhoto_20240905_130938.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externalImg_r_1725604799464_TimePhoto_20240905_130938.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3bf2eeecd47e76f9ea9",
    "name": "externalImg_r_1725604799462_TimePhoto_20240905_130323.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externalImg_r_1725604799462_TimePhoto_20240905_130323.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3bf2eeecd47e76f9eaa",
    "name": "externalImg_r_1725604799463_TimePhoto_20240905_130449.jpg",
```

```
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604799463_TimePhoto_20240905_130449.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3bf2eeecd47e76f9eab",
    "name": "externallmg_r_1725604799467_IMG20240905130401.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604799467_IMG20240905130401.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3bf2eeecd47e76f9eac",
    "name": "externallmg_r_1725604799466_TimePhoto_20240905_131113.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604799466_TimePhoto_20240905_131113.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3bf2eeecd47e76f9ead",
    "name": "externallmg_r_1725604799465_TimePhoto_20240905_131028.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604799465_TimePhoto_20240905_131028.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3bf2eeecd47e76f9eae",
    "name": "externallmg_r_1725604799469_TimePhoto_20240905_124848.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604799469_TimePhoto_20240905_124848.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3bf2eeecd47e76f9eaf",
    "name": "externallmg_r_1725604799470_TimePhoto_20240905_124857.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604799470_TimePhoto_20240905_124857.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66daa3bf2eeecd47e76f9eb0",
  "name": "externallmg_r_1725604799468_TimePhoto_20240905_124700.jpg",
  "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604799468_TimePhoto_20240905_124700.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66daa3bf2eeecd47e76f9eb1",
  "name": "externallmg_r_1725604799472_TimePhoto_20240905_125136.jpg",
  "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604799472_TimePhoto_20240905_125136.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66daa3bf2eeecd47e76f9eb2",
  "name": "externallmg_r_1725604799460_TimePhoto_20240905_130308.jpg",
  "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604799460_TimePhoto_20240905_130308.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66daa3bf2eeecd47e76f9eb3",
  "name": "externallmg_r_1725604799471_TimePhoto_20240905_125124.jpg",
  "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604799471_TimePhoto_20240905_125124.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66daa3cf15784548070e99ac",
  "name": "externallmg_r_1725604815758_TimePhoto_20240905_125209.jpg",
  "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604815758_TimePhoto_20240905_125209.jpg",
  "orientation": "landscape"
}
```

```
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3cf15784548070e99ad",
    "name": "externallmg_r_1725604815759_TimePhoto_20240905_125215.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604815759_TimePhoto_20240905_125215.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3cf15784548070e99ae",
    "name": "externallmg_r_1725604815759_TimePhoto_20240905_125213.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604815759_TimePhoto_20240905_125213.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3cf15784548070e99af",
    "name": "externallmg_r_1725604815761_TimePhoto_20240905_125227.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604815761_TimePhoto_20240905_125227.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3cf15784548070e99b0",
    "name": "externallmg_r_1725604815764_TimePhoto_20240905_125303.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604815764_TimePhoto_20240905_125303.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3cf15784548070e99b1",
    "name": "externallmg_r_1725604815762_TimePhoto_20240905_125239.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604815762_TimePhoto_20240905_125239.jpg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66daa3cf15784548070e99b2",
  "name": "externallmg_r_1725604815765_TimePhoto_20240905_130334.jpg",
  "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604815765_TimePhoto_20240905_130334.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66daa3cf15784548070e99b3",
  "name": "externallmg_r_1725604815753_TimePhoto_20240905_125149.jpg",
  "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604815753_TimePhoto_20240905_125149.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66daa3cf15784548070e99b4",
  "name": "externallmg_r_1725604815780_TimePhoto_20240905_130420.jpg",
  "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604815780_TimePhoto_20240905_130420.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66daa3cf15784548070e99b5",
  "name": "externallmg_r_1725604815825_TimePhoto_20240905_130454.jpg",
  "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604815825_TimePhoto_20240905_130454.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66daa3cf15784548070e99b6",
  "name": "externallmg_r_1725604815826_TimePhoto_20240905_130934.jpg",
  "path": "cases/66d85ebb807b2347dd5b6dc6/
externallmg_r_1725604815826_TimePhoto_20240905_130934.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3cf15784548070e99b7",
    "name": "externalImg_r_1725604815826_TimePhoto_20240905_131003.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externalImg_r_1725604815826_TimePhoto_20240905_131003.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3cf15784548070e99b8",
    "name": "externalImg_r_1725604815820_TimePhoto_20240905_130447.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externalImg_r_1725604815820_TimePhoto_20240905_130447.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3cf15784548070e99b9",
    "name": "externalImg_r_1725604815827_TimePhoto_20240905_131031.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externalImg_r_1725604815827_TimePhoto_20240905_131031.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3cf15784548070e99ba",
    "name": "externalImg_r_1725604815827_TimePhoto_20240905_131033.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externalImg_r_1725604815827_TimePhoto_20240905_131033.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3cf15784548070e99bb",
    "name": "externalImg_r_1725604815828_TimePhoto_20240905_131111.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externalImg_r_1725604815828_TimePhoto_20240905_131111.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "66daa3cf15784548070e99bc",
    "name": "externalImg_r_1725604815828_TimePhoto_20240905_131116.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externalImg_r_1725604815828_TimePhoto_20240905_131116.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa3cf15784548070e99bd",
    "name": "externalImg_r_1725604815829_TimePhoto_20240905_131137.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externalImg_r_1725604815829_TimePhoto_20240905_131137.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa4562eeecd47e76f9fa8",
    "name": "externalImg_r_1725604949858_IMG20240905183423.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externalImg_r_1725604949858_IMG20240905183423.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66daa4562eeecd47e76f9fa9",
    "name": "externalImg_r_1725604949890_IMG20240905183455.jpg",
    "path": "cases/66d85ebb807b2347dd5b6dc6/
externalImg_r_1725604949890_IMG20240905183455.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-09-04T13:20:59.548Z",
"updatedAt": "2024-09-06T06:42:30.105Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
}
```

```
},
"fullAddress": "Residential Flat No. 21, 5th Floor, Wing - C, Mesacon Jewel, L S road,
Village - Vile Parle, Andheri West, Mumbai, 400058",
"updatedBy": "6006d4ce5080a310ac1fdcf2",
"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "Vaishali Vikram Mehta And Vikram Rashmikant Mehta",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9920622118"
}
```

}	Name	Length	Width	Total
Composition :				
Other				
Composition :				