

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "MSME_Loan",
    "label": "MSME Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "64ad25c7d9a15943959faf91"
    },
    "firstName": "Rajan",
    "type": "CREDITOFFICER",
    "_id": "64ad25c7d9a15943959faf93",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "8789563372",
    "email": "rajankmr@idbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "60faa90845132d6a6bde5d38",
  "type": "BANK",
  "name": "IDBI Bank ",
  "displayName": "IDBI Bank ",
  "initial": "IDBI"
},
"branch": {
  "_id": "64ad25c7d9a15943959faf91",
  "name": "Prahlad Nagar Branch",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "rajankmr@idbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "SHOP NO 4A, PINNACLE BUSINESS PARK,\nOPP ROYAL ORCHID,
PRAHLADNAGAR,\nAHMEDABAD, GUJRAT\n380015"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60fba0e9d8cfc56a13fa2fa3",
  "zoneName": "PAN INDIA"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "6006d4ce5080a310ac1fdcf2",
    "role": "ADMIN",
```

```
"firstName": "Jagdish ",
"email": "jagdish.bhatt@vastukala.org",
"lastName": "Bhatt",
"mobileNo": "8425864014",
"shortName": "JB",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6006d4ce5080a310ac1fdcf2\
\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "66891578194f4629de0af6da",
"role": "SITEENGINEER",
"firstName": "Govind",
"email": "govindpande23@gmail.com",
"lastName": "Pande",
"mobileNo": "9096192041",
"designation": "Site Engg",
"shortName": "Deepak",
"workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
}
],
"type": "EMPLOYEE",
```

```
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
```

```
    }
  ]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.24562290772949",
  "longitude": "72.86065116474595"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "14/09/2024 12:37 pm"
    },
    {
      "dateTime": "14/09/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
}
```

```
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": false,
  "name": "Village",
  "key": "village",
  "value": "",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "5",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
```

```
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ami Drashti CHSL\t",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "S V Road\t",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Dahisar",
  "label": false
},
"landmark": {
```

```
"status": false,
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
```



```
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "503",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
```

```
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400068",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dahisar East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
},
```

```
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
```

```
"label": "RCC Footing/Foundation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
"label": "RCC Plinth",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
"label": "Full Building Rcc",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalBrickWork": {
"label": "Internal Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
"label": "External Brick Work",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPlastering": {
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
```



```
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66e53800eff259c8fe6f75df",
"ownerName": "Vijaya Ganesh Gurjar And ganesh U Gurjar",
"ownerPhoneNo": "9920799709",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "9920799709",
"contactPersonName": "Vijaya Ganesh Gurjar And ganesh U Gurjar",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
```

```
"name": "Vijaya Ganesh Gurjar And ganesh U Gurjar",
"phone": "9920799709",
"ownershipShare": "",
"email": "",
"id": "628098"
},
],
"caseReferredBy": "6006d4ce5080a310ac1fdcf2",
"relationWithOwner": "self",
"fullAddress": "Residential Flat No. 503, 5th Floor, Ami Drashti CHSL\t, S V Road\t,
Dahisar, Dahisar East, Mumbai, 400068, State - Maharashtra, India",
"remark": "",
"documents": [
{
"documentType": {
"value": "60ae124eaa6d152c1801b30b",
"label": "Other"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1726298088321_1707461096854_Valuation_Report_Vijaya
_Gujar_Revised_1.pdf",
"path": "cases/66e53800eff259c8fe6f75df/document_1726298088321_1707461096
854_Valuation_Report_Vijaya_Gujar_Revised_1.pdf",
"id": "985531",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Sat Sep 14 2024 12:45:12 GMT+0530 (India Standard Time)"
},
{
"documentType": {
"value": "60ae124eaa6d152c1801b30b",
"label": "Other"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1726298104861_document_1689070411121_scan_1.pdf",
"path": "cases/66e53800eff259c8fe6f75df/
document_1726298104861_document_1689070411121_scan_1.pdf",
"id": "884530",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Sat Sep 14 2024 12:45:12 GMT+0530 (India Standard Time)"
}
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": ""
```

```
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "011210",
"createdBy": "6006d4ce5080a310ac1fd2",
"caseHistory": [
  {
    "id": "179009",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Sat Sep 14 2024 12:45:12 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e7bae1eff259c8fe6fec25",
    "name":
"externalImg_1726462689733_WhatsApp_Image_20240916_at_102158_1.jpeg",
    "path": "cases/66e53800eff259c8fe6f75df/
externalImg_1726462689733_WhatsApp_Image_20240916_at_102158_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e7bae1eff259c8fe6fec26",
    "name":
"externalImg_1726462689735_WhatsApp_Image_20240916_at_102158.jpeg",
    "path": "cases/66e53800eff259c8fe6f75df/
externalImg_1726462689735_WhatsApp_Image_20240916_at_102158.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66e7bae1eff259c8fe6fec27",
  "name":
"externallmg_1726462689736_WhatsApp_Image_20240916_at_102159_1.jpeg",
  "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462689736_WhatsApp_Image_20240916_at_102159_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7bae1eff259c8fe6fec28",
  "name":
"externallmg_1726462689737_WhatsApp_Image_20240916_at_102159_2.jpeg",
  "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462689737_WhatsApp_Image_20240916_at_102159_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7bae1eff259c8fe6fec29",
  "name":
"externallmg_1726462689740_WhatsApp_Image_20240916_at_102159_3.jpeg",
  "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462689740_WhatsApp_Image_20240916_at_102159_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7bae1eff259c8fe6fec2a",
  "name":
"externallmg_1726462689743_WhatsApp_Image_20240916_at_102159.jpeg",
  "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462689743_WhatsApp_Image_20240916_at_102159.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7bae1eff259c8fe6fec2b",
  "name":
"externallmg_1726462689745_WhatsApp_Image_20240916_at_102200_1.jpeg",
  "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462689745_WhatsApp_Image_20240916_at_102200_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e7bae1eff259c8fe6fec2c",
    "name":
"externallmg_1726462689747_WhatsApp_Image_20240916_at_102200_2.jpeg",
    "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462689747_WhatsApp_Image_20240916_at_102200_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e7bae1eff259c8fe6fec2d",
    "name":
"externallmg_1726462689748_WhatsApp_Image_20240916_at_102200.jpeg",
    "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462689748_WhatsApp_Image_20240916_at_102200.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e7bae1eff259c8fe6fec2e",
    "name":
"externallmg_1726462689749_WhatsApp_Image_20240916_at_102201.jpeg",
    "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462689749_WhatsApp_Image_20240916_at_102201.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e7baf8107b3378fb9df14d",
    "name":
"externallmg_1726462712867_WhatsApp_Image_20240916_at_102204.jpeg",
    "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462712867_WhatsApp_Image_20240916_at_102204.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e7baf8107b3378fb9df14e",
```

```
    "name":
"externallmg_1726462712869_WhatsApp_Image_20240916_at_102152.jpeg",
  "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462712869_WhatsApp_Image_20240916_at_102152.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7baf8107b3378fb9df14f",
  "name":
"externallmg_1726462712870_WhatsApp_Image_20240916_at_102153_1.jpeg",
  "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462712870_WhatsApp_Image_20240916_at_102153_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7baf8107b3378fb9df150",
  "name":
"externallmg_1726462712871_WhatsApp_Image_20240916_at_102153.jpeg",
  "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462712871_WhatsApp_Image_20240916_at_102153.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7baf8107b3378fb9df151",
  "name":
"externallmg_1726462712872_WhatsApp_Image_20240916_at_102154_1.jpeg",
  "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462712872_WhatsApp_Image_20240916_at_102154_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7baf8107b3378fb9df152",
  "name":
"externallmg_1726462712873_WhatsApp_Image_20240916_at_102154_2.jpeg",
  "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462712873_WhatsApp_Image_20240916_at_102154_2.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7baf8107b3378fb9df153",
  "name":
"externallmg_1726462712874_WhatsApp_Image_20240916_at_102154_3.jpeg",
  "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462712874_WhatsApp_Image_20240916_at_102154_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7baf8107b3378fb9df154",
  "name":
"externallmg_1726462712875_WhatsApp_Image_20240916_at_102154_4.jpeg",
  "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462712875_WhatsApp_Image_20240916_at_102154_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7baf8107b3378fb9df155",
  "name":
"externallmg_1726462712876_WhatsApp_Image_20240916_at_102154.jpeg",
  "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462712876_WhatsApp_Image_20240916_at_102154.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7baf8107b3378fb9df156",
  "name":
"externallmg_1726462712877_WhatsApp_Image_20240916_at_102156_1.jpeg",
  "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462712877_WhatsApp_Image_20240916_at_102156_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7baf8107b3378fb9df157",
  "name":
"externallmg_1726462712878_WhatsApp_Image_20240916_at_102156_2.jpeg",
```

```
    "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462712878_WhatsApp_Image_20240916_at_102156_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e7baf8107b3378fb9df158",
    "name":
"externallmg_1726462712879_WhatsApp_Image_20240916_at_102156.jpeg",
    "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462712879_WhatsApp_Image_20240916_at_102156.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e7baf8107b3378fb9df159",
    "name":
"externallmg_1726462712880_WhatsApp_Image_20240916_at_102157_1.jpeg",
    "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462712880_WhatsApp_Image_20240916_at_102157_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e7baf8107b3378fb9df15a",
    "name":
"externallmg_1726462712882_WhatsApp_Image_20240916_at_102157_2.jpeg",
    "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462712882_WhatsApp_Image_20240916_at_102157_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e7baf8107b3378fb9df15b",
    "name":
"externallmg_1726462712883_WhatsApp_Image_20240916_at_102157_3.jpeg",
    "path": "cases/66e53800eff259c8fe6f75df/
externallmg_1726462712883_WhatsApp_Image_20240916_at_102157_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```

    "status": false,
    "_id": "66e7baf8107b3378fb9df15c",
    "name":
"externalImg_1726462712885_WhatsApp_Image_20240916_at_102157.jpeg",
    "path": "cases/66e53800eff259c8fe6f75df/
externalImg_1726462712885_WhatsApp_Image_20240916_at_102157.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-09-14T07:15:12.710Z",
"updatedAt": "2024-09-16T04:58:32.931Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "6006d4ce5080a310ac1fdcf2"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			