

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9f4"
    },
    "firstName": "Rohan ",
    "type": "CREDITOFFICER",
    "_id": "64d483a687258203eab0dd0f",
    "lastName": "Raut ",
    "mobileNo": "",
    "workMobileNo": "8097138369",
    "email": "Rohan.racpc.sion@sbi.co.in"
  },
  "fees": {
    "type": "agreed",
    "propertyValue": "0",
    "discussWithPerson": "Rohan ",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9f4",
  "branchCode": "000215",
  "type": "BRANCH",
  "name": "RACPC Sion ",
  "email": "racpc.sion@sbi.co.in",
  "mobileNo": "02225046265",
  "alternateMobileNo": "",
  "address": "B-603 & 604, Kohinoor City, Commercial-1, 6th Floor, Kirol Road, Off
L.B.S. Marg, Kurla (West), Mumbai, Pin Code - 400 070, State - Maharashtra, Country -
India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "63fda584ce84bf289baadaf6",
  "role": "PICKUPPERSON",
  "firstName": "Mahendra",
  "email": "mahindra.bijlaney@gmail.com",
  "lastName": "Bijlaney",
  "mobileNo": "9833016592",
  "shortName": "MB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/63fda584ce84bf289baadaf6/
profilePhoto_1677567364613_WhatsApp_Image_20230228_at_121901_PM.jpeg"
},
"deliveryPerson": {
  "type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdcf2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1720806809901_image.jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
```

```
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "62fe044a48a26047e6552796",
"role": "MAKER",
"firstName": "Pradnya ",
"email": "pradnya@vastukala.org",
"lastName": "Rasam",
"mobileNo": "9529385821",
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64cde526dc9f3034f3fefa49",
"role": "FRONTDESK",
"firstName": "Rashmi",
"email": "rashmijadhav14feb@gmail.com",
"lastName": "Jadhav",
"mobileNo": "7738144625",
"designation": "Back Office Coordination",
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
```

```
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
```

```
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.18086365594468",
  "longitude": "73.07535295342154"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.07535295342154,
    19.18086365594468
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-16",
      "remark": "value required 50 Lakhs"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-15",
      "remark": "MANUAL_IN_TASK"
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "Country - India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Usarghar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "24",
  "label": false
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "12",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane ",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kalyan ",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "My City Phase - II",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Diva Manpada Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
```



```
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Cluster 5, Part III",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "17/1, 17/2, 17/3/A, 17/3/B & others ",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
```

```
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "2402",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```

```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 421 204",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Dombivli (East)",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  }
}
```

```
    },
    "fittings": {
      "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
      "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
    },
    "finishing": {
      "value": "Proposed_Cement_Plastering",
      "label": "Proposed Cement Plastering"
    }
  },
  "general": {
    "ownership": {
      "value": "Joint_Ownership",
      "label": "Joint Ownership"
    },
    "populationClassList": {
      "value": "MiddleClass",
      "label": "Middle Class"
    },
    "populationGroupList": {
      "value": "Urban",
      "label": "Urban"
    },
    "townplanApprovedByList": {
      "value": "Mumbai_Metropolitan_Region_Development_Authority",
      "label": "Mumbai Metropolitan Region Development Authority"
    },
    "whetherCoveredUnderAnyState": {
      "value": "No",
      "label": "No"
    },
    "asPerActualAgreement": {
      "north": "Internal Road ",
      "west": "Internal Road ",
      "south": "My City Cluster 4",
      "east": "Runwal My City Road "
    },
    "asPerDocumentAgreement": {
      "north": "Details not available ",
      "west": "Details not available ",
      "south": "Details not available ",
      "east": "Details not available "
    },
    "unitBoundaries": {
```

```
"asPerActual": {
  "north": "Building is under construction ",
  "east": "Building is under construction ",
  "south": "Building is under construction ",
  "west": "Building is under construction "
},
"asPerDocument": {
  "north": "Details not available ",
  "east": "Details not available ",
  "south": "Details not available ",
  "west": "Details not available "
},
"isDisplay": true,
"title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per Sale Plan, the composition of Flat will be 2
Bedrooms + Living Room + Kitchen + 2 Toilets + Service / Utility Area. (i.e. 2BHK).",
"dateOfIssusApprovePlan": "Copy of Approved Building plans were not provided and
not verified.",
"approvePlanVerified": "N.A.",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "0",
```

```
"depreciationRatioOfBuilding": "",
"salvageValue": "",
"buildingServicesDepreciatedRate": "0",
"depreciatedCostOfConstruction": "12000.00",
"depreciatedBuildingRate": "2700"
},
"igrRate": {
  "propertyName": "Residential Flat",
  "rate": "57200",
  "landRate": "7900",
  "igrImage": "cases/66e54b14eff259c8fe6f8ffa/igr_1726483734193_Image.png",
  "squareMeterGuideLineRate": "65780.00",
  "squareFeetGuideLineRate": "6111.00"
},
"igrFinalRate": {
  "floorRatePercentage": "15",
  "depreciationPercentage": "0",
  "rate": "57200.00",
  "squareMeterGuideLineRate": "65780.00",
  "squareFeetGuideLineRate": "6111.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_is_under_construction_",
    "label": "Building is under construction "
  },
  "monthlyRent": "N.A",
  "assessmentNo": "Details not available ",
  "taxPaidHolderName": "Details not available ",
  "taxAmount": "Details not available ",
  "electricityServiceConnectionNo": "Details not available ",
  "meterCardHolderName": "Details not available ",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available ",
  "floorSpaceIndex": "As per MMRDA norms ",
  "tenantName": "",
  "maintenanceOfFlat": "Building is under construction "
},
"marketability": {
```

```
"marketabilityList": {
  "value": "Good",
  "label": "Good"
},
"anyFavouringForExtraPotentialValue": "Located in developed area ",
"negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "Proposed_R.C.C._Slab",
    "label": "Proposed R.C.C. Slab"
  },
  "partitions": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "waterTank": {
    "value": "Proposed_Municipal_Water_Supply",
    "label": "Proposed Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Proposed,_Yes",
    "label": "Proposed, Yes"
  },
  "carParking": "Proposed Open / Covered Car Parking Space ",
  "constructionWorkStatus": {
    "value": "InProgress",
    "label": "Under Construction"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "",
    "month": "1",
    "year": "2026",
    "fullDate": "1/1/2026"
  },
  "planningArea": {
    "value": "Residential",
    "label": "Residential"
  },
  "typeOfStructure": {
    "value": "Proposed_R.C.C._Framed_Structure",
    "label": "Proposed R.C.C Framed Structure"
  }
}
```

```
},
"typeOfFoundation": {
  "value": "Proposed_R.C.C._Foundation",
  "label": "Proposed R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"materialUsedList": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"buildingSpecification": {
  "value": "Information_Not_Available",
  "label": "Information Not Available"
},
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceOfTheBuilding": {
  "value": "Building_is_under_construction_",
  "label": "Building is under construction "
},
"maintenanceIssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
```



```
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"systemOfAirConditioning": {
"value": "1",
"label": "Yes"
},
"provisionOfFirefighting": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"groundStilt": {
"value": "stilt",
"label": "Stilt"
},
"yearOfConstructionAsPer": {
"value": "As_per_RERA_Certificate",
"label": "As per RERA Certificate"
},
"isSiteVisitAllowed": true,
"totalLifeBuilding": "60",
"estimatedAge": "0",
"ageOfBuilding": "0",
"noOfBasement": "",
"noOfPodium": "2",
"noOfAmenityFloors": "",
"noOfFloors": "25",
"flatFloorNo": "24",
"noOfLifts": "3",
"noOfDwellingUnitsInBuilding": "8"
},
"finalPlinthArea": {
"area": "598.40",
"areaType": "Built Up",
"measurementType": "Sq. Ft.",
"areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
"routeMapDetail": {
"routeMapImg": "cases/66e54b14eff259c8fe6f8ffa/
routeMap_1726492255635_Image.png",
"routeLat": "19.179971",
"routeLng": "73.075634",
"stationName": "Dombivli",
"routeDistance": "6.6 Km. ",
"routeStation": {
```

```
    "value": "Railway_Station",
    "label": "Railway Station"
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
    "id": "7jq5g6",
    "name": "7jq5g6",
    "image": "cases/66e54b14eff259c8fe6f8ffa/routeMap_1726492166264_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
```

```
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "6528000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "98",
"bookValue": "0",
"finalValue": "6528000.00"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Mon Sep 16 2024 18:45:43 GMT+0530 (India Standard Time)",
  "number": "2308205",
  "dayCount": "22",
  "monthCount": "211",
  "generatedBy": "64cde526dc9f3034f3fefa49"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
```

```
"floorsCompleted": "29",
"percentage": "40",
"isHideFloor": false,
"status": true
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "29",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "29",
  "percentage": "7.00",
  "isHideFloor": false,
  "status": true
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "29",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "29",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
}
```

```
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": true
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "71.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "3656822.00",
"selectedBuildUpValue": "598.40",
"selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
"frontPageImages": [
{
"status": false,
"_id": "66e7a5eaeff259c8fe6fde40",
"name": "externalImg_r_1726457319071_1726457311004_image_7.jpg",
"path": "cases/66e54b14eff259c8fe6f8ffa/
externalImg_r_1726457319071_1726457311004_image_7.jpg",
"orientation": "portrait"
}
],
"selfieWithSiteVisitImages": [],
"externalPhotos": [
{
"status": false,
"_id": "66e7a5eaeff259c8fe6fde40",
"name": "externalImg_r_1726457319071_1726457311004_image_7.jpg",
"path": "cases/66e54b14eff259c8fe6f8ffa/
externalImg_r_1726457319071_1726457311004_image_7.jpg",
"orientation": "portrait"
}
},
{
"status": false,
"_id": "66e7a5eaeff259c8fe6fde3f",
"name": "externalImg_r_1726457314356_1726457311004_image_2.jpg",
"path": "cases/66e54b14eff259c8fe6f8ffa/
externalImg_r_1726457314356_1726457311004_image_2.jpg",
"orientation": "portrait"
}
},
}
```

```
{
  "status": false,
  "_id": "66e7a5eaeff259c8fe6fde3d",
  "name": "externallmg_r_1726457315542_1726457311004_image_3.jpg",
  "path": "cases/66e54b14eff259c8fe6f8ffa/
externallmg_r_1726457315542_1726457311004_image_3.jpg",
  "orientation": "portrait"
},
{
  "status": false,
  "_id": "66e7a5eaeff259c8fe6fde41",
  "name": "externallmg_r_1726457317351_1726457311004_image_5.jpg",
  "path": "cases/66e54b14eff259c8fe6f8ffa/
externallmg_r_1726457317351_1726457311004_image_5.jpg",
  "orientation": "portrait"
}
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "10690.00",
    "max": "12872.00"
  },
  "builtUpRateRange": {
    "min": "9718.00",
    "max": "11702.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```

```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "544.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "DELIVERED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66e54b14eff259c8fe6f8ffa",
"ownerName": "Mr. Ravindra Tukaram Khalane & Mrs. Rohini Ravindra Khalane ",
"ownerPhoneNo": "9834291461",
"appAddress": "2402, CL 05-12 My city phase II,Usarghar aDombivali east, ",
"remark": "value required 50 Lakhs",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "11/09/2024",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "M/s. Horizon Projects Pvt. Ltd. ",
      "to": {
        "value": "Purchasers",
        "label": "Purchasers"
      },
      "Purchasers": "Mr. Ravindra Tukaram Khalane & Mrs. Rohini Ravindra Khalane ",
      "number": {
        "value": "No",
        "label": "No"
      }
    }
  },

```

```
    "No": "14779 / 2024"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "513068",
  "path": "cases/66e54b14eff259c8fe6f8ffa/
document_1726302938542_1726302937702_DocScanner_14Sept2024_1231_pm.pdf",
  "fileName": "document_1726302938542_1726302937702_DocScanner_14Sept202
4_1231_pm.pdf"
},
{
  "documentType": {
    "value": "60ae1279aa6d152c1801b3d4",
    "label": "Amended Commencement Certificate"
  },
  "inputs": {
    "documentDate": "08/09/2022",
    "nameOfApprovingAuthority": {
      "value": "Mumbai_Metropolitan_Region_Development_Authority",
      "label": "Mumbai Metropolitan Region Development Authority"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "SROT / Growth Centre / 2401 / BP / ITP - Usarghar & Sandap - 01 / Vol -
18 / 1188 / 2022"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1726490288276_08Sept2022CC.pdf",
  "path": "cases/66e54b14eff259c8fe6f8ffa/
document_1726490288276_08Sept2022CC.pdf",
  "id": "644238",
  "uploadedBy": "62fe044a48a26047e6552796",
  "createdAt": "Mon Sep 16 2024 18:08:08 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "08/09/2021",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
```

```
    "label": "Maharashtra Real Estate Regulatory Authority"
  },
  "number": {
    "value": "No",
    "label": "No"
  },
  "No": "P51700027171"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1726490366761_Agreement.pdf",
"path": "cases/66e54b14eff259c8fe6f8ffa/
document_1726490366761_Agreement.pdf",
"id": "882890",
"uploadedBy": "62fe044a48a26047e6552796",
"createdAt": "Mon Sep 16 2024 18:09:27 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "011215",
"createdBy": "63fda584ce84bf289baadaf6",
"caseHistory": [
  {
    "id": "165638",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Sep 14 2024 14:06:36 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Mr. Ravindra Tukaram Khalane & Mrs. Rohini Ravindra Khalane ",
    "phone": "9834291461",
    "ownershipShare": "",
    "email": "",
    "id": "432895"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "value": "60af48bf2ffdf65bcd6585fa",
```

```
    "label": "Agreement for sale"
  },
  "docMeasurementType": {
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "7111546",
  "selectAreaTypeDocument": "Carpet",
  "totalAreaDocument": "544",
  "squareMeterArea": "50.54",
  "docFinalBuiltUp": "598.4",
  "docFinalBuiltUpSquareMeter": "55.594",
  "docBuiltupPercentage": "10",
  "docSaleablePercentage": "0",
  "docFinalSaleable": "0",
  "docFinalSaleableSquareMeter": "0"
}
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "505.00",
      "squareMeterArea": "46.92",
      "expectedRate": "12871.29",
      "percentage": ""
    },
    "builtUpArea": {
      "area": "555.50",
      "squareMeterArea": "51.61",
      "expectedRate": "11701.17",
      "percentage": "10"
    },
    "saleableArea": {
      "area": "",
      "squareMeterArea": "0.00",
      "expectedRate": "0.00",
      "percentage": ""
    }
  },
  "printlnReport": true,
  "_id": "66e80d47107b3378fb9e6a7f",
  "property": "Residential Flat ",
  "area": "505",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
```

```
"areaType": "Carpet",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "6500000",
"expectedRate": "12871.29",
"builtUpExpectedRate": "11701.17",
"image": "cases/66e54b14eff259c8fe6f8ffa/indicator_1726483508312_Image.png",
"squareMeter": "46.92",
"id": "958475"
},
{
  "carpetArea": {
    "area": "486",
    "squareMeterArea": "45.15",
    "expectedRate": "11728.40",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "535.00",
    "squareMeterArea": "49.70",
    "expectedRate": "10654.21",
    "percentage": ""
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66e80d47107b3378fb9e6a80",
  "property": " Residential Flat",
  "area": "535",
  "builtUpPercentage": "0",
  "saleablePercentage": "0",
  "rateType": "price_Indicator",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Housing.Com",
  "expectedPrice": "5700000",
  "expectedRate": "11728.40",
  "builtUpExpectedRate": "5700000",
  "image": "cases/66e54b14eff259c8fe6f8ffa/indicator_1726483573076_Image.png",
  "squareMeter": "49.70",
  "id": "503489"
},
```

```
{
  "carpetArea": {
    "area": "698.00",
    "squareMeterArea": "64.85",
    "expectedRate": "10689.44",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "767.80",
    "squareMeterArea": "71.33",
    "expectedRate": "9717.67",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printInReport": true,
  "_id": "66e80d47107b3378fb9e6a81",
  "property": "Residential Flat",
  "area": "698",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "7461230",
  "expectedRate": "10689.44",
  "builtUpExpectedRate": "9717.67",
  "image": "cases/66e54b14eff259c8fe6f8ffa/indicator_1726483614301_Image.png",
  "squareMeter": "64.85",
  "id": "895329"
},
{
  "carpetArea": {
    "area": "415.00",
    "squareMeterArea": "38.55",
    "expectedRate": "10740.31",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "456.50",
    "squareMeterArea": "42.41",
```

```
    "expectedRate": "9763.91",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "66e80d47107b3378fb9e6a82",
  "property": "Residential Flat",
  "area": "415",
  "builtUpPercentage": "10",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Carpet",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "4457227",
  "expectedRate": "10740.31",
  "builtUpExpectedRate": "9763.91",
  "image": "cases/66e54b14eff259c8fe6f8ffa/indicator_1726483654201_Image.png",
  "squareMeter": "38.55",
  "id": "699514"
}
],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e7a5eaeff259c8fe6fde3b",
    "name": "externalImg_1726457312351_1726457311004_image_0.png",
    "path": "cases/66e54b14eff259c8fe6f8ffa/
externalImg_1726457312351_1726457311004_image_0.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e7a5eaeff259c8fe6fde3c",
    "name": "externalImg_r_1726457316581_1726457311004_image_4.jpg",
    "path": "cases/66e54b14eff259c8fe6f8ffa/
externalImg_r_1726457316581_1726457311004_image_4.jpg",
    "orientation": "portrait"
  },
]
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7a5eaeff259c8fe6fde3d",
  "name": "externallmg_r_1726457315542_1726457311004_image_3.jpg",
  "path": "cases/66e54b14eff259c8fe6f8ffa/
externallmg_r_1726457315542_1726457311004_image_3.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7a5eaeff259c8fe6fde3e",
  "name": "externallmg_r_1726457313393_1726457311004_image_1.jpg",
  "path": "cases/66e54b14eff259c8fe6f8ffa/
externallmg_r_1726457313393_1726457311004_image_1.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7a5eaeff259c8fe6fde3f",
  "name": "externallmg_r_1726457314356_1726457311004_image_2.jpg",
  "path": "cases/66e54b14eff259c8fe6f8ffa/
externallmg_r_1726457314356_1726457311004_image_2.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7a5eaeff259c8fe6fde40",
  "name": "externallmg_r_1726457319071_1726457311004_image_7.jpg",
  "path": "cases/66e54b14eff259c8fe6f8ffa/
externallmg_r_1726457319071_1726457311004_image_7.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66e7a5eaeff259c8fe6fde41",
  "name": "externallmg_r_1726457317351_1726457311004_image_5.jpg",
  "path": "cases/66e54b14eff259c8fe6f8ffa/
externallmg_r_1726457317351_1726457311004_image_5.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66e7a5eaef259c8fe6fde42",
    "name": "externalimg_r_1726457318300_1726457311004_image_6.jpg",
    "path": "cases/66e54b14eff259c8fe6f8ffa/
externalimg_r_1726457318300_1726457311004_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66e7a5cf107b3378fb9de0c2",
    "name": "externalimg_1726457294814_1726457294059_image_0.png",
    "path": "cases/66e54b14eff259c8fe6f8ffa/
externalimg_1726457294814_1726457294059_image_0.png",
    "orientation": "portrait"
  }
],
"externalDocuments": [
  {
    "originalname": "Ravindra Tukaram Khalane & Mrs. Rohini Ravindra Khalane.pdf",
    "filename":
"1726636345276_Ravindra_Tukaram_Khalane__Mrs_Rohini_Ravindra_Khalane.pdf",
    "path": "cases/66e54b14eff259c8fe6f8ffa/externalDocuments/1726636345276_Ravi
ndra_Tukaram_Khalane__Mrs_Rohini_Ravindra_Khalane.pdf",
    "size": "1850867",
    "documentType": {
      "value": "640ece6024088f0f94ee4ea8",
      "label": "Final PDF Report"
    },
    "createdAt": "Wed Sep 18 2024 10:42:25 GMT+0530 (India Standard Time)",
    "uploadedBy": "63f31d626f9c2254a9b39144"
  },
  {
    "originalname": "Valuation_Report_Ravindra Tukaram Khalane & Mrs. Rohini
Ravindra Khalane.pdf",
    "filename": "1726643351255_Valuation_Report_Ravindra_Tukaram_Khalane__Mrs_
Rohini_Ravindra_Khalane.pdf",
    "path": "cases/66e54b14eff259c8fe6f8ffa/externalDocuments/1726643351255_Valu
ation_Report_Ravindra_Tukaram_Khalane__Mrs_Rohini_Ravindra_Khalane.pdf",
    "size": "2312546",
    "documentType": {
      "value": "640ece6024088f0f94ee4ea8",
      "label": "Final PDF Report"
    },
    "createdAt": "Wed Sep 18 2024 12:39:11 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "63f31d626f9c2254a9b39144"
},
{
  "path": "../CDN/cases/66e54b14eff259c8fe6f8ffa/
externalDocuments/1726911196778_428927.pdf",
  "filename": "1726911196778_428927.pdf",
  "documentType": {
    "organization": {
      "status": true,
      "isdelete": false,
      "_id": "5f2bdee67813470eb443deb4",
      "name": "Vastukala Consultants India Pvt. Ltd.",
      "gstNo": "18AABCT3518Q1ZZ",
      "panNo": "ABCDE1234A",
      "email": "vastukalamumbai@vastukala.com",
      "phone": "9819670183",
      "address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E),
Mumbai - 400 093",
      "shortName": "VCIPL",
      "type": "ORGANIZATION",
      "city": "Mumbai",
      "ownerEmail": "umang@vastukala.org",
      "ownerName": "Umang Patel"
    },
    "_id": "60ae124daa6d152c1801b307",
    "document": {
      "documentType": "Office Copy",
      "documentDate": true,
      "to": false,
      "from": false,
      "amount": false,
      "nameOfApprovingAuthority": false,
      "number": false,
      "remarks": true,
      "caseStatus": {
        "value": "DELIVERED",
        "label": "Delivered"
      }
    }
  },
  "createdAt": "2021-05-26T09:18:05.809Z",
  "updatedAt": "2023-06-20T10:17:50.158Z",
  "__v": 0,
  "label": "Office Copy",
  "value": "60ae124daa6d152c1801b307",
  "Name": "Office Copy",
  "Value": "60ae124daa6d152c1801b307",
```

```
    "caseStatus": {
      "value": "DELIVERED",
      "label": "Delivered"
    }
  },
  "createdAt": "Sat Sep 21 2024 15:03:16 GMT+0530 (India Standard Time)",
  "uploadedBy": "60b7177d2ffdf65bcd65882a"
}
],
"processingDocuments": [
  {
    "originalname": "Calculation Sheet NEW.xlsx",
    "filename": "1726483760798_Calculation_Sheet_NEW.xlsx",
    "path": "cases/66e54b14eff259c8fe6f8ffa/
processingDocuments/1726483760798_Calculation_Sheet_NEW.xlsx",
    "size": "1821154",
    "createdAt": "Mon Sep 16 2024 16:19:21 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  },
  {
    "originalname": "Final report - SBI - Ms. Savita Suraj Yadav.pdf",
    "filename": "1726483760829_Final_report__SBI__Ms_Savita_Suraj_Yadav.pdf",
    "path": "cases/66e54b14eff259c8fe6f8ffa/processingDocuments/1726483760829_Final_report__SBI__Ms_Savita_Suraj_Yadav.pdf",
    "size": "11940029",
    "createdAt": "Mon Sep 16 2024 16:19:21 GMT+0530 (India Standard Time)",
    "uploadedBy": "64cde526dc9f3034f3fefa49"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64cde526dc9f3034f3fefa49",
      "role": "FRONTDESK",
      "firstName": "Rashmi",
      "lastName": "Jadhav",
      "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "66e7f967eff259c8fe703f39",
    "note": "Value given for confirmation ",
  }
]
```

```
"taskId": "66e54d4fa1f1577e0b252649",
"createdAt": "2024-09-16T09:24:55.647Z"
},
{
  "createdBy": {
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "lastName": "Jadhav",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "workType": "CHECKER",
  "display": true,
  "status": true,
  "_id": "66f24bd22d094ed1370a02c8",
  "note": "RV change (Task Reopen)",
  "taskId": "66e82ef3eff259c8fe70964d",
  "createdAt": "2024-09-24T05:19:14.446Z"
},
{
  "createdBy": {
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "lastName": "Jadhav",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "workType": "SIGNED_REPORT_UPLOAD",
  "display": true,
  "status": true,
  "_id": "66f24bda2d094ed1370a02ff",
  "note": "RV change (Task Reopen)",
  "taskId": "66ea5f3ceff259c8fe70be1a",
  "createdAt": "2024-09-24T05:19:22.537Z"
},
{
  "createdBy": {
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "lastName": "Jadhav",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
}
```

```
"workType": "PRINT",
"display": true,
"status": true,
"_id": "66f24be22d094ed1370a034a",
"note": "RV change (Task Reopen)",
"taskId": "66ea5d3aeff259c8fe70bc12",
"createdAt": "2024-09-24T05:19:30.811Z"
}
],
"createdAt": "2024-09-14T08:36:36.916Z",
"updatedAt": "2024-09-24T05:20:25.598Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 2402, 24th Floor, Building No 12, My City Phase -
II, Cluster 5, Part III, Diva Manpada Road, Village - Usarghar, Dombivli (East), Taluka -
Kalyan , District - Thane , PIN - 421 204, State - Maharashtra, Country - India",
"updatedBy": "64cde526dc9f3034f3fefa49",
"addressForMap": "",
"caseReferredBy": "63fda584ce84bf289baadaf6",
"contactPersonName": "Miss. Kajal Mishra ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Customer Relationship Manager",
"siteVisitContactNo": "8097499903",
"buildingServicesRate": "2700",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement for sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 544.00",
"flatRate": "12000",
"landOtherRate": "9300",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  }
},
"roadFacing": false,
```

```

    "mall": false
  },
  "builtupPercentage": "10",
  "carpetTotal": "0",
  "extendOfSiteRemark": "Carpet Area in Sq. Ft. = 511.00\nUtility / Service Area in Sq.
Ft. = 33.00\n\n",
  "finalBuiltupArea": "0.00",
  "finalCarpetArea": "0.00",
  "finalSalableArea": "0.00",
  "otherCarpetTotal": "0",
  "salablePercentage": "10",
  "siteMeasurementRemark": "",
  "toBeAdded": "",
  "finalSaleablePercentage": "0",
  "landDetails": {
    "holdType": {
      "label": "Free Hold",
      "value": "Free_Hold"
    },
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Mon Sep 16 2024 17:52:40 GMT+0530 (India Standard
Time)",
"siteVisitDate": "2024-09-15"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			