

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b9ff"
    },
    "firstName": "Nikita",
    "type": "CREDITOFFICER",
    "_id": "65d31e0addc2ef120ed2adb1",
    "lastName": "Jagtap",
    "mobileNo": "",
    "workMobileNo": "7304948055",
    "email": "8cord.21117@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "3950000",
    "discussWithPerson": "Nikita",
    "expectedFees": 1975,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b9ff",
  "branchCode": "000220",
  "type": "BRANCH",
  "name": "RASMECCC Panvel",
  "email": "cord.21117@sbi.co.in",
  "mobileNo": "02227572748",
  "alternateMobileNo": "",
  "address": "Shop No 5,Ground Floor,Sharda Terrace, Plot No 65,Sector-11,CBD
Belapur, Navi Mumbai, Taluka & District - Thane, State - Maharashtra, Country - India",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7189d2ffdf65bcd65882b",
  "role": "PICKUPPERSON",
  "firstName": "Ravindra",
  "email": "ravindrakasare186@gmail.com",
  "lastName": "Kasare",
  "mobileNo": "9167204055",
  "shortName": "RBK",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60b7189d2ffdf65bcd65882b\\
\\profilePhoto_1622701555488_WhatsApp Image 2021-06-03 at 11.46.40 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "63fc4680ce84bf289ba9c7fc",
  "role": "SITEENGINEER",
  "firstName": "Nikhil ",
  "email": "valtechnical2022@gmail.com",
  "lastName": "Sonawane",
  "mobileNo": "9819470709",
  "designation": "",
  "shortName": "NS",
  "workWithDocumentMaker": "6006d4ce5080a310ac1fdfc2",
  "profilePhoto": "users/63fc4680ce84bf289ba9c7fc/
profilePhoto_1720806809901_image.jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
```

```
    "value": "IBBI/RV/07/2018/10366",
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.229326765335294",
  "longitude": "73.09461021846799"
},
"geo": {
  "type": "Point",
  "coordinates": [
    73.09461021846799,
    19.229326765335294
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "19/09/2024 02:47 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Chole",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "2",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
```

```
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Pandurang Tower CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
}
```

```
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```



```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "203",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
```

```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
```

```
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
    },
    "builtUpRateRange": {
      "min": "0.00",
      "max": "0.00"
    },
    "saleableRateRange": {
      "min": "0.00",
      "max": "0.00"
    }
  },
  "detailsOfValuation": {
    "presentValueOfFlat": {
      "title": "Present value of the flat (incl. car parking, if provided)",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": false
    },
    "wardrobes": {
      "title": "Wardrobes",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "showcases": {
      "title": "Showcases",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "kitchenArrangements": {
      "title": "Kitchen arrangements",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "superfineFinish": {
      "title": "Superfine finish",
      "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```



```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66ebd5b3a1f1577e0b27cc18",
"ownerName": "Girish Sadanand Salunkhe And Vaibhavi Girish Salunkhe",
"ownerPhoneNo": "9702407333",
"appAddress": "flat no .203 2 nd floor A wing pandurang tower co .op housing society
Ltd chole Dombivli ",
"remark": "SSL pinky madam ",
"documents": [
  {
```

```
"documentType": {
  "label": "Index - II",
  "value": "60ae1287aa6d152c1801b415"
},
"isHardCopy": false,
"displayStatus": false,
"path": "cases/66ebd5b3a1f1577e0b27cc18/document_1726731695071_1726731692147_index__Girish_salunke_sbi_Rasmeec_panvel.pdf",
"fileName": "document_1726731695071_1726731692147_index__Girish_salunke_sbi_Rasmeec_panvel.pdf",
"id": "606193",
"uploadedBy": "60b7189d2ffdf65bcd65882b",
"createdAt": "Thu Sep 19 2024 13:11:39 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "011286",
"createdBy": "60b7189d2ffdf65bcd65882b",
"caseHistory": [
  {
    "id": "529270",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Sep 19 2024 13:11:39 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "Girish Sadanand Salunkhe And Vaibhavi Girish Salunkhe",
    "phone": "9702407333",
    "ownershipShare": "",
    "email": "",
    "id": "252220"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
  }
]
```

```
    "_id": "66ed1ffe364a0f4dac129a17",
    "name": "externallmg_r_1726816246341_1726816245459_image_0.jpg",
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816246341_1726816245459_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed2034ada7094de4932048",
    "name": "externallmg_1726816265151_1726816259246_image_1.png",
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_1726816265151_1726816259246_image_1.png",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed2034ada7094de4932049",
    "name": "externallmg_r_1726816270031_1726816259246_image_4.jpg",
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816270031_1726816259246_image_4.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed2034ada7094de493204a",
    "name": "externallmg_r_1726816267972_1726816259246_image_3.jpg",
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816267972_1726816259246_image_3.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed2034ada7094de493204b",
    "name": "externallmg_r_1726816265606_1726816259246_image_2.jpg",
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816265606_1726816259246_image_2.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed2034ada7094de493204c",
```

```
    "name": "externallmg_r_1726816262752_1726816259246_image_0.jpg",
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816262752_1726816259246_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed2034ada7094de493204d",
    "name": "externallmg_r_1726816276207_1726816259246_image_7.jpg",
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816276207_1726816259246_image_7.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed2034ada7094de493204e",
    "name": "externallmg_r_1726816274012_1726816259246_image_6.jpg",
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816274012_1726816259246_image_6.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed2034ada7094de493204f",
    "name": "externallmg_r_1726816272007_1726816259246_image_5.jpg",
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816272007_1726816259246_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed2034ada7094de4932050",
    "name": "externallmg_r_1726816281007_1726816259246_image_9.jpg",
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816281007_1726816259246_image_9.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed2034ada7094de4932051",
    "name": "externallmg_r_1726816283452_1726816259246_image_10.jpg",
```

```
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816283452_1726816259246_image_10.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed2034ada7094de4932052",
    "name": "externallmg_r_1726816278056_1726816259246_image_8.jpg",
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816278056_1726816259246_image_8.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed2034ada7094de4932053",
    "name": "externallmg_r_1726816286152_1726816259246_image_11.jpg",
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816286152_1726816259246_image_11.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed2034ada7094de4932054",
    "name": "externallmg_r_1726816291276_1726816259246_image_13.jpg",
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816291276_1726816259246_image_13.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed2034ada7094de4932055",
    "name": "externallmg_r_1726816288746_1726816259246_image_12.jpg",
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816288746_1726816259246_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66ed2034ada7094de4932056",
    "name": "externallmg_r_1726816296532_1726816259246_image_15.jpg",
    "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816296532_1726816259246_image_15.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ed2034ada7094de4932057",
  "name": "externallmg_r_1726816301331_1726816259246_image_17.jpg",
  "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816301331_1726816259246_image_17.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ed2034ada7094de4932058",
  "name": "externallmg_r_1726816298922_1726816259246_image_16.jpg",
  "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816298922_1726816259246_image_16.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ed2034ada7094de4932059",
  "name": "externallmg_r_1726816293161_1726816259246_image_14.jpg",
  "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816293161_1726816259246_image_14.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ed2034ada7094de493205a",
  "name": "externallmg_r_1726816303312_1726816259246_image_18.jpg",
  "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816303312_1726816259246_image_18.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66ed2034ada7094de493205b",
  "name": "externallmg_r_1726816305547_1726816259246_image_19.jpg",
  "path": "cases/66ebd5b3a1f1577e0b27cc18/
externallmg_r_1726816305547_1726816259246_image_19.jpg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66ed2057ada7094de493210e",
      "name": "externalImg_r_1726816341357_1726816332599_image_2.jpg",
      "path": "cases/66ebd5b3a1f1577e0b27cc18/
externalImg_r_1726816341357_1726816332599_image_2.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66ed2057ada7094de493210f",
      "name": "externalImg_r_1726816337542_1726816332599_image_1.jpg",
      "path": "cases/66ebd5b3a1f1577e0b27cc18/
externalImg_r_1726816337542_1726816332599_image_1.jpg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66ed2057ada7094de4932110",
      "name": "externalImg_r_1726816333947_1726816332599_image_0.jpg",
      "path": "cases/66ebd5b3a1f1577e0b27cc18/
externalImg_r_1726816333947_1726816332599_image_0.jpg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [
    {
      "createdBy": {
        "_id": "64cde526dc9f3034f3fefa49",
        "role": "FRONTDESK",
        "firstName": "Rashmi",
        "lastName": "Jadhav",
        "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
      },
      "workType": "RATE_VERIFY",
      "display": true,
      "status": true,
    }
  ]
}
```

```

    "_id": "66ec1a34ada7094de492b461",
    "note": "Required OC ",
    "taskId": "66ebec32eff259c8fe71d0e3",
    "createdAt": "2024-09-19T12:33:56.313Z"
  }
],
"createdAt": "2024-09-19T07:41:39.532Z",
"updatedAt": "2024-09-20T07:12:23.460Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 203, 2nd Floor, Wing - A, Pandurang Tower CHSL,
Village - Chole",
"updatedBy": "63fc4680ce84bf289ba9c7fc",
"addressForMap": "",
"caseReferredBy": "60b7189d2ffdf65bcd65882b",
"contactPersonName": "Girish Sadanand Salunkhe And Vaibhavi Girish Salunkhe",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9702407333"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			