

```
{
  "typeOfReport": {
    "value": "Land_and_Building",
    "label": "Land and Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Court_Purpose",
    "label": "Court Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "66ed44ddb9ce4dabceedaf"
    },
    "firstName": "Shraddha",
    "type": "CREDITOFFICER",
    "_id": "66ed457cbdd9ce4dabceef03",
    "email": "shraddha.mehta@newindiabank.in",
    "lastName": "Mehta",
    "mobileNo": "",
    "workMobileNo": "0226626419"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "66ed41dc364a0f4dac12cd98",
  "type": "BANK",
  "name": "New India Co Operative Bank Ltd ",
  "displayName": "New India Co Operative Bank Ltd ",
  "initial": "NIB"
},
"branch": {
  "_id": "66ed44ddb9ce4dabceedaf",
  "name": "Administrative office",
  "branchCode": "",
  "mobileNo": "02266264150",
  "alternateMobileNo": "",
  "email": "kalpana.mangarsi@newindiabank.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mahesh Residency, Tandice Building, M G Road, Dahanukar Wadi,
Kandiwali West Mumbai 400067"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "66ed441cbdd9ce4dabceea41",
  "zoneName": "MUMBAI"
},
"staff": {
  "pickupPerson": null,
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
```

```
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\
\profilePhoto_1622114310919_Manoj C.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "17.509333969999496",
  "longitude": "75.25248610828854"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Manjari",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Solapur",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Sangola",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
```

```
"status": false,
"name": "Building Name",
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Sangola- Pandharpur Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```

```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```



```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "413317",
  "label": false
}
```

```
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
```

```
"routeMapImg": "",
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```



```
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66f26b192d094ed1370a4335",
"ownerName": "AYUSH PAPER MILLS",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": "",
"siteVisitContactNo": "0000000000",
"contactPersonName": "AYUSH PAPER MILLS",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "AYUSH PAPER MILLS",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "428294"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "self",
"fullAddress": "Industrial Land and Building No. Ground Floor, Sangola- Pandharpur
Road, Village - Manjari, Taluka - Sangola, District - Solapur, 413317, State -
Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    }
  }
]
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1727163114445_FIRST_Ayush_Paper_Mills_Search_Report_Final01_1.pdf",
    "path": "cases/66f26b192d094ed1370a4335/document_1727163114445_FIRST_Ayush_Paper_Mills_Search_Report_Final01_1.pdf",
    "id": "980614",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Tue Sep 24 2024 13:02:41 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1727163124234_FIRST_Ayush_Paper_Mills_Valuation_Report_1.pdf",
    "path": "cases/66f26b192d094ed1370a4335/document_1727163124234_FIRST_Ayush_Paper_Mills_Valuation_Report_1.pdf",
    "id": "908066",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Tue Sep 24 2024 13:02:41 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1727163135768_FIRST_Shridhan_Valuation_Report_1.pdf",
    "path": "cases/66f26b192d094ed1370a4335/document_1727163135768_FIRST_Shridhan_Valuation_Report_1.pdf",
    "id": "719359",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Tue Sep 24 2024 13:02:41 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    }
  },
}
```

```
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1727163149431_Revised_Final_Project_Report_Ayush_Pa
per_40TPD.pdf",
"path": "cases/66f26b192d094ed1370a4335/
document_1727163149431_Revised_Final_Project_Report_Ayush_Paper_40TPD.pdf",
"id": "289781",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Tue Sep 24 2024 13:02:41 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1727163159606_TV_REPORT_15TPD_AYUSH_PAPER_MILLS.pdf",
  "path": "cases/66f26b192d094ed1370a4335/
document_1727163159606_TV_REPORT_15TPD_AYUSH_PAPER_MILLS.pdf",
  "id": "315755",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Tue Sep 24 2024 13:02:41 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1727179604550_AYUSH_PURCHASE_DEED_.pdf",
  "path": "cases/66f26b192d094ed1370a4335/
document_1727179604550_AYUSH_PURCHASE_DEED_.pdf",
  "id": "417869",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Tue Sep 24 2024 17:37:43 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
```

```
"fileName": "document_1727179614808_33_KV_LINE_QUOTATION.pdf",
"path": "cases/66f26b192d094ed1370a4335/
document_1727179614808_33_KV_LINE_QUOTATION.pdf",
"id": "725477",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Tue Sep 24 2024 17:37:43 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1727179624267_AYUSH_PAPER_MILLS_MPCB_CERTIFICATE.pdf",
  "path": "cases/66f26b192d094ed1370a4335/
document_1727179624267_AYUSH_PAPER_MILLS_MPCB_CERTIFICATE.pdf",
  "id": "628463",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Tue Sep 24 2024 17:37:43 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1727179634060_Grampanchyat__Noc_Ayush_Paper_Mills.pdf",
  "path": "cases/66f26b192d094ed1370a4335/
document_1727179634060_Grampanchyat__Noc_Ayush_Paper_Mills.pdf",
  "id": "268901",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Tue Sep 24 2024 17:37:43 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1727179644112_GRAMPANCHYAT_BANDKAM_PLAN.pdf",
  "path": "cases/66f26b192d094ed1370a4335/
document_1727179644112_GRAMPANCHYAT_BANDKAM_PLAN.pdf",
```

```
    "id": "661527",
    "uploadedBy": "6006d4ce5080a310ac1fdfc2",
    "createdAt": "Tue Sep 24 2024 17:37:43 GMT+0530 (India Standard Time)"
  }
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "011434",
"createdBy": "6006d4ce5080a310ac1fdfc2",
"caseHistory": [
  {
    "id": "333916",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Tue Sep 24 2024 13:02:41 GMT+0530 (India Standard Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65115fcad932b0b155c35",
    "name": "externalimg_r_1727418638292_1727418634424_image_1.jpg",
    "path": "cases/66f26b192d094ed1370a4335/externalimg_r_1727418638292_1727418634424_image_1.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65115fcad932b0b155c36",
    "name": "externalimg_r_1727418638436_1727418634424_image_2.jpg",
```

```
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418638436_1727418634424_image_2.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65115fcad932b0b155c37",
    "name": "externallmg_r_1727418638599_1727418634424_image_3.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418638599_1727418634424_image_3.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65115fcad932b0b155c38",
    "name": "externallmg_r_1727418638020_1727418634424_image_0.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418638020_1727418634424_image_0.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65115fcad932b0b155c39",
    "name": "externallmg_r_1727418639304_1727418634424_image_5.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418639304_1727418634424_image_5.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65115fcad932b0b155c3a",
    "name": "externallmg_r_1727418639499_1727418634424_image_6.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418639499_1727418634424_image_6.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f65115fcad932b0b155c3b",
    "name": "externallmg_r_1727418641446_1727418634424_image_9.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418641446_1727418634424_image_9.jpg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f65115fcad932b0b155c3c",
  "name": "externallmg_r_1727418639220_1727418634424_image_4.jpg",
  "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418639220_1727418634424_image_4.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f65115fcad932b0b155c3d",
  "name": "externallmg_r_1727418640596_1727418634424_image_7.jpg",
  "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418640596_1727418634424_image_7.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f65115fcad932b0b155c3e",
  "name": "externallmg_r_1727418641221_1727418634424_image_8.jpg",
  "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418641221_1727418634424_image_8.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f65115fcad932b0b155c3f",
  "name": "externallmg_r_1727418641755_1727418634424_image_11.jpg",
  "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418641755_1727418634424_image_11.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f65115fcad932b0b155c40",
  "name": "externallmg_r_1727418642029_1727418634424_image_12.jpg",
  "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418642029_1727418634424_image_12.jpg",
  "orientation": "landscape"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66f65115fcad932b0b155c41",
      "name": "externallmg_r_1727418641523_1727418634424_image_10.jpg",
      "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418641523_1727418634424_image_10.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66f65115fcad932b0b155c42",
      "name": "externallmg_r_1727418642352_1727418634424_image_13.jpg",
      "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418642352_1727418634424_image_13.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66f65115fcad932b0b155c43",
      "name": "externallmg_r_1727418642489_1727418634424_image_14.jpg",
      "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418642489_1727418634424_image_14.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66f65115fcad932b0b155c44",
      "name": "externallmg_r_1727418642675_1727418634424_image_15.jpg",
      "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418642675_1727418634424_image_15.jpg",
      "orientation": "landscape"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "66f65115fcad932b0b155c45",
      "name": "externallmg_r_1727418642923_1727418634424_image_16.jpg",
      "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418642923_1727418634424_image_16.jpg",
      "orientation": "landscape"
    },
  },
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f65115fcad932b0b155c46",
  "name": "externallmg_r_1727418643145_1727418634424_image_17.jpg",
  "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418643145_1727418634424_image_17.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f65115fcad932b0b155c47",
  "name": "externallmg_r_1727418643407_1727418634424_image_18.jpg",
  "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418643407_1727418634424_image_18.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f65115fcad932b0b155c48",
  "name": "externallmg_r_1727418643764_1727418634424_image_19.jpg",
  "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418643764_1727418634424_image_19.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f6517a0e53f82b0c6110cc",
  "name": "externallmg_r_1727418736203_1727418732820_image_0.jpg",
  "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418736203_1727418732820_image_0.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f6517a0e53f82b0c6110cd",
  "name": "externallmg_r_1727418736920_1727418732820_image_2.jpg",
  "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418736920_1727418732820_image_2.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6517a0e53f82b0c6110ce",
    "name": "externallmg_r_1727418736544_1727418732820_image_1.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418736544_1727418732820_image_1.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6517a0e53f82b0c6110cf",
    "name": "externallmg_r_1727418737287_1727418732820_image_3.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418737287_1727418732820_image_3.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6517a0e53f82b0c6110d0",
    "name": "externallmg_r_1727418738189_1727418732820_image_4.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418738189_1727418732820_image_4.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6517a0e53f82b0c6110d1",
    "name": "externallmg_r_1727418738557_1727418732820_image_5.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418738557_1727418732820_image_5.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6517a0e53f82b0c6110d2",
    "name": "externallmg_r_1727418739168_1727418732820_image_6.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418739168_1727418732820_image_6.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66f6517a0e53f82b0c6110d3",
  "name": "externalimg_r_1727418739995_1727418732820_image_7.jpg",
  "path": "cases/66f26b192d094ed1370a4335/
externalimg_r_1727418739995_1727418732820_image_7.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f6517a0e53f82b0c6110d4",
  "name": "externalimg_r_1727418740691_1727418732820_image_8.jpg",
  "path": "cases/66f26b192d094ed1370a4335/
externalimg_r_1727418740691_1727418732820_image_8.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f6517a0e53f82b0c6110d5",
  "name": "externalimg_r_1727418742474_1727418732820_image_11.jpg",
  "path": "cases/66f26b192d094ed1370a4335/
externalimg_r_1727418742474_1727418732820_image_11.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f6517a0e53f82b0c6110d6",
  "name": "externalimg_r_1727418741929_1727418732820_image_10.jpg",
  "path": "cases/66f26b192d094ed1370a4335/
externalimg_r_1727418741929_1727418732820_image_10.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f6517a0e53f82b0c6110d7",
  "name": "externalimg_r_1727418743204_1727418732820_image_13.jpg",
  "path": "cases/66f26b192d094ed1370a4335/
externalimg_r_1727418743204_1727418732820_image_13.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "66f6517a0e53f82b0c6110d8",
    "name": "externallmg_r_1727418743462_1727418732820_image_14.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418743462_1727418732820_image_14.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6517a0e53f82b0c6110d9",
    "name": "externallmg_r_1727418742849_1727418732820_image_12.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418742849_1727418732820_image_12.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6517a0e53f82b0c6110da",
    "name": "externallmg_r_1727418741565_1727418732820_image_9.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418741565_1727418732820_image_9.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6517a0e53f82b0c6110db",
    "name": "externallmg_r_1727418744162_1727418732820_image_16.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418744162_1727418732820_image_16.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6517a0e53f82b0c6110dc",
    "name": "externallmg_r_1727418743700_1727418732820_image_15.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418743700_1727418732820_image_15.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6517a0e53f82b0c6110dd",
```

```
    "name": "externallmg_r_1727418744975_1727418732820_image_19.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418744975_1727418732820_image_19.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6517a0e53f82b0c6110de",
    "name": "externallmg_r_1727418744370_1727418732820_image_17.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418744370_1727418732820_image_17.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6517a0e53f82b0c6110df",
    "name": "externallmg_r_1727418744621_1727418732820_image_18.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418744621_1727418732820_image_18.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6519d0e53f82b0c611125",
    "name": "externallmg_r_1727418779711_1727418778277_image_1.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418779711_1727418778277_image_1.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6519d0e53f82b0c611126",
    "name": "externallmg_r_1727418779909_1727418778277_image_2.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418779909_1727418778277_image_2.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6519d0e53f82b0c611127",
    "name": "externallmg_r_1727418780287_1727418778277_image_3.jpg",
```

```
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418780287_1727418778277_image_3.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6519d0e53f82b0c611128",
    "name": "externallmg_r_1727418780474_1727418778277_image_4.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418780474_1727418778277_image_4.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6519d0e53f82b0c611129",
    "name": "externallmg_r_1727418779470_1727418778277_image_0.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418779470_1727418778277_image_0.jpg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f651e20e53f82b0c611180",
    "name": "externallmg_r_1727418850168_1727418836259_image_0.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418850168_1727418836259_image_0.jpg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "66f651e20e53f82b0c611181",
    "name": "externallmg_r_1727418850310_1727418848601_image_0.jpg",
    "path": "cases/66f26b192d094ed1370a4335/
externallmg_r_1727418850310_1727418848601_image_0.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
```

"createdAt": "2024-09-24T07:32:41.311Z",
"updatedAt": "2024-09-27T06:34:10.620Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "5ffe92d27737ca4d986b6453"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			