

```
{
  "typeOfReport": {
    "value": "Project_Finance",
    "label": "Project Finance"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Project_Valuation",
    "label": "Project Valuation"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "firstName": "Manish",
    "type": "CREDITOFFICER",
    "_id": "64338d21d267175d008119f1",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "9049983319",
    "email": "manish.jha9@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "35000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "MAKER",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
  "lastName": "chavan",
  "mobileNo": "8390804382",
  "designation": "Site Engineer",
  "shortName": "BH",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
```

```
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "IBBI"
      },
      {
        "value": "AM161706-3",
        "label": "Chartered Engineer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.10657660147576",
  "longitude": "72.8432158571695"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-09-27",
      "remark": ""
    }
  ],
  "schedule": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Navpada",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "11",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai Suburban",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Vile Parle (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "50",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shanti Sadan",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Dadabhai Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```



```
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Shanti Sadan",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "TPS Vile Parle No. VI (1st Variation) (Final)",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400056",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
}
```

```
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
```



```
"title": "Electricity deposits / electrical fittings, etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
```

```
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66f64950fcad932b0b154f69",
"ownerName": "M/s. Shree Hans Realtors LLP ",
"ownerPhoneNo": "9820343346",
"fullAddress": "Residential Project Finance No. 11th Floor, Shanti Sadan, Shanti
Sadan, Plot No. 50, Dadabhai Road, Village - Navpada, Municipality Ward No. TPS Vile
Parle No. VI (1st Variation) (Final), District - Mumbai Suburban, Vile Parle (West),
400056",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    }
  },
  "inputs": {
    "documentDate": "31/05/2024",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    }
  },
  "number": {
    "value": "Document_No",
```

```
    "label": "Document No"
  },
  "Document_No": "P51800056441"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1727416651038_P51800056441.pdf",
"path": "cases/66f64950fcad932b0b154f69/
document_1727416651038_P51800056441.pdf",
"id": "679692",
"uploadedBy": "60f91822f3dd69653a5922e3",
"createdAt": "Fri Sep 27 2024 11:27:36 GMT+0530 (India Standard Time)"
}
],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "011510",
"createdBy": "60f91822f3dd69653a5922e3",
"caseHistory": [
  {
    "id": "687621",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Sep 27 2024 11:27:36 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "M/s. Shree Hans Realtors LLP ",
    "phone": "9820343346",
    "ownershipShare": "",
    "email": "",
    "id": "481132"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f650020e53f82b0c610d40",
  "name":
"externallmg_1727418370885_WhatsApp_Image_20240927_at_114454_AM.jpeg",
  "path": "cases/66f64950fcad932b0b154f69/
externallmg_1727418370885_WhatsApp_Image_20240927_at_114454_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f6725afcad932b0b15939c",
  "name": "externallmg_1727427157844_externallmg_1727417123052_17274171025
51_image_0.jpeg",
  "path": "cases/66f64950fcad932b0b154f69/externallmg_1727427157844_externall
mg_1727417123052_1727417102551_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f6725afcad932b0b15939d",
  "name": "externallmg_1727427157859_externallmg_1727417123072_17274171025
51_image_1.jpeg",
  "path": "cases/66f64950fcad932b0b154f69/externallmg_1727427157859_externall
mg_1727417123072_1727417102551_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f6725afcad932b0b15939e",
  "name": "externallmg_1727427158466_externallmg_1727417123739_17274171025
51_image_2.jpeg",
  "path": "cases/66f64950fcad932b0b154f69/externallmg_1727427158466_externall
mg_1727417123739_1727417102551_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f6725afcad932b0b15939f",
  "name": "externallmg_1727427159040_externallmg_1727417124280_17274171025
51_image_3.jpeg",
```

```
    "path": "cases/66f64950fcad932b0b154f69/externallmg_1727427159040_externallmg_1727417124280_1727417102551_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6725afcad932b0b1593a0",
    "name": "externallmg_1727427159563_externallmg_1727417124809_1727417102551_image_4.jpeg",
    "path": "cases/66f64950fcad932b0b154f69/externallmg_1727427159563_externallmg_1727417124809_1727417102551_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6725afcad932b0b1593a1",
    "name": "externallmg_1727427160206_externallmg_1727417125458_1727417102551_image_5.jpeg",
    "path": "cases/66f64950fcad932b0b154f69/externallmg_1727427160206_externallmg_1727417125458_1727417102551_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6725afcad932b0b1593a2",
    "name": "externallmg_1727427160563_externallmg_1727417128204_1727417120474_image_0.jpeg",
    "path": "cases/66f64950fcad932b0b154f69/externallmg_1727427160563_externallmg_1727417128204_1727417120474_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f6725afcad932b0b1593a3",
    "name": "externallmg_1727427161141_externallmg_1727417128833_1727417120474_image_1.jpeg",
    "path": "cases/66f64950fcad932b0b154f69/externallmg_1727427161141_externallmg_1727417128833_1727417120474_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "66f6725afcad932b0b1593a4",
  "name": "externalimg_1727427161647_externalimg_1727417129394_1727417120474_image_2.jpeg",
  "path": "cases/66f64950fcad932b0b154f69/externalimg_1727427161647_externalimg_1727417129394_1727417120474_image_2.jpeg",
  "orientation": "landscape"
},
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Shanti Sadan.xlsx",
    "filename": "1727427015217_Shanti_Sadan.xlsx",
    "path": "cases/66f64950fcad932b0b154f69/processingDocuments/1727427015217_Shanti_Sadan.xlsx",
    "size": "3391266",
    "createdAt": "Fri Sep 27 2024 14:20:15 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "101 Ajay Shah & Nandani Shah.pdf",
    "filename": "1727427030035_101_Ajay_Shah__Nandani_Shah.pdf",
    "path": "cases/66f64950fcad932b0b154f69/processingDocuments/1727427030035_101_Ajay_Shah__Nandani_Shah.pdf",
    "size": "31933099",
    "createdAt": "Fri Sep 27 2024 14:20:50 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "102 Ankit Thakkar.pdf",
    "filename": "1727427032737_102_Ankit_Thakkar.pdf",
    "path": "cases/66f64950fcad932b0b154f69/processingDocuments/1727427032737_102_Ankit_Thakkar.pdf",
    "size": "30031564",
    "createdAt": "Fri Sep 27 2024 14:20:50 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "103 Sarla Thakkar_0001.pdf",
    "filename": "1727427035271_103_Sarla_Thakkar_0001.pdf",
    "path": "cases/66f64950fcad932b0b154f69/processingDocuments/1727427035271_103_Sarla_Thakkar_0001.pdf",
    "size": "33642985",
    "createdAt": "Fri Sep 27 2024 14:20:50 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  }
]
```

```
},
{
  "originalname": "201 Surangi Jadav.pdf",
  "filename": "1727427038110_201_Surangi_Jadav.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427038110_201_Surangi_Jadav.pdf",
  "size": "30650414",
  "createdAt": "Fri Sep 27 2024 14:20:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "401 Naresh H. Goradia.pdf",
  "filename": "1727427040697_401_Naresh_H_Goradia.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427040697_401_Naresh_H_Goradia.pdf",
  "size": "9982703",
  "createdAt": "Fri Sep 27 2024 14:20:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "402 Kirti Doshi.pdf",
  "filename": "1727427041539_402_Kirti_Doshi.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427041539_402_Kirti_Doshi.pdf",
  "size": "9741088",
  "createdAt": "Fri Sep 27 2024 14:20:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "601 Ranjen Choksi_0001 (1).pdf",
  "filename": "1727427042362_601_Ranjen_Choksi_0001_1.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427042362_601_Ranjen_Choksi_0001_1.pdf",
  "size": "31811322",
  "createdAt": "Fri Sep 27 2024 14:20:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "602 Ranjan Choksi_0001.pdf",
  "filename": "1727427045046_602_Ranjan_Choksi_0001.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427045046_602_Ranjan_Choksi_0001.pdf",
  "size": "32591282",
  "createdAt": "Fri Sep 27 2024 14:20:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
}
```

```
{
  "originalname": "701 PAAA SCAN COPY (1).pdf",
  "filename": "1727427047873_701_PAAA_SCAN_COPY_1.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427047873_701_PAAA_SCAN_COPY_1.pdf",
  "size": "2208730",
  "createdAt": "Fri Sep 27 2024 14:20:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "902 Vijay Baxi & Aditya Baxi.pdf",
  "filename": "1727427048096_902_Vijay_Baxi__Aditya_Baxi.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427048096_902_Vijay_Baxi__Aditya_Baxi.pdf",
  "size": "32791205",
  "createdAt": "Fri Sep 27 2024 14:20:50 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "902 Vijay Baxi & Aditya Baxi.pdf",
  "filename": "1727427065389_902_Vijay_Baxi__Aditya_Baxi.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427065389_902_Vijay_Baxi__Aditya_Baxi.pdf",
  "size": "32791205",
  "createdAt": "Fri Sep 27 2024 14:21:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "2397789_IOD_signed.pdf",
  "filename": "1727427068153_2397789_IOD_signed.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427068153_2397789_IOD_signed.pdf",
  "size": "208761",
  "createdAt": "Fri Sep 27 2024 14:21:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "62160899-05-02-2024 02-57-58$_$PAYMENT RECEIPTS.pdf",
  "filename":
"1727427068171_6216089905022024_025758_PAYMENT_RECEIPTS.pdf",
  "path": "cases/66f64950fcad932b0b154f69/processingDocuments/1727427068171_
6216089905022024_025758_PAYMENT_RECEIPTS.pdf",
  "size": "248272",
  "createdAt": "Fri Sep 27 2024 14:21:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
}
```



```
{
  "originalname": "1793507053-23-01-2024 04-45-27$_$IOD PAYMENT SHEET
2024.pdf",
  "filename": "1727427068191_179350705323012024_044527_IOD__PAYMENT_SH
EET_2024.pdf",
  "path": "cases/66f64950fcad932b0b154f69/processingDocuments/1727427068191_
179350705323012024_044527_IOD__PAYMENT_SHEET_2024.pdf",
  "size": "217457",
  "createdAt": "Fri Sep 27 2024 14:21:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "1793507053-23-01-2024 04-45-27$_$IOD PAYMENT SHEET.pdf",
  "filename":
"1727427068209_179350705323012024_044527_IOD__PAYMENT_SHEET.pdf",
  "path": "cases/66f64950fcad932b0b154f69/processingDocuments/1727427068209_
179350705323012024_044527_IOD__PAYMENT_SHEET.pdf",
  "size": "217457",
  "createdAt": "Fri Sep 27 2024 14:21:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "0702092138678_signed.pdf",
  "filename": "1727427068237_0702092138678_signed.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427068237_0702092138678_signed.pdf",
  "size": "210193",
  "createdAt": "Fri Sep 27 2024 14:21:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "0702092141942_signed.pdf",
  "filename": "1727427068245_0702092141942_signed.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427068245_0702092141942_signed.pdf",
  "size": "212083",
  "createdAt": "Fri Sep 27 2024 14:21:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "Airport NOC.pdf",
  "filename": "1727427068263_Airport_NOC.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427068263_Airport_NOC.pdf",
  "size": "146011",
  "createdAt": "Fri Sep 27 2024 14:21:08 GMT+0530 (India Standard Time)",
```

```
"uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "Architect Certificate.pdf",
  "filename": "1727427068276_Architect_Certificate.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427068276_Architect_Certificate.pdf",
  "size": "575538",
  "createdAt": "Fri Sep 27 2024 14:21:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "Concession MC approval.pdf",
  "filename": "1727427068324_Concession_MC_approval.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427068324_Concession_MC_approval.pdf",
  "size": "98335",
  "createdAt": "Fri Sep 27 2024 14:21:08 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "consession shanti sadan - parle west.pdf",
  "filename": "1727427097748_consession_shanti_sadan__parle_west.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427097748_consession_shanti_sadan__parle_west.pdf",
  "size": "2373682",
  "createdAt": "Fri Sep 27 2024 14:21:38 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "Demand Note 1.pdf",
  "filename": "1727427097946_Demand_Note_1.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427097946_Demand_Note_1.pdf",
  "size": "139018",
  "createdAt": "Fri Sep 27 2024 14:21:38 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "Demand Note 2.pdf",
  "filename": "1727427097959_Demand_Note_2.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427097959_Demand_Note_2.pdf",
  "size": "143131",
  "createdAt": "Fri Sep 27 2024 14:21:38 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
}
```

```
    },
    {
      "originalname": "Drawing (6)-IOD.pdf",
      "filename": "1727427097971_Drawing_6IOD.pdf",
      "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427097971_Drawing_6IOD.pdf",
      "size": "921958",
      "createdAt": "Fri Sep 27 2024 14:21:38 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91822f3dd69653a5922e3"
    },
    {
      "originalname": "FCA TABLE.pdf",
      "filename": "1727427098049_FCA_TABLE.pdf",
      "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427098049_FCA_TABLE.pdf",
      "size": "166656",
      "createdAt": "Fri Sep 27 2024 14:21:38 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91822f3dd69653a5922e3"
    },
    {
      "originalname": "FirstCC_signed.pdf",
      "filename": "1727427098062_FirstCC_signed.pdf",
      "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427098062_FirstCC_signed.pdf",
      "size": "163337",
      "createdAt": "Fri Sep 27 2024 14:21:38 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91822f3dd69653a5922e3"
    },
    {
      "originalname": "General Power of Attorney - Shanti Sadan.pdf",
      "filename": "1727427098076_General_Power_of_Attorney__Shanti_Sadan.pdf",
      "path": "cases/66f64950fcad932b0b154f69/processingDocuments/1727427098076_
General_Power_of_Attorney__Shanti_Sadan.pdf",
      "size": "2943415",
      "createdAt": "Fri Sep 27 2024 14:21:38 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91822f3dd69653a5922e3"
    },
    {
      "originalname": "P51800056441.pdf",
      "filename": "1727427098325_P51800056441.pdf",
      "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427098325_P51800056441.pdf",
      "size": "702930",
      "createdAt": "Fri Sep 27 2024 14:21:38 GMT+0530 (India Standard Time)",
      "uploadedBy": "60f91822f3dd69653a5922e3"
    },
  ],
```

```
{
  "originalname": "Payment Receipt 1.pdf",
  "filename": "1727427098385_Payment__Receipt_1.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427098385_Payment__Receipt_1.pdf",
  "size": "47132",
  "createdAt": "Fri Sep 27 2024 14:21:38 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "Payment Receipt2.pdf",
  "filename": "1727427098389_Payment__Receipt2.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427098389_Payment__Receipt2.pdf",
  "size": "47132",
  "createdAt": "Fri Sep 27 2024 14:21:38 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "Premium Summary.pdf",
  "filename": "1727427121409_Premium_Summary.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427121409_Premium_Summary.pdf",
  "size": "60533",
  "createdAt": "Fri Sep 27 2024 14:22:02 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "SHANTI SADAN DA COPY DT. 28-04-23.pdf",
  "filename": "1727427121414_SHANTI_SADAN_DA_COPY_DT_280423.pdf",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427121414_SHANTI_SADAN_DA_COPY_DT_280423.pdf",
  "size": "13884454",
  "createdAt": "Fri Sep 27 2024 14:22:02 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
  "originalname": "Tenant List 12.08.2024.xlsx",
  "filename": "1727427122587_Tenant_List_12082024.xlsx",
  "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427122587_Tenant_List_12082024.xlsx",
  "size": "10468",
  "createdAt": "Fri Sep 27 2024 14:22:02 GMT+0530 (India Standard Time)",
  "uploadedBy": "60f91822f3dd69653a5922e3"
},
{
```

```
    "originalname": "Tenant List.xlsx",
    "filename": "1727427122587_Tenant_List.xlsx",
    "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427122587_Tenant_List.xlsx",
    "size": "10468",
    "createdAt": "Fri Sep 27 2024 14:22:02 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "WIP till 22.05.24.jpeg.jpg",
    "filename": "1727427122588_WIP_till_220524jpeg.jpg",
    "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427122588_WIP_till_220524jpeg.jpg",
    "size": "86052",
    "createdAt": "Fri Sep 27 2024 14:22:02 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "WIP till 31.03.2024.xlsx",
    "filename": "1727427122595_WIP_till_31032024.xlsx",
    "path": "cases/66f64950fcad932b0b154f69/
processingDocuments/1727427122595_WIP_till_31032024.xlsx",
    "size": "17280",
    "createdAt": "Fri Sep 27 2024 14:22:02 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-09-27T05:57:36.692Z",
"updatedAt": "2024-09-27T08:52:42.226Z",
"__v": 0,
"updatedBy": "60f91822f3dd69653a5922e3",
"addressForMap": "",
"caseReferredBy": "60f91822f3dd69653a5922e3",
"contactPersonName": "M/s. Shree Hans Realtors LLP ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9820343346"
}
```

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			