

```
{
  "typeOfReport": {
    "value": "Row_House",
    "label": "Row House"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb63"
    },
    "firstName": "Sayali",
    "type": "CREDITOFFICER",
    "_id": "64bb68b0a87c525d5c04abb3",
    "lastName": "Bangar",
    "mobileNo": "",
    "workMobileNo": "8097275708",
    "email": "cord.racpckalyan@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb63",
  "branchCode": "000355",
  "type": "BRANCH",
  "name": "RACPC Kalyan",
  "email": "cord.racpckalyan@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Ground Floor, 1 st Floor, Millenium Heights, Opp. Patedar Bhawan
Marriage Hall, Shahad Mohone Road, Shahad, Kalyan (West) - 421 103 \n\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
  "shortName": "RJ",
  "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
  "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "64cde526dc9f3034f3fefa49",
  "role": "FRONTDESK",
  "firstName": "Rashmi",
  "email": "rashmijadhav14feb@gmail.com",
  "lastName": "Jadhav",
  "mobileNo": "7738144625",
  "designation": "Back Office Coordination",
```

```
"shortName": "RJ",
"workWithDocumentMaker": "60eeaeddf3dd69653a581316",
"profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
},
},
},
```

```
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
},
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.0251518878548",
  "longitude": "73.1032002834867"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
},
```

```
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Airoli",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": true,
    "name": "Building No",
    "key": "buildingNo",
    "value": "Row House No. 6",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
  "city": {
    "status": true,
    "name": "City",
```

```
"key": "city",
"value": "Navi Mumbai",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "130 to 141",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Trailokya Co.-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "2E",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
}
```

```
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
```



```
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "135/2E & 135/6",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
```

```
"status": false,
"name": "SRO",
"key": "SRO",
"value": "",
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 708",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    }
  }
},
```

```
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
```

```
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
```

```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
```

```
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "66f6795c0e53f82b0c615a2b",
"ownerName": "Mrs. Sarita Dharmendra Chaurasia & Mr. Dharmendra Chaurasia ",
```

```
"ownerPhoneNo": "9892169463",
"fullAddress": "Residential Row House No. 135/2E & 135/6, Ground Floor, Building No
Row House No. 6, Trailokya Co.-Op. Hsg. Soc. Ltd., Plot No. 130 to 141, Sector 2E,
Village - Airoli, Navi Mumbai, PIN Code - 400 708, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "26/09/2024",
      "from": {
        "value": "Transferor",
        "label": "Transferor"
      },
      "Transferor": "Mr. Kishor Dattatray Naik",
      "to": {
        "value": "transferee",
        "label": "transferee"
      },
      "transferee": "Mrs. Sarita Dharmendra Chaurasia & Mr. Dharmendra Chaurasia ",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "18559/2024"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1727428934794_S22C124092617560.pdf",
    "path": "cases/66f6795c0e53f82b0c615a2b/
document_1727428934794_S22C124092617560.pdf",
    "id": "336392",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Fri Sep 27 2024 14:52:36 GMT+0530 (India Standard Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "011530",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
```

```
{
  "id": "117917",
  "title": "Create Lead",
  "description": "Create Lead",
  "datetime": "Fri Sep 27 2024 14:52:36 GMT+0530 (India Standard Time)"
}
],
"owners": [
  {
    "name": "Mrs. Sarita Dharmendra Chaurasia & Mr. Dharmendra Chaurasia ",
    "phone": "9892169463",
    "ownershipShare": "",
    "email": "",
    "id": "947728"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7ca41b96a0db847159b",
    "name":
"externallmg_1727514570508_WhatsApp_Image_20240928_at_21124_PM.jpeg",
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514570508_WhatsApp_Image_20240928_at_21124_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7ca41b96a0db847159c",
    "name":
"externallmg_1727514570518_WhatsApp_Image_20240928_at_21126_PM.jpeg",
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514570518_WhatsApp_Image_20240928_at_21126_PM.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7ca41b96a0db847159d",
    "name":
"externallmg_1727514570528_WhatsApp_Image_20240928_at_21127_PM.jpeg",
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514570528_WhatsApp_Image_20240928_at_21127_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7ca41b96a0db847159e",
    "name":
"externallmg_1727514570538_WhatsApp_Image_20240928_at_21129_PM_1.jpeg",
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514570538_WhatsApp_Image_20240928_at_21129_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7ca41b96a0db847159f",
    "name":
"externallmg_1727514570548_WhatsApp_Image_20240928_at_21129_PM.jpeg",
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514570548_WhatsApp_Image_20240928_at_21129_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7ca41b96a0db84715a0",
    "name":
"externallmg_1727514570560_WhatsApp_Image_20240928_at_21130_PM.jpeg",
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514570560_WhatsApp_Image_20240928_at_21130_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7ca41b96a0db84715a1",
    "name":
"externallmg_1727514570570_WhatsApp_Image_20240928_at_21131_PM.jpeg",
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514570570_WhatsApp_Image_20240928_at_21131_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7ca41b96a0db84715a2",
    "name":
"externallmg_1727514570587_WhatsApp_Image_20240928_at_21134_PM.jpeg",
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514570587_WhatsApp_Image_20240928_at_21134_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7ca41b96a0db84715a3",
    "name":
"externallmg_1727514570607_WhatsApp_Image_20240928_at_21136_PM_1.jpeg",
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514570607_WhatsApp_Image_20240928_at_21136_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7e5d531b50db98be120",
    "name":
"externallmg_1727514596877_WhatsApp_Image_20240928_at_21136_PM.jpeg",
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514596877_WhatsApp_Image_20240928_at_21136_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7e5d531b50db98be121",
    "name":
"externallmg_1727514596903_WhatsApp_Image_20240928_at_21137_PM_1.jpeg",
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514596903_WhatsApp_Image_20240928_at_21137_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7e5d531b50db98be122",
```

```
    "name":
"externallmg_1727514596914_WhatsApp_Image_20240928_at_21137_PM_2.jpeg",
  "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514596914_WhatsApp_Image_20240928_at_21137_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f7c7e5d531b50db98be123",
  "name":
"externallmg_1727514596921_WhatsApp_Image_20240928_at_21137_PM_3.jpeg",
  "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514596921_WhatsApp_Image_20240928_at_21137_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f7c7e5d531b50db98be124",
  "name":
"externallmg_1727514596935_WhatsApp_Image_20240928_at_21137_PM.jpeg",
  "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514596935_WhatsApp_Image_20240928_at_21137_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f7c7e5d531b50db98be125",
  "name":
"externallmg_1727514596945_WhatsApp_Image_20240928_at_21138_PM_1.jpeg",
  "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514596945_WhatsApp_Image_20240928_at_21138_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f7c7e5d531b50db98be126",
  "name":
"externallmg_1727514596951_WhatsApp_Image_20240928_at_21138_PM_2.jpeg",
  "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514596951_WhatsApp_Image_20240928_at_21138_PM_2.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f7c7e5d531b50db98be127",
  "name":
"externallmg_1727514596954_WhatsApp_Image_20240928_at_21138_PM.jpeg",
  "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514596954_WhatsApp_Image_20240928_at_21138_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f7c7e5d531b50db98be128",
  "name":
"externallmg_1727514596959_WhatsApp_Image_20240928_at_21139_PM_1.jpeg",
  "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514596959_WhatsApp_Image_20240928_at_21139_PM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f7c7e5d531b50db98be129",
  "name":
"externallmg_1727514596965_WhatsApp_Image_20240928_at_21139_PM_2.jpeg",
  "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514596965_WhatsApp_Image_20240928_at_21139_PM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f7c7e5d531b50db98be12a",
  "name":
"externallmg_1727514596973_WhatsApp_Image_20240928_at_21139_PM_3.jpeg",
  "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514596973_WhatsApp_Image_20240928_at_21139_PM_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "66f7c7e5d531b50db98be12b",
  "name":
"externallmg_1727514596981_WhatsApp_Image_20240928_at_21139_PM.jpeg",
```

```
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514596981_WhatsApp_Image_20240928_at_21139_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7e5d531b50db98be12c",
    "name":
"externallmg_1727514596987_WhatsApp_Image_20240928_at_21140_PM_1.jpeg",
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514596987_WhatsApp_Image_20240928_at_21140_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7e5d531b50db98be12d",
    "name":
"externallmg_1727514596992_WhatsApp_Image_20240928_at_21140_PM_2.jpeg",
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514596992_WhatsApp_Image_20240928_at_21140_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7e5d531b50db98be12e",
    "name":
"externallmg_1727514596998_WhatsApp_Image_20240928_at_21140_PM.jpeg",
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514596998_WhatsApp_Image_20240928_at_21140_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "66f7c7e5d531b50db98be130",
    "name":
"externallmg_1727514597011_WhatsApp_Image_20240928_at_21141_PM_2.jpeg",
    "path": "cases/66f6795c0e53f82b0c615a2b/
externallmg_1727514597011_WhatsApp_Image_20240928_at_21141_PM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "66f7c85a12fe5c0dc6cda128",
  "name":
"externalImg_1727514713762_WhatsApp_Image_20240928_at_21141_PM.jpeg",
  "path": "cases/66f6795c0e53f82b0c615a2b/
externalImg_1727514713762_WhatsApp_Image_20240928_at_21141_PM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "Calculation Sheet NEW.xlsx",
  "filename": "1727683704286_Calculation_Sheet_NEW.xlsx",
  "path": "cases/66f6795c0e53f82b0c615a2b/
processingDocuments/1727683704286_Calculation_Sheet_NEW.xlsx",
  "size": "1321509",
  "createdAt": "Mon Sep 30 2024 13:38:24 GMT+0530 (India Standard Time)",
  "uploadedBy": "64cde526dc9f3034f3fefa49"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
  "createdBy": {
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "lastName": "Jadhav",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "66fa5045d531b50db98c93b4",
  "note": "Value given for confirmation",
  "taskId": "66f679687d6d262b2baa588d",
  "createdAt": "2024-09-30T07:16:21.251Z"
}
],
"createdAt": "2024-09-27T09:22:36.424Z",
"updatedAt": "2024-09-30T10:00:53.132Z",
"__v": 0,
"updatedBy": "64cde526dc9f3034f3fefa49",
```

```
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Mrs. Sarita Dharmendra Chaurasia & Mr. Dharmendra
Chaurasia ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9892169463"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			