

```
{
  "typeOfReport": {
    "label": "Structural Report",
    "value": "Structural_Report"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Education Loan",
    "value": "Education_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6533c9b1619c14402da9ea65"
    },
    "firstName": "Rajeev kumar ",
    "type": "CREDITOFFICER",
    "_id": "654cca24637db60f88b8cf57",
    "lastName": "Ranjan\t",
    "mobileNo": "",
    "workMobileNo": "9967159553",
    "email": "1rajeevrapc.borivali@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "9807620",
    "discussWithPerson": "Rajeev kumar ",
    "expectedFees": 4903.81,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6533c9b1619c14402da9ea65",
  "name": "Racpc Borivali West Shimpoli Road",
  "branchCode": "",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "email": "racpc.borivali@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Elegante Corner Guru Tapsaya CHSL, 620/4, Kastur Park, Shimpoli
Road, Borivali West Mumbai 400092"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60af6ae22ffdf65bcd65861d",
    "role": "PICKUPPERSON",
    "firstName": "Sunil",
    "email": "misalsunil87@gmail.com",
    "lastName": "Misal",
    "mobileNo": "8422982721",
    "shortName": "SM",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "65dee3f79a876858ab30487f",
    "role": "SITEENGINEER",
    "firstName": "Saiprasad",
    "email": "saiprasadpatil1010@gmail.com",
    "lastName": "Patil",
    "mobileNo": "8830049996",
    "designation": "Valuation Engineer",
    "shortName": "SSP",
    "workWithDocumentMaker": "60f91822f3dd69653a5922e3",
    "profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "64cde526dc9f3034f3fefa49",
    "role": "FRONTDESK",
    "firstName": "Rashmi",
    "email": "rashmijadhav14feb@gmail.com",
    "lastName": "Jadhav",
    "mobileNo": "7738144625",
    "designation": "Back Office Coordination",
    "shortName": "RJ",
    "workWithDocumentMaker": "60eeaeddf3dd69653a581316",
    "profilePhoto": "users/64cde526dc9f3034f3fefa49/
profilePhoto_1696055325842_Rashmi_2.jpeg"
  },
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "[N]C.C.I.T/I -14/52/2008-09",
```

```
    "label": "Wealth Tax"
  }
],
"type": "EMPLOYEE",
"_id": "6084131a13f01f158c6ea1f3",
"PANNo": "AEAPC7114Q",
"role": "VALUER",
"firstName": "Sharadkumar",
"fatherName": "Baburao",
"email": "cmd@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9422171100",
"designation": "CMD",
"registrationNo": [
  {
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.22173378778086",
  "longitude": "72.86107839724916"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86107839724916,
    19.22173378778086
  ]
}
},
"siteVisit": {
```

```
"siteVisitStatus": true,
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-10-05",
    "remark": ""
  }
],
"schedule": [],
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  }
}
```

```
},
"buildingNo": {
  "status": true,
  "name": "Building No",
  "key": "buildingNo",
  "value": "5",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
```

```
"key": "buildingName",
"value": "The Discovery CHSL",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Opp Jayaben Khot High School",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Datta Pada Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
}
```

```
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "204",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
```



```
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400066",
  "label": false
},
"suburb": {
```

```
    "status": true,
    "name": "Suburb",
    "key": "suburb",
    "value": "Borivali East",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
```

```
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
},
```

```
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
```

```
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
"min": "0.00",
"max": "0.00"
},
"saleableRateRange": {
"min": "0.00",
"max": "0.00"
}
},
"detailsOfValuation": {
"presentValueOfFlat": {
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
"title": "Wardrobes",
"quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
```

```
"title": "Extra collapsible gates / grill works etc",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
```



```
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "67011343554d3e0d46317791",
"ownerName": "Hitesh Vijaykumar Dave & Shreyansh Hitesh Dave ",
"ownerPhoneNo": "7977002587",
"appAddress": "Flat no 204 2 nd floor Bldg no 5 Discovery Co-op HSG Soc Ltd Opp
Jayaben khot High school Dattapada Road Borivali East Mumbai 400067",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Deed Of Gift",
      "value": "60ae1253aa6d152c1801b323"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67011343554d3e0d46317791/
document_1728123671123_1728123668994_Sbi_Racpc_Borivali_Hitesh_Dave.pdf",
    "fileName":
"document_1728123671123_1728123668994_Sbi_Racpc_Borivali_Hitesh_Dave.pdf",
    "id": "203925",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Sat Oct 05 2024 15:51:55 GMT+0530 (India Standard Time)"
  },
  {
    "documentType": {
      "label": "Other",
      "value": "60ae124eaa6d152c1801b30b"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67011343554d3e0d46317791/
document_1728132880670_1728132877107_BUILDER_TO_Morajkar.pdf",
```

```
"fileName":
"document_1728132880670_1728132877107_BUILDER_TO_Morajkar.pdf",
  "id": "696344",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Sat Oct 05 2024 18:29:54 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67011343554d3e0d46317791/
document_1728133136812_150620.pdf",
  "fileName": "document_1728133136812_150620.pdf",
  "id": "688415",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Sat Oct 05 2024 18:29:54 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "label": "Other",
    "value": "60ae124eaa6d152c1801b30b"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67011343554d3e0d46317791/
document_1728133193872_1728133182449_The_Discovery_Borivali_Flat_204.pdf",
  "fileName":
"document_1728133193872_1728133182449_The_Discovery_Borivali_Flat_204.pdf",
  "id": "365456",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Sat Oct 05 2024 18:29:54 GMT+0530 (India Standard Time)"
}
],
"caseNumber": "011649",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "206663",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Sat Oct 05 2024 15:51:55 GMT+0530 (India Standard Time)"
  }
],
```

```
"owners": [
  {
    "name": "Hitesh Vijaykumar Dave & Shreyansh Hitesh Dave ",
    "phone": "7977002587",
    "ownershipShare": "",
    "email": "",
    "id": "305514"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba2c",
    "name": "externalImg_1728132668363_1728132663292_image_0.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externalImg_1728132668363_1728132663292_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba2d",
    "name": "externalImg_1728132672986_1728132663292_image_1.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externalImg_1728132672986_1728132663292_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba2e",
    "name": "externalImg_1728132673348_1728132663292_image_2.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externalImg_1728132673348_1728132663292_image_2.jpeg",
    "orientation": "portrait"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba2f",
    "name": "externallmg_1728132674262_1728132663292_image_3.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132674262_1728132663292_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba30",
    "name": "externallmg_1728132674692_1728132663292_image_4.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132674692_1728132663292_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba31",
    "name": "externallmg_1728132676726_1728132663292_image_5.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132676726_1728132663292_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba32",
    "name": "externallmg_1728132676777_1728132663292_image_6.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132676777_1728132663292_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba33",
    "name": "externallmg_1728132677074_1728132663292_image_7.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132677074_1728132663292_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "6701364e554d3e0d4631ba34",
    "name": "externallmg_1728132677827_1728132663292_image_8.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132677827_1728132663292_image_8.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba35",
    "name": "externallmg_1728132678886_1728132663292_image_9.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132678886_1728132663292_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba36",
    "name": "externallmg_1728132679777_1728132663292_image_10.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132679777_1728132663292_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba37",
    "name": "externallmg_1728132680248_1728132663292_image_11.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132680248_1728132663292_image_11.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba38",
    "name": "externallmg_1728132680936_1728132663292_image_12.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132680936_1728132663292_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "6701364e554d3e0d4631ba39",
    "name": "externallmg_1728132681441_1728132663292_image_13.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132681441_1728132663292_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba3a",
    "name": "externallmg_1728132682328_1728132663292_image_14.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132682328_1728132663292_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba3b",
    "name": "externallmg_1728132682726_1728132663292_image_15.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132682726_1728132663292_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba3c",
    "name": "externallmg_1728132683264_1728132663292_image_16.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132683264_1728132663292_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba3d",
    "name": "externallmg_1728132683662_1728132663292_image_17.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132683662_1728132663292_image_17.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba3e",
```

```
    "name": "externallmg_1728132684437_1728132663292_image_18.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132684437_1728132663292_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6701364e554d3e0d4631ba3f",
    "name": "externallmg_1728132685294_1728132663292_image_19.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132685294_1728132663292_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67013665de702a0d39587cb3",
    "name": "externallmg_1728132706348_1728132701754_image_0.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132706348_1728132701754_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67013665de702a0d39587cb4",
    "name": "externallmg_1728132706921_1728132701754_image_1.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132706921_1728132701754_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67013665de702a0d39587cb5",
    "name": "externallmg_1728132707270_1728132701754_image_2.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132707270_1728132701754_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67013665de702a0d39587cb6",
    "name": "externallmg_1728132707373_1728132701754_image_3.jpeg",
```

```
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132707373_1728132701754_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67013665de702a0d39587cb7",
    "name": "externallmg_1728132707701_1728132701754_image_4.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132707701_1728132701754_image_4.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67013665de702a0d39587cb8",
    "name": "externallmg_1728132708223_1728132701754_image_5.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132708223_1728132701754_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67013665de702a0d39587cb9",
    "name": "externallmg_1728132708257_1728132701754_image_6.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132708257_1728132701754_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67013665de702a0d39587cba",
    "name": "externallmg_1728132708410_1728132701754_image_7.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132708410_1728132701754_image_7.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67013665de702a0d39587cbb",
    "name": "externallmg_1728132708613_1728132701754_image_8.jpeg",
    "path": "cases/67011343554d3e0d46317791/
externallmg_1728132708613_1728132701754_image_8.jpeg",
```



```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67013665de702a0d39587cbc",
  "name": "externallmg_1728132709024_1728132701754_image_9.jpeg",
  "path": "cases/67011343554d3e0d46317791/
externallmg_1728132709024_1728132701754_image_9.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67013609c514c90d3866970d",
  "name": "externallmg_1728132615130_1728132601080_image_0.jpeg",
  "path": "cases/67011343554d3e0d46317791/
externallmg_1728132615130_1728132601080_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67013609c514c90d3866970e",
  "name": "externallmg_1728132615410_1728132601080_image_1.jpeg",
  "path": "cases/67011343554d3e0d46317791/
externallmg_1728132615410_1728132601080_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67013609c514c90d3866970f",
  "name": "externallmg_1728132615537_1728132601080_image_2.jpeg",
  "path": "cases/67011343554d3e0d46317791/
externallmg_1728132615537_1728132601080_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "67013609c514c90d38669710",
  "name": "externallmg_1728132615991_1728132601080_image_3.jpeg",
  "path": "cases/67011343554d3e0d46317791/
externallmg_1728132615991_1728132601080_image_3.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67013609c514c90d38669711",
      "name": "externalImg_1728132616059_1728132601080_image_4.jpeg",
      "path": "cases/67011343554d3e0d46317791/
externalImg_1728132616059_1728132601080_image_4.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67013609c514c90d38669712",
      "name": "externalImg_1728132616201_1728132601080_image_5.jpeg",
      "path": "cases/67011343554d3e0d46317791/
externalImg_1728132616201_1728132601080_image_5.jpeg",
      "orientation": "landscape"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67013609c514c90d38669713",
      "name": "externalImg_1728132616306_1728132601080_image_6.jpeg",
      "path": "cases/67011343554d3e0d46317791/
externalImg_1728132616306_1728132601080_image_6.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "MEASUREMENT_IMAGE",
      "status": false,
      "_id": "67013609c514c90d38669714",
      "name": "externalImg_1728132616771_1728132601080_image_7.jpeg",
      "path": "cases/67011343554d3e0d46317791/
externalImg_1728132616771_1728132601080_image_7.jpeg",
      "orientation": "portrait"
    }
  ],
  "externalDocuments": [],
  "processingDocuments": [],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [],
  "createdAt": "2024-10-05T10:21:55.183Z",
  "updatedAt": "2024-10-05T12:59:54.671Z",
  "__v": 0,
```

```

"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Structural Report No. 204, 2nd Floor, Building No 5, The
Discovery CHSL, Opp Jayaben Khot High School, Datta Pada Road, Borivali East,
Mumbai, 400066",
"updatedBy": "65dee3f79a876858ab30487f",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Hitesh Vijaykumar Dave & Shreyansh Hitesh Dave ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "7977002587"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			