

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6728ad5b21492f3332edd922"
    },
    "firstName": "Anil",
    "type": "CREDITOFFICER",
    "_id": "6728ad78d873843300658436",
    "email": "anil.kumar22@sbi.co.in",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "8595479100"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6728ad5b21492f3332edd922",
  "name": "RACPC JAIPUR",
  "branchCode": "",
  "mobileNo": "0000000000",
  "alternateMobileNo": "",
  "email": "Mgrcord.10305@sbi.co.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "2nd FLOOR, KAILASH TOWER, LALKOTHI, TONK ROAD JAIPUR
302015"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "60b7177d2ffdf65bcd65882a",
```

```
"role": "PICKUPPERSON",
"firstName": "Saurabh",
"email": "saurabhvelonde143@gmail.com",
"lastName": "Velonde",
"mobileNo": "8691048846",
"shortName": "SSV",
"workWithDocumentMaker": "",
"profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "648fcad91b499c2d52dc86f3",
"role": "SITEENGINEER",
"firstName": "Barkat",
"email": "barkathodekar68@gmail.com",
"lastName": "Hodekar",
"mobileNo": "8879011615",
"designation": "Site Engg",
"shortName": "Barkat",
"workWithDocumentMaker": "",
"profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
```

```
    "label": "IBBI"
  },
  "_id": "60af80072ffdf65bcd658651",
  "number": "IBBI/RV/07/2018/10366"
},
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.072758117373255",
  "longitude": "72.87800878286362"
```

```
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87800878286362,
    19.072758117373255
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "4/11/2024 12:00 am"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Kurla",
    "label": true
  }
}
```

```
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "10",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
```

```
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Jaswanti Bliss",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
}
```

```
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
```



```
"value": "1001",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
```

```
"status": false,
"name": "Postal Code",
"key": "postalCode",
"value": "",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kurla",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
}
```

```
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
"detailsOfValuation": {
```

```
"presentValueOfFlat": {
  "title": "Present value of the flat (incl. car parking, if provided)",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
```



```
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "671234dc477b35348d3f76f4",
"ownerName": "VIRENDRA SINGH RATHORE AND VIJESH RATHORE ",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat no. 1001, 10th Floor, Wing - A, Jaswanti Bliss, Kurla West ",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Draft Agreement",
      "value": "60ae124aaa6d152c1801b2f8"
    }
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/671234dc477b35348d3f76f4/document_1729246416675_172924641
4607_A1001_kurla_Rera_Sale_Draft_Agreement.pdf",
  "fileName": "document_1729246416675_1729246414607_A1001_kurla_Rera_Sale
_Draft_Agreement.pdf",
  "id": "586189",
  "uploadedBy": "60b7177d2ffdf65bcd65882a",
```

```
"createdAt": "Fri Oct 18 2024 15:43:48 GMT+0530 (India Standard Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1730719702927_Flat_Bookig_Application.pdf",
  "path": "cases/671234dc477b35348d3f76f4/
document_1730719702927_Flat_Bookig_Application.pdf",
  "id": "824902",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Mon Nov 04 2024 11:28:55 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1730719712381_OC_COPY.pdf",
  "path": "cases/671234dc477b35348d3f76f4/
document_1730719712381_OC_COPY.pdf",
  "id": "225337",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Mon Nov 04 2024 11:28:55 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1730719722275_VASTUKALA_CONSULTANT_jaswanti_bliss.pdf",
  "path": "cases/671234dc477b35348d3f76f4/
document_1730719722275_VASTUKALA_CONSULTANT_jaswanti_bliss.pdf",
  "id": "325791",
  "uploadedBy": "6006d4ce5080a310ac1fdcf2",
  "createdAt": "Mon Nov 04 2024 11:28:55 GMT+0000 (Coordinated Universal Time)"
},
{
```

```
"documentType": {
  "value": "60ae124eaa6d152c1801b30b",
  "label": "Other"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1730719732647_VS_LEGAL_JASWANI_BLISS.pdf",
"path": "cases/671234dc477b35348d3f76f4/
document_1730719732647_VS_LEGAL_JASWANI_BLISS.pdf",
"id": "923499",
"uploadedBy": "6006d4ce5080a310ac1fdcf2",
"createdAt": "Mon Nov 04 2024 11:28:55 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "011894",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "569692",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Oct 18 2024 15:43:48 GMT+0530 (India Standard Time)"
  }
],
"owners": [
  {
    "name": "VIRENDRA SINGH RATHORE AND VIJESH RATHORE ",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "179306"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6728bf6440c166c89c7433cd",
```

```
    "name": "externallmg_1730723683362_1730723682101_image_0.jpeg",
    "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730723683362_1730723682101_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6728bf6440c166c89c7433ce",
    "name": "externallmg_1730723683445_1730723682104_image_1.jpeg",
    "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730723683445_1730723682104_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6728bf6440c166c89c7433cf",
    "name": "externallmg_1730723683767_1730723682104_image_2.jpeg",
    "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730723683767_1730723682104_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67299d9e40c166c89c743d59",
    "name": "externallmg_1730780565454_1730780562017_image_0.jpeg",
    "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780565454_1730780562017_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67299d9e40c166c89c743d5a",
    "name": "externallmg_1730780567840_1730780562017_image_1.jpeg",
    "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780567840_1730780562017_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67299d9e40c166c89c743d5b",
    "name": "externallmg_1730780569090_1730780562017_image_2.jpeg",
```

```
    "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780569090_1730780562017_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67299d9e40c166c89c743d5c",
    "name": "externallmg_1730780569188_1730780562017_image_3.jpeg",
    "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780569188_1730780562017_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67299d9e40c166c89c743d5d",
    "name": "externallmg_1730780569662_1730780562017_image_4.jpeg",
    "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780569662_1730780562017_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67299d9e40c166c89c743d5e",
    "name": "externallmg_1730780570368_1730780562017_image_5.jpeg",
    "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780570368_1730780562017_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67299d9e40c166c89c743d5f",
    "name": "externallmg_1730780571567_1730780562017_image_6.jpeg",
    "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780571567_1730780562017_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67299d9e40c166c89c743d60",
    "name": "externallmg_1730780571590_1730780562017_image_7.jpeg",
    "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780571590_1730780562017_image_7.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67299d9e40c166c89c743d61",
  "name": "externallmg_1730780571610_1730780562017_image_8.jpeg",
  "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780571610_1730780562017_image_8.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67299d9e40c166c89c743d62",
  "name": "externallmg_1730780572053_1730780562017_image_9.jpeg",
  "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780572053_1730780562017_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67299d9e40c166c89c743d63",
  "name": "externallmg_1730780572312_1730780562017_image_10.jpeg",
  "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780572312_1730780562017_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67299d9e40c166c89c743d64",
  "name": "externallmg_1730780572688_1730780562017_image_11.jpeg",
  "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780572688_1730780562017_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67299d9e40c166c89c743d65",
  "name": "externallmg_1730780572932_1730780562017_image_12.jpeg",
  "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780572932_1730780562017_image_12.jpeg",
  "orientation": "portrait"
}
```

```
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67299d9e40c166c89c743d66",
      "name": "externallmg_1730780573480_1730780562017_image_13.jpeg",
      "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780573480_1730780562017_image_13.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67299d9e40c166c89c743d67",
      "name": "externallmg_1730780573606_1730780562017_image_14.jpeg",
      "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780573606_1730780562017_image_14.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67299dbad8738433006598f7",
      "name": "externallmg_1730780599648_1730780597444_image_0.jpeg",
      "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780599648_1730780597444_image_0.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67299dbad8738433006598f8",
      "name": "externallmg_1730780600361_1730780597444_image_1.jpeg",
      "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780600361_1730780597444_image_1.jpeg",
      "orientation": "portrait"
    },
    {
      "type": "EXTERNAL_IMAGES",
      "status": false,
      "_id": "67299dbad8738433006598f9",
      "name": "externallmg_1730780600500_1730780597444_image_2.jpeg",
      "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780600500_1730780597444_image_2.jpeg",
      "orientation": "portrait"
    },
  ],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67299dbad8738433006598fa",
  "name": "externallmg_1730780600849_1730780597444_image_3.jpeg",
  "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780600849_1730780597444_image_3.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67299dbad8738433006598fb",
  "name": "externallmg_1730780600933_1730780597444_image_4.jpeg",
  "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780600933_1730780597444_image_4.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67299dbad8738433006598fc",
  "name": "externallmg_1730780601328_1730780597444_image_5.jpeg",
  "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780601328_1730780597444_image_5.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67299dbad8738433006598fd",
  "name": "externallmg_1730780601519_1730780597444_image_6.jpeg",
  "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780601519_1730780597444_image_6.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67299dbad8738433006598fe",
  "name": "externallmg_1730780602034_1730780597444_image_7.jpeg",
  "path": "cases/671234dc477b35348d3f76f4/
externallmg_1730780602034_1730780597444_image_7.jpeg",
  "orientation": "portrait"
}
],
```



```
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Virendra Rathore -Flat No. 1001 - State Bank of India ( RACPC
Sion ).xlsx",
    "filename": "1729257962842_Virendra_Rathore_Flat_No_1001__State_Bank_of_In
dia__RACPC_Sion_.xlsx",
    "path": "cases/671234dc477b35348d3f76f4/processingDocuments/1729257962842
_Virendra_Rathore_Flat_No_1001__State_Bank_of_India__RACPC_Sion_.xlsx",
    "size": "1742263",
    "createdAt": "Fri Oct 18 2024 18:56:02 GMT+0530 (India Standard Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "671261cd2c873c347146c1cc",
    "note": "Value Given for confirmation",
    "taskId": "671234dc477b35348d3f7708",
    "createdAt": "2024-10-18T13:25:33.534Z"
  }
],
"createdAt": "2024-10-18T10:13:48.289Z",
"updatedAt": "2024-11-05T04:23:22.693Z",
"__v": 0,
"updatedBy": "648fcad91b499c2d52dc86f3",
"reason": "For Valuation",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1001, 10th Floor, Jaswanti Bliss, Village - Kurla,
Kurla",
```

```

"addressForMap": "",
"caseReferredBy": "60b7177d2ffdf65bcd65882a",
"contactPersonName": "VIRENDRA SINGH RATHORE AND VIJESH RATHORE ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerId": "",
"siteVisitContactNo": "0000000000"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			