

```
{
  "typeOfReport": {
    "value": "Bungalow",
    "label": "Bungalow"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb63"
    },
    "firstName": "Sayali",
    "type": "CREDITOFFICER",
    "_id": "64bb68b0a87c525d5c04abb3",
    "lastName": "Bangar",
    "mobileNo": "",
    "workMobileNo": "8097275708",
    "email": "cord.racpckalyan@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb63",
  "branchCode": "000355",
  "type": "BRANCH",
  "name": "RACPC Kalyan",
  "email": "cord.racpckalyan@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "Ground Floor, 1 st Floor, Millenium Heights, Opp. Patedar Bhawan
Marriage Hall, Shahad Mohone Road, Shahad, Kalyan (West) - 421 103 \n\n",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62724142afd7d55eddede405",
  "role": "FRONTDESK",
  "firstName": "Sanjay",
  "email": "sanjayrphadol@gmail.com",
  "lastName": "Phadol",
  "mobileNo": "9890380564",
  "designation": "",
  "shortName": "SP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62724142afd7d55eddede405/
profilePhoto_1689235732454_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvanta",
```

```
"mobileNo": "9821518537",
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddedd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": []
},
"clientType": {
"value": "BANK",
"label": "BANK"
},
"location": {
"latitude": "19.6963271323389",
"longitude": "73.56107190314785"
},
"geo": {
"type": "Point",
"coordinates": [
0,
0
]
},
"siteVisit": {
"siteVisitStatus": false,
"schedule": [],
"visitedDate": []
},
"marketAnalysisAndRemark": {
"audioNotes": []
},
"externalReportDetails": {
"finalAreaType": "Built_Up",
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
"state": {
"status": true,
"name": "State",
"key": "state",
"value": "Maharashtra",
"label": true
},

```

```
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Lgatpuri Shahar",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
```

```
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Moon House Celebration ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
```

```
"status": false,
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
```

```
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "B - 07",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
```



```
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": true,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "17/3A, 17/3B & 17/2",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 422 403",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
},
```

```
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
```

```
"status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
```

```
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
```

```
"min": "0.00",
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
```

```
"title": "Superfine finish",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67173e159415217725ec3013",
"ownerName": "Mr. Hareshkumar Roopchand Nathani & Mrs. Pinky Hareshkumar Nathani",
"ownerPhoneNo": "9890451555",
"fullAddress": "Residential Flat No. B - 07, Ground Floor, Moon House Celebration , Village - Lgatpuri Shahar, Gut No. 17/3A, 17/3B & 17/2, PIN Code - 422 403, State -
```



```
Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "10/09/2024",
      "from": {
        "value": "Promoter",
        "label": "Promoter"
      },
      "Promoter": "Moonhouse Lifestyle LLP",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Mr. Hareshkumar Roopchand Nathani & Mrs. Pinky Hareshkumar
Nathani",
      "number": {
        "value": "No",
        "label": "No"
      },
      "No": "3775/2024"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1729576442968_AGREEMENT_0001_2.pdf",
    "path": "cases/67173e159415217725ec3013/
document_1729576442968_AGREEMENT_0001_2.pdf",
    "id": "417607",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Tue Oct 22 2024 05:54:29 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae129faa6d152c1801b47d",
      "label": "RERA Certificate"
    },
    "inputs": {
      "documentDate": "09/09/2021",
      "nameOfApprovingAuthority": {
        "value": "Maharashtra_Real_Estate_Regulatory_Authority",
        "label": "Maharashtra Real Estate Regulatory Authority"
      }
    }
  }
]
```

```
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "P51600050554"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "id": "470029",
  "path": "cases/67173e159415217725ec3013/
document_1729576463373_RERA_0001.pdf",
  "fileName": "document_1729576463373_RERA_0001.pdf"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "08/03/2022",
    "nameOfApprovingAuthority": {
      "value": "Igatpuri_Municipal_Council",
      "label": "Igatpuri Municipal Council"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "INP / PWD / B.P./ 03 / 2022"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1730876089953_46a62defcb0d48c4b44f0c8d2d7fa2fb.pdf",
  "path": "cases/67173e159415217725ec3013/
document_1730876089953_46a62defcb0d48c4b44f0c8d2d7fa2fb.pdf",
  "id": "865436",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed Nov 06 2024 06:57:05 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
```

```
"documentDate": "08/03/2022",
"nameOfApprovingAuthority": {
  "value": "Igatpuri_Municipal_Council",
  "label": "Igatpuri Municipal Council"
},
"number": {
  "value": "No",
  "label": "No"
},
"No": "INP / PWD / B.P/ 03 / 2022 "
},
"isHardCopy": false,
"displayStatus": true,
"fileName": "document_1730876224429_Approved_Building_Plan.pdf",
"path": "cases/67173e159415217725ec3013/
document_1730876224429_Approved_Building_Plan.pdf",
"id": "354342",
"uploadedBy": "627222afafd7d55eddeddd82",
"createdAt": "Wed Nov 06 2024 06:57:05 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "011971",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "896671",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Oct 22 2024 05:54:29 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Hareshkumar Roopchand Nathani & Mrs. Pinky Hareshkumar Nathani",
    "phone": "9890451555",
    "ownershipShare": "",
    "email": "",
    "id": "624282"
  }
],
"proposePurchasers": [],
"siteInspection": [],
```

```
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671b1f94857cdb68fa97acfd",
    "name":
"externalImg_1729830803832_WhatsApp_Image_20241024_at_61718_PM.jpeg",
    "path": "cases/67173e159415217725ec3013/
externalImg_1729830803832_WhatsApp_Image_20241024_at_61718_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671b1f94857cdb68fa97acfe",
    "name":
"externalImg_1729830803857_WhatsApp_Image_20241024_at_61719_PM_1.jpeg",
    "path": "cases/67173e159415217725ec3013/
externalImg_1729830803857_WhatsApp_Image_20241024_at_61719_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671b1f94857cdb68fa97acff",
    "name":
"externalImg_1729830803886_WhatsApp_Image_20241024_at_61719_PM_2.jpeg",
    "path": "cases/67173e159415217725ec3013/
externalImg_1729830803886_WhatsApp_Image_20241024_at_61719_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671b1f94857cdb68fa97ad00",
    "name":
"externalImg_1729830803910_WhatsApp_Image_20241024_at_61719_PM.jpeg",
    "path": "cases/67173e159415217725ec3013/
externalImg_1729830803910_WhatsApp_Image_20241024_at_61719_PM.jpeg",
    "orientation": "landscape"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671b1f94857cdb68fa97ad01",
  "name":
  "externallmg_1729830803941_WhatsApp_Image_20241024_at_61721_PM.jpeg",
  "path": "cases/67173e159415217725ec3013/
externallmg_1729830803941_WhatsApp_Image_20241024_at_61721_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671b1f94857cdb68fa97ad02",
  "name":
  "externallmg_1729830803977_WhatsApp_Image_20241024_at_61723_PM.jpeg",
  "path": "cases/67173e159415217725ec3013/
externallmg_1729830803977_WhatsApp_Image_20241024_at_61723_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671b1f94857cdb68fa97ad03",
  "name":
  "externallmg_1729830804016_WhatsApp_Image_20241024_at_61724_PM.jpeg",
  "path": "cases/67173e159415217725ec3013/
externallmg_1729830804016_WhatsApp_Image_20241024_at_61724_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671b1f94857cdb68fa97ad04",
  "name":
  "externallmg_1729830804051_WhatsApp_Image_20241024_at_61726_PM.jpeg",
  "path": "cases/67173e159415217725ec3013/
externallmg_1729830804051_WhatsApp_Image_20241024_at_61726_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671b1f94857cdb68fa97ad05",
  "name":
  "externallmg_1729830804081_WhatsApp_Image_20241024_at_61727_PM.jpeg",
```

```
    "path": "cases/67173e159415217725ec3013/
externallmg_1729830804081_WhatsApp_Image_20241024_at_61727_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671b1f94857cdb68fa97ad06",
    "name":
"externallmg_1729830804118_WhatsApp_Image_20241024_at_61729_PM.jpeg",
    "path": "cases/67173e159415217725ec3013/
externallmg_1729830804118_WhatsApp_Image_20241024_at_61729_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671b1f94857cdb68fa97ad07",
    "name":
"externallmg_1729830804150_WhatsApp_Image_20241024_at_61730_PM.jpeg",
    "path": "cases/67173e159415217725ec3013/
externallmg_1729830804150_WhatsApp_Image_20241024_at_61730_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671b1f94857cdb68fa97ad08",
    "name":
"externallmg_1729830804197_WhatsApp_Image_20241024_at_61732_PM.jpeg",
    "path": "cases/67173e159415217725ec3013/
externallmg_1729830804197_WhatsApp_Image_20241024_at_61732_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671b1f94857cdb68fa97ad09",
    "name":
"externallmg_1729830804225_WhatsApp_Image_20241024_at_61734_PM.jpeg",
    "path": "cases/67173e159415217725ec3013/
externallmg_1729830804225_WhatsApp_Image_20241024_at_61734_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "671b1f94857cdb68fa97ad0a",
    "name":
"externallmg_1729830804267_WhatsApp_Image_20241024_at_61735_PM.jpeg",
    "path": "cases/67173e159415217725ec3013/
externallmg_1729830804267_WhatsApp_Image_20241024_at_61735_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671b1f94857cdb68fa97ad0b",
    "name":
"externallmg_1729830804297_WhatsApp_Image_20241024_at_61737_PM.jpeg",
    "path": "cases/67173e159415217725ec3013/
externallmg_1729830804297_WhatsApp_Image_20241024_at_61737_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671b1f94857cdb68fa97ad0c",
    "name":
"externallmg_1729830804338_WhatsApp_Image_20241024_at_61738_PM.jpeg",
    "path": "cases/67173e159415217725ec3013/
externallmg_1729830804338_WhatsApp_Image_20241024_at_61738_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671b1f94857cdb68fa97ad0d",
    "name":
"externallmg_1729830804375_WhatsApp_Image_20241024_at_61740_PM.jpeg",
    "path": "cases/67173e159415217725ec3013/
externallmg_1729830804375_WhatsApp_Image_20241024_at_61740_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671b1f94857cdb68fa97ad0e",
    "name":
"externallmg_1729830804405_WhatsApp_Image_20241024_at_61742_PM.jpeg",
    "path": "cases/67173e159415217725ec3013/
externallmg_1729830804405_WhatsApp_Image_20241024_at_61742_PM.jpeg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671b1f94857cdb68fa97ad0f",
  "name":
"externallmg_1729830804439_WhatsApp_Image_20241024_at_61743_PM.jpeg",
  "path": "cases/67173e159415217725ec3013/
externallmg_1729830804439_WhatsApp_Image_20241024_at_61743_PM.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "Hareshkumar Roopchand Nathani & Mrs. Pinky Hareshkumar
Nathani - Bungalow - State Bank of India ( RACPC Kalyan ).xlsx",
  "filename": "1730791947006_Hareshkumar_Roopchand_Nathani__Mrs_Pinky_Hare
shkumar_Nathani__Bungalow__State_Bank_of_India__RACPC_Kalyan_.xlsx",
  "path": "cases/67173e159415217725ec3013/processingDocuments/173079194700
6_Hareshkumar_Roopchand_Nathani__Mrs_Pinky_Hareshkumar_Nathani__Bungalow
__State_Bank_of_India__RACPC_Kalyan_.xlsx",
  "size": "1203061",
  "createdAt": "Tue Nov 05 2024 07:32:27 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "64dc7184ccaf1e7b7f637f47"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
  "createdBy": {
    "_id": "64dc7184ccaf1e7b7f637f47",
    "role": "FRONTDESK",
    "firstName": "Binumon",
    "lastName": "Moozhickal",
    "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
  },
  "workType": "RATE_VERIFY",
  "display": true,
  "status": true,
  "_id": "672874b5d873843300655e99",
  "note": "Pending for approved plan",
  "taskId": "67173e1fb80efc7737fbeab9",
}
```



```

    "createdAt": "2024-11-04T07:16:05.677Z"
  }
],
"createdAt": "2024-10-22T05:54:29.488Z",
"updatedAt": "2024-11-06T06:57:05.562Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "6410199a140f140ffc59b58c",
"contactPersonName": "Mr. Hareshkumar Roopchand Nathani & Mrs. Pinky
Hareshkumar Nathani",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "9890451555",
"reralid": ""
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			