

```
{
  "typeOfReport": {
    "label": "Structural Report",
    "value": "Structural_Report"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb60"
    },
    "firstName": "Vitthal",
    "type": "CREDITOFFICER",
    "_id": "6526806e703d7c40db9adf56",
    "lastName": "Mane",
    "mobileNo": "",
    "workMobileNo": "8108129226",
    "email": "vitthal.mane@janasevabank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "4000000",
    "discussWithPerson": "Vitthal",
    "expectedFees": 2000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank (Borivali) LTD",
  "displayName": "Janaseva Sahakari Bank (Borivali) LTD",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb60",
  "branchCode": "0000010",
  "type": "BRANCH",
  "name": "Bhayander (East) Branch",
  "email": "vitthal.mane@janasevabank.in",
  "mobileNo": "02228171617",
  "alternateMobileNo": "02228171618",
  "address": "Janki Avaneue 1st floor, phatak road, Bhayander East Thane-401105",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "66850df5d9f18310ed2e5d98",
  "role": "SITEENGINEER",
  "firstName": "Krishna",
  "email": "krishnagawade9@gmail.com",
  "lastName": "Gawde",
  "mobileNo": "9821646373",
  "designation": "Site Engg",
  "shortName": "Krishna",
  "workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        }
      }
    ]
  }
]
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.301477537997016",
  "longitude": "72.85162673049221"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    72.85162673049221,
    19.301477537997016
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "22/10/2024 06:06 pm"
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  }
},
```

```
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
```

```
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "GOKUL THERESSA CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
```

```
"status": false,
"name": "Project Name",
"key": "projectName",
"value": "",
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "402",
```



```
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
```

```
"name": "Postal Code",
"key": "postalCode",
"value": "",
"label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Bhaynder West ",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
}
```

```
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
```

```
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,

```

```
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
```

```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
```



```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "671778e79415217725ec8613",
"ownerName": "SHEETAL SANJAY MADAV",
"ownerPhoneNo": "8108129226",
"appAddress": "FLAT NO 402 D WING GOKUL THERESSA CHS LTD LEPORA
STREET BHAYNDER WEST THANE",
"remark": "structural stability report",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    }
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/671778e79415217725ec8613/
document_1729591411341_1729591408963_sheetal_madav_agreement_1.pdf",
  "fileName":
"document_1729591411341_1729591408963_sheetal_madav_agreement_1.pdf",
  "id": "643029",
  "uploadedBy": "659ccce98f39506e83489828",
```

```
    "createdAt": "Tue Oct 22 2024 10:05:26 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "011983",
"createdBy": "659cccce98f39506e83489828",
"caseHistory": [
  {
    "id": "795053",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Oct 22 2024 10:05:27 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "SHEETAL SANJAY MADAV",
    "phone": "8108129226",
    "ownershipShare": "",
    "email": "",
    "id": "225610"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671a0301fd14bf9350ab31f6",
    "name":
"externallmg_1729757953323_WhatsApp_Image_20241024_at_124755.jpeg",
    "path": "cases/671778e79415217725ec8613/
externallmg_1729757953323_WhatsApp_Image_20241024_at_124755.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671a0301fd14bf9350ab31f7",
    "name":
"externallmg_1729757953327_WhatsApp_Image_20241024_at_124531.jpeg",
```

```
    "path": "cases/671778e79415217725ec8613/
externallmg_1729757953327_WhatsApp_Image_20241024_at_124531.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671a0301fd14bf9350ab31f8",
    "name":
"externallmg_1729757953351_WhatsApp_Image_20241024_at_124547_1.jpeg",
    "path": "cases/671778e79415217725ec8613/
externallmg_1729757953351_WhatsApp_Image_20241024_at_124547_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671a0301fd14bf9350ab31f9",
    "name":
"externallmg_1729757953355_WhatsApp_Image_20241024_at_124547.jpeg",
    "path": "cases/671778e79415217725ec8613/
externallmg_1729757953355_WhatsApp_Image_20241024_at_124547.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671a0301fd14bf9350ab31fa",
    "name":
"externallmg_1729757953357_WhatsApp_Image_20241024_at_124652_1.jpeg",
    "path": "cases/671778e79415217725ec8613/
externallmg_1729757953357_WhatsApp_Image_20241024_at_124652_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671a0301fd14bf9350ab31fb",
    "name":
"externallmg_1729757953380_WhatsApp_Image_20241024_at_124652.jpeg",
    "path": "cases/671778e79415217725ec8613/
externallmg_1729757953380_WhatsApp_Image_20241024_at_124652.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "671a0301fd14bf9350ab31fc",
  "name":
"externallmg_1729757953387_WhatsApp_Image_20241024_at_124655.jpeg",
  "path": "cases/671778e79415217725ec8613/
externallmg_1729757953387_WhatsApp_Image_20241024_at_124655.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671a0301fd14bf9350ab31fd",
  "name":
"externallmg_1729757953429_WhatsApp_Image_20241024_at_124656_1.jpeg",
  "path": "cases/671778e79415217725ec8613/
externallmg_1729757953429_WhatsApp_Image_20241024_at_124656_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671a0301fd14bf9350ab31fe",
  "name":
"externallmg_1729757953432_WhatsApp_Image_20241024_at_124656.jpeg",
  "path": "cases/671778e79415217725ec8613/
externallmg_1729757953432_WhatsApp_Image_20241024_at_124656.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671a0301fd14bf9350ab31ff",
  "name":
"externallmg_1729757953468_WhatsApp_Image_20241024_at_124658.jpeg",
  "path": "cases/671778e79415217725ec8613/
externallmg_1729757953468_WhatsApp_Image_20241024_at_124658.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671a030d03856193623212ed",
  "name":
"externallmg_1729757965139_WhatsApp_Image_20241024_at_124659_1.jpeg",
  "path": "cases/671778e79415217725ec8613/
externallmg_1729757965139_WhatsApp_Image_20241024_at_124659_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671a030d03856193623212ee",
    "name":
"externallmg_1729757965146_WhatsApp_Image_20241024_at_124659.jpeg",
    "path": "cases/671778e79415217725ec8613/
externallmg_1729757965146_WhatsApp_Image_20241024_at_124659.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671a030d03856193623212ef",
    "name":
"externallmg_1729757965169_WhatsApp_Image_20241024_at_124700_1.jpeg",
    "path": "cases/671778e79415217725ec8613/
externallmg_1729757965169_WhatsApp_Image_20241024_at_124700_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671a030d03856193623212f0",
    "name":
"externallmg_1729757965188_WhatsApp_Image_20241024_at_124700_2.jpeg",
    "path": "cases/671778e79415217725ec8613/
externallmg_1729757965188_WhatsApp_Image_20241024_at_124700_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671a030d03856193623212f1",
    "name":
"externallmg_1729757965191_WhatsApp_Image_20241024_at_124700.jpeg",
    "path": "cases/671778e79415217725ec8613/
externallmg_1729757965191_WhatsApp_Image_20241024_at_124700.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671a030d03856193623212f2",
```

```
"name":
"externallmg_1729757965218_WhatsApp_Image_20241024_at_124701_1.jpeg",
  "path": "cases/671778e79415217725ec8613/
externallmg_1729757965218_WhatsApp_Image_20241024_at_124701_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671a030d03856193623212f3",
  "name":
"externallmg_1729757965221_WhatsApp_Image_20241024_at_124701_2.jpeg",
  "path": "cases/671778e79415217725ec8613/
externallmg_1729757965221_WhatsApp_Image_20241024_at_124701_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671a030d03856193623212f4",
  "name":
"externallmg_1729757965252_WhatsApp_Image_20241024_at_124701.jpeg",
  "path": "cases/671778e79415217725ec8613/
externallmg_1729757965252_WhatsApp_Image_20241024_at_124701.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671a030d03856193623212f5",
  "name":
"externallmg_1729757965255_WhatsApp_Image_20241024_at_124702_1.jpeg",
  "path": "cases/671778e79415217725ec8613/
externallmg_1729757965255_WhatsApp_Image_20241024_at_124702_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671a030d03856193623212f6",
  "name":
"externallmg_1729757965293_WhatsApp_Image_20241024_at_124702_2.jpeg",
  "path": "cases/671778e79415217725ec8613/
externallmg_1729757965293_WhatsApp_Image_20241024_at_124702_2.jpeg",
  "orientation": "portrait"
},
},
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671a030d03856193623212f7",
  "name":
"externallmg_1729757965297_WhatsApp_Image_20241024_at_124702.jpeg",
  "path": "cases/671778e79415217725ec8613/
externallmg_1729757965297_WhatsApp_Image_20241024_at_124702.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671a030d03856193623212f8",
  "name":
"externallmg_1729757965319_WhatsApp_Image_20241024_at_124703_1.jpeg",
  "path": "cases/671778e79415217725ec8613/
externallmg_1729757965319_WhatsApp_Image_20241024_at_124703_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671a030d03856193623212f9",
  "name":
"externallmg_1729757965322_WhatsApp_Image_20241024_at_124703_2.jpeg",
  "path": "cases/671778e79415217725ec8613/
externallmg_1729757965322_WhatsApp_Image_20241024_at_124703_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671a030d03856193623212fa",
  "name":
"externallmg_1729757965350_WhatsApp_Image_20241024_at_124703.jpeg",
  "path": "cases/671778e79415217725ec8613/
externallmg_1729757965350_WhatsApp_Image_20241024_at_124703.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "671a030d03856193623212fb",
  "name":
"externallmg_1729757965355_WhatsApp_Image_20241024_at_124704_1.jpeg",
```

```
    "path": "cases/671778e79415217725ec8613/
externallmg_1729757965355_WhatsApp_Image_20241024_at_124704_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671a030d03856193623212fc",
    "name":
"externallmg_1729757965378_WhatsApp_Image_20241024_at_124704_2.jpeg",
    "path": "cases/671778e79415217725ec8613/
externallmg_1729757965378_WhatsApp_Image_20241024_at_124704_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "671a030d03856193623212fd",
    "name":
"externallmg_1729757965382_WhatsApp_Image_20241024_at_124704.jpeg",
    "path": "cases/671778e79415217725ec8613/
externallmg_1729757965382_WhatsApp_Image_20241024_at_124704.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-10-22T10:05:27.180Z",
"updatedAt": "2024-10-24T08:19:25.568Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Structural Report No. 402, 4th Floor, GOKUL THERESSA
CHSL, Bhaynder West ",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "SHEETAL SANJAY MADAV",
"email": "",
"isExternal": "false",
"isUrgent": "false",
```


"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"siteVisitContactNo": "8108129226"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other

Composition :
