

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856baa0"
    },
    "firstName": "Ashish",
    "type": "CREDITOFFICER",
    "_id": "66f3bd047d6d262b2ba806c1",
    "email": "ashish.bhabad@sbi.co.in",
    "lastName": "Bhabad",
    "mobileNo": "",
    "workMobileNo": "7709815152"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856baa0",
  "branchCode": "000286",
  "type": "BRANCH",
  "name": "RASMECCC Bhayandar",
  "email": "Coorddesk.rasmecbhy@sbi.co.in",
  "mobileNo": "02225140903",
  "alternateMobileNo": "",
  "address": "RASMECCC Bhayandar Branch Unit No. 101, 102, 103B, 1st Floor, IT
Landmark Building, 150ft. Road, Near Hotel Shree Nidhi, Opp. Maxus Mall, Bhayander
(West), Thane – 401 101, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "66850df5d9f18310ed2e5d98",
  "role": "SITEENGINEER",
  "firstName": "Krishna",
  "email": "krishnagawade9@gmail.com",
  "lastName": "Gawde",
  "mobileNo": "9821646373",
  "designation": "Site Engg",
  "shortName": "Krishna",
  "workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": null,
"maker": {
  "type": "EMPLOYEE",
  "_id": "627221f4afd7d55eddeddcb4",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Prajakta",
  "email": "prajakta@vastukala.org",
  "lastName": "Patil",
  "mobileNo": "9769797568",
  "designation": "",
  "shortName": "P",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/627221f4afd7d55eddeddcb4/
profilePhoto_1668057197188_WhatsApp_Image_20221110_at_104044_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f915d3f3dd69653a592199",
  "role": "MAKER + RATE VERIFIER + CHEAKER",
  "firstName": "Shobha",
  "email": "shobha@vastukala.org",
```

```
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
```

```
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.283008853134735",
  "longitude": "72.87949854219214"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.87949854219214,
    19.283008853134735
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [
    {
      "dateTime": "5/11/2024 12:00 am"
    }
  ]
},
"visitedDate": [
  {
    "status": "COMPLETED",
    "dateTime": "2024-11-06",
```

```
    "remark": "MANUAL_IN_TASK"
  }
]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "1BHK",
  "label": "1 BHK"
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Ghodbunder",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "12",
    "label": false
  },
  "buildingNo": {
```

```
"status": true,
"name": "Building No",
"key": "buildingNo",
"value": "1",
"label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Salasar Courtyard ",
```

```
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Hatkesh Industrial Road",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Opp. Green Court Club",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Green Wood Enclave",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
```



```
"name": "Old Survey No.",
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "90, Hissa No. 2, 4 (P), Survey No. 91, Hissa No. 1B (Part)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "1204",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
}
```

```
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 401 107",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
```

```
"key": "suburb",
"value": "Mira Road (East)",
"label": false
},
"flatSpecifications": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "flooring": {
    "value": "Proposed_Vitrified_tiles_flooring",
    "label": "Proposed Vitrified tiles flooring"
  },
  "doors": {
    "value": "Proposed_Teak_wood_door_frame_with_flush_doors",
    "label": "Proposed Teak wood door frame with flush doors"
  },
  "windows": {
    "value": "Proposed_Powder_coated_aluminium_sliding_windows",
    "label": "Proposed Powder coated aluminium sliding windows"
  },
  "fittings": {
    "value": "Proposed_Concealed_plumbing_with_C.P._fittings._Proposed_Electrical_wiring_with_Concealed.",
    "label": "Proposed Concealed plumbing with C.P. fittings. Proposed Electrical wiring with Concealed."
  },
  "finishing": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  }
},
"general": {
  "ownership": {
    "value": "Sole_Ownership",
    "label": "Sole Ownership"
  },
  "populationClassList": {
    "value": "MiddleClass",
    "label": "Middle Class"
  },
  "populationGroupList": {
    "value": "Urban",
    "label": "Urban"
  }
},
```

```
"townplanApprovedByList": {
  "value": "Mira_Bhayander_Municipal_Corporation",
  "label": "Mira Bhayander Municipal Corporation"
},
"whetherCoveredUnderAnyState": {
  "value": "No",
  "label": "No"
},
"asPerActualAgreement": {
  "north": "Road",
  "west": "Open Plot",
  "south": "Tower No. 3, Lodha Casa Maxima",
  "east": "Internal Road"
},
"asPerDocumentAgreement": {
  "north": "S. No. 85",
  "west": "S. No. 77",
  "south": "S. No. 97",
  "east": "S. No. 89"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "Building is Under Construction",
    "east": "Building is Under Construction",
    "south": "Building is Under Construction",
    "west": "Building is Under Construction"
  },
  "asPerDocument": {
    "north": "Lobby, Staircase & Flat No. 1205",
    "east": "Marginal Space",
    "south": "Marginal Space",
    "west": "Flat No. 1203"
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  }
},
```

```
"privateCars": {
  "title": "Private Cars"
}
},
"extraDetailOfProperty": "As per Approved Plan, the composition of Residential Flat will be 1 Bedroom + Living Room + Kitchen + Bath + W.C. + Flowerbed area + Dry Balcony area.",
"dateOfIssusApprovePlan": "Copy of Approved Building Plan Document No. MNP / NR / 2341 / 2022 - 2023 Dated 20.09.2022 issued by Mira Bhayander Municipal Corporation",
"approvePlanVerified": "N.A., Building is under construction ",
"empanelledOfApprovePlan": "N.A.",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
}
},
"apfDetails": {
  "buildings": [],
  "compositions": []
}
},
"compositeRate": {
  "remark": "At the time of visit, Builder has not allowed for Internal site inspection, measurement and Internal Photographs of the property. The details about the work progress status has been provided by Site Person - Mr. Michelle - 7506978458",
  "depreciationPercentage": "",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "",
  "depreciatedCostOfConstruction": "",
  "depreciatedBuildingRate": ""
}
},
"igrRate": {
  "propertyName": "Residential",
  "rate": "101400",
  "landRate": "27700",
  "igrImage": "cases/6729ba710e38ca1455e955e9/igr_1730976859700_Image.png",
  "squareMeterGuideLineRate": "111540.00",
  "squareFeetGuideLineRate": "10362.00"
}
},
"igrFinalRate": {
  "floorRatePercentage": "10",
  "depreciationPercentage": "0",
  "rate": "101400.00",
```

```
"squareMeterGuideLineRate": "111540.00",
"squareFeetGuideLineRate": "10362.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Medium",
    "label": "Medium"
  },
  "propertyTypeOfUseList": {
    "value": "Proposed_Residential_Purpose",
    "label": "Proposed Residential Purpose"
  },
  "propertyOccupiedByList": {
    "value": "Building_Under_Construction",
    "label": "Building Under Construction"
  },
  "monthlyRent": "14,000/- (Expected rental income per month after completion\n\nof
construction works)",
  "assessmentNo": "Details not available",
  "taxPaidHolderName": "Details not available",
  "taxAmount": "Details not available",
  "electricityServiceConnectionNo": "Details not available",
  "meterCardHolderName": "Details not available",
  "undividedAreaOfLandAsPerSaleDeed": "Details not available",
  "floorSpaceIndex": "As per MBMC norms",
  "tenantName": "",
  "maintenanceOfFlat": "Building Under Construction"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in Developed Area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "Proposed_6\"_Thk._Brick_Masonry",
    "label": "Proposed 6\" Thk. Brick Masonry"
  },
  "waterTank": {
```

```
"value": "Proposed_Municipal_Water_Supply",
"label": "Proposed Municipal Water Supply"
},
"pavementLaid": {
"value": "Proposed,_Yes",
"label": "Proposed, Yes"
},
"carParking": "Proposed Stilt Car Parking",
"constructionWorkStatus": {
"value": "InProgress",
"label": "Under Construction"
},
"asthetikLook": {
"value": "Plain_Looking",
"label": "Plain Looking"
},
"dateOfConstruction": {
"date": "",
"month": "1",
"year": "2025",
"fullDate": "1/1/2025"
},
"planningArea": {
"value": "Residential",
"label": "Residential"
},
"typeOfStructure": {
"value": "Proposed_R.C.C_Framed_Structure",
"label": "Proposed R.C.C Framed Structure"
},
"typeOfFoundation": {
"value": "rcc",
"label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
"value": "UnderConstruction",
"label": "Building Under Construction"
},
"materialUsedList": {
"value": "Building_Under_Construction",
"label": "Building Under Construction"
},
"buildingSpecification": {
"value": "Proposed_Standard",
"label": "Proposed Standard"
},
}
```

```
"structuralSafety": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"protAgainstNatDis": {
  "value": "Information_not_available",
  "label": "Information not available"
},
"sewerageSystem": {
  "value": "Proposed_Connected_to_Municipal_Sewerage_System_",
  "label": "Proposed Connected to Municipal Sewerage System "
},
"walls": {
  "value": "Proposed,_Yes",
  "label": "Proposed, Yes"
},
"appearanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceOfTheBuilding": {
  "value": "UnderConstruction",
  "label": "Building Under Construction"
},
"maintenanceIssues": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"visibleDamageInBuilding": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"systemOfAirConditioning": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"provisionOfFirefighting": {
  "value": "Building_Under_Construction",
  "label": "Building Under Construction"
},
"groundStilt": {
  "value": "stilt",
  "label": "Stilt"
},
"yearOfConstructionAsPer": {
  "value": "as_per_site_information",
```



```
    "label": "As per site information"
  },
  "isSiteVisitAllowed": true,
  "totalLifeBuilding": "60",
  "estimatedAge": "0",
  "ageOfBuilding": "0",
  "noOfBasement": "",
  "noOfPodium": "",
  "noOfAmenityFloors": "",
  "noOfFloors": "22",
  "flatFloorNo": "12",
  "noOfLifts": "4",
  "noOfDwellingUnitsInBuilding": "16"
},
"finalPlinthArea": {
  "area": "379.50",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
  "areaAsPer": "Carpet Area + 10%"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6729ba710e38ca1455e955e9/
routeMap_1730978048106_Image.png",
    "routeLat": "19.282763",
    "routeLng": "72.880275",
    "stationName": "Mira Road",
    "routeDistance": "3.3 Km.",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  }
},
"finalLatLng": {
  "coordinates": [
    0,
    0
  ],
  "type": "Point"
},
"showLocation": {
  "latLng": false,
  "finallatLng": false
},
"locationMapImg": [
  {
```

```
    "id": "6uvfed",
    "name": "6uvfed",
    "image": "cases/6729ba710e38ca1455e955e9/
routeMap_1730977952675_Image.png"
  }
]
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  },
  "wardrobesRate": "0",
  "totalwardrobesRate": "0",
  "wardrobesQty": "0",
  "showcasesQty": "0",
  "showcasesRate": "0",
  "totalshowcasesRate": "0",
  "kitchenArrangementsQty": "0",
  "kitchenArrangementsRate": "0",
  "totalkitchenArrangementsRate": "0",
  "superfineFinishQty": "0",
  "superfineFinishRate": "0",
  "totalsuperfineFinishRate": "0",
  "interiorDecorationsQty": "0",
  "interiorDecorationsRate": "0",
  "totalinteriorDecorationsRate": "0",
  "electricityDepositsQty": "0",
  "electricityDepositsRate": "0",
  "totalelectricityDepositsRate": "0",
  "extraCollapsibleGatesQty": "0",
  "extraCollapsibleGatesRate": "0",
  "totalextraCollapsibleGatesRate": "0",
  "potentialValueQty": "0",
  "potentialValueRate": "0",
  "totalpotentialValueRate": "0",
  "othersQty": "0",
  "othersRate": "0",
  "totalothersRate": "0",
  "finaltotal": "5106000.00",
  "distressValuePercentage": "80",
  "realizableValuePercentage": "98",
  "bookValue": "0",
  "finalValue": "5106000.00"
```

```
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "Complete",
    "percentage": "5",
    "isHideFloor": false,
    "status": true
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "24",
    "percentage": "40",
    "isHideFloor": false,
    "status": true
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "24",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "24",
    "percentage": "7.00",
    "isHideFloor": false,
    "status": true
  },
  "internalPlastering": {
    "label": "Internal Plastering",
```

```
"floorsCompleted": "24",
"percentage": "3.50",
"isHideFloor": false,
"status": true
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "24",
  "percentage": "3.50",
  "isHideFloor": false,
  "status": true
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
}
```

```
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "71.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "3932379.00",
  "selectedBuildUpValue": "379.50",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,

```

```
    "_id": "672c423ed6092bb57512d24e",
    "name":
"externallmg_1730953789890_WhatsApp_Image_20241107_at_095524_2.jpeg",
    "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789890_WhatsApp_Image_20241107_at_095524_2.jpeg",
    "orientation": "portrait"
  }
],
"selfieWithSiteVisitImages": [
  {
    "status": false,
    "_id": "672c423ed6092bb57512d24d",
    "name":
"externallmg_1730953789883_WhatsApp_Image_20241107_at_095524_1.jpeg",
    "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789883_WhatsApp_Image_20241107_at_095524_1.jpeg",
    "orientation": "portrait"
  }
],
"externalPhotos": [
  {
    "status": false,
    "_id": "672c423ed6092bb57512d246",
    "name":
"externallmg_1730953789687_WhatsApp_Image_20241107_at_095518_1.jpeg",
    "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789687_WhatsApp_Image_20241107_at_095518_1.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "672c423ed6092bb57512d24f",
    "name":
"externallmg_1730953789940_WhatsApp_Image_20241107_at_095524.jpeg",
    "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789940_WhatsApp_Image_20241107_at_095524.jpeg",
    "orientation": "portrait"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "14611.00",
```

```
"max": "15064.00"
},
"builtUpRateRange": {
  "min": "13283.00",
  "max": "13695.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Approximate Rate Lead",
  "value": "APPROXIMATE_LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": false,
"finalValuationArea": "345.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "READYFORCHECKER",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6729ba710e38ca1455e955e9",
"ownerName": "Mr. Samiruddin Shafiuddin Kazi",
"ownerPhoneNo": "9892978666",
"appAddress": "FLAT NO 1/1204 BLDG NO 1 12TH FLOOR SALASAR COURT YARD
GREEN WOODS ENCLAVE HATKESH INDUSTRIAL ROAD OFF GREEN COURT
```

CLUB GHODBUNDER VILLAGE MIRA ROAD EAST THANE",

"remark": "Sourcing person Ashish Bhabad 7709815152",

"documents": [

```
{
  "documentType": {
    "value": "60ae1246aa6d152c1801b2e4",
    "label": "Index- II"
  },
```

```
"inputs": {
  "documentDate": "27/09/2024",
  "from": {
    "value": "Builder",
    "label": "Builder"
  },
```

```
"Builder": "M/s. Salasar Maxus Builder LLP",
```

```
"to": {
  "value": "purchaser",
  "label": "purchaser"
},
```

```
"purchaser": "Mr. Samiruddin Shafiuddin Kazi",
```

```
"number": {
  "value": "Document_No",
  "label": "Document No"
},
```

```
"Document_No": "19296/2024"
```

```
},
"isHardCopy": false,
"displayStatus": true,
"id": "328602",
```

```
"path": "cases/6729ba710e38ca1455e955e9/
```

document\_1730804681327\_30831.pdf",

```
"fileName": "document_1730804681327_30831.pdf"
```

```
},
{
  "documentType": {
    "label": "Agreement For Sale",
    "value": "60ae1254aa6d152c1801b326"
```

```
},
"inputs": {
  "documentDate": "27/09/2024",
  "from": {
    "value": "Builder",
    "label": "Builder"
  },
```

```
"Builder": "M/s. Salasar Maxus Builder LLP",
```

```
"to": {
```

```
    "value": "purchaser",
    "label": "purchaser"
  },
  "purchaser": "Mr. Samiruddin Shafiuddin Kazi",
  "number": {
    "value": "Document_No",
    "label": "Document No"
  },
  "Document_No": "19296/2024"
},
"isHardCopy": false,
"displayStatus": true,
"id": "333365",
"path": "cases/6729ba710e38ca1455e955e9/
document_1730809951955_1730809949955_SAMIRUDDIN_KAZI_AGREEMENT.pdf",
"fileName":
"document_1730809951955_1730809949955_SAMIRUDDIN_KAZI_AGREEMENT.pdf"
},
{
  "documentType": {
    "value": "60ae129faa6d152c1801b47d",
    "label": "RERA Certificate"
  },
  "inputs": {
    "documentDate": "10/05/2022",
    "nameOfApprovingAuthority": {
      "value": "Maharashtra_Real_Estate_Regulatory_Authority",
      "label": "Maharashtra Real Estate Regulatory Authority"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "P51700035177"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1730979601448_rera.pdf",
  "path": "cases/6729ba710e38ca1455e955e9/document_1730979601448_rera.pdf",
  "id": "703860",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Thu Nov 07 2024 11:40:01 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2ea",
```

```
    "label": "Commencement Certificate"
  },
  "inputs": {
    "documentDate": "20/09/2022",
    "nameOfApprovingAuthority": {
      "value": "Mira_Bhayander_Municipal_Corporation",
      "label": "Mira Bhayander Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "MNP / NR / 2341 / 2022 - 2023"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1730979646365_150987.pdf",
  "path": "cases/6729ba710e38ca1455e955e9/
document_1730979646365_150987.pdf",
  "id": "215617",
  "uploadedBy": "627221f4afd7d55eddeddcb4",
  "createdAt": "Thu Nov 07 2024 11:40:46 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1277aa6d152c1801b3cc",
    "label": "Approved Building Plan"
  },
  "inputs": {
    "documentDate": "20/09/2022",
    "nameOfApprovingAuthority": {
      "value": "Mira_Bhayander_Municipal_Corporation",
      "label": "Mira Bhayander Municipal Corporation"
    },
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "MNP / NR / 2341 / 2022 - 2023"
  },
  "isHardCopy": false,
  "displayStatus": true,
  "fileName": "document_1731400277594_125583.pdf",
  "path": "cases/6729ba710e38ca1455e955e9/
document_1731400277594_125583.pdf",
  "id": "394625",
```

```
"uploadedBy": "627221f4afd7d55eddeddcb4",
"createdAt": "Tue Nov 12 2024 08:31:17 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "012179",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "449451",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Nov 05 2024 06:25:53 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. Samiruddin Shafiuddin Kazi",
    "phone": "9892978666",
    "ownershipShare": "",
    "email": "",
    "id": "475207"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Carpet",
    "squareMeterArea": "32.05",
    "totalAreaDocument": "345",
    "docBultupPercentage": "10",
    "docFinalBultUp": "379.50",
    "docFinalBultUpSquareMeter": "35.26",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
```

```
"docFinalSaleableSquareMeter": "0.00",
"id": "525291"
}
],
"images": [],
"indicatorArr": [
{
"carpetArea": {
"area": "345.00",
"squareMeterArea": "32.05",
"expectedRate": "14637.68",
"percentage": ""
},
"builtUpArea": {
"area": "379.50",
"squareMeterArea": "35.26",
"expectedRate": "13306.98",
"percentage": "10"
},
"saleableArea": {
"area": "",
"squareMeterArea": "0.00",
"expectedRate": "0.00",
"percentage": ""
},
"printInReport": true,
"_id": "672c9cb252140a502a6a268e",
"property": "Salasar Courtyard, Mira Road",
"area": "345",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Middle",
"source": "Housing.Com",
"expectedPrice": "5050000",
"expectedRate": "14637.68",
"builtUpExpectedRate": "13306.98",
"image": "cases/6729ba710e38ca1455e955e9/
indicator_1730976505252_Image.png",
"squareMeter": "32.05",
"id": "724333"
},
{
"carpetArea": {
"area": "345.00",
```

```
"squareMeterArea": "32.05",
"expectedRate": "15063.77",
"percentage": ""
},
"builtUpArea": {
  "area": "379.50",
  "squareMeterArea": "35.26",
  "expectedRate": "13694.33",
  "percentage": "10"
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "672c9cb252140a502a6a268f",
"property": "Salasar Courtyard, Mira Road",
"area": "345",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Carpet",
"floor": "Higher",
"source": "square_yards",
"expectedPrice": "5197000",
"expectedRate": "15063.77",
"builtUpExpectedRate": "13694.33",
"image": "cases/6729ba710e38ca1455e955e9/
indicator_1730976573463_Image.png",
"squareMeter": "32.05",
"id": "455318"
},
{
  "carpetArea": {
    "area": "231.00",
    "squareMeterArea": "21.46",
    "expectedRate": "14766.23",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "254.10",
    "squareMeterArea": "23.61",
    "expectedRate": "13423.85",
    "percentage": "10"
  }
}
```

```
},
"saleableArea": {
  "area": "",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "672c9cb252140a502a6a2690",
"property": "Salasar Courtyard, Mira Road",
"area": "231",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "16",
"source": "Index_no.2",
"expectedPrice": "3411000",
"expectedRate": "14766.23",
"builtUpExpectedRate": "13423.85",
"image": "cases/6729ba710e38ca1455e955e9/
indicator_1730976674850_Image.png",
"squareMeter": "21.46",
"id": "830423"
},
{
  "carpetArea": {
    "area": "231.00",
    "squareMeterArea": "21.46",
    "expectedRate": "14610.39",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "254.10",
    "squareMeterArea": "23.61",
    "expectedRate": "13282.17",
    "percentage": "10"
  },
  "saleableArea": {
    "area": "",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "672c9cb252140a502a6a2691",
```



```
"property": "Salasar Courtyard, Mira Road",
"area": "231",
"builtUpPercentage": "10",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "21",
"source": "Index_no.2",
"expectedPrice": "3375000",
"expectedRate": "14610.39",
"builtUpExpectedRate": "13282.17",
"image": "cases/6729ba710e38ca1455e955e9/
indicator_1730976730852_Image.png",
"squareMeter": "21.46",
"id": "792795"
}
],
"externallImages": [
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672c423ed6092bb57512d245",
  "name":
"externallmg_1730953789668_WhatsApp_Image_20241107_at_095447.jpeg",
  "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789668_WhatsApp_Image_20241107_at_095447.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672c423ed6092bb57512d246",
  "name":
"externallmg_1730953789687_WhatsApp_Image_20241107_at_095518_1.jpeg",
  "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789687_WhatsApp_Image_20241107_at_095518_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672c423ed6092bb57512d247",
  "name":
"externallmg_1730953789696_WhatsApp_Image_20241107_at_095518.jpeg",
  "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789696_WhatsApp_Image_20241107_at_095518.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672c423ed6092bb57512d248",
    "name":
"externallmg_1730953789729_WhatsApp_Image_20241107_at_095520.jpeg",
    "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789729_WhatsApp_Image_20241107_at_095520.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672c423ed6092bb57512d249",
    "name":
"externallmg_1730953789739_WhatsApp_Image_20241107_at_095521.jpeg",
    "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789739_WhatsApp_Image_20241107_at_095521.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672c423ed6092bb57512d24a",
    "name":
"externallmg_1730953789783_WhatsApp_Image_20241107_at_095522.jpeg",
    "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789783_WhatsApp_Image_20241107_at_095522.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672c423ed6092bb57512d24b",
    "name":
"externallmg_1730953789823_WhatsApp_Image_20241107_at_095523_1.jpeg",
    "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789823_WhatsApp_Image_20241107_at_095523_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "672c423ed6092bb57512d24c",
```

```
    "name":
"externallmg_1730953789830_WhatsApp_Image_20241107_at_095523.jpeg",
  "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789830_WhatsApp_Image_20241107_at_095523.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672c423ed6092bb57512d24d",
  "name":
"externallmg_1730953789883_WhatsApp_Image_20241107_at_095524_1.jpeg",
  "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789883_WhatsApp_Image_20241107_at_095524_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672c423ed6092bb57512d24e",
  "name":
"externallmg_1730953789890_WhatsApp_Image_20241107_at_095524_2.jpeg",
  "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789890_WhatsApp_Image_20241107_at_095524_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672c423ed6092bb57512d24f",
  "name":
"externallmg_1730953789940_WhatsApp_Image_20241107_at_095524.jpeg",
  "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789940_WhatsApp_Image_20241107_at_095524.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672c423ed6092bb57512d250",
  "name":
"externallmg_1730953789948_WhatsApp_Image_20241107_at_095525_1.jpeg",
  "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789948_WhatsApp_Image_20241107_at_095525_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "672c423ed6092bb57512d251",
  "name":
"externallmg_1730953789998_WhatsApp_Image_20241107_at_095525.jpeg",
  "path": "cases/6729ba710e38ca1455e955e9/
externallmg_1730953789998_WhatsApp_Image_20241107_at_095525.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
{
  "originalname": "igr_16042.pdf",
  "filename": "1730976890978_igr_16042.pdf",
  "path": "cases/6729ba710e38ca1455e955e9/
processingDocuments/1730976890978_igr_16042.pdf",
  "size": "160416",
  "createdAt": "Thu Nov 07 2024 10:54:51 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "1720849454325_1720174948082.xlsx",
  "filename": "1730976890996_1720849454325_1720174948082.xlsx",
  "path": "cases/6729ba710e38ca1455e955e9/
processingDocuments/1730976890996_1720849454325_1720174948082.xlsx",
  "size": "1842515",
  "createdAt": "Thu Nov 07 2024 10:54:51 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "igr_1436.pdf",
  "filename": "1730976891204_igr_1436.pdf",
  "path": "cases/6729ba710e38ca1455e955e9/
processingDocuments/1730976891204_igr_1436.pdf",
  "size": "158937",
  "createdAt": "Thu Nov 07 2024 10:54:51 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "igr_11299.pdf",
  "filename": "1730976891220_igr_11299.pdf",
  "path": "cases/6729ba710e38ca1455e955e9/
processingDocuments/1730976891220_igr_11299.pdf",
  "size": "162595",
```

```
"createdAt": "Thu Nov 07 2024 10:54:51 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "igr_14594.pdf",
  "filename": "1730976891224_igr_14594.pdf",
  "path": "cases/6729ba710e38ca1455e955e9/processingDocuments/1730976891224_igr_14594.pdf",
  "size": "159273",
  "createdAt": "Thu Nov 07 2024 10:54:51 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "60f915d3f3dd69653a592199"
},
{
  "originalname": "WhatsApp Image 2024-11-12 at 1.54.18 PM.jpeg",
  "filename": "1731401236094_WhatsApp_Image_20241112_at_15418_PM.jpeg",
  "path": "cases/6729ba710e38ca1455e955e9/processingDocuments/1731401236094_WhatsApp_Image_20241112_at_15418_PM.jpeg",
  "size": "125583",
  "createdAt": "Tue Nov 12 2024 08:47:16 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "627221f4afd7d55eddeddcb4"
},
{
  "originalname": "WhatsApp Image 2024-11-12 at 1.54.26 PM.jpeg",
  "filename": "1731401236213_WhatsApp_Image_20241112_at_15426_PM.jpeg",
  "path": "cases/6729ba710e38ca1455e955e9/processingDocuments/1731401236213_WhatsApp_Image_20241112_at_15426_PM.jpeg",
  "size": "92877",
  "createdAt": "Tue Nov 12 2024 08:47:16 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "627221f4afd7d55eddeddcb4"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "60f915d3f3dd69653a592199",
      "role": "MAKER + RATE VERIFIER + CHEAKER",
      "firstName": "Shobha",
      "lastName": "Kuperkar",
      "profilePhoto": "users/60f915d3f3dd69653a592199/profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
  }
]
```

```
    "_id": "672a0311e299eb15f587f1e6",
    "note": "51 Lakh approx.",
    "taskId": "6729ba71fec5941487b38bd0",
    "createdAt": "2024-11-05T11:35:45.437Z"
  }
],
"createdAt": "2024-11-05T06:25:53.162Z",
"updatedAt": "2024-11-12T09:40:11.566Z",
"__v": 0,
"updatedBy": "60f915d3f3dd69653a592199",
"uniqueNo": "",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 1204, 12th Floor, Building No 1, Salasar
Courtyard , Green Wood Enclave, Hatkesh Industrial Road, Opp. Green Court Club,
Village - Ghodbunder, Mira Road (East), Taluka - Thane, District - Thane, PIN Code -
401 107, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "Mr. Michelle",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Site Person",
"rerald": "",
"siteVisitContactNo": "7506978458",
"buildingServicesRate": "2700",
"finalAreaType": "Carpet Area",
"finalAsPerArea": "Agreement For Sale",
"finalBuiltUpPercentage": "10",
"finalCarpetConvertToBuiltUpPer": "10",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Carpet Area in Sq. Ft. = 345.00",
"flatRate": "14800",
"landOtherRate": "12100",
"shopDetails": {
  "typeOfShops": null,
  "roadFacing": false,
  "mall": false
},
"landDetails": {
```

```

"holdType": {
  "label": "Free Hold",
  "value": "Free_Hold"
},
"leaseDetails": {
  "lessorName": "",
  "lesseeName": "",
  "leasePremium": "",
  "leaseRent": "",
  "leasePeriod": 0,
  "leaseFrom": "",
  "leaseTo": "",
  "remainingLeasePeriod": 0,
  "leaseDate": ""
}
},
"finalSaleablePercentage": "0",
"builtupPercentage": "10",
"carpetTotal": "0",
"extendOfSiteRemark": "",
"finalBuiltupArea": "0.00",
"finalCarpetArea": "0.00",
"finalSalableArea": "0.00",
"otherCarpetTotal": "0",
"salablePercentage": "10",
"siteMeasurementRemark": "",
"toBeAdded": "",
"reportGeneratedDate": "Tue Nov 12 2024 08:26:43 GMT+0000 (Coordinated
Universal Time)",
"siteVisitDate": "2024-11-06"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			