

```
{
  "typeOfReport": {
    "label": "Unit",
    "value": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "MSME Loan",
    "value": "MSME_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "firstName": "Roshni",
    "type": "CREDITOFFICER",
    "_id": "66989d3fac43b53f525a159f",
    "email": "roshni.namdeo@sbi.co.in",
    "lastName": "Patil",
    "mobileNo": "",
    "workMobileNo": "7905337863"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "0",
    "discussWithPerson": "Roshni",
    "expectedFees": null,
    "quotedAmount": "5000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60b7177d2ffdf65bcd65882a",
  "role": "PICKUPPERSON",
  "firstName": "Saurabh",
  "email": "saurabhvelonde143@gmail.com",
  "lastName": "Velonde",
  "mobileNo": "8691048846",
  "shortName": "SSV",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60b7177d2ffdf65bcd65882a/
profilePhoto_1722582806298_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "648fcad91b499c2d52dc86f3",
  "role": "SITEENGINEER",
  "firstName": "Barkat",
  "email": "barkathodekar68@gmail.com",
  "lastName": "Hodekar",
  "mobileNo": "8879011615",
  "designation": "Site Engg",
  "shortName": "Barkat",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62691c48afd7d55eddecfda3",
  "role": "FRONTDESK",
  "firstName": "Bhavika",
  "email": "bhavikachavan0102@gmail.com",
```

```
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "64dc7184ccaf1e7b7f637f47",
"role": "FRONTDESK",
"firstName": "Binumon",
"email": "binu@vastukala.org",
"lastName": "Moozhickal",
"mobileNo": "9930252906",
"designation": "Back Office Team Leader",
"shortName": "BS",
"workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
"profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
}
],
},
]
```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.048424763063096",
  "longitude": "72.91038773953915"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.91038773953915,
```

```
19.048424763063096
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-16",
      "remark": "Vastukala + Yogesh Vankar"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-14",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-13",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-14",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-15",
      "remark": "MANUAL_IN_TASK"
    },
    {
      "status": "COMPLETED",
      "dateTime": "2024-11-15",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"compositionFlatType": {
  "value": "Single_Unit",
  "label": "Single Unit"
},
}
```

```
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Borla",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": " Mumbai Suburban",
```

```
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Unity Industrial Premises Co-op. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
```



```
"name": "Street 1",
"key": "street1",
"value": "Waman Tukaram Patil Road, Deonar",
"label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Majithia Industrial Estate",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "57(Part) & 58(Part)",
  "label": true
}
```

```
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "851 & 852 ",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "4A",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
```

```
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN – 400 088",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"flatSpecifications": {
  "roof": {
    "value": "ACC_Sheet_Roofing",
    "label": "ACC Sheet Roofing"
  },
  "flooring": {
```

```
"value": "Kota_Flooring",
"label": "Kota Flooring"
},
"doors": {
"value": "MS_Rolling_Shutter",
"label": "MS Rolling Shutter"
},
"windows": {
"value": "N.A.",
"label": "N.A."
},
"fittings": {
"value": "Open-Conduit_plumbing_with_Casing_Capping_Electrical_wiring_",
"label": "Open-Conduit plumbing with Casing Capping Electrical wiring "
},
"finishing": {
"value": "Cement_Plastering",
"label": "Cement Plastering"
}
},
"general": {
"ownership": {
"value": "sole_ownership",
"label": "sole ownership"
},
"populationClassList": {
"value": "MiddleClass",
"label": "Middle Class"
},
"populationGroupList": {
"value": "Semi_Urban",
"label": "Semi Urban"
},
"townplanApprovedByList": {
"value": "MCGM",
"label": "Municipal Corporation of Greater Mumbai (MCGM)"
},
"whetherCoveredUnderAnyState": {
"value": "No",
"label": "No"
},
"asPerActualAgreement": {
"north": "DP Road",
"west": "Eastern Fwy",
"south": "D'Mart",
"east": "Open Plot"
}
```

```
},
"asPerDocumentAgreement": {
  "north": "Details not available",
  "west": "Details not available",
  "south": "Details not available",
  "east": "Details not available"
},
"unitBoundaries": {
  "asPerActual": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "asPerDocument": {
    "north": "",
    "west": "",
    "south": "",
    "east": ""
  },
  "isDisplay": false,
  "title": "Boundaries of The Flat"
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"extraDetailOfProperty": "As per site inspection the composition of Unit is Working Area + Cabin + Toilet",
"dateOfIssusApprovePlan": "As Occupancy Certificate is available it may be assumed that the construction is as per Sanctioned Plan.",
"approvePlanVerified": "N.A",
"empanelledOfApprovePlan": "N.A",
"unauthorizedConstruction": "",
"extraDetailOfBuilding": "",
"compoundWall": ""
```

```
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"compositeRate": {
  "remark": "",
  "depreciationPercentage": "72",
  "depreciationRatioOfBuilding": "",
  "salvageValue": "10",
  "depreciatedCostOfConstruction": "19700",
  "depreciatedBuildingRate": "700"
},
"igrRate": {
  "propertyName": "Industrial",
  "rate": "162880",
  "landRate": "83100",
  "igrImage": "cases/6735773bdca8ac11abc27fef/igr_1731739555979_Image.png",
  "squareMeterGuideLineRate": "162880.00",
  "squareFeetGuideLineRate": "15132.00"
},
"igrFinalRate": {
  "floorRatePercentage": "0",
  "depreciationPercentage": "52",
  "rate": "11574.00",
  "squareMeterGuideLineRate": "124586.00",
  "squareFeetGuideLineRate": "11574.00"
},
"outgoingDetail": {
  "areaStatusList": {
    "value": "Middle_Class",
    "label": "Middle Class"
  },
  "propertyTypeOfUseList": {
    "value": "Industrial",
    "label": "Industrial"
  },
  "propertyOccupiedByList": {
    "value": "Owner_Occupied",
    "label": "Owner Occupied"
  },
  "monthlyRent": "N.A",
```

```
"assessmentNo": "Details not available",
"taxPaidHolderName": "Details not available",
"taxAmount": "Details not available",
"electricityServiceConnectionNo": "Details not available",
"meterCardHolderName": "Details not available",
"undividedAreaOfLandAsPerSaleDeed": "Details not available",
"floorSpaceIndex": "As per MCGM norms",
"tenantName": "",
"maintenanceOfFlat": "Normal"
},
"marketability": {
  "marketabilityList": {
    "value": "Good",
    "label": "Good"
  },
  "anyFavouringForExtraPotentialValue": "Located in developed area",
  "negativeFactorsOfAffectMarketValue": "No"
},
"siteMeasurement": {
  "roof": {
    "value": "rcc_Slab",
    "label": "R. C. C. Slab"
  },
  "partitions": {
    "value": "6\"_Thk._Brick_Masonry",
    "label": "6\" Thk. Brick Masonery"
  },
  "waterTank": {
    "value": "MunicipalWaterSupply",
    "label": "Municipal Water Supply"
  },
  "pavementLaid": {
    "value": "Yes",
    "label": "Yes"
  },
  "carParking": "Open Car Parking ",
  "constructionWorkStatus": {
    "value": "Completed",
    "label": "Completed"
  },
  "asthetikLook": {
    "value": "Plain_Looking",
    "label": "Plain Looking"
  },
  "dateOfConstruction": {
    "date": "1",
```

```
"month": "1",
"year": "1976",
"fullDate": "1/1/1976"
},
"planningArea": {
  "value": "Residential",
  "label": "Residential"
},
"typeOfStructure": {
  "value": "R.C.C._Framed_Structure",
  "label": "R.C.C. Framed Structure"
},
"typeOfFoundation": {
  "value": "rcc",
  "label": "R.C.C. Foundation"
},
"qualityOfConstruction": {
  "value": "Normal",
  "label": "Normal"
},
"materialUsedList": {
  "value": "Good",
  "label": "Good"
},
"buildingSpecification": {
  "value": "Standard",
  "label": "Standard"
},
"structuralSafety": {
  "value": "Normal",
  "label": "Normal"
},
"protAgainstNatDis": {
  "value": "Designed_as_per_I.S._codes",
  "label": "Designed as per I.S. codes"
},
"sewerageSystem": {
  "value": "MunicipalSewerageSystem",
  "label": "Connected to Municipal Sewerage System"
},
"walls": {
  "value": "1",
  "label": "Yes"
},
"appearanceOfTheBuilding": {
  "value": "Normal",
```



```
"label": "Normal"
},
"maintenanceOfTheBuilding": {
  "value": "Normal",
  "label": "Normal"
},
"maintenancelssues": {
  "value": "1",
  "label": "Yes"
},
"visibleDamageInBuilding": {
  "value": "1",
  "label": "Yes"
},
"systemOfAirConditioning": {
  "value": "1",
  "label": "Yes"
},
"provisionOfFirefighting": {
  "value": "1",
  "label": "Yes"
},
"groundStilt": {
  "value": "ground",
  "label": "Ground"
},
"yearOfConstructionAsPer": {
  "value": "Building_Completion_Certificate",
  "label": "Building Completion Certificate"
},
"isSiteVisitAllowed": true,
"ageOfBuilding": "48",
"totalLifeBuilding": "60",
"estimatedAge": "12",
"noOfBasement": "",
"noOfPodium": "",
"noOfAmenityFloors": "",
"noOfFloors": "2",
"flatFloorNo": "1",
"noOfLifts": "1",
"noOfDwellingUnitsInBuilding": "18"
},
"finalPlinthArea": {
  "area": "640.00",
  "areaType": "Built Up",
  "measurementType": "Sq. Ft.",
```

```
"areaAsPer": "Area as per Agreement"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "cases/6735773bdca8ac11abc27fef/
routeMap_1731752833786_Image.png",
    "routeLat": "19.048556",
    "routeLng": "72.910389",
    "stationName": "Govandi",
    "routeDistance": "1.3 Km",
    "routeStation": {
      "value": "Railway_Station",
      "label": "Railway Station"
    }
  },
  "finalLatLng": {
    "coordinates": [
      0,
      0
    ],
    "type": "Point"
  },
  "showLocation": {
    "latLng": false,
    "finallatLng": false
  },
  "locationMapImg": [
    {
      "id": "z86dww",
      "name": "z86dww",
      "image": "cases/6735773bdca8ac11abc27fef/
routeMap_1731752617538_Image.png"
    }
  ],
  "valuation": {
    "fairMarketValue": {
      "costOfConstruction": "",
      "depreciationPercentage": "",
      "depreciatedCostOfConstruction": "",
      "totalFairMarketValue": ""
    },
    "wardrobesRate": "0",
    "totalwardrobesRate": "0",
    "wardrobesQty": "0",
    "showcasesQty": "0",
```

```
"showcasesRate": "0",
"totalshowcasesRate": "0",
"kitchenArrangementsQty": "0",
"kitchenArrangementsRate": "0",
"totalkitchenArrangementsRate": "0",
"superfineFinishQty": "0",
"superfineFinishRate": "0",
"totalsuperfineFinishRate": "0",
"interiorDecorationsQty": "0",
"interiorDecorationsRate": "0",
"totalinteriorDecorationsRate": "0",
"electricityDepositsQty": "0",
"electricityDepositsRate": "0",
"totalelectricityDepositsRate": "0",
"extraCollapsibleGatesQty": "0",
"extraCollapsibleGatesRate": "0",
"totalextraCollapsibleGatesRate": "0",
"potentialValueQty": "0",
"potentialValueRate": "0",
"totalpotentialValueRate": "0",
"othersQty": "0",
"othersRate": "0",
"totalothersRate": "0",
"finaltotal": "12608000.00",
"finalValue": "12608000.00",
"distressValuePercentage": "80",
"realizableValuePercentage": "90",
"bookValueDocument": null,
"purchaseValueDocument": null,
"bookValue": "0"
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Sat Nov 16 2024 10:46:44 GMT+0000 (Coordinated Universal Time)",
  "number": "2309094",
  "dayCount": "13",
  "monthCount": "179",
  "generatedBy": "64dc7184ccaf1e7b7f637f47"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "7407360.00",
  "selectedBuildUpValue": "640.00",
  "selectedBuildUpMeasurementType": "Sq. Ft."
},
"reportImages": {
  "frontPageImages": [
    {
      "status": false,
      "_id": "673818e8d1078a4ea7f5b314",
      "name": "externalImg_1731729639530_1731729624845_image_19.jpeg",
      "path": "cases/6735773bdca8ac11abc27fef/
externalImg_1731729639530_1731729624845_image_19.jpeg",
      "orientation": "landscape"
    }
  ],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [
    {
      "status": false,
```

```
    "_id": "673818e8d1078a4ea7f5b314",
    "name": "externallmg_1731729639530_1731729624845_image_19.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729639530_1731729624845_image_19.jpeg",
    "orientation": "landscape"
  }
],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": [
  {
    "status": false,
    "_id": "673818e8d1078a4ea7f5b302",
    "name": "Working Area",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729630990_1731729624845_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "673818e8d1078a4ea7f5b304",
    "name": "Working Area",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729631929_1731729624845_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "673818e8d1078a4ea7f5b30a",
    "name": "Working Area",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729634712_1731729624845_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "673818e8d1078a4ea7f5b30d",
    "name": "Working Area",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729635922_1731729624845_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "673818e8d1078a4ea7f5b306",
    "name": "Working Area",
```

```
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729632809_1731729624845_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "673818e8d1078a4ea7f5b311",
    "name": "Working Area",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729637847_1731729624845_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "status": false,
    "_id": "6738190e572e264e52130948",
    "name": "Working Area",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729676629_1731729674263_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "status": false,
    "_id": "673818e8d1078a4ea7f5b305",
    "name": "Working Area",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729632436_1731729624845_image_4.jpeg",
    "orientation": "portrait"
  }
]
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "20728.00",
    "max": "27000.00"
  },
  "builtUpRateRange": {
    "min": "17273.00",
    "max": "22500.00"
  },
  "saleableRateRange": {
    "min": "18750.00",
    "max": "18750.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
```



```
"title": "Present value of the flat (incl. car parking, if provided)",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
},
"wardrobes": {
  "title": "Wardrobes",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```

```
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
```

```
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "640.00",
"empanelmentNo": [
  "SME/TCC/38/IBBI/3"
],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SIGNEDREPORTATTACH",
"paymentStatus": "PENDING",
"invoiceIds": [],
"paymentIds": [],
"_id": "6735773bdca8ac11abc27fef",
"ownerName": "Mr.Porkodi & Others",
"ownerPhoneNo": "9004197987",
"appAddress": "Unit no. 4A, First Floor, Majiyhia Industrial Estate, Chembur ",
"remark": "Vastukala + Yogesh Vankar",
"documents": [
  {
    "documentType": {
      "value": "60af48bf2ffdf65bcd6585fa",
      "label": "Agreement for sale"
    },
    "inputs": {
      "documentDate": "18/04/1979",
      "from": {
        "value": "Builder",
        "label": "Builder"
      }
    },
    "Builder": "The Space Builder Private Limited",
```

```
"to": {
  "value": "purchaser",
  "label": "purchaser"
},
"purchaser": "P. Nadarajan",
"number": {
  "value": "No",
  "label": "No"
},
"No": "P 730/75"
},
"isHardCopy": false,
"displayStatus": true,
"id": "480840",
"path": "cases/6735773bdca8ac11abc27fef/
document_1731557133251_1731557129936_4A.pdf",
"fileName": "document_1731557133251_1731557129936_4A.pdf"
},
{
  "documentType": {
    "value": "60ae1267aa6d152c1801b380",
    "label": "Building Completion Certificate"
  },
  "inputs": {
    "documentDate": "04/10/1976",
    "nameOfApprovingAuthority": {
      "value": "Municipal_Corporation_of_Greater_Mumbai",
      "label": "Municipal Corporation of Greater Mumbai"
    },
    "number": {
      "value": "No",
      "label": "No"
    },
    "No": "CE / 1480 / BSIII / AH"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1731753004915_document_1689226683211_BCC.pdf",
  "path": "cases/6735773bdca8ac11abc27fef/
document_1731753004915_document_1689226683211_BCC.pdf",
  "id": "204623",
  "uploadedBy": "62691c48afd7d55eddecfda3",
  "createdAt": "Sat Nov 16 2024 10:30:05 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
```

```
    "value": "60ae1249aa6d152c1801b2f1",
    "label": "Society Maintenance Bill"
  },
  "inputs": {
    "documentDate": "16/06/2019",
    "remark": "In the name of Mr.Porkodi & Others",
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "166"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/6735773bdca8ac11abc27fef/
document_1731759399067_maintanance_bill.pdf",
  "fileName": "document_1731759399067_maintanance_bill.pdf",
  "id": "716672",
  "uploadedBy": "64dc7184ccaf1e7b7f637f47",
  "createdAt": "Sat Nov 16 2024 12:17:19 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "012369",
"createdBy": "60b7177d2ffdf65bcd65882a",
"caseHistory": [
  {
    "id": "120091",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Nov 14 2024 04:06:19 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr.Porkodi & Others",
    "phone": "9004197987",
    "ownershipShare": "",
    "email": "",
    "id": "701860"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [
  {
    "measurementType": {
```

```
    "value": "Square_Feet",
    "label": "Square Feet"
  },
  "id": "421729",
  "name": "Working Area",
  "length": "34.08",
  "length1": "34",
  "length2": "1",
  "width": "15.58",
  "width1": "15",
  "width2": "7",
  "totalArea": "531.13",
  "images": [],
  "extraAreas": [],
  "finalArea": "531.13"
}
],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [
  {
    "typeOfDocument": {
      "label": " Agreement",
      "value": "652d16a0316e1359cebd3c15"
    },
    "docMeasurementType": {
      "value": "Square_Feet",
      "label": "Square Feet"
    },
    "selectAreaTypeDocument": "Built_Up",
    "squareMeterArea": "59.46",
    "totalAreaDocument": "640",
    "docBultupPercentage": "",
    "docFinalBuiltUp": "0.00",
    "docFinalBuiltUpSquareMeter": "0.00",
    "docSaleablePercentage": "",
    "docFinalSaleable": "0.00",
    "docFinalSaleableSquareMeter": "0.00",
    "id": "810272"
  }
],
"images": [],
"indicatorArr": [
  {
    "carpetArea": {
      "area": "916.67",
```

```
"squareMeterArea": "85.16",
"expectedRate": "20727.20",
"percentage": ""
},
"builtUpArea": {
  "area": "1100.00",
  "squareMeterArea": "102.19",
  "expectedRate": "17272.73",
  "percentage": "20"
},
"saleableArea": {
  "area": "0.00",
  "squareMeterArea": "0.00",
  "expectedRate": "0.00",
  "percentage": ""
},
"printlnReport": true,
"_id": "67383fe7e077c54e5323a5fd",
"property": "Industrial Unit",
"area": "1100",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "price_Indicator",
"areaType": "Built_Up",
"floor": "",
"source": "https://www.99acres.com/",
"expectedPrice": "19000000",
"expectedRate": "20727.20",
"builtUpExpectedRate": "19000000",
"image": "cases/6735773bdca8ac11abc27fef/
indicator_1731738623802_Image.png",
"squareMeter": "102.19",
"id": "641612"
},
{
  "carpetArea": {
    "area": "1388.89",
    "squareMeterArea": "129.03",
    "expectedRate": "26999.98",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1666.67",
    "squareMeterArea": "154.84",
    "expectedRate": "22499.96",
    "percentage": "20"
  }
}
```

```
},
"saleableArea": {
  "area": "2000.00",
  "squareMeterArea": "185.81",
  "expectedRate": "18750.00",
  "percentage": "20"
},
"printlnReport": true,
"_id": "67383fe8e077c54e5323a5fe",
"property": "Industrial Unit",
"area": "2000",
"builtUpPercentage": "20",
"saleablePercentage": "20",
"rateType": "price_Indicator",
"areaType": "Saleable",
"floor": "",
"source": "magic_bricks",
"expectedPrice": "37500000",
"expectedRate": "18750",
"builtUpExpectedRate": "22499.96",
"image": "cases/6735773bdca8ac11abc27fef/
indicator_1731738837739_Image.png",
"squareMeter": "185.81",
"id": "603390"
},
{
  "carpetArea": {
    "area": "180.00",
    "squareMeterArea": "16.72",
    "expectedRate": "23333.33",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "216.00",
    "squareMeterArea": "20.07",
    "expectedRate": "19444.44",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67383fe8e077c54e5323a600",
```



```
"property": "Industrial Unit",
"area": "180",
"builtUpPercentage": "20",
"saleablePercentage": "0",
"rateType": "sale_Instance",
"areaType": "Carpet",
"floor": "",
"source": "Index_no.2",
"expectedPrice": "4200000",
"expectedRate": "23333.33",
"builtUpExpectedRate": "19444.44",
"image": "cases/6735773bdca8ac11abc27fef/
indicator_1731739415986_Image.png",
"squareMeter": "16.72",
"id": "282169"
},
{
  "carpetArea": {
    "area": "833.57",
    "squareMeterArea": "77.44",
    "expectedRate": "25252.83",
    "percentage": ""
  },
  "builtUpArea": {
    "area": "1000.29",
    "squareMeterArea": "92.93",
    "expectedRate": "21043.90",
    "percentage": "20"
  },
  "saleableArea": {
    "area": "0.00",
    "squareMeterArea": "0.00",
    "expectedRate": "0.00",
    "percentage": ""
  },
  "printlnReport": true,
  "_id": "67383fe8e077c54e5323a601",
  "property": "Industrial Unit",
  "area": "1000.29",
  "builtUpPercentage": "20",
  "saleablePercentage": "0",
  "rateType": "sale_Instance",
  "areaType": "Built_Up",
  "floor": "",
  "source": "Index_no.2",
  "expectedPrice": "21050000",
```

```
    "expectedRate": "25252.83",
    "builtUpExpectedRate": "21050000",
    "image": "cases/6735773bdca8ac11abc27fef/
indicator_1731739473279_Image.png",
    "squareMeter": "92.93",
    "id": "861185"
  }
],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b301",
    "name": "externallmg_1731729630771_1731729624845_image_0.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729630771_1731729624845_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b302",
    "name": "externallmg_1731729630990_1731729624845_image_1.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729630990_1731729624845_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b303",
    "name": "externallmg_1731729631448_1731729624845_image_2.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729631448_1731729624845_image_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b304",
    "name": "externallmg_1731729631929_1731729624845_image_3.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729631929_1731729624845_image_3.jpeg",
    "orientation": "landscape"
  },
  {

```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b305",
    "name": "externallmg_1731729632436_1731729624845_image_4.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729632436_1731729624845_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b306",
    "name": "externallmg_1731729632809_1731729624845_image_5.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729632809_1731729624845_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b307",
    "name": "externallmg_1731729633228_1731729624845_image_6.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729633228_1731729624845_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b308",
    "name": "externallmg_1731729634043_1731729624845_image_7.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729634043_1731729624845_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b309",
    "name": "externallmg_1731729634450_1731729624845_image_8.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729634450_1731729624845_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "673818e8d1078a4ea7f5b30a",
    "name": "externallmg_1731729634712_1731729624845_image_9.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729634712_1731729624845_image_9.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b30b",
    "name": "externallmg_1731729635181_1731729624845_image_10.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729635181_1731729624845_image_10.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b30c",
    "name": "externallmg_1731729635469_1731729624845_image_11.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729635469_1731729624845_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b30d",
    "name": "externallmg_1731729635922_1731729624845_image_12.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729635922_1731729624845_image_12.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b30e",
    "name": "externallmg_1731729636481_1731729624845_image_13.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729636481_1731729624845_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "673818e8d1078a4ea7f5b30f",
    "name": "externallmg_1731729637006_1731729624845_image_14.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729637006_1731729624845_image_14.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b310",
    "name": "externallmg_1731729637360_1731729624845_image_15.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729637360_1731729624845_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b311",
    "name": "externallmg_1731729637847_1731729624845_image_16.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729637847_1731729624845_image_16.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b312",
    "name": "externallmg_1731729638083_1731729624845_image_17.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729638083_1731729624845_image_17.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b313",
    "name": "externallmg_1731729638790_1731729624845_image_18.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729638790_1731729624845_image_18.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "673818e8d1078a4ea7f5b314",
```

```
    "name": "externallmg_1731729639530_1731729624845_image_19.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729639530_1731729624845_image_19.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6738190e572e264e52130947",
    "name": "externallmg_1731729675969_1731729674263_image_0.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729675969_1731729674263_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6738190e572e264e52130948",
    "name": "externallmg_1731729676629_1731729674263_image_1.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729676629_1731729674263_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6738190e572e264e52130949",
    "name": "externallmg_1731729676896_1731729674263_image_2.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729676896_1731729674263_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6738190e572e264e5213094a",
    "name": "externallmg_1731729677281_1731729674263_image_3.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externallmg_1731729677281_1731729674263_image_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6738184c572e264e52130910",
    "name": "externallmg_1731729484214_1731729480149_image_0.jpeg",
```

```
    "path": "cases/6735773bdca8ac11abc27fef/
externalImg_1731729484214_1731729480149_image_0.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "6738184c572e264e52130911",
    "name": "externalImg_1731729484340_1731729480150_image_1.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externalImg_1731729484340_1731729480150_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "67381858e077c54e5323571e",
    "name": "externalImg_1731729496339_1731729492339_image_0.jpeg",
    "path": "cases/6735773bdca8ac11abc27fef/
externalImg_1731729496339_1731729492339_image_0.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [
  {
    "originalname": "P. Nadarajan.pdf",
    "filename": "1731756251905_P_Nadarajan.pdf",
    "path": "cases/6735773bdca8ac11abc27fef/
externalDocuments/1731756251905_P_Nadarajan.pdf",
    "size": "1801940",
    "documentType": {
      "value": "640ece6024088f0f94ee4ea8",
      "label": "Final PDF Report"
    },
    "createdAt": "Sat Nov 16 2024 11:24:12 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "63f31d626f9c2254a9b39144"
  }
],
"processingDocuments": [
  {
    "originalname": "Ponvel Nadarajan - Unit No. 4A - State Bank of India ( SME
Chembur Branch ).xlsx",
    "filename": "1731739616419_Ponvel_Nadarajan___Unit_No_4A___State_Bank_of
India__SME_Chembur_Branch_.xlsx",
    "path": "cases/6735773bdca8ac11abc27fef/processingDocuments/1731739616419_
Ponvel_Nadarajan___Unit_No_4A___State_Bank_of_India__SME_Chembur_Branch_.
```

```
xlsx",
  "size": "2545270",
  "createdAt": "Sat Nov 16 2024 06:46:56 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "64dc7184ccaf1e7b7f637f47"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "RATE_VERIFY",
    "display": true,
    "status": true,
    "_id": "67384085e077c54e5323a629",
    "note": "Value given for confirmation",
    "taskId": "67357d95dca8ac11abc2841e",
    "createdAt": "2024-11-16T06:49:41.880Z"
  },
  {
    "createdBy": {
      "_id": "64dc7184ccaf1e7b7f637f47",
      "role": "FRONTDESK",
      "firstName": "Binumon",
      "lastName": "Moozhickal",
      "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
    },
    "workType": "CHECKER",
    "display": true,
    "status": true,
    "_id": "67388d69572e264e5213ae16",
    "note": "name change (Task Reopen)",
    "taskId": "67387589572e264e52138da5",
    "createdAt": "2024-11-16T12:17:45.237Z"
  }
],
"createdAt": "2024-11-14T04:06:19.355Z",
"updatedAt": "2024-11-16T12:19:17.900Z",
```



```
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Industrial Unit No. 4A, 1st Floor, Unity Industrial Premises Co-op. Soc.
Ltd., Majithia Industrial Estate, New/Current Survey No. 57(Part) & 58(Part), CTS No.
851 & 852 , Waman Tukaram Patil Road, Deonar, Village - Borla, Taluka - Kurla, District
- Mumbai Suburban, PIN – 400 088, State - Maharashtra, India",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "",
"contactPersonName": "Mr. Vignesh Kumar Nadarajan",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Owner Representative",
"reald": "",
"siteVisitContactNo": "9004197987",
"siteVisitDate": "2024-11-15",
"buildingServicesRate": "2500",
"finalAreaType": "Built Up Area",
"finalAsPerArea": " Agreement",
"finalBuiltUpPercentage": "0",
"finalCarpetConvertToBuiltUpPer": "0",
"finalMeasurementType": "Sq. Ft.",
"finalValuationAreaString": "Built Up Area in Sq. Ft. = 640.00",
"flatRate": "21500",
"landOtherRate": "19000",
"shopDetails": {
  "typeOfShops": {
    "label": "Independent Building",
    "value": "Independent_Building"
  }
},
"roadFacing": false,
"mall": false
},
"briefDescOfProperty": "Working Area",
"carpetTotal": "531.13",
"otherCarpetTotal": "0.00",
"builtupPercentage": "10",
"finalBuiltupArea": "584.24",
"finalCarpetArea": "531.13",
```

```

"finalSalableArea": "642.67",
"salablePercentage": "10",
"toBeAdded": "",
"extendOfSiteRemark": "",
"siteMeasurementRemark": "",
"finalSaleablePercentage": "0",
"landDetails": {
  "holdType": {
    "label": "Free Hold",
    "value": "Free_Hold"
  },
  "leaseDetails": {
    "lessorName": "",
    "lesseeName": "",
    "leasePremium": "",
    "leaseRent": "",
    "leasePeriod": 0,
    "leaseFrom": "",
    "leaseTo": "",
    "remainingLeasePeriod": 0,
    "leaseDate": ""
  }
},
"reportGeneratedDate": "Sat Nov 16 2024 09:35:19 GMT+0000 (Coordinated
Universal Time)",
"otherCompositionBuiltUpTotal": "0.00",
"otherCompositionCarpetTotal": "0.00",
"otherCompositionSaleableTotal": "0.00"
}

```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Working Area	34'1"	15'7"	531.13
Other Composition :			