

```
{
  "typeOfReport": {
    "label": "Office",
    "value": "Office"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63ae7335191f7b344b004725"
    },
    "firstName": "Kamal R",
    "type": "CREDITOFFICER",
    "_id": "6716053ae73f0c3db52c0f1d",
    "email": "vjgore@bankofbaroda.com",
    "lastName": "Singh",
    "mobileNo": "",
    "workMobileNo": "8657744604"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "5046840",
    "discussWithPerson": "Kamal R",
    "expectedFees": 2523.42,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180c",
  "type": "BANK",
  "name": "Bank Of Baroda",
  "displayName": "Bank Of Baroda",
  "initial": "BOB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63ae7335191f7b344b004725",
  "name": "JAWAHAR NAGAR-2 BRANCH- GOREGAON (WEST) ",
  "branchCode": "",
  "mobileNo": "022-28770825",
  "alternateMobileNo": "",
  "email": "vjgore@bankofbaroda.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "179/180, Jawahar Nagar, Road No. 2, Groegaon (West), \nMumbai -
400014."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f90106f3dd69653a590b0b",
  "zoneName": "Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "66891578194f4629de0af6da",
  "role": "SITEENGINEER",
  "firstName": "Govind",
  "email": "govindpande23@gmail.com",
  "lastName": "Pande",
  "mobileNo": "9096192041",
  "designation": "Site Engg",
  "shortName": "Deepak",
  "workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
      {
```

```
    "title": {
      "value": "Wealth_Tax",
      "label": "Wealth Tax"
    },
    "_id": "6084131a13f01f158c6ea1f4",
    "number": "[N]C.C.I.T/I -14/52/2008-09"
  }
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.22750589087691",
  "longitude": "72.86283340658964"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.86283340658964,
    19.22750589087691
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "26/11/2024 12:00 am"
    }
  ]
},
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "4",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Mumbai",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sagar Niwas ",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Road No 5",
  "label": false
}
```

```
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Rai Dongari",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "B",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```

```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "401",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```



```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400066",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Borivali East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    }
  }
}
```

```
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
```

```
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
```

```
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
},
```

```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```

```
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
```



```
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67459550e077c54e53294b28",
"ownerName": "Somil Ramesh Mehta & Purnima Ramesh Mehta ",
"ownerPhoneNo": "9323692166",
"appAddress": "Office no 401 4th floor B-wing Sagar Niwas Carter road no 5 Borivali
East Mumbai 400066",
"remark": "Visit time Engg ko bolo Approval Plan copy & Bldg Occupation Certificate
Leneko sir ",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67459550e077c54e53294b28/document_1732613361098_17326133
58103_Bob_Jawahar_Nagar_Somil_Mehta_Office_401.pdf",
    "fileName": "document_1732613361098_1732613358103_Bob_Jawahar_Nagar_So
mil_Mehta_Office_401.pdf",
    "id": "569730",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Tue Nov 26 2024 09:30:55 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "label": "Old Valution Report ",
      "value": "60ae1296aa6d152c1801b455"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/67459550e077c54e53294b28/document_1732613413946_17326134
11019_Somil_Mehta_Valuation_report_2021_office_401.pdf",
    "fileName": "document_1732613413946_1732613411019_Somil_Mehta_Valuation_
report_2021_office_401.pdf",
    "id": "121218",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Tue Nov 26 2024 09:30:55 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "012600",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
```

```
    "id": "285766",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Nov 26 2024 09:30:56 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Somil Ramesh Mehta & Purnima Ramesh Mehta ",
    "phone": "9323692166",
    "ownershipShare": "",
    "email": "",
    "id": "373127"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747dfcfd1078a4ea7fb842a",
    "name":
"externallmg_1732763598787_WhatsApp_Image_20241128_at_012835_2.jpeg",
    "path": "cases/67459550e077c54e53294b28/
externallmg_1732763598787_WhatsApp_Image_20241128_at_012835_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747dfcfd1078a4ea7fb842b",
    "name":
"externallmg_1732763598796_WhatsApp_Image_20241128_at_012836_1.jpeg",
    "path": "cases/67459550e077c54e53294b28/
externallmg_1732763598796_WhatsApp_Image_20241128_at_012836_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6747dfcfd1078a4ea7fb842c",
  "name":
"externallmg_1732763598799_WhatsApp_Image_20241128_at_012836_2.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763598799_WhatsApp_Image_20241128_at_012836_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfcfd1078a4ea7fb842d",
  "name":
"externallmg_1732763598840_WhatsApp_Image_20241128_at_012836.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763598840_WhatsApp_Image_20241128_at_012836.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfcfd1078a4ea7fb842e",
  "name":
"externallmg_1732763598846_WhatsApp_Image_20241128_at_012854.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763598846_WhatsApp_Image_20241128_at_012854.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfcfd1078a4ea7fb842f",
  "name":
"externallmg_1732763598882_WhatsApp_Image_20241128_at_012821.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763598882_WhatsApp_Image_20241128_at_012821.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfcfd1078a4ea7fb8430",
  "name":
"externallmg_1732763598899_WhatsApp_Image_20241128_at_012822.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763598899_WhatsApp_Image_20241128_at_012822.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747dfcfd1078a4ea7fb8431",
    "name":
"externallmg_1732763598910_WhatsApp_Image_20241128_at_012823_1.jpeg",
    "path": "cases/67459550e077c54e53294b28/
externallmg_1732763598910_WhatsApp_Image_20241128_at_012823_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747dfcfd1078a4ea7fb8432",
    "name":
"externallmg_1732763598985_WhatsApp_Image_20241128_at_012823.jpeg",
    "path": "cases/67459550e077c54e53294b28/
externallmg_1732763598985_WhatsApp_Image_20241128_at_012823.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747dfcfd1078a4ea7fb8433",
    "name":
"externallmg_1732763598994_WhatsApp_Image_20241128_at_012824.jpeg",
    "path": "cases/67459550e077c54e53294b28/
externallmg_1732763598994_WhatsApp_Image_20241128_at_012824.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747dfde520246c6c062ccc0",
    "name":
"externallmg_1732763614248_WhatsApp_Image_20241128_at_012825.jpeg",
    "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614248_WhatsApp_Image_20241128_at_012825.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747dfde520246c6c062ccc1",
```

```
    "name":
"externallmg_1732763614260_WhatsApp_Image_20241128_at_012826_1.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614260_WhatsApp_Image_20241128_at_012826_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfde520246c6c062ccc2",
  "name":
"externallmg_1732763614264_WhatsApp_Image_20241128_at_012826.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614264_WhatsApp_Image_20241128_at_012826.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfde520246c6c062ccc3",
  "name":
"externallmg_1732763614320_WhatsApp_Image_20241128_at_012827_1.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614320_WhatsApp_Image_20241128_at_012827_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfde520246c6c062ccc4",
  "name":
"externallmg_1732763614325_WhatsApp_Image_20241128_at_012827_2.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614325_WhatsApp_Image_20241128_at_012827_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfde520246c6c062ccc5",
  "name":
"externallmg_1732763614352_WhatsApp_Image_20241128_at_012827.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614352_WhatsApp_Image_20241128_at_012827.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfde520246c6c062ccc6",
  "name":
"externallmg_1732763614356_WhatsApp_Image_20241128_at_012828_1.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614356_WhatsApp_Image_20241128_at_012828_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfde520246c6c062ccc7",
  "name":
"externallmg_1732763614378_WhatsApp_Image_20241128_at_012828_2.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614378_WhatsApp_Image_20241128_at_012828_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfde520246c6c062ccc8",
  "name":
"externallmg_1732763614382_WhatsApp_Image_20241128_at_012828.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614382_WhatsApp_Image_20241128_at_012828.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfde520246c6c062ccc9",
  "name":
"externallmg_1732763614401_WhatsApp_Image_20241128_at_012829.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614401_WhatsApp_Image_20241128_at_012829.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfde520246c6c062ccca",
  "name":
"externallmg_1732763614416_WhatsApp_Image_20241128_at_012830.jpeg",
```

```
    "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614416_WhatsApp_Image_20241128_at_012830.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747dfde520246c6c062cccb",
    "name":
"externallmg_1732763614420_WhatsApp_Image_20241128_at_012831_1.jpeg",
    "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614420_WhatsApp_Image_20241128_at_012831_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747dfde520246c6c062cccc",
    "name":
"externallmg_1732763614446_WhatsApp_Image_20241128_at_012831.jpeg",
    "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614446_WhatsApp_Image_20241128_at_012831.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747dfde520246c6c062cccd",
    "name":
"externallmg_1732763614449_WhatsApp_Image_20241128_at_012832_1.jpeg",
    "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614449_WhatsApp_Image_20241128_at_012832_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747dfde520246c6c062ccce",
    "name":
"externallmg_1732763614474_WhatsApp_Image_20241128_at_012832_2.jpeg",
    "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614474_WhatsApp_Image_20241128_at_012832_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6747dfde520246c6c062cccf",
  "name":
"externallmg_1732763614478_WhatsApp_Image_20241128_at_012832.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614478_WhatsApp_Image_20241128_at_012832.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfde520246c6c062ccd0",
  "name":
"externallmg_1732763614509_WhatsApp_Image_20241128_at_012833.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614509_WhatsApp_Image_20241128_at_012833.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfde520246c6c062ccd1",
  "name":
"externallmg_1732763614513_WhatsApp_Image_20241128_at_012834.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614513_WhatsApp_Image_20241128_at_012834.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfde520246c6c062ccd2",
  "name":
"externallmg_1732763614550_WhatsApp_Image_20241128_at_012835_1.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614550_WhatsApp_Image_20241128_at_012835_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747dfde520246c6c062ccd3",
  "name":
"externallmg_1732763614558_WhatsApp_Image_20241128_at_012835.jpeg",
  "path": "cases/67459550e077c54e53294b28/
externallmg_1732763614558_WhatsApp_Image_20241128_at_012835.jpeg",
```



```

    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-11-26T09:30:56.143Z",
"updatedAt": "2024-11-28T03:13:34.755Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Office No. 401, 4th Floor, Wing - B, Sagar Niwas , Road No
5, Rai Dongari, Borivali East, Mumbai, 400066",
"updatedBy": "6006d4ce5080a310ac1fdfc2",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Somil Ramesh Mehta & Purnima Ramesh Mehta ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "9323692166"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			