

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6273b00bafd7d55eddee5f69"
    },
    "firstName": "Vinod",
    "type": "CREDITOFFICER",
    "_id": "668bb750e61b5802e8d945c7",
    "email": "sbi.04205@sbi.co.in",
    "lastName": "Jagtap",
    "mobileNo": "",
    "workMobileNo": "9860443086"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "00",
    "discussWithPerson": "Vinod",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6273b00bafd7d55eddee5f69",
  "name": "SPL PBB Fort",
  "branchCode": "4205 ",
  "mobileNo": "02223662641",
  "alternateMobileNo": "",
  "email": "sbi.04205@sbi.co.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Mumbai Main Branch Building, Gate No. 1, Horniman Circle, Mumbai
Samachar Marg, Fort, Mumbai, State - Maharashtra, Country - India"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
    "_id": "60af3d172ffdf65bcd6585cd",
    "role": "PICKUPPERSON",
    "firstName": "Sachin",
    "email": "sachin.joshi@vastukala.org",
    "lastName": "Joshi",
    "mobileNo": "9167204063",
    "shortName": "SJ",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\60af3d172ffdf65bcd6585cd\\
\\profilePhoto_1622372567671_Sachin Joshi Photo 3 (2).jpg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62550ed0aba01e0af98f2f75",
    "role": "SITEENGINEER",
    "firstName": "Chandan",
    "email": "ck06806@gmail.com",
    "lastName": "Singh",
    "mobileNo": "8454863607",
    "designation": "",
    "shortName": "CH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "5fc78e26625ecd20ec1f88e9",
    "role": "MAKER+CHECKER",
    "firstName": "Vaishali",
    "email": "v.sarmalkar@vastukala.org",
    "lastName": "Sarmalkar",
    "mobileNo": "9004437379",
    "shortName": "VS",
    "workWithDocumentMaker": "1",
    "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
    "designation": ""
  },
  "maker": null,
  "checker": null,
  "valuers": [
    {
      "valuersRegistrationNumber": [
        {
          "value": "IBBI/RV/07/2018/10366",
```

```
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
```

```
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.153591525401556",
  "longitude": "72.88729337055537"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.88729337055537,
    19.153591525401556
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
```

```
"key": "country",
"value": "India",
"label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Maroshi",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "4",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
}
```

```
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Garden View Apartment CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Aarey Mil COlony",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Near Unit no 26",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
```

```
"value": "",
"label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "L",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
```



```
"status": false,
"name": "Block No",
"key": "blockNo",
"value": "",
"label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "405",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
```

```
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400065",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Goregaon East",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
}
```

```
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
```

```
"rccFootingFoundation": {
  "label": "RCC Footing/Foundation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
```

```
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
}
},
```

```
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
```



```
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67459e5cd1078a4ea7fa84f9",
"ownerName": "Vivek Kumar Tarve",
"ownerPhoneNo": "0000000000",
"appAddress": "Flat no 405,4Floor,Garden view Apartment,Aarey millk colony,Royal
Palms,Goregaon East ",
"remark": "Contact Person Tiwari +91 62614 53447",
"documents": [
  {
    "documentType": {
```

```
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67459e5cd1078a4ea7fa84f9/document_1732615659536_1732615657327_1732613531736110900_attach_139519063341180180.pdf",
  "fileName": "document_1732615659536_1732615657327_1732613531736110900_attach_139519063341180180.pdf",
  "id": "127781",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Tue Nov 26 2024 10:09:32 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": " Agreement",
    "value": "652d16a0316e1359cebd3c15"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67459e5cd1078a4ea7fa84f9/document_1732615677749_1732615671106_1732613531736110900_attach_139519063341180120.pdf",
  "fileName": "document_1732615677749_1732615671106_1732613531736110900_attach_139519063341180120.pdf",
  "id": "398121",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Tue Nov 26 2024 10:09:32 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "label": "Occupancy Certificate",
    "value": "60ae124baa6d152c1801b2fd"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "path": "cases/67459e5cd1078a4ea7fa84f9/document_1732615691421_1732615689484_1732613531736110900_attach_139519063341180150.pdf",
  "fileName": "document_1732615691421_1732615689484_1732613531736110900_attach_139519063341180150.pdf",
  "id": "984953",
  "uploadedBy": "60af3d172ffdf65bcd6585cd",
  "createdAt": "Tue Nov 26 2024 10:09:32 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "012604",
"createdBy": "60af3d172ffdf65bcd6585cd",
```

```
"caseHistory": [
  {
    "id": "890397",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Nov 26 2024 10:09:32 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Vivek Kumar Tarve",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "838866"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747e932520246c6c062cf57",
    "name":
"externalImg_1732766002253_WhatsApp_Image_20241128_at_091421.jpeg",
    "path": "cases/67459e5cd1078a4ea7fa84f9/
externalImg_1732766002253_WhatsApp_Image_20241128_at_091421.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747e932520246c6c062cf58",
    "name":
"externalImg_1732766002260_WhatsApp_Image_20241128_at_091422_1.jpeg",
    "path": "cases/67459e5cd1078a4ea7fa84f9/
externalImg_1732766002260_WhatsApp_Image_20241128_at_091422_1.jpeg",
    "orientation": "portrait"
  },
],
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747e932520246c6c062cf59",
  "name":
"externallmg_1732766002265_WhatsApp_Image_20241128_at_091422_2.jpeg",
  "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766002265_WhatsApp_Image_20241128_at_091422_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747e932520246c6c062cf5a",
  "name":
"externallmg_1732766002286_WhatsApp_Image_20241128_at_091422.jpeg",
  "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766002286_WhatsApp_Image_20241128_at_091422.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747e93f520246c6c062cf8f",
  "name":
"externallmg_1732766014636_WhatsApp_Image_20241128_at_091423.jpeg",
  "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014636_WhatsApp_Image_20241128_at_091423.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747e93f520246c6c062cf90",
  "name":
"externallmg_1732766014639_WhatsApp_Image_20241128_at_091424.jpeg",
  "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014639_WhatsApp_Image_20241128_at_091424.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747e93f520246c6c062cf91",
  "name":
"externallmg_1732766014642_WhatsApp_Image_20241128_at_091425_1.jpeg",
```

```
    "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014642_WhatsApp_Image_20241128_at_091425_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747e93f520246c6c062cf92",
    "name":
"externallmg_1732766014662_WhatsApp_Image_20241128_at_091425.jpeg",
    "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014662_WhatsApp_Image_20241128_at_091425.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747e93f520246c6c062cf93",
    "name":
"externallmg_1732766014678_WhatsApp_Image_20241128_at_091426_1.jpeg",
    "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014678_WhatsApp_Image_20241128_at_091426_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747e93f520246c6c062cf94",
    "name":
"externallmg_1732766014683_WhatsApp_Image_20241128_at_091426.jpeg",
    "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014683_WhatsApp_Image_20241128_at_091426.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747e93f520246c6c062cf95",
    "name":
"externallmg_1732766014707_WhatsApp_Image_20241128_at_091427_1.jpeg",
    "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014707_WhatsApp_Image_20241128_at_091427_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6747e93f520246c6c062cf96",
  "name":
"externallmg_1732766014713_WhatsApp_Image_20241128_at_091427.jpeg",
  "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014713_WhatsApp_Image_20241128_at_091427.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747e93f520246c6c062cf97",
  "name":
"externallmg_1732766014738_WhatsApp_Image_20241128_at_091428_1.jpeg",
  "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014738_WhatsApp_Image_20241128_at_091428_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747e93f520246c6c062cf98",
  "name":
"externallmg_1732766014741_WhatsApp_Image_20241128_at_091428.jpeg",
  "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014741_WhatsApp_Image_20241128_at_091428.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747e93f520246c6c062cf99",
  "name":
"externallmg_1732766014766_WhatsApp_Image_20241128_at_091429.jpeg",
  "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014766_WhatsApp_Image_20241128_at_091429.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747e93f520246c6c062cf9a",
  "name":
"externallmg_1732766014770_WhatsApp_Image_20241128_at_091430.jpeg",
  "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014770_WhatsApp_Image_20241128_at_091430.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747e93f520246c6c062cf9b",
    "name":
"externallmg_1732766014796_WhatsApp_Image_20241128_at_091431_1.jpeg",
    "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014796_WhatsApp_Image_20241128_at_091431_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747e93f520246c6c062cf9c",
    "name":
"externallmg_1732766014803_WhatsApp_Image_20241128_at_091431.jpeg",
    "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014803_WhatsApp_Image_20241128_at_091431.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747e93f520246c6c062cf9d",
    "name":
"externallmg_1732766014830_WhatsApp_Image_20241128_at_091432.jpeg",
    "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014830_WhatsApp_Image_20241128_at_091432.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747e93f520246c6c062cf9e",
    "name":
"externallmg_1732766014839_WhatsApp_Image_20241128_at_091433_1.jpeg",
    "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014839_WhatsApp_Image_20241128_at_091433_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6747e93f520246c6c062cf9f",
```

```
"name":
"externallmg_1732766014876_WhatsApp_Image_20241128_at_091433_2.jpeg",
  "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014876_WhatsApp_Image_20241128_at_091433_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747e93f520246c6c062cfa0",
  "name":
"externallmg_1732766014879_WhatsApp_Image_20241128_at_091433.jpeg",
  "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014879_WhatsApp_Image_20241128_at_091433.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6747e93f520246c6c062cfa1",
  "name":
"externallmg_1732766014897_WhatsApp_Image_20241128_at_091434.jpeg",
  "path": "cases/67459e5cd1078a4ea7fa84f9/
externallmg_1732766014897_WhatsApp_Image_20241128_at_091434.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "igr1.pdf",
    "filename": "1732683793316_igr1.pdf",
    "path": "cases/67459e5cd1078a4ea7fa84f9/
processingDocuments/1732683793316_igr1.pdf",
    "size": "131185",
    "createdAt": "Wed Nov 27 2024 05:03:13 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr2.pdf",
    "filename": "1732683793333_igr2.pdf",
    "path": "cases/67459e5cd1078a4ea7fa84f9/
processingDocuments/1732683793333_igr2.pdf",
    "size": "131062",
    "createdAt": "Wed Nov 27 2024 05:03:13 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  }
]
```



```
    },
    {
      "originalName": "igr3.pdf",
      "filename": "1732683793337_igr3.pdf",
      "path": "cases/67459e5cd1078a4ea7fa84f9/
processingDocuments/1732683793337_igr3.pdf",
      "size": "132400",
      "createdAt": "Wed Nov 27 2024 05:03:13 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalName": "igr4.pdf",
      "filename": "1732683793363_igr4.pdf",
      "path": "cases/67459e5cd1078a4ea7fa84f9/
processingDocuments/1732683793363_igr4.pdf",
      "size": "136995",
      "createdAt": "Wed Nov 27 2024 05:03:13 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    },
    {
      "originalName": "Summary - tarve.xlsx",
      "filename": "1732683793368_Summary__tarve.xlsx",
      "path": "cases/67459e5cd1078a4ea7fa84f9/
processingDocuments/1732683793368_Summary__tarve.xlsx",
      "size": "2333031",
      "createdAt": "Wed Nov 27 2024 05:03:13 GMT+0000 (Coordinated Universal Time)",
      "uploadedBy": "5fc78e26625ecd20ec1f88e9"
    }
  ],
  "leadRemarks": [],
  "audioRemarks": [],
  "remarks": [
    {
      "createdBy": {
        "_id": "5fc78e26625ecd20ec1f88e9",
        "role": "MAKER+CHECKER",
        "firstName": "Vaishali",
        "lastName": "Sarmalkar",
        "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\\
\\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
      },
      "workType": "RATE_VERIFY",
      "display": true,
      "status": true,
      "_id": "6746a804d1078a4ea7fae6ff",
      "note": "working done. visit pending",
    }
  ]
}
```

```

      "taskId": "6745a2c7e077c54e53296d85",
      "createdAt": "2024-11-27T05:03:00.540Z"
    }
  ],
  "createdAt": "2024-11-26T10:09:32.340Z",
  "updatedAt": "2024-11-28T03:53:35.111Z",
  "__v": 0,
  "assignmentType": {
    "value": "Retail",
    "label": "Retail"
  },
  "fullAddress": "Residential Flat No. 405, 4th Floor, Wing - L, Garden View Apartment
CHSL, Aarey Mil Colony, Near Unit no 26, Village - Maroshi, Goregaon East, Mumbai,
400065, State - Maharashtra, India",
  "updatedBy": "6006d4ce5080a310ac1fdfc2",
  "addressForMap": "",
  "caseReferredBy": "60af3d172ffdf65bcd6585cd",
  "contactPersonName": "Mr Tiwari",
  "email": "",
  "isExternal": "false",
  "isUrgent": "false",
  "ownershipShare": "",
  "proposePurchaserName": "",
  "purchaseValueAsPerDocument": "",
  "relationWithOwner": "Contact Person",
  "reralId": "",
  "siteVisitContactNo": "6261453447"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			