

```
{
  "typeOfReport": {
    "value": "Cost_Vetting",
    "label": "Cost Vetting"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b8c3"
    },
    "firstName": "Mrunal Sakhare",
    "type": "CREDITOFFICER",
    "_id": "64c762ee05efe8082a8ca604",
    "lastName": "Sakhare",
    "mobileNo": "",
    "workMobileNo": "9096019666",
    "email": "RMSME1.11688@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b8c3",
  "branchCode": "11688",
  "type": "BRANCH",
  "name": "SME Backbay Reclamation Branch",
  "email": "sbi.11688@sbi.co.in",
  "mobileNo": "22819539",
  "alternateMobileNo": "",
  "address": "Mittal Court, 'B' Wing, Ground Floor, Nariman Point, Mumbai - 400 021,
State - Maharashtra, Country - India.",
  "ledgerName": "Vishok Kumar",
  "fax": "22023508",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
```

```
"pickupPerson": {
  "type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddedd82",
  "profilePhoto": "users/656aa949cebbe1714411d21b/
profilePhoto_1731643469657_WhatsApp_Image_20241115_at_93358_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": ""
}
```

```
"shortName": "AV",
"workWithDocumentMaker": ""
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ]
  }
]
```

```
    },
    {
      "title": {
        "value": "Chartered_Engineer",
        "label": "Chartered Engineer"
      },
      "_id": "60af80072ffdf65bcd658653",
      "number": "AM161706-3"
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.07581492248006",
  "longitude": "72.87588980876649"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
}
```

```
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",
    "value": "",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "1",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
```

```
"status": true,
"name": "District",
"key": "district",
"value": "Mumbai",
"label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Kurla West",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Kanakia Zillon",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
```

```
"label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "F Tower, LBS Marg",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
```



```
"name": "New/Current Survey No.",
"key": "newSurveyNumber",
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "117",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
}
```

```
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 070",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
```

```
"isDisplay": false
},
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
```

```
"coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
```

```
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
}
```

```
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6746df87e077c54e532a3607",
"ownerName": "Salasar Mobility Pvt Ltd",
"ownerPhoneNo": "7506935038",
"fullAddress": "Residential Cost Vetting No. 117, 1st Floor, Kanakia Zillon, F Tower,
LBS Marg, District - Mumbai, Kurla West, PIN Code - 400 070",
"remark": "",
"documents": [],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "012643",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "686078",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Nov 27 2024 08:59:51 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Salasar Mobility Pvt Ltd",
    "phone": "7506935038",
    "ownershipShare": "",
    "email": "",
    "id": "614593"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
```

```
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef71fe077c54e532f3f57",
    "name":
"externalImg_1733228318703_WhatsApp_Image_20241123_at_113457_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externalImg_1733228318703_WhatsApp_Image_20241123_at_113457_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef71fe077c54e532f3f58",
    "name":
"externalImg_1733228318725_WhatsApp_Image_20241123_at_113458_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externalImg_1733228318725_WhatsApp_Image_20241123_at_113458_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef71fe077c54e532f3f59",
    "name":
"externalImg_1733228318774_WhatsApp_Image_20241123_at_113500_AM_1.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externalImg_1733228318774_WhatsApp_Image_20241123_at_113500_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef71fe077c54e532f3f5a",
    "name":
"externalImg_1733228318798_WhatsApp_Image_20241123_at_113500_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externalImg_1733228318798_WhatsApp_Image_20241123_at_113500_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "674ef71fe077c54e532f3f5b",
  "name":
"externallmg_1733228318802_WhatsApp_Image_20241123_at_113501_AM_1.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228318802_WhatsApp_Image_20241123_at_113501_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef71fe077c54e532f3f5c",
  "name":
"externallmg_1733228318837_WhatsApp_Image_20241123_at_113501_AM_2.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228318837_WhatsApp_Image_20241123_at_113501_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef71fe077c54e532f3f5d",
  "name":
"externallmg_1733228318840_WhatsApp_Image_20241123_at_113501_AM.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228318840_WhatsApp_Image_20241123_at_113501_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef71fe077c54e532f3f5e",
  "name":
"externallmg_1733228318871_WhatsApp_Image_20241123_at_113502_AM_1.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228318871_WhatsApp_Image_20241123_at_113502_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef71fe077c54e532f3f5f",
  "name":
"externallmg_1733228318903_WhatsApp_Image_20241123_at_113502_AM_2.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228318903_WhatsApp_Image_20241123_at_113502_AM_2.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef71fe077c54e532f3f60",
    "name":
"externallmg_1733228318935_WhatsApp_Image_20241123_at_113502_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228318935_WhatsApp_Image_20241123_at_113502_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef71fe077c54e532f3f61",
    "name":
"externallmg_1733228318965_WhatsApp_Image_20241123_at_113504_AM_1.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228318965_WhatsApp_Image_20241123_at_113504_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef71fe077c54e532f3f62",
    "name":
"externallmg_1733228318985_WhatsApp_Image_20241123_at_113504_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228318985_WhatsApp_Image_20241123_at_113504_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef71fe077c54e532f3f63",
    "name":
"externallmg_1733228319010_WhatsApp_Image_20241123_at_113505_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228319010_WhatsApp_Image_20241123_at_113505_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef71fe077c54e532f3f64",
```

```
    "name":
"externallmg_1733228319044_WhatsApp_Image_20241123_at_113506_AM.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228319044_WhatsApp_Image_20241123_at_113506_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef71fe077c54e532f3f65",
  "name":
"externallmg_1733228319071_WhatsApp_Image_20241123_at_113507_AM.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228319071_WhatsApp_Image_20241123_at_113507_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef71fe077c54e532f3f66",
  "name":
"externallmg_1733228319089_WhatsApp_Image_20241123_at_113508_AM_1.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228319089_WhatsApp_Image_20241123_at_113508_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef72ed1078a4ea7ff1270",
  "name":
"externallmg_1733228334439_WhatsApp_Image_20241123_at_113508_AM.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334439_WhatsApp_Image_20241123_at_113508_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef72ed1078a4ea7ff1271",
  "name":
"externallmg_1733228334450_WhatsApp_Image_20241123_at_113509_AM_1.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334450_WhatsApp_Image_20241123_at_113509_AM_1.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef72ed1078a4ea7ff1272",
  "name":
"externallmg_1733228334466_WhatsApp_Image_20241123_at_113509_AM.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334466_WhatsApp_Image_20241123_at_113509_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef72ed1078a4ea7ff1273",
  "name":
"externallmg_1733228334479_WhatsApp_Image_20241123_at_113510_AM.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334479_WhatsApp_Image_20241123_at_113510_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef72ed1078a4ea7ff1274",
  "name":
"externallmg_1733228334500_WhatsApp_Image_20241123_at_113511_AM_1.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334500_WhatsApp_Image_20241123_at_113511_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef72ed1078a4ea7ff1275",
  "name":
"externallmg_1733228334526_WhatsApp_Image_20241123_at_113511_AM_2.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334526_WhatsApp_Image_20241123_at_113511_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef72ed1078a4ea7ff1276",
  "name":
"externallmg_1733228334540_WhatsApp_Image_20241123_at_113511_AM.jpeg",
```

```
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334540_WhatsApp_Image_20241123_at_113511_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef72ed1078a4ea7ff1277",
    "name":
"externallmg_1733228334548_WhatsApp_Image_20241123_at_113512_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334548_WhatsApp_Image_20241123_at_113512_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef72ed1078a4ea7ff1278",
    "name":
"externallmg_1733228334567_WhatsApp_Image_20241123_at_113513_AM_1.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334567_WhatsApp_Image_20241123_at_113513_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef72ed1078a4ea7ff1279",
    "name":
"externallmg_1733228334582_WhatsApp_Image_20241123_at_113513_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334582_WhatsApp_Image_20241123_at_113513_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef72ed1078a4ea7ff127a",
    "name":
"externallmg_1733228334590_WhatsApp_Image_20241123_at_113514_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334590_WhatsApp_Image_20241123_at_113514_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
    "status": false,
    "_id": "674ef72ed1078a4ea7ff127b",
    "name":
"externallmg_1733228334618_WhatsApp_Image_20241123_at_113515_AM_1.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334618_WhatsApp_Image_20241123_at_113515_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef72ed1078a4ea7ff127c",
    "name":
"externallmg_1733228334632_WhatsApp_Image_20241123_at_113515_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334632_WhatsApp_Image_20241123_at_113515_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef72ed1078a4ea7ff127d",
    "name":
"externallmg_1733228334668_WhatsApp_Image_20241123_at_113516_AM_1.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334668_WhatsApp_Image_20241123_at_113516_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef72ed1078a4ea7ff127e",
    "name":
"externallmg_1733228334721_WhatsApp_Image_20241123_at_113516_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334721_WhatsApp_Image_20241123_at_113516_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef72ed1078a4ea7ff127f",
    "name":
"externallmg_1733228334740_WhatsApp_Image_20241123_at_113518_AM_1.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228334740_WhatsApp_Image_20241123_at_113518_AM_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef744e077c54e532f3fb7",
    "name":
"externallmg_1733228355805_WhatsApp_Image_20241123_at_113518_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228355805_WhatsApp_Image_20241123_at_113518_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef744e077c54e532f3fb8",
    "name":
"externallmg_1733228355832_WhatsApp_Image_20241123_at_113520_AM_1.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228355832_WhatsApp_Image_20241123_at_113520_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef744e077c54e532f3fb9",
    "name":
"externallmg_1733228355861_WhatsApp_Image_20241123_at_113520_AM_2.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228355861_WhatsApp_Image_20241123_at_113520_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef744e077c54e532f3fba",
    "name":
"externallmg_1733228355883_WhatsApp_Image_20241123_at_113520_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228355883_WhatsApp_Image_20241123_at_113520_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef744e077c54e532f3fbb",
```

```
    "name":
"externallmg_1733228355909_WhatsApp_Image_20241123_at_113521_AM_1.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228355909_WhatsApp_Image_20241123_at_113521_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef744e077c54e532f3fbc",
  "name":
"externallmg_1733228355937_WhatsApp_Image_20241123_at_113521_AM.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228355937_WhatsApp_Image_20241123_at_113521_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef744e077c54e532f3fbd",
  "name":
"externallmg_1733228355994_WhatsApp_Image_20241123_at_113522_AM.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228355994_WhatsApp_Image_20241123_at_113522_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef744e077c54e532f3fbe",
  "name":
"externallmg_1733228355998_WhatsApp_Image_20241123_at_113523_AM.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228355998_WhatsApp_Image_20241123_at_113523_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef744e077c54e532f3fbf",
  "name":
"externallmg_1733228356030_WhatsApp_Image_20241123_at_113524_AM_1.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228356030_WhatsApp_Image_20241123_at_113524_AM_1.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef744e077c54e532f3fc0",
  "name":
"externallmg_1733228356053_WhatsApp_Image_20241123_at_113524_AM.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228356053_WhatsApp_Image_20241123_at_113524_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef744e077c54e532f3fc1",
  "name":
"externallmg_1733228356069_WhatsApp_Image_20241123_at_113525_AM.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228356069_WhatsApp_Image_20241123_at_113525_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef744e077c54e532f3fc2",
  "name":
"externallmg_1733228356091_WhatsApp_Image_20241123_at_113526_AM.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228356091_WhatsApp_Image_20241123_at_113526_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef744e077c54e532f3fc3",
  "name":
"externallmg_1733228356125_WhatsApp_Image_20241123_at_113528_AM_1.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228356125_WhatsApp_Image_20241123_at_113528_AM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef744e077c54e532f3fc4",
  "name":
"externallmg_1733228356169_WhatsApp_Image_20241123_at_113528_AM_2.jpeg",
```

```
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228356169_WhatsApp_Image_20241123_at_113528_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef744e077c54e532f3fc5",
    "name":
"externallmg_1733228356198_WhatsApp_Image_20241123_at_113528_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228356198_WhatsApp_Image_20241123_at_113528_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef744e077c54e532f3fc6",
    "name":
"externallmg_1733228356237_WhatsApp_Image_20241123_at_113529_AM_1.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228356237_WhatsApp_Image_20241123_at_113529_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef755d7693ad1c93a8959",
    "name":
"externallmg_1733228373402_WhatsApp_Image_20241123_at_113529_AM_2.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228373402_WhatsApp_Image_20241123_at_113529_AM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef755d7693ad1c93a895a",
    "name":
"externallmg_1733228373424_WhatsApp_Image_20241123_at_113529_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228373424_WhatsApp_Image_20241123_at_113529_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "674ef755d7693ad1c93a895b",
  "name":
"externallmg_1733228373453_WhatsApp_Image_20241123_at_113530_AM_1.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228373453_WhatsApp_Image_20241123_at_113530_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef755d7693ad1c93a895c",
  "name":
"externallmg_1733228373493_WhatsApp_Image_20241123_at_113530_AM_2.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228373493_WhatsApp_Image_20241123_at_113530_AM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef755d7693ad1c93a895d",
  "name":
"externallmg_1733228373521_WhatsApp_Image_20241123_at_113530_AM.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228373521_WhatsApp_Image_20241123_at_113530_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef755d7693ad1c93a895e",
  "name":
"externallmg_1733228373531_WhatsApp_Image_20241123_at_113531_AM_1.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228373531_WhatsApp_Image_20241123_at_113531_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674ef755d7693ad1c93a895f",
  "name":
"externallmg_1733228373561_WhatsApp_Image_20241123_at_113531_AM_2.jpeg",
  "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228373561_WhatsApp_Image_20241123_at_113531_AM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef755d7693ad1c93a8960",
    "name":
"externallmg_1733228373564_WhatsApp_Image_20241123_at_113531_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228373564_WhatsApp_Image_20241123_at_113531_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674ef755d7693ad1c93a8961",
    "name":
"externallmg_1733228373582_WhatsApp_Image_20241123_at_113532_AM.jpeg",
    "path": "cases/6746df87e077c54e532a3607/
externallmg_1733228373582_WhatsApp_Image_20241123_at_113532_AM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-11-27T08:59:51.930Z",
"updatedAt": "2024-12-03T12:19:33.746Z",
"__v": 0,
"updatedBy": "656aa949cebbe1714411d21b",
"addressForMap": "",
"caseReferredBy": "62720b21afd7d55eddedc545",
"contactPersonName": "Salasar Mobility Pvt Ltd",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "7506935038"
}
```

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			