

```
{
  "typeOfReport": {
    "value": "APF",
    "label": "APF"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Banking_Purpose",
    "label": "Banking Purpose"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "641ef58a695fbc66ee1a2c39"
    },
    "firstName": "Manish ",
    "type": "CREDITOFFICER",
    "_id": "641ef58a695fbc66ee1a2c3b",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "7506921112",
    "email": ""
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "5900"
  },
}
```

```
"organization": {
  "_id": "643a5bee108b68389ed736e5",
  "name": "Nashik Branch",
  "shortName": "NSK",
  "email": "nashik@vastukala.org",
  "address": "4, 1st Floor, Madhusa Elite, Vrundavan Nagar, Jatra - Nandur Naka Link
Road, Adgaon, Nashik - 422003",
  "city": "Nashik"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "641ef58a695fbc66ee1a2c39",
  "name": "RLP Nashik\t",
  "branchCode": "",
  "mobileNo": "02532571977\t",
  "alternateMobileNo": "",
  "email": "ulpnasik@unionbankofindia.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Union Loanpoint Nashiik,\nNawandar Sankul Racca Colony, Near Soni
Paithani, Sharanpur road Nashik-02"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63fda9ecce84bf289baadd43",
  "zoneName": "Nashik Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "63f9ed37ce84bf289ba991ac",
"role": "FRONTDESK",
"firstName": "Rushikesh",
"email": "rushipingle2201@gmail.com",
"lastName": "Pingle",
"mobileNo": "8788210361",
"shortName": "RUP",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9ed37ce84bf289ba991ac/
profilePhoto_1690263811066_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "63f9f4adce84bf289ba9956e",
"role": "FRONTDESK + ENGINEER",
"firstName": "Swapnnil",
"email": "waghswapnil309@gmail.com",
"lastName": "Wagh",
"mobileNo": "8237116625",
"designation": "",
"shortName": "SW",
"workWithDocumentMaker": "",
"profilePhoto": "users/63f9f4adce84bf289ba9956e/
profilePhoto_1719821841098_image.jpg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
"mobileNo": "8007230780",
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chaudhari_Photo_2.jpg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "636a1ad14d42487767af3f91",
"role": "MAKER + RATE VERFIER",
"firstName": "Chintamani",
"email": "chintamanichaudhari099@gmail.com",
"lastName": "Chaudhari",
```

```
"mobileNo": "8007230780",
"designation": "",
"shortName": "cc",
"workWithDocumentMaker": "62724142afd7d55eddede405",
"profilePhoto": "users/63f9ebf9ce84bf289ba990ff/
profilePhoto_1677323257433_Chintamani_Chauthari_Photo_2.jpg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      }
    }
  ],
  "_id": "6084131a13f01f158c6ea1f4",
```

```
        "number": "[N]C.C.I.T/I -14/52/2008-09"
      }
    ],
    "shortName": "SBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
  }
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.99712601929621",
  "longitude": "73.81200012038579"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "27/11/2024 12:00 am"
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
```

```
"key": "state",
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Nashik ",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Basement",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Nashik",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Nashik",
  "label": false
},
}
```

```
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Nashik",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "3+4+10+11+12+13",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Tapovan Link Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
```

```
"value": "",
"label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Opp Maruti Wafers Office , Near Lokesh Plywood,",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": ".388/1+2A(P)",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
```



```
"status": false,
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
```

```
"label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "422005",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
```

```
    "title": "Private Cars"
  }
}
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
```

```
"status": false,
"remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
```

```
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
```

```
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```

```
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
```



```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6747057de077c54e532a7b29",
"ownerName": "SAI COURT",
```

```
"ownerPhoneNo": "0737878789",
"fullAddress": "Residential APF No. Basement Floor, Opp Maruti Wafers Office ,
Near Lokesh Plywood,, Plot No. 3+4+10+11+12+13, New/Current Survey
No. .388/1+2A(P), Tapovan Link Road, Village - Nashik , Taluka - Nashik, District -
Nashik, Nashik, 422005",
"remark": "",
"documents": [],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "012652",
"createdBy": "63f9ed37ce84bf289ba991ac",
"caseHistory": [
  {
    "id": "808687",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Nov 27 2024 11:41:49 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "SAI COURT",
    "phone": "0737878789",
    "ownershipShare": "",
    "email": "",
    "id": "317636"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705c8e077c54e532a7c45",
    "name":
"externalImg_1732707783407_WhatsApp_Image_20241119_at_35302_PM.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externalImg_1732707783407_WhatsApp_Image_20241119_at_35302_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705c8e077c54e532a7c46",
    "name":
"externallmg_1732707783503_WhatsApp_Image_20241119_at_35303_PM_1.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707783503_WhatsApp_Image_20241119_at_35303_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705c8e077c54e532a7c47",
    "name":
"externallmg_1732707783539_WhatsApp_Image_20241119_at_35303_PM_2.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707783539_WhatsApp_Image_20241119_at_35303_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705c8e077c54e532a7c48",
    "name":
"externallmg_1732707783560_WhatsApp_Image_20241119_at_35303_PM.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707783560_WhatsApp_Image_20241119_at_35303_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705c8e077c54e532a7c49",
    "name":
"externallmg_1732707783592_WhatsApp_Image_20241119_at_35304_PM_1.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707783592_WhatsApp_Image_20241119_at_35304_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705c8e077c54e532a7c4a",
```

```
"name":
"externallmg_1732707783622_WhatsApp_Image_20241119_at_35304_PM_2.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707783622_WhatsApp_Image_20241119_at_35304_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705c8e077c54e532a7c4b",
  "name":
"externallmg_1732707783656_WhatsApp_Image_20241119_at_35304_PM.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707783656_WhatsApp_Image_20241119_at_35304_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705c8e077c54e532a7c4c",
  "name":
"externallmg_1732707783660_WhatsApp_Image_20241119_at_35305_PM_1.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707783660_WhatsApp_Image_20241119_at_35305_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705c8e077c54e532a7c4d",
  "name":
"externallmg_1732707783706_WhatsApp_Image_20241119_at_35305_PM.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707783706_WhatsApp_Image_20241119_at_35305_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705c8e077c54e532a7c4e",
  "name":
"externallmg_1732707783712_WhatsApp_Image_20241119_at_35306_PM_1.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707783712_WhatsApp_Image_20241119_at_35306_PM_1.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705c8e077c54e532a7c4f",
  "name":
"externallmg_1732707783764_WhatsApp_Image_20241119_at_35306_PM.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707783764_WhatsApp_Image_20241119_at_35306_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705c8e077c54e532a7c50",
  "name":
"externallmg_1732707783771_WhatsApp_Image_20241119_at_35307_PM_1.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707783771_WhatsApp_Image_20241119_at_35307_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705c8e077c54e532a7c51",
  "name":
"externallmg_1732707783821_WhatsApp_Image_20241119_at_35307_PM_2.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707783821_WhatsApp_Image_20241119_at_35307_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705c8e077c54e532a7c52",
  "name":
"externallmg_1732707783826_WhatsApp_Image_20241119_at_35307_PM.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707783826_WhatsApp_Image_20241119_at_35307_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705c8e077c54e532a7c53",
  "name":
"externallmg_1732707783877_WhatsApp_Image_20241119_at_35308_PM_1.jpeg",
```

```
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707783877_WhatsApp_Image_20241119_at_35308_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705c8e077c54e532a7c54",
    "name":
"externallmg_1732707783881_WhatsApp_Image_20241119_at_35308_PM.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707783881_WhatsApp_Image_20241119_at_35308_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705c8e077c54e532a7c55",
    "name":
"externallmg_1732707784202_WhatsApp_Image_20241119_at_35309_PM_1.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707784202_WhatsApp_Image_20241119_at_35309_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705c8e077c54e532a7c56",
    "name":
"externallmg_1732707784231_WhatsApp_Image_20241119_at_35309_PM_2.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707784231_WhatsApp_Image_20241119_at_35309_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705c8e077c54e532a7c57",
    "name":
"externallmg_1732707784249_WhatsApp_Image_20241119_at_35309_PM.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707784249_WhatsApp_Image_20241119_at_35309_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "674705c8e077c54e532a7c58",
  "name":
"externallmg_1732707784264_WhatsApp_Image_20241119_at_35310_PM_1.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707784264_WhatsApp_Image_20241119_at_35310_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705d1e077c54e532a7ca2",
  "name":
"externallmg_1732707792184_WhatsApp_Image_20241119_at_35310_PM.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792184_WhatsApp_Image_20241119_at_35310_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705d1e077c54e532a7ca3",
  "name":
"externallmg_1732707792289_WhatsApp_Image_20241119_at_35311_PM_1.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792289_WhatsApp_Image_20241119_at_35311_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705d1e077c54e532a7ca4",
  "name":
"externallmg_1732707792388_WhatsApp_Image_20241119_at_35311_PM.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792388_WhatsApp_Image_20241119_at_35311_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705d1e077c54e532a7ca5",
  "name":
"externallmg_1732707792475_WhatsApp_Image_20241119_at_35312_PM_1.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792475_WhatsApp_Image_20241119_at_35312_PM_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705d1e077c54e532a7ca6",
    "name":
"externallmg_1732707792500_WhatsApp_Image_20241119_at_35312_PM.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792500_WhatsApp_Image_20241119_at_35312_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705d1e077c54e532a7ca7",
    "name":
"externallmg_1732707792508_WhatsApp_Image_20241119_at_35313_PM_1.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792508_WhatsApp_Image_20241119_at_35313_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705d1e077c54e532a7ca8",
    "name":
"externallmg_1732707792538_WhatsApp_Image_20241119_at_35313_PM_2.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792538_WhatsApp_Image_20241119_at_35313_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705d1e077c54e532a7ca9",
    "name":
"externallmg_1732707792542_WhatsApp_Image_20241119_at_35313_PM.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792542_WhatsApp_Image_20241119_at_35313_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705d1e077c54e532a7caa",
```



```
    "name":
"externallmg_1732707792577_WhatsApp_Image_20241119_at_35314_PM_1.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792577_WhatsApp_Image_20241119_at_35314_PM_1.jpeg",
    "orientation": "landscape"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705d1e077c54e532a7cab",
    "name":
"externallmg_1732707792583_WhatsApp_Image_20241119_at_35314_PM.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792583_WhatsApp_Image_20241119_at_35314_PM.jpeg",
    "orientation": "landscape"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705d1e077c54e532a7cac",
    "name":
"externallmg_1732707792628_WhatsApp_Image_20241119_at_35317_PM.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792628_WhatsApp_Image_20241119_at_35317_PM.jpeg",
    "orientation": "landscape"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705d1e077c54e532a7cad",
    "name":
"externallmg_1732707792631_WhatsApp_Image_20241119_at_35321_PM_1.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792631_WhatsApp_Image_20241119_at_35321_PM_1.jpeg",
    "orientation": "landscape"
},
{
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705d1e077c54e532a7cae",
    "name":
"externallmg_1732707792679_WhatsApp_Image_20241119_at_35321_PM.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792679_WhatsApp_Image_20241119_at_35321_PM.jpeg",
    "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705d1e077c54e532a7caf",
  "name":
"externallmg_1732707792686_WhatsApp_Image_20241119_at_35322_PM_1.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792686_WhatsApp_Image_20241119_at_35322_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705d1e077c54e532a7cb0",
  "name":
"externallmg_1732707792729_WhatsApp_Image_20241119_at_35322_PM_2.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792729_WhatsApp_Image_20241119_at_35322_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705d1e077c54e532a7cb1",
  "name":
"externallmg_1732707792767_WhatsApp_Image_20241119_at_35322_PM.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792767_WhatsApp_Image_20241119_at_35322_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705d1e077c54e532a7cb2",
  "name":
"externallmg_1732707792790_WhatsApp_Image_20241119_at_35323_PM_1.jpeg",
  "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792790_WhatsApp_Image_20241119_at_35323_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "674705d1e077c54e532a7cb3",
  "name":
"externallmg_1732707792832_WhatsApp_Image_20241119_at_35323_PM.jpeg",
```

```
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707792832_WhatsApp_Image_20241119_at_35323_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705d1e077c54e532a7cb4",
    "name":
"externallmg_1732707793204_WhatsApp_Image_20241119_at_35324_PM_1.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707793204_WhatsApp_Image_20241119_at_35324_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705d1e077c54e532a7cb5",
    "name":
"externallmg_1732707793235_WhatsApp_Image_20241119_at_35324_PM.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707793235_WhatsApp_Image_20241119_at_35324_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705d9d1078a4ea7fb6391",
    "name":
"externallmg_1732707801575_WhatsApp_Image_20241119_at_35325_PM_1.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707801575_WhatsApp_Image_20241119_at_35325_PM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "674705d9d1078a4ea7fb6392",
    "name":
"externallmg_1732707801703_WhatsApp_Image_20241119_at_35325_PM.jpeg",
    "path": "cases/6747057de077c54e532a7b29/
externallmg_1732707801703_WhatsApp_Image_20241119_at_35325_PM.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
```

"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2024-11-27T11:41:49.240Z",
"updatedAt": "2024-11-27T11:43:21.952Z",
"__v": 0,
"updatedBy": "63f9ed37ce84bf289ba991ac",
"addressForMap": "",
"caseReferredBy": "643a91f233d16f6b1237a4ee",
"contactPersonName": "SAI COURT",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reId": "",
"siteVisitContactNo": "0737878789"

}

Name	Length	Width	Total
<hr/>			
Composition :			
<hr/>			
Other			
Composition :			
<hr/>			