

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6759740cbc26c2bda04e1e97"
    },
    "firstName": "Gautam",
    "type": "CREDITOFFICER",
    "_id": "6759746a7e4dc2bd6ef9ae6e",
    "email": "vikhroliParksite.Navimumbai@bankofindia.co.in",
    "lastName": "Kishor",
    "mobileNo": "",
    "workMobileNo": "9370326369"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d180a",
  "type": "BANK",
  "name": "Bank of India",
  "displayName": "Bank of India",
  "initial": "BOI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6759740cbc26c2bda04e1e97",
  "name": "Vikhroli Parkside Branch ",
  "branchCode": "",
  "mobileNo": "2240021556",
  "alternateMobileNo": "2240021557",
  "email": "vikhroliParkside.Navimumbai@bankofindia.co.in",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Aarti Building, Amrunt Nagar, Ghatkopar West, Mumbai 400086"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e2f4b16576061dae469446",
  "zoneName": "Navi Mumbai Zone"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "627222afafd7d55eddeddd82",
```

```
"role": "FRONTDESK",
"firstName": "Pratibha",
"email": "shilvanta_pratibha@yahoo.co.in",
"lastName": "Shilvanta",
"mobileNo": "9821518537",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "648fcad91b499c2d52dc86f3",
"role": "SITEENGINEER",
"firstName": "Barkat",
"email": "barkathodekar68@gmail.com",
"lastName": "Hodekar",
"mobileNo": "8879011615",
"designation": "Site Engg",
"shortName": "Barkat",
"workWithDocumentMaker": "",
"profilePhoto": "users/648fcad91b499c2d52dc86f3/
profilePhoto_1687758876977_image.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"maker": {
"type": "EMPLOYEE",
"_id": "627222afafd7d55eddeddd82",
"role": "FRONTDESK",
"firstName": "Pratibha",
"email": "shilvanta_pratibha@yahoo.co.in",
"lastName": "Shilvanta",
"mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.101240147454305",
  "longitude": "72.91136037558317"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.91136037558317,
    19.101240147454305
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Ghatkopar ",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
    "key": "district",
    "value": "Mumbai Suburban",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Ghatkopar (West)",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Kurla",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "B-2",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Sundeep Kanan Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
}
```

```
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "LBS Marg",
  "label": false
},
"landmark": {
  "status": true,
  "name": "Landmark",
  "key": "landmark",
  "value": "Kanan Apartment Co-Op. Hsg. Soc. Ltd., Amrut Nagar",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```



```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "28 Part",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "201",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```

```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code - 400 086",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    }
  }
}
```

```
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
```

```
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
```

```
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  }
},
```

```
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
```

```
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67598236bc26c2bda04e3647",
"ownerName": "Mrs. Vrushali Shailesh Bavdane & Mr. Shailesh Gangaram Bavdane",
"ownerPhoneNo": "8169101520",
"fullAddress": "Residential Flat No. 201, 2nd Floor, Sundeep Kanan Apartment, Kanan
Apartment Co-Op. Hsg. Soc. Ltd., Amrut Nagar, Plot No. B-2,, LBS Marg, Village -
Ghatkopar , Taluka - Kurla, District - Mumbai Suburban, Ghatkopar (West), PIN Code -
400 086, State - Maharashtra, India",
"remark": "",
"documents": [
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1733919263778_BOI_Vikhroli_Mr_Bavdane_1.pdf",
  "path": "cases/67598236bc26c2bda04e3647/
document_1733919263778_BOI_Vikhroli_Mr_Bavdane_1.pdf",
  "id": "652533",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed Dec 11 2024 12:14:46 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1733919278030_BOI_Vikhroli_Mrbavdane_val_report_2.pdf",
  "path": "cases/67598236bc26c2bda04e3647/
document_1733919278030_BOI_Vikhroli_Mrbavdane_val_report_2.pdf",
  "id": "160197",
  "uploadedBy": "627222afafd7d55eddeddd82",
  "createdAt": "Wed Dec 11 2024 12:14:46 GMT+0000 (Coordinated Universal Time)"
}
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
}
```

```
"caseNumber": "013014",
"createdBy": "627222afafd7d55eddeddd82",
"caseHistory": [
  {
    "id": "387718",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Wed Dec 11 2024 12:14:46 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mrs. Vrushali Shailesh Bavdane & Mr. Shailesh Gangaram Bavdane",
    "phone": "8169101520",
    "ownershipShare": "",
    "email": "",
    "id": "252349"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "675bacc6bc26c2bda04ef783",
    "name": "externallmg_1734061252717_1734061245119_image_0.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/externallmg_1734061252717_1734061245119_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "675bacc6bc26c2bda04ef784",
    "name": "externallmg_1734061253550_1734061245119_image_1.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/externallmg_1734061253550_1734061245119_image_1.jpeg",
    "orientation": "portrait"
  }
],
```

```
{
  "type": "MEASUREMENT_IMAGE",
  "status": false,
  "_id": "675bacc6bc26c2bda04ef785",
  "name": "externallmg_1734061254162_1734061245119_image_2.jpeg",
  "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061254162_1734061245119_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675bace4bc26c2bda04ef7c2",
  "name": "externallmg_1734061275913_1734061272749_image_0.jpeg",
  "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061275913_1734061272749_image_0.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675bace4bc26c2bda04ef7c3",
  "name": "externallmg_1734061278072_1734061272749_image_1.jpeg",
  "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061278072_1734061272749_image_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675bace4bc26c2bda04ef7c4",
  "name": "externallmg_1734061279644_1734061272749_image_2.jpeg",
  "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061279644_1734061272749_image_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675bace4bc26c2bda04ef7c5",
  "name": "externallmg_1734061280001_1734061272749_image_3.jpeg",
  "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061280001_1734061272749_image_3.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bace4bc26c2bda04ef7c6",
    "name": "externallmg_1734061280425_1734061272749_image_4.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061280425_1734061272749_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bace4bc26c2bda04ef7c7",
    "name": "externallmg_1734061281397_1734061272749_image_5.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061281397_1734061272749_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bace4bc26c2bda04ef7c8",
    "name": "externallmg_1734061282298_1734061272749_image_6.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061282298_1734061272749_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bace4bc26c2bda04ef7c9",
    "name": "externallmg_1734061282607_1734061272749_image_7.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061282607_1734061272749_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bace4bc26c2bda04ef7ca",
    "name": "externallmg_1734061283131_1734061272749_image_8.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061283131_1734061272749_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "675bace4bc26c2bda04ef7cb",
    "name": "externallmg_1734061283550_1734061272749_image_9.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061283550_1734061272749_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bace4bc26c2bda04ef7cc",
    "name": "externallmg_1734061284012_1734061272749_image_10.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061284012_1734061272749_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bace4bc26c2bda04ef7cd",
    "name": "externallmg_1734061284291_1734061272749_image_11.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061284291_1734061272749_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac656",
    "name": "externallmg_1734061327138_1734061319151_image_0.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061327138_1734061319151_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac657",
    "name": "externallmg_1734061329713_1734061319151_image_1.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061329713_1734061319151_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
```

```
    "_id": "675bad207e4dc2bd6efac658",
    "name": "externallmg_1734061331841_1734061319151_image_2.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061331841_1734061319151_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac659",
    "name": "externallmg_1734061332206_1734061319151_image_3.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061332206_1734061319151_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac65a",
    "name": "externallmg_1734061332489_1734061319151_image_4.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061332489_1734061319151_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac65b",
    "name": "externallmg_1734061332879_1734061319151_image_5.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061332879_1734061319151_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac65c",
    "name": "externallmg_1734061335122_1734061319151_image_6.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061335122_1734061319151_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac65d",
```

```
    "name": "externallmg_1734061335622_1734061319151_image_7.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061335622_1734061319151_image_7.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac65e",
    "name": "externallmg_1734061336573_1734061319151_image_8.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061336573_1734061319151_image_8.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac65f",
    "name": "externallmg_1734061337103_1734061319151_image_9.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061337103_1734061319151_image_9.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac660",
    "name": "externallmg_1734061337597_1734061319151_image_10.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061337597_1734061319151_image_10.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac661",
    "name": "externallmg_1734061338152_1734061319151_image_11.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061338152_1734061319151_image_11.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac662",
    "name": "externallmg_1734061338716_1734061319151_image_12.jpeg",
```



```
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061338716_1734061319151_image_12.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac663",
    "name": "externallmg_1734061339449_1734061319151_image_13.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061339449_1734061319151_image_13.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac664",
    "name": "externallmg_1734061340146_1734061319151_image_14.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061340146_1734061319151_image_14.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac665",
    "name": "externallmg_1734061341599_1734061319151_image_15.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061341599_1734061319151_image_15.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac666",
    "name": "externallmg_1734061342129_1734061319151_image_16.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061342129_1734061319151_image_16.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "675bad207e4dc2bd6efac667",
    "name": "externallmg_1734061342930_1734061319151_image_17.jpeg",
    "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061342930_1734061319151_image_17.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "675bad207e4dc2bd6efac668",
  "name": "externallmg_1734061343366_1734061319151_image_18.jpeg",
  "path": "cases/67598236bc26c2bda04e3647/
externallmg_1734061343366_1734061319151_image_18.jpeg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "igr1.pdf",
    "filename": "1734003141498_igr1.pdf",
    "path": "cases/67598236bc26c2bda04e3647/
processingDocuments/1734003141498_igr1.pdf",
    "size": "133850",
    "createdAt": "Thu Dec 12 2024 11:32:21 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr2.pdf",
    "filename": "1734003141503_igr2.pdf",
    "path": "cases/67598236bc26c2bda04e3647/
processingDocuments/1734003141503_igr2.pdf",
    "size": "133746",
    "createdAt": "Thu Dec 12 2024 11:32:21 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr3.pdf",
    "filename": "1734003141507_igr3.pdf",
    "path": "cases/67598236bc26c2bda04e3647/
processingDocuments/1734003141507_igr3.pdf",
    "size": "135772",
    "createdAt": "Thu Dec 12 2024 11:32:21 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "5fc78e26625ecd20ec1f88e9"
  },
  {
    "originalname": "igr4.pdf",
    "filename": "1734003141541_igr4.pdf",
    "path": "cases/67598236bc26c2bda04e3647/
processingDocuments/1734003141541_igr4.pdf",
```

```
"size": "136439",
"createdAt": "Thu Dec 12 2024 11:32:21 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
"originalname": "igr5.pdf",
"filename": "1734003141559_igr5.pdf",
"path": "cases/67598236bc26c2bda04e3647/
processingDocuments/1734003141559_igr5.pdf",
"size": "136636",
"createdAt": "Thu Dec 12 2024 11:32:21 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
"originalname": "Summary - vrushali.xlsx",
"filename": "1734003141582_Summary__vrushali.xlsx",
"path": "cases/67598236bc26c2bda04e3647/
processingDocuments/1734003141582_Summary__vrushali.xlsx",
"size": "1907334",
"createdAt": "Thu Dec 12 2024 11:32:21 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"lastName": "Sarmalkar",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "675ac9c9bc26c2bda04ed40d",
"note": "working done. visit pending",
"taskId": "6759824a74fe66bd67c347c8",
"createdAt": "2024-12-12T11:32:25.872Z"
}
],
"createdAt": "2024-12-11T12:14:46.586Z",
"updatedAt": "2024-12-13T03:42:24.831Z",
```

"\_\_v": 0,  
"updatedBy": "648fcad91b499c2d52dc86f3",  
"addressForMap": "",  
"caseReferredBy": "64abdb2806d6ec174986d16b",  
"contactPersonName": "Mrs. Vrushali Shailesh Bavdane & Mr. Shailesh Gangaram  
Bavdane",  
"email": "",  
"isExternal": "false",  
"isUrgent": "false",  
"ownershipShare": "",  
"proposePurchaserName": "",  
"purchaseValueAsPerDocument": "",  
"relationWithOwner": "self",  
"reald": "",  
"siteVisitContactNo": "8169101520"

}

<b>Name</b>	<b>Length</b>	<b>Width</b>	<b>Total</b>
Composition :			
Other Composition :			