

```
{
  "typeOfReport": {
    "value": "Land",
    "label": "Land"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Market_Value",
    "label": "Market Value"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "67615338b3971e94fccc616c",
    "type": "PRIVATE_CLIENT",
  }
}
```

```
"name": "Shiva Foundation",
"displayname": "Shiva Foundation",
"initial": "S"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "shortName": "MBC",
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "5ff3ead28cda966090eacbbe",
    "role": "VALUER",
    "firstName": "Umang",
    "email": "umang@vastukala.org",
    "lastName": "Patel",
    "mobileNo": "9819670183",
    "shortName": "umang",
    "workWithDocumentMaker": "5fc75d341095af19d8b34239",
    "designation": "",
    "profilePhoto": "users/5ff3ead28cda966090eacbbe/
profilePhoto_1678667749982_image.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "60016f965256c07aec8e6dd6",
    "role": "MAKER + RATE VERFIER + CHEAKER",
```

```
"firstName": "Akhilesh",
"email": "akhilesh.yadav@vastukala.org",
"lastName": "Yadav",
"mobileNo": "9545753921",
"designation": "Processing Officer",
"workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
"profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
"shortName": "AY"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60016f965256c07aec8e6dd6",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "firstName": "Akhilesh",
  "email": "akhilesh.yadav@vastukala.org",
  "lastName": "Yadav",
  "mobileNo": "9545753921",
  "designation": "Processing Officer",
  "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf",
  "profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
  "shortName": "AY"
},
"checker": {
  "_id": "60016f965256c07aec8e6dd6",
  "profilePhoto": "users\\60016f965256c07aec8e6dd6\
\profilePhoto_1622371927126_Akhilesh Photo (2).jpg",
  "firstName": "Akhilesh",
  "lastName": "Yadav",
  "shortName": "AY",
  "email": "akhilesh.yadav@vastukala.org",
  "designation": "Processing Officer",
  "mobileNo": "9545753921",
  "role": "MAKER + RATE VERFIER + CHEAKER",
  "type": "EMPLOYEE",
  "workWithDocumentMaker": "6009222ca16fab0f2af9b0bf"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  }
],
```

```
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
```

```
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.154116905870033",
  "longitude": "72.88667969405651"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.88667969405651,
    19.154116905870033
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-12-20",
      "remark": ""
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  }
},
```

```
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Maroshi",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "NA",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
```

```
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "84",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Royal Palms",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
```

```
"status": false,
"name": "Landmark",
"key": "landmark",
"value": "",
"label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
```



```
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
```

```
"name": "Police Station(P.S)",
"key": "policeStation",
"value": "",
"label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
},
```

```
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": true,
  "remark": "SYSTEMGENERATED",
  "date": "Fri Jan 03 2025 05:35:25 GMT+0000 (Coordinated Universal Time)",
  "number": "2309903",
  "dayCount": "1",
  "monthCount": "22",
  "generatedBy": "60016f965256c07aec8e6dd6"
},
```

```
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
}
```

```
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
```

```
"carpetRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
}
```

```
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
```



```
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "true",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": true,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REPORTGENERATED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67615338b3971e94fccc6172",
"ownerName": "Shiva Foundation",
"ownerPhoneNo": "0000000000",
"ownershipShare": "",
"email": ""
```

```
"siteVisitContactNo": "9819360007",
"contactPersonName": "Santosh Damani",
"purchaseValueAsPerDocument": "0",
"owners": [
  {
    "name": "Shiva Foundation",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "752314"
  }
],
"caseReferredBy": "5ffe92d27737ca4d986b6453",
"relationWithOwner": "Contact Person",
"fullAddress": "Residential Land No. NA Floor, Plot No. 84, Royal Palms, Village -
Maroshi, State - Maharashtra, India",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1734431533620_DocScanner_Dec_17_2024_1018.pdf",
    "path": "cases/67615338b3971e94fccc6172/
document_1734431533620_DocScanner_Dec_17_2024_1018.pdf",
    "id": "542064",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Tue Dec 17 2024 10:32:24 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName": "document_1734673834352_Shiva_Foundation.pdf",
    "path": "cases/67615338b3971e94fccc6172/
document_1734673834352_Shiva_Foundation.pdf",
    "id": "493540",
    "uploadedBy": "6006d4ce5080a310ac1fdcf2",
    "createdAt": "Fri Dec 20 2024 05:50:36 GMT+0000 (Coordinated Universal Time)"
  }
]
```

```
],
"isUrgent": "false",
"isExternal": "false",
"proposePurchaserName": "",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"rerald": "",
"scheduleSiteVisitDate": "Invalid date",
"caseNumber": "013130",
"createdBy": "6006d4ce5080a310ac1fdcf2",
"caseHistory": [
  {
    "id": "575953",
    "title": "Create Case",
    "description": "Create Case",
    "datetime": "Tue Dec 17 2024 10:32:24 GMT+0000 (Coordinated Universal Time)"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677778a8a5477d50e7dbd70a",
    "name": "externallmg_1735882917614_externallmg_1734674653942_1734674647917_image_1.jpeg",
    "path": "cases/67615338b3971e94fccc6172/externallmg_1735882917614_externallmg_1734674653942_1734674647917_image_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677778a8a5477d50e7dbd70b",
    "name": "externallmg_1735882917694_externallmg_1734674786272_1734674770179_image_0.jpeg",
    "path": "cases/67615338b3971e94fccc6172/externallmg_1735882917694_externall
```

```
mg_1734674786272_1734674770179_image_0.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677778a8a5477d50e7dbd70c",
  "name": "externallmg_1735882917723_externallmg_1734674799538_1734674770180_image_1.jpeg",
  "path": "cases/67615338b3971e94fcc6172/externallmg_1735882917723_externallmg_1734674799538_1734674770180_image_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677778a8a5477d50e7dbd70d",
  "name": "externallmg_1735882918079_externallmg_1734674815512_1734674770180_image_2.jpeg",
  "path": "cases/67615338b3971e94fcc6172/externallmg_1735882918079_externallmg_1734674815512_1734674770180_image_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677778a8a5477d50e7dbd70e",
  "name": "externallmg_1735882918412_externallmg_1734674840062_1734674770180_image_3.jpeg",
  "path": "cases/67615338b3971e94fcc6172/externallmg_1735882918412_externallmg_1734674840062_1734674770180_image_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677778a8a5477d50e7dbd70f",
  "name": "externallmg_1735882918474_externallmg_1734674856299_1734674770180_image_4.jpeg",
  "path": "cases/67615338b3971e94fcc6172/externallmg_1735882918474_externallmg_1734674856299_1734674770180_image_4.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "677778a8a5477d50e7dbd710",
    "name": "externalimg_1735882919150_externalimg_1734674872102_17346747701
80_image_5.jpeg",
    "path": "cases/67615338b3971e94fccc6172/externalimg_1735882919150_external
mg_1734674872102_1734674770180_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677778a8a5477d50e7dbd711",
    "name": "externalimg_1735882919433_externalimg_1734674886324_17346747701
80_image_6.jpeg",
    "path": "cases/67615338b3971e94fccc6172/externalimg_1735882919433_external
mg_1734674886324_1734674770180_image_6.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677778a8a5477d50e7dbd712",
    "name":
"externalimg_1735882919500_WhatsApp_Image_20241223_at_44336_PM_1.jpeg",
    "path": "cases/67615338b3971e94fccc6172/
externalimg_1735882919500_WhatsApp_Image_20241223_at_44336_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677778a8a5477d50e7dbd713",
    "name":
"externalimg_1735882919866_WhatsApp_Image_20241223_at_44336_PM.jpeg",
    "path": "cases/67615338b3971e94fccc6172/
externalimg_1735882919866_WhatsApp_Image_20241223_at_44336_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677778a8a5477d50e7dbd714",
    "name":
"externalimg_1735882919880_WhatsApp_Image_20241223_at_44337_PM_1.jpeg",
    "path": "cases/67615338b3971e94fccc6172/
externalimg_1735882919880_WhatsApp_Image_20241223_at_44337_PM_1.jpeg",
    "orientation": "landscape"
  }
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677778a8a5477d50e7dbd715",
  "name":
  "externallmg_1735882919975_WhatsApp_Image_20241223_at_44337_PM_2.jpeg",
  "path": "cases/67615338b3971e94fccc6172/
externallmg_1735882919975_WhatsApp_Image_20241223_at_44337_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677778a8a5477d50e7dbd716",
  "name":
  "externallmg_1735882920125_WhatsApp_Image_20241223_at_44337_PM_3.jpeg",
  "path": "cases/67615338b3971e94fccc6172/
externallmg_1735882920125_WhatsApp_Image_20241223_at_44337_PM_3.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677778bfa5477d50e7dbd770",
  "name":
  "externallmg_1735882942217_WhatsApp_Image_20241223_at_44337_PM.jpeg",
  "path": "cases/67615338b3971e94fccc6172/
externallmg_1735882942217_WhatsApp_Image_20241223_at_44337_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677778bfa5477d50e7dbd771",
  "name":
  "externallmg_1735882942257_WhatsApp_Image_20241223_at_44338_PM_1.jpeg",
  "path": "cases/67615338b3971e94fccc6172/
externallmg_1735882942257_WhatsApp_Image_20241223_at_44338_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "677778bfa5477d50e7dbd772",
  "name":
  "externallmg_1735882942281_WhatsApp_Image_20241223_at_44338_PM_2.jpeg",
```

```
    "path": "cases/67615338b3971e94fccc6172/
externallmg_1735882942281_WhatsApp_Image_20241223_at_44338_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677778bfa5477d50e7dbd773",
    "name":
"externallmg_1735882942356_WhatsApp_Image_20241223_at_44338_PM.jpeg",
    "path": "cases/67615338b3971e94fccc6172/
externallmg_1735882942356_WhatsApp_Image_20241223_at_44338_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677778bfa5477d50e7dbd774",
    "name":
"externallmg_1735882942534_WhatsApp_Image_20241223_at_44339_PM_1.jpeg",
    "path": "cases/67615338b3971e94fccc6172/
externallmg_1735882942534_WhatsApp_Image_20241223_at_44339_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677778bfa5477d50e7dbd775",
    "name":
"externallmg_1735882942552_WhatsApp_Image_20241223_at_44339_PM_2.jpeg",
    "path": "cases/67615338b3971e94fccc6172/
externallmg_1735882942552_WhatsApp_Image_20241223_at_44339_PM_2.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677778bfa5477d50e7dbd776",
    "name":
"externallmg_1735882942633_WhatsApp_Image_20241223_at_44339_PM_3.jpeg",
    "path": "cases/67615338b3971e94fccc6172/
externallmg_1735882942633_WhatsApp_Image_20241223_at_44339_PM_3.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "677778bfa5477d50e7dbd777",
    "name":
"externalImg_1735882942744_WhatsApp_Image_20241223_at_44339_PM.jpeg",
    "path": "cases/67615338b3971e94fccc6172/
externalImg_1735882942744_WhatsApp_Image_20241223_at_44339_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "677778caa5477d50e7dbd79e",
    "name": "externalImg_1735882954546_externalImg_1734674651420_17346746479
17_image_0.jpeg",
    "path": "cases/67615338b3971e94fccc6172/externalImg_1735882954546_externalI
mg_1734674651420_1734674647917_image_0.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [
  {
    "originalName": "Shiva Foundation - Marol Maroshi.doc",
    "filename": "1734931210528_Shiva_Foundation__Marol_Maroshi.doc",
    "path": "cases/67615338b3971e94fccc6172/
externalDocuments/1734931210528_Shiva_Foundation__Marol_Maroshi.doc",
    "size": "15870464",
    "documentType": {
      "value": "649998c6cab24d3d1a2cc577",
      "label": "Draft Word Report"
    },
    "createdAt": "Mon Dec 23 2024 05:20:12 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  },
  {
    "originalName": "Shiva Foundation - Marol Maroshi.doc",
    "filename": "1735882817528_Shiva_Foundation__Marol_Maroshi.doc",
    "path": "cases/67615338b3971e94fccc6172/
externalDocuments/1735882817528_Shiva_Foundation__Marol_Maroshi.doc",
    "size": "21173760",
    "documentType": {
      "value": "64058cdf10de22571d01b37",
      "label": "Final Word Report"
    },
    "createdAt": "Fri Jan 03 2025 05:40:19 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  }
]
```



```
],
"processingDocuments": [
  {
    "originalname":
"document_1734431533620_DocScanner_Dec_17_2024_1018.pdf",
    "filename":
"1734931222544_document_1734431533620_DocScanner_Dec_17_2024_1018.pdf",
    "path": "cases/67615338b3971e94fccc6172/processingDocuments/1734931222544
_document_1734431533620_DocScanner_Dec_17_2024_1018.pdf",
    "size": "587269",
    "createdAt": "Mon Dec 23 2024 05:20:22 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  },
  {
    "originalname": "Indenture of Lease.pdf",
    "filename": "1734952921335_Indenture_of_Lease.pdf",
    "path": "cases/67615338b3971e94fccc6172/
processingDocuments/1734952921335_Indenture_of_Lease.pdf",
    "size": "6726427",
    "createdAt": "Mon Dec 23 2024 11:22:02 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  },
  {
    "originalname":
"document_1734431533620_DocScanner_Dec_17_2024_1018.pdf",
    "filename":
"1735882837800_document_1734431533620_DocScanner_Dec_17_2024_1018.pdf",
    "path": "cases/67615338b3971e94fccc6172/processingDocuments/1735882837800
_document_1734431533620_DocScanner_Dec_17_2024_1018.pdf",
    "size": "587269",
    "createdAt": "Fri Jan 03 2025 05:40:38 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  },
  {
    "originalname": "Indenture of Lease.pdf",
    "filename": "1735882837822_Indenture_of_Lease.pdf",
    "path": "cases/67615338b3971e94fccc6172/
processingDocuments/1735882837822_Indenture_of_Lease.pdf",
    "size": "6726427",
    "createdAt": "Fri Jan 03 2025 05:40:38 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60016f965256c07aec8e6dd6"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
```

"createdAt": "2024-12-17T10:32:24.613Z",
"updatedAt": "2025-01-03T05:42:34.738Z",
"__v": 0,
"addressForMap": "",
"updatedBy": "60016f965256c07aec8e6dd6",
"siteVisitDate": "2024-12-20"

}

Name	Length	Width	Total
-------------	---------------	--------------	--------------

Composition :

Other

Composition :
