

```
{
  "typeOfReport": {
    "value": "Lenders_Engineers_Report_(LIE)",
    "label": "Lenders_Engineers Report (LIE)"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Bank_Loan",
    "label": "Bank Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7d8"
    },
    "firstName": "Prasad G Deodhar",
    "type": "CREDITOFFICER",
    "_id": "5fc732036229d08b94230eda",
    "email": "0_default_prasad.deodhar@sbi.co.in",
    "mobileNo": "0_DEFAULT_022-26830363",
    "workMobileNo": "0_DEFAULT_91-7506177041"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
```

```
"_id": "643a5702108b68389ed72f71",
"name": "Mumbai",
"shortName": "VCIPL/Mumbai",
"email": "vastukalamumbai@vastukala.com",
"address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
"city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7d8",
  "branchCode": "000031",
  "type": "BRANCH",
  "name": "Industrial Finance Branch, Andheri (East)",
  "email": "varsha.bhat@sbi.co.in",
  "mobileNo": "022-26819792",
  "alternateMobileNo": "022-26822158",
  "address": "102, Natraj Building, 194, Sir M. V. Road, W. E. Highway-Metro Junction,
Andheri (East), Mumbai - 400 069, State - Maharashtra, Country - India.\r\n\r\n\r\n\r\n",
  "ledgerName": "STATE BANK OF INDIA - IFB ANDHERI(E)",
  "fax": "022-26831648",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvanta",
  "mobileNo": "9821518537",
  "shortName": "PS",
  "workWithDocumentMaker": "60f915d3f3dd69653a592199",
  "profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
}
```

```
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "62720b21afd7d55eddedc545",
  "role": "MAKER+CHECKER",
  "firstName": "Avinash",
  "email": "avinash.pandey@vastukala.org",
  "lastName": "Pandey",
  "mobileNo": "9021605621",
  "designation": "",
  "shortName": "AV",
  "workWithDocumentMaker": ""
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      },
      {
        "title": {
          "value": "FIIV",
          "label": "FIIV"
        },
        "_id": "60af80072ffdf65bcd658652",
        "number": "CAT-I-F-1763"
      }
    ]
  }
]
```

```
"title": {
  "value": "Chartered_Engineer",
  "label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "21.362035459281167",
  "longitude": "74.88796513738677"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
```

```
"audioNotes": [],
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Dahiwad",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Basement",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": true,
    "name": "District",
```

```
"key": "district",
"value": "Dhule",
"label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Shirpur",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": false,
  "name": "Building Name",
  "key": "buildingName",
  "value": "",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
}
```

```
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
```



```
"value": "",
"label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
```

```
"status": false,
"name": "Mouza",
"key": "mouza",
"value": "",
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": true,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "59",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN Code-425 405",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  }
},
```

```
"whichTheLocalityIsServed": {
  "buses": {
    "title": "Buses"
  },
  "taxies": {
    "title": "Taxies"
  },
  "auto": {
    "title": "Auto"
  },
  "privateCars": {
    "title": "Private Cars"
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
```

```
"costOfConstruction": "",
"depreciationPercentage": "",
"depreciatedCostOfConstruction": "",
"totalFairMarketValue": ""
}
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
```

```
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
"label": "Electrification, Plumbing, Sanitary Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"liftInstallation": {
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
```

```
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
{others": {
"title": "Others / Car Parking",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
totalValues": {
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
taskStatus": {
"SITE_INSPECTION": false,
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
createCase": "false",
type": "CASE",
leadType": {
"label": "Lead",
"value": "LEAD"
},
siteVisitType": "FULL",
isExternalReport": false,
isSiteMeasurementAllowed": true,
finalValuationArea": "0",
empanelmentNo": [],
isAdvanceInvoice": false,
```

```
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67764cef6353dde0a7ae28bb",
"ownerName": "M/s. Prath Cotspin Pvt. Ltd",
"ownerPhoneNo": "0000000000",
"fullAddress": "Residential Lenders_Engineers Report (LIE) No. Basement Floor,
Village - Dahiwad, Gut No. 59, Taluka - Shirpur, District - Dhule, PIN Code-425 405",
"remark": "",
"documents": [],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "013440",
"createdBy": "627222afafd7d55eddeddd82",
"caseHistory": [
  {
    "id": "798546",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jan 02 2025 08:23:11 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "M/s. Prath Cotspin Pvt. Ltd",
    "phone": "0000000000",
    "ownershipShare": "",
    "email": "",
    "id": "625409"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67764ed140248ae0addc9e49",
  "name":
"externallmg_1735806672793_WhatsApp_Image_20241107_at_121459_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806672793_WhatsApp_Image_20241107_at_121459_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764ed140248ae0addc9e4a",
  "name":
"externallmg_1735806672959_WhatsApp_Image_20241107_at_121525_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806672959_WhatsApp_Image_20241107_at_121525_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764ed140248ae0addc9e4b",
  "name":
"externallmg_1735806673025_WhatsApp_Image_20241107_at_121531_PM_1.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806673025_WhatsApp_Image_20241107_at_121531_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764ed140248ae0addc9e4c",
  "name":
"externallmg_1735806673090_WhatsApp_Image_20241107_at_121531_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806673090_WhatsApp_Image_20241107_at_121531_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764ed140248ae0addc9e4d",
  "name":
"externallmg_1735806673119_WhatsApp_Image_20241107_at_121645_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806673119_WhatsApp_Image_20241107_at_121645_PM.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67764ed140248ae0addc9e4e",
    "name":
"externallmg_1735806673310_WhatsApp_Image_20241107_at_121741_PM.jpeg",
    "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806673310_WhatsApp_Image_20241107_at_121741_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67764ed140248ae0addc9e4f",
    "name":
"externallmg_1735806673357_WhatsApp_Image_20241107_at_121742_PM_1.jpeg",
    "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806673357_WhatsApp_Image_20241107_at_121742_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67764ed140248ae0addc9e50",
    "name":
"externallmg_1735806673385_WhatsApp_Image_20241107_at_121742_PM.jpeg",
    "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806673385_WhatsApp_Image_20241107_at_121742_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67764ed140248ae0addc9e51",
    "name":
"externallmg_1735806673392_WhatsApp_Image_20241107_at_121750_PM.jpeg",
    "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806673392_WhatsApp_Image_20241107_at_121750_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67764ed140248ae0addc9e52",
```

```
    "name":
"externallmg_1735806673453_WhatsApp_Image_20241107_at_121804_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806673453_WhatsApp_Image_20241107_at_121804_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764ed140248ae0addc9e53",
  "name":
"externallmg_1735806673532_WhatsApp_Image_20241107_at_122250_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806673532_WhatsApp_Image_20241107_at_122250_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764ed140248ae0addc9e54",
  "name":
"externallmg_1735806673537_WhatsApp_Image_20241107_at_122253_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806673537_WhatsApp_Image_20241107_at_122253_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764ee840248ae0addc9e90",
  "name":
"externallmg_1735806695601_WhatsApp_Image_20241107_at_122255_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806695601_WhatsApp_Image_20241107_at_122255_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764ee840248ae0addc9e91",
  "name":
"externallmg_1735806695664_WhatsApp_Image_20241107_at_122256_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806695664_WhatsApp_Image_20241107_at_122256_PM.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764ee840248ae0addc9e92",
  "name":
"externallmg_1735806695698_WhatsApp_Image_20241107_at_122258_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806695698_WhatsApp_Image_20241107_at_122258_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764ee840248ae0addc9e93",
  "name":
"externallmg_1735806695727_WhatsApp_Image_20241107_at_122259_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806695727_WhatsApp_Image_20241107_at_122259_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764ee840248ae0addc9e94",
  "name":
"externallmg_1735806695770_WhatsApp_Image_20241107_at_122301_PM_1.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806695770_WhatsApp_Image_20241107_at_122301_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764ee840248ae0addc9e95",
  "name":
"externallmg_1735806695811_WhatsApp_Image_20241107_at_122301_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806695811_WhatsApp_Image_20241107_at_122301_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764ee840248ae0addc9e96",
  "name":
"externallmg_1735806695843_WhatsApp_Image_20241107_at_122302_PM.jpeg",
```

```
    "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806695843_WhatsApp_Image_20241107_at_122302_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67764ee840248ae0addc9e97",
    "name":
"externallmg_1735806695874_WhatsApp_Image_20241107_at_122303_PM.jpeg",
    "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806695874_WhatsApp_Image_20241107_at_122303_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67764ee840248ae0addc9e98",
    "name":
"externallmg_1735806695906_WhatsApp_Image_20241107_at_122304_PM_1.jpeg",
    "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806695906_WhatsApp_Image_20241107_at_122304_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67764ee840248ae0addc9e99",
    "name":
"externallmg_1735806695950_WhatsApp_Image_20241107_at_122304_PM.jpeg",
    "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806695950_WhatsApp_Image_20241107_at_122304_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67764ee840248ae0addc9e9a",
    "name":
"externallmg_1735806695992_WhatsApp_Image_20241107_at_122305_PM.jpeg",
    "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806695992_WhatsApp_Image_20241107_at_122305_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67764ee840248ae0addc9e9b",
  "name":
"externallmg_1735806696027_WhatsApp_Image_20241107_at_122306_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806696027_WhatsApp_Image_20241107_at_122306_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764efa6353dde0a7ae2ac6",
  "name":
"externallmg_1735806713708_WhatsApp_Image_20241107_at_122307_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806713708_WhatsApp_Image_20241107_at_122307_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764efa6353dde0a7ae2ac7",
  "name":
"externallmg_1735806713762_WhatsApp_Image_20241107_at_122308_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806713762_WhatsApp_Image_20241107_at_122308_PM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764efa6353dde0a7ae2ac8",
  "name":
"externallmg_1735806713819_WhatsApp_Image_20241107_at_122310_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806713819_WhatsApp_Image_20241107_at_122310_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764efa6353dde0a7ae2ac9",
  "name":
"externallmg_1735806713930_WhatsApp_Image_20241107_at_122311_PM_1.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806713930_WhatsApp_Image_20241107_at_122311_PM_1.jpeg",
```



```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67764efa6353dde0a7ae2aca",
    "name":
"externallmg_1735806714080_WhatsApp_Image_20241107_at_122311_PM.jpeg",
    "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806714080_WhatsApp_Image_20241107_at_122311_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67764efa6353dde0a7ae2acb",
    "name":
"externallmg_1735806714098_WhatsApp_Image_20241107_at_122312_PM_1.jpeg",
    "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806714098_WhatsApp_Image_20241107_at_122312_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67764efa6353dde0a7ae2acc",
    "name":
"externallmg_1735806714122_WhatsApp_Image_20241107_at_122312_PM.jpeg",
    "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806714122_WhatsApp_Image_20241107_at_122312_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67764efa6353dde0a7ae2acd",
    "name":
"externallmg_1735806714269_WhatsApp_Image_20241107_at_122313_PM.jpeg",
    "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806714269_WhatsApp_Image_20241107_at_122313_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67764efa6353dde0a7ae2ace",
```

```
    "name":
"externallmg_1735806714291_WhatsApp_Image_20241107_at_122314_PM_1.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806714291_WhatsApp_Image_20241107_at_122314_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764efa6353dde0a7ae2acf",
  "name":
"externallmg_1735806714329_WhatsApp_Image_20241107_at_122314_PM_2.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806714329_WhatsApp_Image_20241107_at_122314_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764efa6353dde0a7ae2ad0",
  "name":
"externallmg_1735806714361_WhatsApp_Image_20241107_at_122314_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806714361_WhatsApp_Image_20241107_at_122314_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764efa6353dde0a7ae2ad1",
  "name":
"externallmg_1735806714407_WhatsApp_Image_20241107_at_122315_PM_1.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806714407_WhatsApp_Image_20241107_at_122315_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764f096353dde0a7ae2b12",
  "name":
"externallmg_1735806728548_WhatsApp_Image_20241107_at_122315_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806728548_WhatsApp_Image_20241107_at_122315_PM.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764f096353dde0a7ae2b13",
  "name":
"externallmg_1735806728624_WhatsApp_Image_20241107_at_122316_PM_1.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806728624_WhatsApp_Image_20241107_at_122316_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764f096353dde0a7ae2b14",
  "name":
"externallmg_1735806728650_WhatsApp_Image_20241107_at_122316_PM_2.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806728650_WhatsApp_Image_20241107_at_122316_PM_2.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764f096353dde0a7ae2b15",
  "name":
"externallmg_1735806728682_WhatsApp_Image_20241107_at_122316_PM.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806728682_WhatsApp_Image_20241107_at_122316_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764f096353dde0a7ae2b16",
  "name":
"externallmg_1735806728793_WhatsApp_Image_20241107_at_122317_PM_1.jpeg",
  "path": "cases/67764cef6353dde0a7ae28bb/
externallmg_1735806728793_WhatsApp_Image_20241107_at_122317_PM_1.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67764f096353dde0a7ae2b17",
  "name":
"externallmg_1735806728817_WhatsApp_Image_20241107_at_122317_PM.jpeg",
```

```

    "path": "cases/67764cef6353dde0a7ae28bb/
externalImg_1735806728817_WhatsApp_Image_20241107_at_122317_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-02T08:23:11.453Z",
"updatedAt": "2025-01-02T08:32:09.033Z",
"__v": 0,
"updatedBy": "62720b21afd7d55eddedc545",
"addressForMap": "",
"caseReferredBy": "62720b21afd7d55eddedc545",
"contactPersonName": "M/s. Prath Cotspin Pvt. Ltd",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "0000000000"
}

```

}	Name	Length	Width	Total
Composition :				
Other				
Composition :				