

```
{
  "typeOfReport": {
    "label": "Unit",
    "value": "Unit"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cb"
    },
    "firstName": "Mukesh",
    "type": "CREDITOFFICER",
    "_id": "668bb759e61b5802e8d945d3",
    "email": "amt5so.09276@sbi.co.in",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "7208509979"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6484648",
    "discussWithPerson": "Mukesh",
    "expectedFees": 3242.324,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cb",
  "branchCode": "000019",
  "type": "BRANCH",
  "name": "Diamond Branch (BKC)",
  "email": "sbi.09276@sbi.co.in",
  "mobileNo": "022-2675 2300",
  "alternateMobileNo": "",
  "address": "D/3, West Core, Bharat Dimond Bourse, Bandra-Kurla Complex, Bandra
(East), Mumbai - 400 051, State - Maharashtra, Country - India.\r\n",
  "ledgerName": "STATE BANK OF INDIA - BHARAT DIAMOND BRANCH",
  "fax": "022-2675 2381",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "62723addafd7d55eddeddfe4",
  "role": "PICKUPPERSON",
  "firstName": "Ramkrishna ",
  "email": "rampatakar1991@gmail.com",
  "lastName": "Patkar",
  "mobileNo": "7045746060",
  "shortName": "RP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/62723addafd7d55eddeddfe4/
profilePhoto_1668056044525_WhatsApp_Image_20221110_at_102139_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "6006d4ce5080a310ac1fdfc2",
  "role": "ADMIN",
  "firstName": "Jagdish ",
  "email": "jagdish.bhatt@vastukala.org",
  "lastName": "Bhatt",
  "mobileNo": "8425864014",
  "designation": "",
  "shortName": "JB",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6006d4ce5080a310ac1fdfc2\\
\\profilePhoto_1622372166238_Jagdish Photo (2).jpg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
```

```
    "value": "IBBI/RV/07/2018/10366",
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
```

```
    "workWithDocumentMaker": "",
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "21.112408946435245",
  "longitude": "72.79632787774673"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.79632787774673,
    21.112408946435245
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "16/01/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
```

```
"value": "Maharashtra",
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Vesu",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "16",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Surat",
  "label": false
},
"tahasilNo": {
```

```
"status": false,
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Surat Diamond Bourse",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
```

```
"label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
```



```
"name": "CTS No.",
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": " 1632,1633,1634,1635,1636,1637",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
}
```

```
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
```

```
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
}
```

```
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
```

```
"max": "0.00"
},
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": true,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "678893d9601c90e69621187b",
"ownerName": "Unique dimex ",
"ownerPhoneNo": "8128813799",
"appAddress": "Residential office no - 1632,1633,1634,1635,1636,1637, 16th floor,
Surat diamond bourse, Surat ",
"remark": "",
"documents": [],
```

```
"caseNumber": "013690",
"createdBy": "62723addafd7d55eddeddfe4",
"caseHistory": [
  {
    "id": "401555",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Thu Jan 16 2025 05:06:33 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Unique dimex ",
    "phone": "8128813799",
    "ownershipShare": "",
    "email": "",
    "id": "453928"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6788bdfc5a336ce64e5485a6",
    "name":
"externallmg_1737014779811_WhatsApp_Image_20250115_at_53211_PM.jpeg",
    "path": "cases/678893d9601c90e69621187b/
externallmg_1737014779811_WhatsApp_Image_20250115_at_53211_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6788bdfc5a336ce64e5485a7",
    "name":
"externallmg_1737014779834_WhatsApp_Image_20250115_at_53212_PM_1.jpeg",
    "path": "cases/678893d9601c90e69621187b/
externallmg_1737014779834_WhatsApp_Image_20250115_at_53212_PM_1.jpeg",
```

```
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6788bdfc5a336ce64e5485a8",
    "name":
"externallmg_1737014779849_WhatsApp_Image_20250115_at_53212_PM.jpeg",
    "path": "cases/678893d9601c90e69621187b/
externallmg_1737014779849_WhatsApp_Image_20250115_at_53212_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6788bdfc5a336ce64e5485a9",
    "name":
"externallmg_1737014779904_WhatsApp_Image_20250115_at_53213_PM.jpeg",
    "path": "cases/678893d9601c90e69621187b/
externallmg_1737014779904_WhatsApp_Image_20250115_at_53213_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6788bdfc5a336ce64e5485aa",
    "name":
"externallmg_1737014779915_WhatsApp_Image_20250115_at_53214_PM.jpeg",
    "path": "cases/678893d9601c90e69621187b/
externallmg_1737014779915_WhatsApp_Image_20250115_at_53214_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6788bdfc5a336ce64e5485ab",
    "name":
"externallmg_1737014779975_WhatsApp_Image_20250115_at_53215_PM.jpeg",
    "path": "cases/678893d9601c90e69621187b/
externallmg_1737014779975_WhatsApp_Image_20250115_at_53215_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6788bdfc5a336ce64e5485ac",
```

```
    "name":
"externallmg_1737014779985_WhatsApp_Image_20250115_at_53216_PM.jpeg",
    "path": "cases/678893d9601c90e69621187b/
externallmg_1737014779985_WhatsApp_Image_20250115_at_53216_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6788bdfc5a336ce64e5485ad",
    "name":
"externallmg_1737014780050_WhatsApp_Image_20250115_at_53217_PM_1.jpeg",
    "path": "cases/678893d9601c90e69621187b/
externallmg_1737014780050_WhatsApp_Image_20250115_at_53217_PM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6788bdfc5a336ce64e5485ae",
    "name":
"externallmg_1737014780059_WhatsApp_Image_20250115_at_53217_PM.jpeg",
    "path": "cases/678893d9601c90e69621187b/
externallmg_1737014780059_WhatsApp_Image_20250115_at_53217_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6788bdfc5a336ce64e5485af",
    "name":
"externallmg_1737014780128_WhatsApp_Image_20250115_at_53218_PM.jpeg",
    "path": "cases/678893d9601c90e69621187b/
externallmg_1737014780128_WhatsApp_Image_20250115_at_53218_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6788be0f290edae64f185812",
    "name":
"externallmg_1737014798763_WhatsApp_Image_20250115_at_53219_PM.jpeg",
    "path": "cases/678893d9601c90e69621187b/
externallmg_1737014798763_WhatsApp_Image_20250115_at_53219_PM.jpeg",
    "orientation": "landscape"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6788be0f290edae64f185813",
  "name":
"externallmg_1737014798770_WhatsApp_Image_20250115_at_53220_PM.jpeg",
  "path": "cases/678893d9601c90e69621187b/
externallmg_1737014798770_WhatsApp_Image_20250115_at_53220_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6788be0f290edae64f185814",
  "name":
"externallmg_1737014798789_WhatsApp_Image_20250115_at_53221_PM.jpeg",
  "path": "cases/678893d9601c90e69621187b/
externallmg_1737014798789_WhatsApp_Image_20250115_at_53221_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6788be0f290edae64f185815",
  "name":
"externallmg_1737014798802_WhatsApp_Image_20250115_at_53222_PM.jpeg",
  "path": "cases/678893d9601c90e69621187b/
externallmg_1737014798802_WhatsApp_Image_20250115_at_53222_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6788be0f290edae64f185816",
  "name":
"externallmg_1737014798928_WhatsApp_Image_20250115_at_53223_PM.jpeg",
  "path": "cases/678893d9601c90e69621187b/
externallmg_1737014798928_WhatsApp_Image_20250115_at_53223_PM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6788be0f290edae64f185817",
  "name":
"externallmg_1737014798939_WhatsApp_Image_20250115_at_53224_PM.jpeg",
```

```
    "path": "cases/678893d9601c90e69621187b/
externallmg_1737014798939_WhatsApp_Image_20250115_at_53224_PM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6788be0f290edae64f185818",
    "name":
"externallmg_1737014799001_WhatsApp_Image_20250115_at_53225_PM.jpeg",
    "path": "cases/678893d9601c90e69621187b/
externallmg_1737014799001_WhatsApp_Image_20250115_at_53225_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6788be0f290edae64f185819",
    "name":
"externallmg_1737014799012_WhatsApp_Image_20250115_at_53226_PM.jpeg",
    "path": "cases/678893d9601c90e69621187b/
externallmg_1737014799012_WhatsApp_Image_20250115_at_53226_PM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6788be0f290edae64f18581a",
    "name":
"externallmg_1737014799082_WhatsApp_Image_20250115_at_53227_PM.jpeg",
    "path": "cases/678893d9601c90e69621187b/
externallmg_1737014799082_WhatsApp_Image_20250115_at_53227_PM.jpeg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "SDB - 1632 - DASTAVEJ.pdf",
    "filename": "1737014587546_SDB__1632__DASTAVEJ.pdf",
    "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014587546_SDB__1632__DASTAVEJ.pdf",
    "size": "47360484",
    "createdAt": "Thu Jan 16 2025 08:03:23 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },

```

```
{
  "originalname": "SDB - 1632 - INDEX COPY.pdf",
  "filename": "1737014588517_SDB__1632__INDEX_COPY.pdf",
  "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014588517_SDB__1632__INDEX_COPY.pdf",
  "size": "1060792",
  "createdAt": "Thu Jan 16 2025 08:03:23 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "64dc7184ccaf1e7b7f637f47"
},
{
  "originalname": "SDB - 1632 - REGISTRATION COPY.pdf",
  "filename": "1737014588543_SDB__1632__REGISTRATION_COPY.pdf",
  "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014588543_SDB__1632__REGISTRATION_COPY.pdf",
  "size": "1088628",
  "createdAt": "Thu Jan 16 2025 08:03:23 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "64dc7184ccaf1e7b7f637f47"
},
{
  "originalname": "SDB - 1633 - DASTAVEJ.pdf",
  "filename": "1737014592661_SDB__1633__DASTAVEJ.pdf",
  "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014592661_SDB__1633__DASTAVEJ.pdf",
  "size": "47728110",
  "createdAt": "Thu Jan 16 2025 08:03:23 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "64dc7184ccaf1e7b7f637f47"
},
{
  "originalname": "SDB - 1633 - INDEX COPY.pdf",
  "filename": "1737014593513_SDB__1633__INDEX_COPY.pdf",
  "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014593513_SDB__1633__INDEX_COPY.pdf",
  "size": "1191097",
  "createdAt": "Thu Jan 16 2025 08:03:23 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "64dc7184ccaf1e7b7f637f47"
},
{
  "originalname": "SDB - 1633 - REGISTRATION COPY.pdf",
  "filename": "1737014593554_SDB__1633__REGISTRATION_COPY.pdf",
  "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014593554_SDB__1633__REGISTRATION_COPY.pdf",
  "size": "1064609",
  "createdAt": "Thu Jan 16 2025 08:03:23 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "64dc7184ccaf1e7b7f637f47"
},
{
```

```
    "originalname": "SDB - 1634 - DASTAVEJ.pdf",
    "filename": "1737014597698_SDB__1634__DASTAVEJ.pdf",
    "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014597698_SDB__1634__DASTAVEJ.pdf",
    "size": "48619647",
    "createdAt": "Thu Jan 16 2025 08:03:23 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "SDB - 1634 - INDEX COPY.pdf",
    "filename": "1737014598625_SDB__1634__INDEX_COPY.pdf",
    "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014598625_SDB__1634__INDEX_COPY.pdf",
    "size": "1210085",
    "createdAt": "Thu Jan 16 2025 08:03:23 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "SDB - 1634 - REGISTRATION COPY.pdf",
    "filename": "1737014598667_SDB__1634__REGISTRATION_COPY.pdf",
    "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014598667_SDB__1634__REGISTRATION_COPY.pdf",
    "size": "1108681",
    "createdAt": "Thu Jan 16 2025 08:03:23 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "SDB - 1635 - DASTAVEJ.pdf",
    "filename": "1737014616319_SDB__1635__DASTAVEJ.pdf",
    "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014616319_SDB__1635__DASTAVEJ.pdf",
    "size": "48394335",
    "createdAt": "Thu Jan 16 2025 08:03:46 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "SDB - 1635 - INDEX COPY.pdf",
    "filename": "1737014617207_SDB__1635__INDEX_COPY.pdf",
    "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014617207_SDB__1635__INDEX_COPY.pdf",
    "size": "1121593",
    "createdAt": "Thu Jan 16 2025 08:03:46 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "SDB - 1635 - REGISTRATION COPY.pdf",
```



```
    "filename": "1737014617226_SDB__1635__REGISTRATION_COPY.pdf",
    "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014617226_SDB__1635__REGISTRATION_COPY.pdf",
    "size": "1124581",
    "createdAt": "Thu Jan 16 2025 08:03:46 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "SDB - 1636 - INDEX COPY.pdf",
    "filename": "1737014621446_SDB__1636__INDEX_COPY.pdf",
    "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014621446_SDB__1636__INDEX_COPY.pdf",
    "size": "1064159",
    "createdAt": "Thu Jan 16 2025 08:03:46 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "SDB - 1636 - REGISTRATION COPY.pdf",
    "filename": "1737014621488_SDB__1636__REGISTRATION_COPY.pdf",
    "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014621488_SDB__1636__REGISTRATION_COPY.pdf",
    "size": "1069430",
    "createdAt": "Thu Jan 16 2025 08:03:46 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "SDB - 1637 - DASTAVEJ.pdf",
    "filename": "1737014621652_SDB__1637__DASTAVEJ.pdf",
    "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014621652_SDB__1637__DASTAVEJ.pdf",
    "size": "47311107",
    "createdAt": "Thu Jan 16 2025 08:03:46 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "SDB - 1637 - INDEX COPY.pdf",
    "filename": "1737014622370_SDB__1637__INDEX_COPY.pdf",
    "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014622370_SDB__1637__INDEX_COPY.pdf",
    "size": "1136937",
    "createdAt": "Thu Jan 16 2025 08:03:46 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "SDB - 1637 - REGISTRATION COPY.pdf",
    "filename": "1737014622394_SDB__1637__REGISTRATION_COPY.pdf",
```

```

    "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014622394_SDB__1637__REGISTRATION_COPY.pdf",
    "size": "1083415",
    "createdAt": "Thu Jan 16 2025 08:03:46 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  },
  {
    "originalname": "SDB BILL.pdf",
    "filename": "1737014703517_SDB_BILL.pdf",
    "path": "cases/678893d9601c90e69621187b/
processingDocuments/1737014703517_SDB_BILL.pdf",
    "size": "5550313",
    "createdAt": "Thu Jan 16 2025 08:05:04 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "64dc7184ccaf1e7b7f637f47"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-16T05:06:33.435Z",
"updatedAt": "2025-01-16T08:06:39.321Z",
"__v": 0,
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"fullAddress": "Residential Unit No. 1632,1633,1634,1635,1636,1637, 16th Floor,
Surat Diamond Bourse, Village - Vesu, Surat, State - Gujrat",
"updatedBy": "64dc7184ccaf1e7b7f637f47",
"addressForMap": "",
"caseReferredBy": "62723addafd7d55eddeddfe4",
"contactPersonName": "Unique dimex ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "8128813799"
}

```

Name	Length	Width	Total
Composition :			

Other
Composition :
