

```
{
  "typeOfReport": {
    "label": "Land and Building",
    "value": "Land_and_Building"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Bank Loan",
    "value": "Bank_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "63ad7dca191f7b344b003ede"
    },
    "firstName": "Shashank ",
    "type": "CREDITOFFICER",
    "_id": "65c33048b0ec7f2151fdb8bc",
    "lastName": "Kumar",
    "mobileNo": "",
    "workMobileNo": "7905284698",
    "email": "shashank.kumar@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "107543807",
    "discussWithPerson": "Shashank ",
    "expectedFees": 53771.9035,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "63ad7dca191f7b344b003ede",
  "name": "UBI-GOREGAON (EAST)",
  "branchCode": "",
  "mobileNo": "\"022-26863400 022-26862835\"",
  "alternateMobileNo": "",
  "email": "goregaon@unionbankofindia.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "172/73, Shree Sadan, Shantaben Estate, Goregoan (East), Mumbai -
400 063."
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Industrial",
  "value": "Industrial"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "60af6ae22ffdf65bcd65861d",
"role": "PICKUPPERSON",
"firstName": "Sunil",
"email": "misalsunil87@gmail.com",
"lastName": "Misal",
"mobileNo": "8422982721",
"shortName": "SM",
"workWithDocumentMaker": "",
"profilePhoto": "users\\60af6ae22ffdf65bcd65861d\
\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "65dee3f79a876858ab30487f",
"role": "SITEENGINEER",
"firstName": "Saiprasad",
"email": "saiprasadpatil1010@gmail.com",
"lastName": "Patil",
```

```
"mobileNo": "8830049996",
"designation": "Valuation Engineer",
"shortName": "SSP",
"workWithDocumentMaker": "60f91822f3dd69653a5922e3",
"profilePhoto": "users/65dee3f79a876858ab30487f/
profilePhoto_1717393558148_image.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ]
  }
]
```

```
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "21.78170064514643",
  "longitude": "72.8201928032399"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.8201928032399,
    21.78170064514643
  ]
}
```

```
]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "21/01/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Sykha",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
```

```
"value": "Ground",
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Bharuch",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Vagra",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "DP-119",
  "label": true
},
"buildingName": {
```

```
"status": false,
"name": "Building Name",
"key": "buildingName",
"value": "",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "G I D C ",
  "label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Sykha Industrial Estate",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
```



```
"label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "91/5",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "",
  "label": false
},
"municipalityWardNo": {
  "status": false,
```

```
"name": "Municipality Ward No.",
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "392140",
  "label": false
}
```

```
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
```

```
"routeMapImg": "",
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
```

```
"status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
}
```

```
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
```

```
"title": "Wardrobes",
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
}
```



```
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
}
```

```
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "678e38af5a336ce64e56ab51",
"ownerName": "M/s Bbell Industry LLP ",
"ownerPhoneNo": "7021735435",
"appAddress": "Plot no DP- 119 G.I.G.C Saykha Industrial Estate Revenue Survey No
19 /P Village Saykha Tal Vegra Dist Bharuch Gujarat 392140",
"remark": "urgent hey Valution report bank ",
"documents": [
  {
    "documentType": {
      "label": "Lease Deed",
      "value": "60ae1247aa6d152c1801b2eb"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/678e38af5a336ce64e56ab51/document_1737373834415_17373738
23253_UBI_Goregoan_Documents_Copy_Of_Lease_DeedAllotment_LetterPossession
_ReceiptCertificate_of_Registration__Office_Order_in_Consideration_from.pdf",
    "fileName": "document_1737373834415_1737373823253_UBI_Goregoan_Docume
nts_Copy_Of_Lease_DeedAllotment_LetterPossession_ReceiptCertificate_of_Registrat
ion__Office_Order_in_Consideration_from.pdf",
    "id": "568580",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Mon Jan 20 2025 11:51:11 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "label": "Valuation Report",
      "value": "60ae1255aa6d152c1801b32b"
    }
  }
]
```

```
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/678e38af5a336ce64e56ab51/document_1737373931990_17373739
29321_UBI_Goregoan_East_Plot_no_119_Bharuch_Gujarat_Land__bldg_1.pdf",
    "fileName": "document_1737373931990_1737373929321_UBI_Goregoan_East_Plo
t_no_119_Bharuch_Gujarat_Land__bldg_1.pdf",
    "id": "899906",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Mon Jan 20 2025 11:52:18 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124aaa6d152c1801b2f7",
      "label": "Any Other Document"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1738215586422_BBELL_FULL_TRANSFER_ORDER_OF_PLOT.pdf",
    "path": "cases/678e38af5a336ce64e56ab51/
document_1738215586422_BBELL_FULL_TRANSFER_ORDER_OF_PLOT.pdf",
    "id": "273960",
    "uploadedBy": "65dee3f79a876858ab30487f",
    "createdAt": "Thu Jan 30 2025 05:45:29 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae124eaa6d152c1801b30b",
      "label": "Other"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "fileName":
"document_1738215606527_BBELL_HANDING_OVER_POSESSION_LETTER.pdf",
    "path": "cases/678e38af5a336ce64e56ab51/
document_1738215606527_BBELL_HANDING_OVER_POSESSION_LETTER.pdf",
    "id": "866916",
    "uploadedBy": "65dee3f79a876858ab30487f",
    "createdAt": "Thu Jan 30 2025 05:45:29 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "value": "60ae126eaa6d152c1801b39f",
      "label": "Agreement"
    },
  },
```

```
"inputs": {
  "from": {
    "value": "Owner",
    "label": "Owner"
  },
  "Owner": "Bbell Industries",
  "to": {
    "value": "Member",
    "label": "Member"
  },
  "Member": "Bbell Industries"
},
"isHardCopy": false,
"displayStatus": false,
"fileName": "document_1738215761861_BBELL_INDUSTRY_LLP_AGREEMENT_
SIGNED__COLOUR.pdf",
"path": "cases/678e38af5a336ce64e56ab51/document_1738215761861_BBELL_IN
DUSTRY_LLP_AGREEMENT_SIGNED__COLOUR.pdf",
"id": "512783",
"uploadedBy": "65dee3f79a876858ab30487f",
"createdAt": "Thu Jan 30 2025 05:45:29 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1258aa6d152c1801b339",
    "label": "Possession Letter"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1738215781331_BBELL_PLOT_POSSESSION_LETTER_original.pdf",
  "path": "cases/678e38af5a336ce64e56ab51/
document_1738215781331_BBELL_PLOT_POSSESSION_LETTER_original.pdf",
  "id": "501430",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Thu Jan 30 2025 05:45:29 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae12b3aa6d152c1801b4de",
    "label": "Form of Application"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1738215799598_Certificate_FACTORY_LICENSE.pdf",
  "path": "cases/678e38af5a336ce64e56ab51/
document_1738215799598_Certificate_FACTORY_LICENSE.pdf",
```

```
"id": "234342",
"uploadedBy": "65dee3f79a876858ab30487f",
"createdAt": "Thu Jan 30 2025 05:45:29 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae124eaa6d152c1801b30b",
    "label": "Other"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1738215814698_FINAL_CCA.pdf",
  "path": "cases/678e38af5a336ce64e56ab51/
document_1738215814698_FINAL_CCA.pdf",
  "id": "635618",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Thu Jan 30 2025 05:45:29 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae1247aa6d152c1801b2eb",
    "label": "Lease Deed"
  },
  "inputs": {
    "from": {
      "value": "Transferor",
      "label": "Transferor"
    },
    "Transferor": "GIDC",
    "to": {
      "value": "Lessee",
      "label": "Lessee"
    },
    "Lessee": "Bbell Industries"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1738215897198_Lease_Deed.pdf",
  "path": "cases/678e38af5a336ce64e56ab51/
document_1738215897198_Lease_Deed.pdf",
  "id": "236734",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Thu Jan 30 2025 05:45:29 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
```

```
    "value": "60ae124eaa6d152c1801b308",
    "label": "Building Plan"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName":
"document_1738215915016_PDF_Drawing_Saykha_Dahejll_SCR_1000_7.pdf",
  "path": "cases/678e38af5a336ce64e56ab51/
document_1738215915016_PDF_Drawing_Saykha_Dahejll_SCR_1000_7.pdf",
  "id": "661013",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Thu Jan 30 2025 05:45:29 GMT+0000 (Coordinated Universal Time)"
},
{
  "documentType": {
    "value": "60ae126aaa6d152c1801b38c",
    "label": "Water bill"
  },
  "inputs": {
    "number": {
      "value": "Document_No",
      "label": "Document No"
    },
    "Document_No": "00"
  },
  "isHardCopy": false,
  "displayStatus": false,
  "fileName": "document_1738215929634_Water_Bill.pdf",
  "path": "cases/678e38af5a336ce64e56ab51/
document_1738215929634_Water_Bill.pdf",
  "id": "356585",
  "uploadedBy": "65dee3f79a876858ab30487f",
  "createdAt": "Thu Jan 30 2025 05:45:29 GMT+0000 (Coordinated Universal Time)"
}
],
"caseNumber": "013785",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "171258",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Jan 20 2025 11:51:11 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
```

```
{
  "name": "M/s Bbell Industry LLP ",
  "phone": "7021735435",
  "ownershipShare": "",
  "email": "",
  "id": "156307"
},
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679760162f3738a577c82206",
    "name":
"externallmg_1737973775213_20250122_123928PMBByGPSMapCamera.jpg",
    "path": "cases/678e38af5a336ce64e56ab51/
externallmg_1737973775213_20250122_123928PMBByGPSMapCamera.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679760162f3738a577c82207",
    "name":
"externallmg_1737973775327_20250122_123930PMBByGPSMapCamera.jpg",
    "path": "cases/678e38af5a336ce64e56ab51/
externallmg_1737973775327_20250122_123930PMBByGPSMapCamera.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679760162f3738a577c82208",
    "name":
"externallmg_1737973775443_20250122_123938PMBByGPSMapCamera.jpg",
    "path": "cases/678e38af5a336ce64e56ab51/
externallmg_1737973775443_20250122_123938PMBByGPSMapCamera.jpg",
    "orientation": "landscape"
  }
]
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679760162f3738a577c82209",
  "name": "externallmg_r_1737973775586_IMG_20250122_120441.jpg",
  "path": "cases/678e38af5a336ce64e56ab51/
externallmg_r_1737973775586_IMG_20250122_120441.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679760162f3738a577c8220a",
  "name": "externallmg_r_1737973775856_IMG_20250122_120448.jpg",
  "path": "cases/678e38af5a336ce64e56ab51/
externallmg_r_1737973775856_IMG_20250122_120448.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679760162f3738a577c8220b",
  "name": "externallmg_r_1737973776861_IMG_20250122_120746.jpg",
  "path": "cases/678e38af5a336ce64e56ab51/
externallmg_r_1737973776861_IMG_20250122_120746.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679760162f3738a577c8220c",
  "name": "externallmg_r_1737973776425_IMG_20250122_120732.jpg",
  "path": "cases/678e38af5a336ce64e56ab51/
externallmg_r_1737973776425_IMG_20250122_120732.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679760162f3738a577c8220d",
  "name": "externallmg_r_1737973778216_IMG_20250122_123901.jpg",
  "path": "cases/678e38af5a336ce64e56ab51/
externallmg_r_1737973778216_IMG_20250122_123901.jpg",
  "orientation": "landscape"
},
}
```



```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679760162f3738a577c8220e",
  "name": "externallmg_r_1737973778630_IMG_20250122_124107__01.jpg",
  "path": "cases/678e38af5a336ce64e56ab51/
externallmg_r_1737973778630_IMG_20250122_124107__01.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679760162f3738a577c8220f",
  "name": "externallmg_r_1737973777241_IMG_20250122_121001.jpg",
  "path": "cases/678e38af5a336ce64e56ab51/
externallmg_r_1737973777241_IMG_20250122_121001.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679760162f3738a577c82210",
  "name": "externallmg_r_1737973777817_IMG_20250122_123843.jpg",
  "path": "cases/678e38af5a336ce64e56ab51/
externallmg_r_1737973777817_IMG_20250122_123843.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679760162f3738a577c82211",
  "name": "externallmg_r_1737973778785_IMG_20250122_124119.jpg",
  "path": "cases/678e38af5a336ce64e56ab51/
externallmg_r_1737973778785_IMG_20250122_124119.jpg",
  "orientation": "landscape"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Bbell Industry LLP.xlsx",
    "filename": "1737973899774_Bbell_Industry_LLP.xlsx",
    "path": "cases/678e38af5a336ce64e56ab51/
processingDocuments/1737973899774_Bbell_Industry_LLP.xlsx",
    "size": "678306",
    "createdAt": "Mon Jan 27 2025 10:31:39 GMT+0000 (Coordinated Universal Time)",
```

```

    "uploadedBy": "60f91822f3dd69653a5922e3"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-20T11:51:11.799Z",
"updatedAt": "2025-01-30T05:45:29.771Z",
"__v": 0,
"uniqueNo": "",
"updatedBy": "65dee3f79a876858ab30487f",
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Industrial Land and Building No. Ground Floor, Plot No. DP-119, New/
Current Survey No. 91/5, G I D C , Sykha Industrial Estate, Village - Sykha, Taluka -
Vagra, District - Bharuch, 392140, State - Maharashtra, India",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "M/s Bbell Industry LLP ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "7021735435"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			