

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856bb65"
    },
    "firstName": "Dinesh",
    "type": "CREDITOFFICER",
    "_id": "66cdbe320f117327db778450",
    "email": "bo1317@pnb.co.in",
    "lastName": "Mandewala",
    "mobileNo": "",
    "workMobileNo": "9324100424"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "12600000",
    "discussWithPerson": "Dinesh",
    "expectedFees": 6300,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1812",
  "type": "BANK",
  "name": "Punjab National Bank",
  "displayName": "Punjab National Bank",
  "initial": "PNB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856bb65",
  "branchCode": "000082",
  "type": "BRANCH",
  "name": "Borivali West Branch ",
  "email": "bo1317@pnb.co.in",
  "mobileNo": "02228954767",
  "alternateMobileNo": "",
  "address": "Ganjawala Elegance, Ganjawala Lane, Near Chamunda Circle Petrol
Pump Borivali West, Mumbai - 400092",
  "ledgerName": "",
  "fax": "",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f7fcadf3dd69653a58d9d7",
  "zoneName": "Mumbai Zone (Maharashtra)"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60af6ae22ffdf65bcd65861d",
  "role": "PICKUPPERSON",
  "firstName": "Sunil",
  "email": "misalsunil87@gmail.com",
  "lastName": "Misal",
  "mobileNo": "8422982721",
  "shortName": "SM",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\60af6ae22ffdf65bcd65861d\\
\\profilePhoto_1622701583996_WhatsApp Image 2021-06-03 at 11.43.11 AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "67776d60a5477d50e7dbc213",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "AJAY",
  "email": "ajayrewale503@gmail.com",
  "lastName": "REWALE",
  "mobileNo": "9766640171",
  "designation": "",
  "shortName": "AJAY",
  "workWithDocumentMaker": ""
},
"rateVerifier": null,
"maker": null,
"checker": null,
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "[N]C.C.I.T/I -14/52/2008-09",
        "label": "Wealth Tax"
      }
    ]
  },
  {
    "type": "EMPLOYEE",
    "_id": "6084131a13f01f158c6ea1f3",
    "PANNo": "AEAPC7114Q",
    "role": "VALUER",
    "firstName": "Sharadkumar",
    "fatherName": "Baburao",
    "email": "cmd@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9422171100",
    "designation": "CMD",
    "registrationNo": [
```

```
{
  "title": {
    "value": "Wealth_Tax",
    "label": "Wealth Tax"
  },
  "_id": "6084131a13f01f158c6ea1f4",
  "number": "[N]C.C.I.T/I -14/52/2008-09"
}
],
"shortName": "SBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.21711330725979",
  "longitude": "72.82153103517295"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.82153103517295,
    19.21711330725979
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "21/01/2025 12:00 am",
      "remark": ""
    }
  ]
},
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
```

```
"finalMeasurementType": "Sq. Ft.",
"underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Charkop",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "2",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
}
```

```
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "26",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Charkop Sukhkarta CHSL",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
```

```
"value": "RSC 22",
"label": false
},
"street2": {
  "status": true,
  "name": "Street 2",
  "key": "street2",
  "value": "Swami Samarth Road",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": true,
  "name": "Wing",
  "key": "wing",
  "value": "A",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
```

```
"status": false,
"name": "Hissa No.",
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "202",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
```



```
"label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400067",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    }
  },
}
```

```
"taxies": {
  "title": "Taxies"
},
"auto": {
  "title": "Auto"
},
"privateCars": {
  "title": "Private Cars"
}
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
}
```

```
}
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
```

```
"label": "Internal Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
"label": "External Plastering",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
"label": "Door",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"window": {
"label": "Window",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"flooringTilingKitchenPlatform": {
"label": "Flooring, Tiling, Kitchen Platform",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
"label": "Internal Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPainting": {
"label": "External Painting",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
```

```
"status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
```

```
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
}
```

```
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
```



```
"paymentIds": [],
"_id": "678f44a7290edae64f1b7954",
"ownerName": "Umesh Shivaji Patel & Narmada Umesh Patel ",
"ownerPhoneNo": "9699621250",
"appAddress": "Flat no 202 2 nd floor A-wing Charkop Sukhakarta Co-op HSG Soc
Ltd Charkop Road Swami Samarth Mandir Kandivali West Mumbai 400067",
"remark": "",
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/678f44a7290edae64f1b7954/document_1737442405324_173744240
3484_Umesh_Patel_PNB_Bori_Borivali_West_1_2.pdf",
    "fileName": "document_1737442405324_1737442403484_Umesh_Patel_PNB_Bori
_Borivali_West_1_2.pdf",
    "id": "146239",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Tue Jan 21 2025 06:54:30 GMT+0000 (Coordinated Universal Time)"
  },
  {
    "documentType": {
      "label": "Old Valution Report ",
      "value": "60ae1296aa6d152c1801b455"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/678f44a7290edae64f1b7954/document_1737442454092_173744245
2703_Umesh_Patel_Old_Valuation_report_Borivali_West.pdf",
    "fileName": "document_1737442454092_1737442452703_Umesh_Patel_Old_Valua
tion_report_Borivali_West.pdf",
    "id": "277448",
    "uploadedBy": "60af6ae22ffdf65bcd65861d",
    "createdAt": "Tue Jan 21 2025 06:54:30 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "013797",
"createdBy": "60af6ae22ffdf65bcd65861d",
"caseHistory": [
  {
    "id": "970040",
    "title": "Create Lead",
    "description": "Create Lead",
```

```
    "datetime": "Tue Jan 21 2025 06:54:31 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Umesh Shivaji Patel & Narmada Umesh Patel ",
    "phone": "9699621250",
    "ownershipShare": "",
    "email": "",
    "id": "372713"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f6634950c3df32fe85528",
    "name": "externalImg_1737451040253_1737451032345_image_0.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/externalImg_1737451040253_1737451032345_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f6634950c3df32fe85529",
    "name": "externalImg_1737451040614_1737451032345_image_1.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/externalImg_1737451040614_1737451032345_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f6634950c3df32fe8552a",
    "name": "externalImg_1737451041967_1737451032345_image_2.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/externalImg_1737451041967_1737451032345_image_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f6634950c3df32fe8552b",
    "name": "externallmg_1737451043016_1737451032345_image_3.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451043016_1737451032345_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f6634950c3df32fe8552c",
    "name": "externallmg_1737451046064_1737451032345_image_4.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451046064_1737451032345_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f6634950c3df32fe8552d",
    "name": "externallmg_1737451046380_1737451032345_image_5.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451046380_1737451032345_image_5.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f6634950c3df32fe8552e",
    "name": "externallmg_1737451047704_1737451032345_image_6.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451047704_1737451032345_image_6.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f6634950c3df32fe8552f",
    "name": "externallmg_1737451050036_1737451032345_image_7.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451050036_1737451032345_image_7.jpeg",
    "orientation": "portrait"
  }
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678f6634950c3df32fe85530",
  "name": "externallmg_1737451051101_1737451032345_image_8.jpeg",
  "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451051101_1737451032345_image_8.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678f6634950c3df32fe85531",
  "name": "externallmg_1737451051919_1737451032345_image_9.jpeg",
  "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451051919_1737451032345_image_9.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678f6634950c3df32fe85532",
  "name": "externallmg_1737451052906_1737451032345_image_10.jpeg",
  "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451052906_1737451032345_image_10.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678f6634950c3df32fe85533",
  "name": "externallmg_1737451053732_1737451032345_image_11.jpeg",
  "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451053732_1737451032345_image_11.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678f6634950c3df32fe85534",
  "name": "externallmg_1737451054755_1737451032345_image_12.jpeg",
  "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451054755_1737451032345_image_12.jpeg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678f6634950c3df32fe85535",
  "name": "externallmg_1737451055288_1737451032345_image_13.jpeg",
  "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451055288_1737451032345_image_13.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678f6634950c3df32fe85536",
  "name": "externallmg_1737451055921_1737451032345_image_14.jpeg",
  "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451055921_1737451032345_image_14.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678f6634950c3df32fe85537",
  "name": "externallmg_1737451056187_1737451032345_image_15.jpeg",
  "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451056187_1737451032345_image_15.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678f6634950c3df32fe85538",
  "name": "externallmg_1737451056746_1737451032345_image_16.jpeg",
  "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451056746_1737451032345_image_16.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "678f6634950c3df32fe85539",
  "name": "externallmg_1737451057435_1737451032345_image_17.jpeg",
  "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451057435_1737451032345_image_17.jpeg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f6634950c3df32fe8553a",
    "name": "externallmg_1737451058373_1737451032345_image_18.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451058373_1737451032345_image_18.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f6634950c3df32fe8553b",
    "name": "externallmg_1737451058981_1737451032345_image_19.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451058981_1737451032345_image_19.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f66565a336ce64e573ee8",
    "name": "externallmg_1737451086085_1737451080756_image_0.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451086085_1737451080756_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f66565a336ce64e573ee9",
    "name": "externallmg_1737451087755_1737451080756_image_1.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451087755_1737451080756_image_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f66565a336ce64e573eea",
    "name": "externallmg_1737451088865_1737451080756_image_2.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451088865_1737451080756_image_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
    "status": false,
    "_id": "678f66565a336ce64e573eeb",
    "name": "externallmg_1737451089970_1737451080756_image_3.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451089970_1737451080756_image_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f66565a336ce64e573eec",
    "name": "externallmg_1737451091035_1737451080756_image_4.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451091035_1737451080756_image_4.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "678f66565a336ce64e573eed",
    "name": "externallmg_1737451093485_1737451080756_image_5.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737451093485_1737451080756_image_5.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "678f923101810047879b9731",
    "name": "externallmg_1737462318999_1737462317668_image_0.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737462318999_1737462317668_image_0.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "MEASUREMENT_IMAGE",
    "status": false,
    "_id": "678f923101810047879b9732",
    "name": "externallmg_1737462319789_1737462317668_image_1.jpeg",
    "path": "cases/678f44a7290edae64f1b7954/
externallmg_1737462319789_1737462317668_image_1.jpeg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
```

```

"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-21T06:54:31.073Z",
"updatedAt": "2025-01-21T12:25:21.170Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Flat No. 202, 2nd Floor, Wing - A, Charkop Sukhkarta
CHSL, Plot No. 26, RSC 22, Swami Samarth Road, Village - Charkop, Kandivali West,
Mumbai, 400067",
"updatedBy": "67776d60a5477d50e7dbc213",
"addressForMap": "",
"caseReferredBy": "60af6ae22ffdf65bcd65861d",
"contactPersonName": "Umesh Shivaji Patel & Narmada Umesh Patel ",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9699621250"

```

}	Name	Length	Width	Total
Composition :				
Other				
Composition :				