

```
{
  "typeOfReport": {
    "value": "Lenders_Engineers_Report_(LIE)",
    "label": "Lenders_Engineers Report (LIE)"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Lenders_Engineers_Report_(LIE)",
    "label": "Lenders_Engineers Report (LIE)"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "firstName": "Manish",
    "type": "CREDITOFFICER",
    "_id": "64338d21d267175d008119f1",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "9049983319",
    "email": "manish.jha9@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "15000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
```

```
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
"type": "EMPLOYEE",
"_id": "60f91822f3dd69653a5922e3",
"role": "SITEENGINEER+MAKAR+CHECKER",
"firstName": "Prayush ",
"email": "prayush@vastukala.org",
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "AM161706-3",
"label": "Chartered Engineer"
},
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
]
},
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
}
```

```
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.113944946207358",
  "longitude": "72.84152141681274"
},
```

```
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2024-10-18",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Vile Parle",
```

```
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "9",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Andheri (West)",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": true,
```

```
"name": "Plot No.",
"key": "plotNo",
"value": "1",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Aneesh Apartment",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Azad Lane, Off S. V. Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
}
```



```
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Aneesh Apartment",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": true,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "212A, 214 Part",
  "label": true
},
"hissaNo": {
  "status": true,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "3",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "503C",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
  "name": "Flat / Unit / Office / Gala No.",
```

```
"key": "selectNo",
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": true,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "K / W Ward",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
}
```

```
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400058",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"landAndBuildingDetails": {
  "actualBuildingBoundaries": [],
  "documentsBuildingBoundaries": []
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
```

```
"monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
```

```
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
}
```

```
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
},
```

```
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "interiorDecorations": {
    "title": "Interior Decorations",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
```



```
"status": true,
"isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
```

```
"RATE_VERIFY": false,
"MAKER": false,
"CHECKER": false,
"PREPARE_INVOICE": false,
"PRINT": false,
"SIGN": false,
"SIGNED_REPORT_UPLOAD": false,
"DELIVERY": false,
"PAYMENT_COLLECT": false,
"COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "CASE",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [
  "6763f5a231b0132fc5822ad3",
  "67850129290edae64f165815"
],
"_id": "67922bff936736429e697bff",
"ownerName": "M/s. Banaji Silverline Developers LLP ",
"ownerPhoneNo": "9326124271",
"fullAddress": "Residential Lenders_Engineers Report (LIE) No. 9th Floor, Aneesh
Apartment, Aneesh Apartment, Plot No. 1, New/Current Survey No. 212A, 214 Part,
Hissa No. 3, CTS No. 503C, Azad Lane, Off S. V. Road, Village - Vile Parle, Municipality
Ward No. K / W Ward, Andheri (West), 400058, State - Maharashtra, India",
"remark": "3rd LIE Report",
"documents": [],
"assignmentType": {
  "value": "Commercial",
  "label": "Commercial"
},
"caseNumber": "013874",
"createdBy": "60f91822f3dd69653a5922e3",
```

```
"caseHistory": [
  {
    "id": "720166",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Mon Dec 02 2024 04:31:16 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "M/s. Banaji Silverline Developers LLP ",
    "phone": "9326124271",
    "ownershipShare": "",
    "email": "",
    "id": "584893"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c577d5dfa42c9cad7de",
    "name":
"externalImg_1737632840257_20250107_124442PMBByGPSMapCamera.jpg",
    "path": "cases/67922bff936736429e697bff/
externalImg_1737632840257_20250107_124442PMBByGPSMapCamera.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c577d5dfa42c9cad7df",
    "name":
"externalImg_1737632840494_20250107_124443PMBByGPSMapCamera.jpg",
    "path": "cases/67922bff936736429e697bff/
externalImg_1737632840494_20250107_124443PMBByGPSMapCamera.jpg",
    "orientation": "landscape"
  },
]
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c577d5dfa42c9cad7e0",
  "name": "externallmg_r_1737632842099_IMG_20250107_123933.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632842099_IMG_20250107_123933.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c577d5dfa42c9cad7e1",
  "name": "externallmg_r_1737632841449_IMG_20250107_123932.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632841449_IMG_20250107_123932.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c577d5dfa42c9cad7e2",
  "name": "externallmg_r_1737632841049_IMG_20250107_123931.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632841049_IMG_20250107_123931.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c577d5dfa42c9cad7e3",
  "name": "externallmg_r_1737632840550_IMG_20250107_123929.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632840550_IMG_20250107_123929.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c577d5dfa42c9cad7e4",
  "name": "externallmg_r_1737632842625_IMG_20250107_124032.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632842625_IMG_20250107_124032.jpg",
  "orientation": "landscape"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c577d5dfa42c9cad7e5",
    "name": "externallmg_r_1737632844254_IMG_20250107_124036.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632844254_IMG_20250107_124036.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c577d5dfa42c9cad7e6",
    "name": "externallmg_r_1737632843797_IMG_20250107_124035.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632843797_IMG_20250107_124035.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c577d5dfa42c9cad7e7",
    "name": "externallmg_r_1737632843031_IMG_20250107_124034.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632843031_IMG_20250107_124034.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c577d5dfa42c9cad7e8",
    "name": "externallmg_r_1737632844866_IMG_20250107_124108.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632844866_IMG_20250107_124108.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c577d5dfa42c9cad7e9",
    "name": "externallmg_r_1737632845842_IMG_20250107_124112.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632845842_IMG_20250107_124112.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67922c577d5dfa42c9cad7ea",
  "name": "externallmg_r_1737632845263_IMG_20250107_124110.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632845263_IMG_20250107_124110.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c577d5dfa42c9cad7eb",
  "name": "externallmg_r_1737632846300_IMG_20250107_124132.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632846300_IMG_20250107_124132.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c577d5dfa42c9cad7ec",
  "name": "externallmg_r_1737632846882_IMG_20250107_124133.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632846882_IMG_20250107_124133.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c577d5dfa42c9cad7ed",
  "name": "externallmg_r_1737632847241_IMG_20250107_124139.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632847241_IMG_20250107_124139.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c577d5dfa42c9cad7ee",
  "name": "externallmg_r_1737632847796_IMG_20250107_124140.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632847796_IMG_20250107_124140.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67922c577d5dfa42c9cad7ef",
    "name": "externallmg_r_1737632848676_IMG_20250107_124159.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632848676_IMG_20250107_124159.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c577d5dfa42c9cad7f0",
    "name": "externallmg_r_1737632848124_IMG_20250107_124158.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632848124_IMG_20250107_124158.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c577d5dfa42c9cad7f1",
    "name": "externallmg_r_1737632848841_IMG_20250107_124201.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632848841_IMG_20250107_124201.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c80936736429e697d0f",
    "name": "externallmg_1737632889492_IMG_20250107_124411.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_1737632889492_IMG_20250107_124411.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c80936736429e697d10",
    "name": "externallmg_1737632889945_IMG_20250107_124412.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_1737632889945_IMG_20250107_124412.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c80936736429e697d11",
```

```
    "name": "externallmg_r_1737632879815_IMG_20250107_124206.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632879815_IMG_20250107_124206.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c80936736429e697d12",
    "name": "externallmg_r_1737632879416_IMG_20250107_124205.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632879416_IMG_20250107_124205.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c80936736429e697d13",
    "name": "externallmg_r_1737632880934_IMG_20250107_124235.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632880934_IMG_20250107_124235.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c80936736429e697d14",
    "name": "externallmg_r_1737632880424_IMG_20250107_124232.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632880424_IMG_20250107_124232.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c80936736429e697d15",
    "name": "externallmg_r_1737632881679_IMG_20250107_124236.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632881679_IMG_20250107_124236.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c80936736429e697d16",
    "name": "externallmg_r_1737632883622_IMG_20250107_124251.jpg",
```



```
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632883622_IMG_20250107_124251.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c80936736429e697d17",
    "name": "externallmg_r_1737632882210_IMG_20250107_124242.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632882210_IMG_20250107_124242.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c80936736429e697d18",
    "name": "externallmg_r_1737632882649_IMG_20250107_124243.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632882649_IMG_20250107_124243.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c80936736429e697d19",
    "name": "externallmg_r_1737632883951_IMG_20250107_124256.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632883951_IMG_20250107_124256.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c80936736429e697d1a",
    "name": "externallmg_r_1737632885268_IMG_20250107_124333.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632885268_IMG_20250107_124333.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67922c80936736429e697d1b",
    "name": "externallmg_r_1737632884824_IMG_20250107_124258.jpg",
    "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632884824_IMG_20250107_124258.jpg",
```

```
"orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c80936736429e697d1c",
  "name": "externallmg_r_1737632885744_IMG_20250107_124334.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632885744_IMG_20250107_124334.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c80936736429e697d1d",
  "name": "externallmg_r_1737632886082_IMG_20250107_124336.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632886082_IMG_20250107_124336.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c80936736429e697d1e",
  "name": "externallmg_r_1737632887345_IMG_20250107_124348.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632887345_IMG_20250107_124348.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c80936736429e697d1f",
  "name": "externallmg_r_1737632886894_IMG_20250107_124338.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632886894_IMG_20250107_124338.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c80936736429e697d20",
  "name": "externallmg_r_1737632888142_IMG_20250107_124349.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632888142_IMG_20250107_124349.jpg",
  "orientation": "landscape"
}
```

```
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c80936736429e697d21",
  "name": "externallmg_r_1737632888384_IMG_20250107_124405.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632888384_IMG_20250107_124405.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c80936736429e697d22",
  "name": "externallmg_r_1737632888946_IMG_20250107_124406.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632888946_IMG_20250107_124406.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c9222c790429f69af00",
  "name": "externallmg_1737632909509_IMG_20250107_124414.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_1737632909509_IMG_20250107_124414.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c9222c790429f69af01",
  "name": "externallmg_r_1737632910006_IMG_20250107_124527.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632910006_IMG_20250107_124527.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c9222c790429f69af02",
  "name": "externallmg_r_1737632911052_IMG_20250107_124629.jpg",
  "path": "cases/67922bff936736429e697bff/
externallmg_r_1737632911052_IMG_20250107_124629.jpg",
  "orientation": "landscape"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67922c9222c790429f69af03",
  "name": "externalimg_r_1737632910409_IMG_20250107_124623.jpg",
  "path": "cases/67922bff936736429e697bff/
externalimg_r_1737632910409_IMG_20250107_124623.jpg",
  "orientation": "landscape"
}
],
"externalDocuments": [
  {
    "originalname": "2nd LIE Report Aneesh Apartment.docx",
    "filename": "1733114031994_2nd__LIE_Report_Aneesh_Apartment.docx",
    "path": "cases/67922bff936736429e697bff/
externalDocuments/1733114031994_2nd__LIE_Report_Aneesh_Apartment.docx",
    "size": "5409222",
    "documentType": {
      "value": "649998c6cab24d3d1a2cc577",
      "label": "Draft Word Report"
    },
    "createdAt": "Mon Dec 02 2024 04:33:52 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "2nd LIE Report Aneesh Apartment.docx",
    "filename": "1733114084494_2nd__LIE_Report_Aneesh_Apartment.docx",
    "path": "cases/67922bff936736429e697bff/
externalDocuments/1733114084494_2nd__LIE_Report_Aneesh_Apartment.docx",
    "size": "5409214",
    "documentType": {
      "value": "64058cdff10de22571d01b37",
      "label": "Final Word Report"
    },
    "createdAt": "Mon Dec 02 2024 04:34:45 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "2nd__LIE_Report_Aneesh_Apartment.pdf",
    "filename": "1733121645357_2nd__LIE_Report_Aneesh_Apartment.pdf",
    "path": "cases/67922bff936736429e697bff/
externalDocuments/1733121645357_2nd__LIE_Report_Aneesh_Apartment.pdf",
    "size": "3201437",
    "documentType": {
      "value": "640ece6024088f0f94ee4ea8",
      "label": "Final PDF Report"
    }
  }
]
```

```
    },
    "createdAt": "Mon Dec 02 2024 06:40:45 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f9589345132d6a6bddcc3a"
  },
  {
    "originalname": "valuation report-2nd__LIE_Report_Aneesh_Apartment.pdf",
    "filename":
"1733133331055_valuation_report2nd__LIE_Report_Aneesh_Apartment.pdf",
    "path": "cases/67922bff936736429e697bff/externalDocuments/1733133331055_val
uation_report2nd__LIE_Report_Aneesh_Apartment.pdf",
    "size": "3042869",
    "documentType": {
      "value": "640ece6024088f0f94ee4ea8",
      "label": "Final PDF Report"
    },
    },
    "createdAt": "Mon Dec 02 2024 09:55:32 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f9589345132d6a6bddcc3a"
  },
  {
    "path": "../CDN/cases/67922bff936736429e697bff/
externalDocuments/1733224356070_407847.pdf",
    "filename": "1733224356070_407847.pdf",
    "documentType": {
      "organization": {
        "status": true,
        "isdelete": false,
        "_id": "5f2bdee67813470eb443deb4",
        "name": "Vastukala Consultants India Pvt. Ltd.",
        "gstNo": "18AABCT3518Q1ZZ",
        "panNo": "ABCDE1234A",
        "email": "vastukalamumbai@vastukala.com",
        "phone": "9819670183",
        "address": "121, 1 st Floor, Ackruti Star, Central Road, MIDC, Andheri (E),
Mumbai - 400 093",
        "shortName": "VCIPL",
        "type": "ORGANIZATION",
        "city": "Mumbai",
        "ownerEmail": "umang@vastukala.org",
        "ownerName": "Umang Patel"
      },
      },
      "_id": "60ae124daa6d152c1801b307",
      "document": {
        "documentType": "Office Copy",
        "documentDate": true,
        "to": false,
        "from": false,
      }
    }
  }
}
```

```
    "amount": false,
    "nameOfApprovingAuthority": false,
    "number": false,
    "remarks": true,
    "caseStatus": {
      "value": "DELIVERED",
      "label": "Delivered"
    }
  },
  "createdAt": "2021-05-26T09:18:05.809Z",
  "updatedAt": "2023-06-20T10:17:50.158Z",
  "__v": 0,
  "label": "Office Copy",
  "value": "60ae124daa6d152c1801b307",
  "Name": "Office Copy",
  "Value": "60ae124daa6d152c1801b307",
  "caseStatus": {
    "value": "DELIVERED",
    "label": "Delivered"
  }
},
"createdAt": "Tue Dec 03 2024 11:12:36 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "60b7177d2ffdf65bcd65882a"
},
],
"processingDocuments": [
  {
    "originalname": "2nd LIE Report Aneesh Apartment.xlsx",
    "filename": "1733113982561_2nd_LIE_Report_Aneesh_Apartment.xlsx",
    "path": "cases/67922bff936736429e697bff/
processingDocuments/1733113982561_2nd_LIE_Report_Aneesh_Apartment.xlsx",
    "size": "147416",
    "createdAt": "Mon Dec 02 2024 04:33:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "2439703_FurtherCC_signed.pdf",
    "filename": "1733113982570_2439703_FurtherCC_signed.pdf",
    "path": "cases/67922bff936736429e697bff/
processingDocuments/1733113982570_2439703_FurtherCC_signed.pdf",
    "size": "164443",
    "createdAt": "Mon Dec 02 2024 04:33:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "BANAJI_SILVERLINE_DEED_OF_MORTGAGE_0001.pdf",
```

```
    "filename":
"1733113982583_BANAJI_SILVERLINE_DEED_OF_MORTGAGE_0001.pdf",
    "path": "cases/67922bff936736429e697bff/processingDocuments/1733113982583_
BANAJI_SILVERLINE_DEED_OF_MORTGAGE_0001.pdf",
    "size": "865695",
    "createdAt": "Mon Dec 02 2024 04:33:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "CAR POLICY valid till Mar 2027.pdf",
    "filename": "1733113982655_CAR_POLICY_valid_till_Mar_2027.pdf",
    "path": "cases/67922bff936736429e697bff/
processingDocuments/1733113982655_CAR_POLICY_valid_till_Mar_2027.pdf",
    "size": "462851",
    "createdAt": "Mon Dec 02 2024 04:33:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "Form-1 Architect Certificate 04.11.2024 (1).pdf",
    "filename": "1733113982741_Form1_Architect_Certificate_04112024_1.pdf",
    "path": "cases/67922bff936736429e697bff/
processingDocuments/1733113982741_Form1_Architect_Certificate_04112024_1.pdf",
    "size": "2074574",
    "createdAt": "Mon Dec 02 2024 04:33:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "Form-2 Engineer Certificate 30-09-24.pdf",
    "filename": "1733113982870_Form2_Engineer_Certificate_300924.pdf",
    "path": "cases/67922bff936736429e697bff/
processingDocuments/1733113982870_Form2_Engineer_Certificate_300924.pdf",
    "size": "659445",
    "createdAt": "Mon Dec 02 2024 04:33:03 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-23T11:46:07.386Z",
"updatedAt": "2025-01-23T11:48:34.206Z",
"__v": 0,
"updatedBy": "60f91822f3dd69653a5922e3",
"addressForMap": "",
"caseReferredBy": "60f91822f3dd69653a5922e3",
"contactPersonName": "M/s. Banaji Silverline Developers LLP "
```

```
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9326124271",
"reportGeneratedDate": "Fri Nov 29 2024 04:34:02 GMT+0000 (Coordinated Universal Time)",
"siteVisitDate": "2024-10-18",
"refCaseld": "674d3814e077c54e532dabfb"
}
```

Name	Length	Width	Total
Composition :			
Other			
Composition :			