

```
{
  "typeOfReport": {
    "value": "Single_Flat",
    "label": "Single Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Housing_Loan",
    "label": "Housing Loan"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "665fec420cceba15c44cd8b6"
    },
    "firstName": "Preetam ",
    "type": "CREDITOFFICER",
    "_id": "665fec420cceba15c44cd8b8",
    "lastName": "Pingale",
    "mobileNo": "",
    "workMobileNo": "9920439864",
    "email": "pinglepm@svcbank.com"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "6418456a96b58848585f8cb2",
  "name": "Thane",
  "email": "thane@vastukala.com",
  "phone": "1234567890",
  "address": "101, 1st Floor, B Wing, Beth Shalom, Near Civil Hospital, Thane (W) -
400 601",
  "city": "Thane",
  "shortName": "VCIPL/Thane"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d185c",
  "type": "BANK",
  "name": "SVC CO-OPERATIVE BANK LTD",
  "displayName": "SVC BANK",
  "initial": "SVC",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "665fec420cceba15c44cd8b6",
  "name": "Sanpada Branch",
  "branchCode": "",
  "mobileNo": "02227811791",
  "alternateMobileNo": "",
  "email": "pinglepm@svcbank.com",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Shop No 1, Bhumiraj Manor CHSL, Plot No 3, Sector 14, Sanpada (East)
Navi MUmbai 400705"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60fbaf81d8cfc56a13fa8863",
  "zoneName": "PAN INDIA"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "656aa949cebbe1714411d21b",
  "role": "FRONTDESK",
  "firstName": "Priyanka",
  "email": "thane@vastukala.org",
  "lastName": "Pawar",
  "mobileNo": "8928414480",
  "shortName": "PCP",
  "workWithDocumentMaker": "627222afafd7d55eddeddd82",
  "profilePhoto": "users/656aa949cebbe1714411d21b/
profilePhoto_1731643469657_WhatsApp_Image_20241115_at_93358_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f9343b45132d6a6bdd96e8",
  "role": "SITEENGINEER",
  "firstName": "Rajesh",
  "email": "rajeshb.ghadi@gmail.com",
  "lastName": "Ghadi",
  "mobileNo": "8652092666",
  "designation": "",
  "shortName": "RHG",
  "workWithDocumentMaker": ""
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "5fc78e26625ecd20ec1f88e9",
  "role": "MAKER+CHECKER",
  "firstName": "Vaishali",
  "email": "v.sarmalkar@vastukala.org",
  "lastName": "Sarmalkar",
  "mobileNo": "9004437379",
  "shortName": "VS",
  "workWithDocumentMaker": "1",
  "profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
  "designation": ""
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "627222afafd7d55eddeddd82",
  "role": "FRONTDESK",
  "firstName": "Pratibha",
  "email": "shilvanta_pratibha@yahoo.co.in",
  "lastName": "Shilvanta",
  "mobileNo": "9821518537",
```

```
"designation": "",
"shortName": "PS",
"workWithDocumentMaker": "60f915d3f3dd69653a592199",
"profilePhoto": "users/627222afafd7d55eddeddd82/
profilePhoto_1668057073669_Pratibha_Photo.jpg"
},
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
"label": "Registered Valuer"
}
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
{
"title": {
"label": "IBBI"
},
"_id": "60af80072ffdf65bcd658651",
"number": "IBBI/RV/07/2018/10366"
},
{
"title": {
"value": "FIIV",
"label": "FIIV"
},
"_id": "60af80072ffdf65bcd658652",
"number": "CAT-I-F-1763"
},
{
"title": {
"value": "Chartered_Engineer",
"label": "Chartered Engineer"
},
"_id": "60af80072ffdf65bcd658653",
"number": "AM161706-3"
}
```

```
    },
    {
      "title": {
        "value": "Registered_Valuer",
        "label": "Registered Valuer"
      },
      "_id": "60af80072ffdf65bcd658654",
      "number": "IBBI/RV/07/2018/10366"
    }
  ],
  "shortName": "MBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
  "PANNo": "AERPC9086P",
  "fatherName": "Baburao"
}
]
},
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "19.161834380262924",
  "longitude": "72.99698873303605"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
}
```

```
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Airoli",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
    "name": "Building No",
    "key": "buildingNo",
    "value": "",
    "label": true
  },
  "district": {
    "status": false,
    "name": "District",
    "key": "district",
    "value": "",
    "label": true
  },
  "city": {
    "status": true,
```

```
"name": "City",
"key": "city",
"value": "Navi Mumbai",
"label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Ekta Co.-Op. Hsg. Soc. Ltd.",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "2",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
}
```

```
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
```



```
"key": "hissaNo",
"value": "",
"label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "SS-I/A-352",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
}
```

```
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    }
  }
}
```

```
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
}
```

```
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
>window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": []
}
```

```
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
```



```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "SITEVISITCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "679379b9704afe987367614b",
```

```
"ownerName": "Smt. Sushma Popat Surwase",
"ownerPhoneNo": "8355979845",
"fullAddress": "Residential Flat No. SS-I/A-352, Ground Floor, Ekta Co.-Op. Hsg. Soc.
Ltd., Sector 2, Village - Airoli, Navi Mumbai",
"remark": "",
"documents": [
  {
    "documentType": {
      "value": "60ae1269aa6d152c1801b389",
      "label": "Deed of Apartment"
    },
    "inputs": {
      "documentDate": "12/10/2012",
      "from": {
        "value": "Developers",
        "label": "Developers"
      },
      "Developers": "City And Industrial Development Corporation Of Maharashtra Ltd ",
      "to": {
        "value": "purchaser",
        "label": "purchaser"
      },
      "purchaser": "Smt. Sushma Popat Surwase"
    },
    "isHardCopy": false,
    "displayStatus": true,
    "fileName": "document_1737718195683_71286.pdf",
    "path": "cases/679379b9704afe987367614b/
document_1737718195683_71286.pdf",
    "id": "205030",
    "uploadedBy": "656aa949cebbe1714411d21b",
    "createdAt": "Fri Jan 24 2025 11:30:00 GMT+0000 (Coordinated Universal Time)"
  }
],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "013901",
"createdBy": "656aa949cebbe1714411d21b",
"caseHistory": [
  {
    "id": "827861",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Fri Jan 24 2025 11:30:01 GMT+0000 (Coordinated Universal Time)"
  }
]
```

```
}
],
"owners": [
  {
    "name": "Smt. Sushma Popat Surwase",
    "phone": "8355979845",
    "ownershipShare": "",
    "email": "",
    "id": "572902"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679715c22796f10d2526f30a",
    "name":
"externalImg_1737954754329_WhatsApp_Image_20250127_at_103933_AM.jpeg",
    "path": "cases/679379b9704afe987367614b/
externalImg_1737954754329_WhatsApp_Image_20250127_at_103933_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679715c22796f10d2526f30b",
    "name":
"externalImg_1737954754335_WhatsApp_Image_20250127_at_103934_AM_1.jpeg",
    "path": "cases/679379b9704afe987367614b/
externalImg_1737954754335_WhatsApp_Image_20250127_at_103934_AM_1.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679715c22796f10d2526f30c",
    "name":
"externalImg_1737954754359_WhatsApp_Image_20250127_at_103934_AM.jpeg",
```

```
    "path": "cases/679379b9704afe987367614b/
externallmg_1737954754359_WhatsApp_Image_20250127_at_103934_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679715c22796f10d2526f30d",
    "name":
"externallmg_1737954754374_WhatsApp_Image_20250127_at_103935_AM_1.jpeg",
    "path": "cases/679379b9704afe987367614b/
externallmg_1737954754374_WhatsApp_Image_20250127_at_103935_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679715c22796f10d2526f30e",
    "name":
"externallmg_1737954754393_WhatsApp_Image_20250127_at_103935_AM.jpeg",
    "path": "cases/679379b9704afe987367614b/
externallmg_1737954754393_WhatsApp_Image_20250127_at_103935_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679715c22796f10d2526f30f",
    "name":
"externallmg_1737954754428_WhatsApp_Image_20250127_at_103936_AM_1.jpeg",
    "path": "cases/679379b9704afe987367614b/
externallmg_1737954754428_WhatsApp_Image_20250127_at_103936_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679715c22796f10d2526f310",
    "name":
"externallmg_1737954754445_WhatsApp_Image_20250127_at_103936_AM_2.jpeg",
    "path": "cases/679379b9704afe987367614b/
externallmg_1737954754445_WhatsApp_Image_20250127_at_103936_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "679715c22796f10d2526f311",
  "name":
"externallmg_1737954754448_WhatsApp_Image_20250127_at_103936_AM.jpeg",
  "path": "cases/679379b9704afe987367614b/
externallmg_1737954754448_WhatsApp_Image_20250127_at_103936_AM.jpeg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679715c22796f10d2526f312",
  "name":
"externallmg_1737954754467_WhatsApp_Image_20250127_at_103937_AM_1.jpeg",
  "path": "cases/679379b9704afe987367614b/
externallmg_1737954754467_WhatsApp_Image_20250127_at_103937_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679715c22796f10d2526f313",
  "name":
"externallmg_1737954754470_WhatsApp_Image_20250127_at_103937_AM.jpeg",
  "path": "cases/679379b9704afe987367614b/
externallmg_1737954754470_WhatsApp_Image_20250127_at_103937_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679715ce2aadad0ced139af1",
  "name":
"externallmg_1737954766143_WhatsApp_Image_20250127_at_103938_AM_1.jpeg",
  "path": "cases/679379b9704afe987367614b/
externallmg_1737954766143_WhatsApp_Image_20250127_at_103938_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679715ce2aadad0ced139af2",
  "name":
"externallmg_1737954766161_WhatsApp_Image_20250127_at_103938_AM_2.jpeg",
  "path": "cases/679379b9704afe987367614b/
externallmg_1737954766161_WhatsApp_Image_20250127_at_103938_AM_2.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679715ce2aadad0ced139af3",
    "name":
"externallmg_1737954766162_WhatsApp_Image_20250127_at_103938_AM.jpeg",
    "path": "cases/679379b9704afe987367614b/
externallmg_1737954766162_WhatsApp_Image_20250127_at_103938_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679715ce2aadad0ced139af4",
    "name":
"externallmg_1737954766165_WhatsApp_Image_20250127_at_103939_AM_1.jpeg",
    "path": "cases/679379b9704afe987367614b/
externallmg_1737954766165_WhatsApp_Image_20250127_at_103939_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679715ce2aadad0ced139af5",
    "name":
"externallmg_1737954766166_WhatsApp_Image_20250127_at_103939_AM_2.jpeg",
    "path": "cases/679379b9704afe987367614b/
externallmg_1737954766166_WhatsApp_Image_20250127_at_103939_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679715ce2aadad0ced139af6",
    "name":
"externallmg_1737954766178_WhatsApp_Image_20250127_at_103939_AM_3.jpeg",
    "path": "cases/679379b9704afe987367614b/
externallmg_1737954766178_WhatsApp_Image_20250127_at_103939_AM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679715ce2aadad0ced139af7",
```

```
    "name":
"externallmg_1737954766184_WhatsApp_Image_20250127_at_103939_AM.jpeg",
  "path": "cases/679379b9704afe987367614b/
externallmg_1737954766184_WhatsApp_Image_20250127_at_103939_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679715ce2aadad0ced139af8",
  "name":
"externallmg_1737954766186_WhatsApp_Image_20250127_at_103940_AM_1.jpeg",
  "path": "cases/679379b9704afe987367614b/
externallmg_1737954766186_WhatsApp_Image_20250127_at_103940_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679715ce2aadad0ced139af9",
  "name":
"externallmg_1737954766194_WhatsApp_Image_20250127_at_103940_AM_2.jpeg",
  "path": "cases/679379b9704afe987367614b/
externallmg_1737954766194_WhatsApp_Image_20250127_at_103940_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679715ce2aadad0ced139afa",
  "name":
"externallmg_1737954766204_WhatsApp_Image_20250127_at_103940_AM.jpeg",
  "path": "cases/679379b9704afe987367614b/
externallmg_1737954766204_WhatsApp_Image_20250127_at_103940_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679715ce2aadad0ced139afb",
  "name":
"externallmg_1737954766225_WhatsApp_Image_20250127_at_103941_AM_1.jpeg",
  "path": "cases/679379b9704afe987367614b/
externallmg_1737954766225_WhatsApp_Image_20250127_at_103941_AM_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679715ce2aadad0ced139afc",
  "name":
"externallmg_1737954766227_WhatsApp_Image_20250127_at_103941_AM.jpeg",
  "path": "cases/679379b9704afe987367614b/
externallmg_1737954766227_WhatsApp_Image_20250127_at_103941_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679715ce2aadad0ced139afd",
  "name":
"externallmg_1737954766230_WhatsApp_Image_20250127_at_103942_AM_1.jpeg",
  "path": "cases/679379b9704afe987367614b/
externallmg_1737954766230_WhatsApp_Image_20250127_at_103942_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679715ce2aadad0ced139afe",
  "name":
"externallmg_1737954766231_WhatsApp_Image_20250127_at_103942_AM_2.jpeg",
  "path": "cases/679379b9704afe987367614b/
externallmg_1737954766231_WhatsApp_Image_20250127_at_103942_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679715ce2aadad0ced139aff",
  "name":
"externallmg_1737954766243_WhatsApp_Image_20250127_at_103942_AM.jpeg",
  "path": "cases/679379b9704afe987367614b/
externallmg_1737954766243_WhatsApp_Image_20250127_at_103942_AM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "reference report.pdf",
    "filename": "1737783339191_reference_report.pdf",
```



```
"path": "cases/679379b9704afe987367614b/
processingDocuments/1737783339191_reference_report.pdf",
"size": "8801125",
"createdAt": "Sat Jan 25 2025 05:35:40 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
},
{
"originalname": "Summary - sushma.xlsx",
"filename": "1737783339362_Summary__sushma.xlsx",
"path": "cases/679379b9704afe987367614b/
processingDocuments/1737783339362_Summary__sushma.xlsx",
"size": "1172572",
"createdAt": "Sat Jan 25 2025 05:35:40 GMT+0000 (Coordinated Universal Time)",
"uploadedBy": "5fc78e26625ecd20ec1f88e9"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [
{
"createdBy": {
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"lastName": "Sarmalkar",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
},
"workType": "RATE_VERIFY",
"display": true,
"status": true,
"_id": "67947818704afe9873679aa8",
"note": "working done, visit pending",
"taskId": "679379c4704afe98736761a9",
"createdAt": "2025-01-25T05:35:20.913Z"
},
{
"createdBy": {
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"lastName": "Sarmalkar",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg"
},
"workType": "RATE_VERIFY",
```

```

    "display": true,
    "status": true,
    "_id": "67985afb2f3738a577c86a36",
    "note": "working done, required CIDCO Plan / OC / possession ltr\n",
    "taskId": "679379c4704afe98736761a9",
    "createdAt": "2025-01-28T04:20:11.715Z"
  }
],
"createdAt": "2025-01-24T11:30:01.260Z",
"updatedAt": "2025-01-29T10:51:52.590Z",
"__v": 0,
"updatedBy": "627222afafd7d55eddedd82",
"addressForMap": "",
"caseReferredBy": "64abdb2806d6ec174986d16b",
"contactPersonName": "Smt. Sushma Popat Surwase",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reId": "",
"siteVisitContactNo": "8355979845"
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			