

```
{
  "typeOfReport": {
    "value": "Project_Finance",
    "label": "Project Finance"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": false,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Project_Valuation",
    "label": "Project Valuation"
  },
  "masterTypeOfPurpose": {
    "value": "Non_SARFAESI",
    "label": "Non SARFAESI"
  },
  "toAssess": {
    "value": "Fair_Market_Value",
    "label": "Fair Market Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856b7cc"
    },
    "firstName": "Manish",
    "type": "CREDITOFFICER",
    "_id": "64338d21d267175d008119f1",
    "lastName": "Jha",
    "mobileNo": "",
    "workMobileNo": "9049983319",
    "email": "manish.jha9@sbi.co.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": "20000"
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d17f4",
  "type": "BANK",
  "name": "State Bank of India",
  "displayName": "State Bank of India",
  "initial": "SBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856b7cc",
  "branchCode": "13340",
  "type": "BRANCH",
  "name": "SME Chembur Branch",
  "email": "sbi.13340@sbi.co.in",
  "mobileNo": "02225273906",
  "alternateMobileNo": "02225273907",
  "address": "Unit No. 11, (BLDG NO. 11), Ground Floor, Corporate Park, Sion-
Trombay Road, Chembur, Mumbai – 400 071, State – Maharashtra, Country – India.",
  "ledgerName": "",
  "fax": "02225274524",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential cum Commercial",
  "value": "Residential_cum_commercial"
},
"zone": {
  "_id": "60e03dac6576061dae462469",
  "zoneName": "Mumbai (Metro) & Maharashtra"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
```

```
"lastName": "Parekh ",
"mobileNo": "9767983840",
"designation": "",
"shortName": "PPP",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "60f91822f3dd69653a5922e3",
  "role": "SITEENGINEER+MAKAR+CHECKER",
  "firstName": "Prayush ",
  "email": "prayush@vastukala.org",
  "lastName": "Parekh ",
  "mobileNo": "9767983840",
  "designation": "",
  "shortName": "PPP",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/60f91822f3dd69653a5922e3/
profilePhoto_1668228546081_WhatsApp_Image_20221112_at_101614_AM.jpeg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "IBBI"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
  },

```

```
{
  "title": {
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
],
"clientType": {
  "value": "BANK",
  "label": "BANK"
},
"location": {
  "latitude": "18.95884885595709",
  "longitude": "72.82317045916884"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
```

```
0
]
},
"siteVisit": {
  "siteVisitStatus": true,
  "schedule": [],
  "visitedDate": [
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-20",
      "remark": ""
    },
    {
      "status": "COMPLETED",
      "dateTime": "2023-12-04",
      "remark": "MANUAL_IN_TASK"
    }
  ]
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": false,
    "name": "Village",
    "key": "village",

```

```
"value": "",
"label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "22",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Mumbai",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Girgaon",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tahasil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
```

```
"status": false,
"name": "Plot No.",
"key": "plotNo",
"value": "",
"label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shreeji Heights",
  "label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Khethwadi 7th Lane",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
```



```
"label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": true,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "802, 803 & 804",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": false,
```

```
"name": "Flat / Unit / Office / Gala No.",
"key": "selectNo",
"value": "",
"label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
}
```

```
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400004",
  "label": false
},
"suburb": {
  "status": false,
  "name": "Suburb",
  "key": "suburb",
  "value": "",
  "label": false
}
},
"general": {
  "populationClassList": {
    "label": "Higher Middle Class",
    "value": "HigherMiddleClass"
  },
  "populationGroupList": {
    "label": "Urban",
    "value": "Urban"
  },
  "townplanApprovedByList": {
    "label": "Municipal Corporation of Greater Mumbai (MCGM)",
    "value": "MCGM"
  },
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
```

```
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
```

```
"rccFootingFoundation": {
  "label": "RCC Footing/Foundation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": true
},
"rccPlinth": {
  "label": "RCC Plinth",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"fullBuildingRcc": {
  "label": "Full Building Rcc",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
```

```
"label": "Lift Installation",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"passageStaircaseLobbyDevelopment": {
"label": "Passage, Staircase & Lobby Development",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"externalDevelopmentFinalFinishing": {
"label": "External Development & Final Finishing",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": false
},
"workCompleted": {
"label": "Work Completed (%)",
"floorsCompleted": "",
"percentage": "0.00",
"isHideFloor": true,
"status": true
}
},
"guidelineDetails": {
"finalGuidelineValue": "0",
"selectedBuildUpValue": "0",
"selectedBuildUpMeasurementType": ""
},
"reportImages": {
"frontPageImages": [],
"selfieWithSiteVisitImages": [],
"externalPhotos": [],
"parkingImages": [],
"societyNameBoardImage": [],
"compositionImages": []
},
"indicatorRange": {
"carpetRateRange": {
"min": "0.00",
"max": "0.00"
}
},
```

```
"builtUpRateRange": {
  "min": "0.00",
  "max": "0.00"
},
"saleableRateRange": {
  "min": "0.00",
  "max": "0.00"
}
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "showcases": {
    "title": "Showcases",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "kitchenArrangements": {
    "title": "Kitchen arrangements",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": true
  },
  "superfineFinish": {
    "title": "Superfine finish",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
```



```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
```

```
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": true,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "PARTIAL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "CASE",
"paymentStatus": "NA",
"invoiceIds": [
  "66472d2e46d99f42db912483",
  "66277ebb87da884a83a736e1"
],
"paymentIds": [
  "66472cca46d99f42db912373"
],
"_id": "67947927704afe9873679d05",
"ownerName": "Anupam Creations",
"ownerPhoneNo": "9920825249",
"fullAddress": "Residential cum Commercial Project Finance No. 22nd Floor, Shreeji
```

Heights, CTS No. 802, 803 & 804, Khethwadi 7th Lane, District - Mumbai, Girgaon, 400004, State - Maharashtra, India",

"remark": "",

"documents": [

{

"documentType": {

"value": "60ae129faa6d152c1801b47d",

"label": "RERA Certificate"

},

"inputs": {

"documentDate": "19/07/2023",

"nameOfApprovingAuthority": {

"value": "Maharashtra\_Real\_Estate\_Regulatory\_Authority",

"label": "Maharashtra Real Estate Regulatory Authority"

},

"number": {

"value": "Document\_No",

"label": "Document No"

},

"Document\_No": "P51900052017"

},

"isHardCopy": false,

"displayStatus": false,

"fileName": "document\_1703066697654\_Rera\_Certificate.pdf",

"path": "cases/67947927704afe9873679d05/

document\_1703066697654\_Rera\_Certificate.pdf",

"id": "552129",

"uploadedBy": "60f91822f3dd69653a5922e3",

"createdAt": "Wed Dec 20 2023 15:35:04 GMT+0530 (India Standard Time)"

}

],

"assignmentType": {

"value": "Commercial",

"label": "Commercial"

},

"caseNumber": "013909",

"createdBy": "60f91822f3dd69653a5922e3",

"caseHistory": [

{

"id": "703952",

"title": "Create Lead",

"description": "Create Lead",

"datetime": "Wed Dec 20 2023 15:35:04 GMT+0530 (India Standard Time)"

}

],

"owners": [

```
{
  "name": "Anupam Creations",
  "phone": "9920825249",
  "ownershipShare": "",
  "email": "",
  "id": "334022"
},
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67947cb1704afe987367a2bb",
    "name":
"externallmg_1737784480385_20250107_52436PMBByGPSMapCamera.jpg",
    "path": "cases/67947927704afe9873679d05/
externallmg_1737784480385_20250107_52436PMBByGPSMapCamera.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67947cb1704afe987367a2bc",
    "name":
"externallmg_1737784480908_20250107_52438PMBByGPSMapCamera.jpg",
    "path": "cases/67947927704afe9873679d05/
externallmg_1737784480908_20250107_52438PMBByGPSMapCamera.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67947cb1704afe987367a2bd",
    "name": "externallmg_1737784489157_IMG_20250107_172218.jpg",
    "path": "cases/67947927704afe9873679d05/
externallmg_1737784489157_IMG_20250107_172218.jpg",
    "orientation": "portrait"
  },
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67947cb1704afe987367a2be",
  "name": "externallmg_1737784490752_IMG_20250107_172218__01.jpg",
  "path": "cases/67947927704afe9873679d05/
externallmg_1737784490752_IMG_20250107_172218__01.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67947cb1704afe987367a2bf",
  "name": "externallmg_1737784490979_IMG_20250107_172235.jpg",
  "path": "cases/67947927704afe9873679d05/
externallmg_1737784490979_IMG_20250107_172235.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67947cb1704afe987367a2c0",
  "name": "externallmg_1737784491699_IMG_20250107_172235__01.jpg",
  "path": "cases/67947927704afe9873679d05/
externallmg_1737784491699_IMG_20250107_172235__01.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67947cb1704afe987367a2c1",
  "name": "externallmg_1737784492206_IMG_20250107_172356.jpg",
  "path": "cases/67947927704afe9873679d05/
externallmg_1737784492206_IMG_20250107_172356.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67947cb1704afe987367a2c2",
  "name": "externallmg_1737784492522_IMG_20250107_172358.jpg",
  "path": "cases/67947927704afe9873679d05/
externallmg_1737784492522_IMG_20250107_172358.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67947cb1704afe987367a2c3",
    "name": "externallmg_r_1737784481461_IMG_20250107_163905.jpg",
    "path": "cases/67947927704afe9873679d05/
externallmg_r_1737784481461_IMG_20250107_163905.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67947cb1704afe987367a2c4",
    "name": "externallmg_r_1737784482434_IMG_20250107_164004.jpg",
    "path": "cases/67947927704afe9873679d05/
externallmg_r_1737784482434_IMG_20250107_164004.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67947cb1704afe987367a2c5",
    "name": "externallmg_r_1737784480939_IMG_20250107_163904.jpg",
    "path": "cases/67947927704afe9873679d05/
externallmg_r_1737784480939_IMG_20250107_163904.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67947cb1704afe987367a2c6",
    "name": "externallmg_r_1737784481964_IMG_20250107_163907.jpg",
    "path": "cases/67947927704afe9873679d05/
externallmg_r_1737784481964_IMG_20250107_163907.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67947cb1704afe987367a2c7",
    "name": "externallmg_r_1737784482766_IMG_20250107_164005.jpg",
    "path": "cases/67947927704afe9873679d05/
externallmg_r_1737784482766_IMG_20250107_164005.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67947cb1704afe987367a2c8",
  "name": "externallmg_r_1737784484009_IMG_20250107_164041.jpg",
  "path": "cases/67947927704afe9873679d05/
externallmg_r_1737784484009_IMG_20250107_164041.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67947cb1704afe987367a2c9",
  "name": "externallmg_r_1737784483307_IMG_20250107_164008.jpg",
  "path": "cases/67947927704afe9873679d05/
externallmg_r_1737784483307_IMG_20250107_164008.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67947cb1704afe987367a2ca",
  "name": "externallmg_r_1737784484382_IMG_20250107_164045.jpg",
  "path": "cases/67947927704afe9873679d05/
externallmg_r_1737784484382_IMG_20250107_164045.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67947cb1704afe987367a2cb",
  "name": "externallmg_r_1737784485187_IMG_20250107_164047.jpg",
  "path": "cases/67947927704afe9873679d05/
externallmg_r_1737784485187_IMG_20250107_164047.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67947cb1704afe987367a2cc",
  "name": "externallmg_r_1737784485486_IMG_20250107_164051.jpg",
  "path": "cases/67947927704afe9873679d05/
externallmg_r_1737784485486_IMG_20250107_164051.jpg",
  "orientation": "landscape"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "67947cb1704afe987367a2cd",
    "name": "externallmg_r_1737784486951_IMG_20250107_164114.jpg",
    "path": "cases/67947927704afe9873679d05/
externallmg_r_1737784486951_IMG_20250107_164114.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67947cb1704afe987367a2ce",
    "name": "externallmg_r_1737784487391_IMG_20250107_164128.jpg",
    "path": "cases/67947927704afe9873679d05/
externallmg_r_1737784487391_IMG_20250107_164128.jpg",
    "orientation": "landscape"
  }
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Agreement.pdf",
    "filename": "1703243639938_Agreement.pdf",
    "path": "cases/67947927704afe9873679d05/
processingDocuments/1703243639938_Agreement.pdf",
    "size": "1048387",
    "createdAt": "Fri Dec 22 2023 16:44:00 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "CA- CERTIFICATE UP TO 30.11.2023.pdf",
    "filename": "1703243646853_CA_CERTIFICATE_UP_TO_30112023.pdf",
    "path": "cases/67947927704afe9873679d05/
processingDocuments/1703243646853_CA_CERTIFICATE_UP_TO_30112023.pdf",
    "size": "1341667",
    "createdAt": "Fri Dec 22 2023 16:44:06 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "CC.pdf",
    "filename": "1703243654342_CC.pdf",
    "path": "cases/67947927704afe9873679d05/
processingDocuments/1703243654342_CC.pdf",
    "size": "193447",
    "createdAt": "Fri Dec 22 2023 16:44:14 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
```



```
    "originalname": "Coveyance 1.pdf",
    "filename": "1703243660999_Coveyance_1.pdf",
    "path": "cases/67947927704afe9873679d05/
processingDocuments/1703243660999_Coveyance_1.pdf",
    "size": "5907652",
    "createdAt": "Fri Dec 22 2023 16:44:21 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "Coveyance.pdf",
    "filename": "1703243668518_Coveyance.pdf",
    "path": "cases/67947927704afe9873679d05/
processingDocuments/1703243668518_Coveyance.pdf",
    "size": "5747178",
    "createdAt": "Fri Dec 22 2023 16:44:29 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "Deed of indemnity.pdf",
    "filename": "1703243676644_Deed__of_indemnity.pdf",
    "path": "cases/67947927704afe9873679d05/
processingDocuments/1703243676644_Deed__of_indemnity.pdf",
    "size": "2061583",
    "createdAt": "Fri Dec 22 2023 16:44:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "Deed Release 1.pdf",
    "filename": "1703243686198_Deed_Release_1.pdf",
    "path": "cases/67947927704afe9873679d05/
processingDocuments/1703243686198_Deed_Release_1.pdf",
    "size": "12803936",
    "createdAt": "Fri Dec 22 2023 16:44:47 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "Deed Release 2.pdf",
    "filename": "1703243687269_Deed_Release_2.pdf",
    "path": "cases/67947927704afe9873679d05/
processingDocuments/1703243687269_Deed_Release_2.pdf",
    "size": "1753278",
    "createdAt": "Fri Dec 22 2023 16:44:47 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "Deed Release 3.pdf",
```

```
    "filename": "1703243687418_Deed_Release_3.pdf",
    "path": "cases/67947927704afe9873679d05/
processingDocuments/1703243687418_Deed_Release_3.pdf",
    "size": "1762849",
    "createdAt": "Fri Dec 22 2023 16:44:47 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "Deed Release.pdf",
    "filename": "1703243687566_Deed_Release.pdf",
    "path": "cases/67947927704afe9873679d05/
processingDocuments/1703243687566_Deed_Release.pdf",
    "size": "2146649",
    "createdAt": "Fri Dec 22 2023 16:44:47 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "Final Drawing.pdf",
    "filename": "1703243720871_Final_Drawing.pdf",
    "path": "cases/67947927704afe9873679d05/
processingDocuments/1703243720871_Final_Drawing.pdf",
    "size": "7231770",
    "createdAt": "Fri Dec 22 2023 16:45:24 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "Nath Niwas CC 2404071_FurtherCC_signed-1.pdf",
    "filename": "1703243735989_Nath_Niwas_CC_2404071_FurtherCC_signed1.pdf",
    "path": "cases/67947927704afe9873679d05/processingDocuments/1703243735989
_Nath_Niwas_CC_2404071_FurtherCC_signed1.pdf",
    "size": "163844",
    "createdAt": "Fri Dec 22 2023 16:45:36 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "NOC.pdf",
    "filename": "1703243743081_NOC.pdf",
    "path": "cases/67947927704afe9873679d05/
processingDocuments/1703243743081_NOC.pdf",
    "size": "823351",
    "createdAt": "Fri Dec 22 2023 16:45:43 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  },
  {
    "originalname": "Title Report.pdf",
    "filename": "1703243757457_Title_Report.pdf",
```

```

    "path": "cases/67947927704afe9873679d05/
processingDocuments/1703243757457_Title_Report.pdf",
    "size": "889719",
    "createdAt": "Fri Dec 22 2023 16:45:57 GMT+0530 (India Standard Time)",
    "uploadedBy": "60f91822f3dd69653a5922e3"
  }
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-25T05:39:52.259Z",
"updatedAt": "2025-01-25T05:54:57.399Z",
"__v": 0,
"updatedBy": "60f91822f3dd69653a5922e3",
"addressForMap": "",
"caseReferredBy": "60f91822f3dd69653a5922e3",
"contactPersonName": "Yogesh",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "Accountant",
"siteVisitContactNo": "9920825249",
"reportGeneratedDate": "Fri Dec 15 2023 16:48:39 GMT+0530 (India Standard Time)",
"siteVisitDate": "2023-12-04",
"refCaseId": "6582bc5065d49d78457f1c6b",
"proposePurchaserName": "",
"reralId": ""
}

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			