

```
{
  "typeOfReport": {
    "label": "Single Flat",
    "value": "Single_Flat"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "6405bf97dd383b243e8482fe"
    },
    "firstName": "Nisha",
    "type": "CREDITOFFICER",
    "_id": "661f43907e1d7332c87e10a7",
    "lastName": "Aswekar",
    "mobileNo": "",
    "workMobileNo": "9768319662",
    "email": "charkop@janasevabank.in"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "7500000",
    "discussWithPerson": "Nisha",
    "expectedFees": 3750,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1836",
  "type": "BANK",
  "name": "Janaseva Sahakari Bank (Borivali) LTD",
  "displayName": "Janaseva Sahakari Bank (Borivali) LTD",
  "initial": "JSB",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "6405bf97dd383b243e8482fe",
  "name": "Charkop Branch",
  "branchCode": "",
  "mobileNo": "02228683113",
  "alternateMobileNo": "",
  "email": "charkop@janasevabank.in",
  "fax": "",
  "ledgerName": "",
  "sendStructuralCertificate": "0",
  "address": "Charkop Shivneri RDP-4 , Sector 5, Charkop, Kandiwali Westy, Mumbai
40007"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "63afe4ff191f7b344b007ea6",
  "zoneName": "Pan India"
},
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
```

```
"_id": "659ccce98f39506e83489828",
"role": "DELIVERYPERSON",
"firstName": "Amit",
"email": "amitsalvi2909@gmail.com",
"lastName": "Salvi",
"mobileNo": "7499830659",
"shortName": "Amit",
"workWithDocumentMaker": "",
"profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
"type": "EMPLOYEE",
"_id": "62691c48afd7d55eddecfda3",
"role": "FRONTDESK",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"rateVerifier": {
"type": "EMPLOYEE",
"_id": "60f915d3f3dd69653a592199",
"role": "MAKER + RATE VERIFIER + CHEAKER",
"firstName": "Shobha",
"email": "shobha@vastukala.org",
"lastName": "Kuperkar",
"mobileNo": "9004134140",
"designation": "",
"shortName": "SH",
"workWithDocumentMaker": "",
"profilePhoto": "users/60f915d3f3dd69653a592199/
profilePhoto_1668059695582_WhatsApp_Image_20221110_at_112058_AM.jpeg"
},
"maker": null,
"checker": null,
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "IBBI/RV/07/2018/10366",
```

```
    "label": "Registered Valuer"
  }
],
"type": "EMPLOYEE",
"_id": "5ffe92d27737ca4d986b6453",
"role": "VALUER",
"firstName": "Manoj",
"email": "manoj@vastukala.org",
"lastName": "Chalikwar",
"mobileNo": "9819597579",
"designation": "Registered Valuer",
"registrationNo": [
  {
    "title": {
      "label": "IBBI"
    },
    "_id": "60af80072ffdf65bcd658651",
    "number": "IBBI/RV/07/2018/10366"
  },
  {
    "title": {
      "value": "FIIV",
      "label": "FIIV"
    },
    "_id": "60af80072ffdf65bcd658652",
    "number": "CAT-I-F-1763"
  },
  {
    "title": {
      "value": "Chartered_Engineer",
      "label": "Chartered Engineer"
    },
    "_id": "60af80072ffdf65bcd658653",
    "number": "AM161706-3"
  },
  {
    "title": {
      "value": "Registered_Valuer",
      "label": "Registered Valuer"
    },
    "_id": "60af80072ffdf65bcd658654",
    "number": "IBBI/RV/07/2018/10366"
  }
],
"shortName": "MBC",
"workWithDocumentMaker": "",
```

```
    "profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
    "PANNo": "AERPC9086P",
    "fatherName": "Baburao"
  }
]
},
"clientType": {
  "label": "Bank",
  "value": "BANK"
},
"location": {
  "latitude": "19.21682824032885",
  "longitude": "72.83289433774368"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.83289433774368,
    19.21682824032885
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "28/01/2025 12:00 am",
      "remark": ""
    }
  ]
},
"visitedDate": [],
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
```

```
"label": true
},
"country": {
  "status": true,
  "name": "Country",
  "key": "country",
  "value": "India",
  "label": false
},
"village": {
  "status": true,
  "name": "Village",
  "key": "village",
  "value": "Charkop",
  "label": true
},
"floorNo": {
  "status": true,
  "name": "Floor No",
  "key": "floorNo",
  "value": "Ground",
  "label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": true,
  "name": "City",
  "key": "city",
  "value": "Mumbai",
  "label": false
},
"tahasilNo": {
  "status": false,
```

```
"name": "Tehsil",
"key": "tahasilNo",
"value": "",
"label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Borivali",
  "label": true
},
"plotNo": {
  "status": true,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "937",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Shree Ganesh CHSL",
  "label": false
},
"selectArea": {
  "status": true,
  "name": "Sector",
  "key": "selectArea",
  "value": "9",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "RSC 15",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
}
```

```
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
```



```
"key": "CTSNo",
"value": "",
"label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "A28",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
}
```

```
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "400067",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Kandivali West",
  "label": false
}
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
}
```

```
}
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  },
  "finalLatLng": {
    "coordinates": []
  },
  "locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
}
```

```
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalBrickWork": {
    "label": "External Brick Work",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalPlastering": {
    "label": "Internal Plastering",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "externalPlastering": {
    "label": "External Plastering",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
}
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
}
```

```
    },
    "builtUpRateRange": {
      "min": "0.00",
      "max": "0.00"
    },
    "saleableRateRange": {
      "min": "0.00",
      "max": "0.00"
    }
  },
  "detailsOfValuation": {
    "presentValueOfFlat": {
      "title": "Present value of the flat (incl. car parking, if provided)",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": false
    },
    "wardrobes": {
      "title": "Wardrobes",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "showcases": {
      "title": "Showcases",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "kitchenArrangements": {
      "title": "Kitchen arrangements",
      "quantity": "0.00",
      "ratePerUnit": "0.00",
      "estimatedValue": "0.00",
      "status": true,
      "isEditable": true
    },
    "superfineFinish": {
      "title": "Superfine finish",
      "quantity": "0.00",
```

```
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
```



```
"title": "Total",
"quantity": "",
"ratePerUnit": "",
"estimatedValue": "0.00",
"status": true,
"isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "6798a3362f3738a577c8d44b",
"ownerName": "MRS TAMUBAI KISHANLAL JOSHI AND MR KISHANLAL NANALAL JOSHI",
"ownerPhoneNo": "9869901359",
"appAddress": "ROOM NO A-28 GROUND FLOOR PLOT NO 937 RSC 15 SURVEY 41 CHARKOP SHREE GANESHA CHS LTD CHARKOP VILLAGE CHARKOP KANDIVALI WEST MUMBAI 400067",
"remark": "Visit Done Bhavika chavan",
```

```
"documents": [
  {
    "documentType": {
      "label": "Agreement For Sale",
      "value": "60ae1254aa6d152c1801b326"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/6798a3362f3738a577c8d44b/
document_1738056456427_1738056454157_Tamubai_joshi_agreement.pdf",
    "fileName":
"document_1738056456427_1738056454157_Tamubai_joshi_agreement.pdf",
    "id": "165398",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Tue Jan 28 2025 09:28:21 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "013977",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "960156",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Jan 28 2025 09:28:22 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "MRS TAMUBAI KISHANLAL JOSHI AND MR KISHANLAL NANALAL
JOSHI",
    "phone": "9869901359",
    "ownershipShare": "",
    "email": "",
    "id": "952148"
  }
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externallImages": [
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6799c8687dd57116683c7a6b",
  "name": "externallmg_1738131559673_IMG20250129WA0038.jpg",
  "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131559673_IMG20250129WA0038.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6799c8687dd57116683c7a6c",
  "name": "externallmg_1738131559679_IMG20250129WA0039.jpg",
  "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131559679_IMG20250129WA0039.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6799c8687dd57116683c7a6d",
  "name": "externallmg_1738131559686_IMG20250129WA0017.jpg",
  "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131559686_IMG20250129WA0017.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6799c8687dd57116683c7a6e",
  "name": "externallmg_1738131559716_IMG20250129WA0018.jpg",
  "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131559716_IMG20250129WA0018.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6799c8687dd57116683c7a6f",
  "name": "externallmg_1738131559719_IMG20250129WA0019.jpg",
  "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131559719_IMG20250129WA0019.jpg",
  "orientation": "portrait"
},
{
```

```
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c8687dd57116683c7a70",
    "name": "externallmg_1738131559740_IMG20250129WA0020.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131559740_IMG20250129WA0020.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c8687dd57116683c7a71",
    "name": "externallmg_1738131559758_IMG20250129WA0021.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131559758_IMG20250129WA0021.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c8687dd57116683c7a72",
    "name": "externallmg_1738131559767_IMG20250129WA0022.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131559767_IMG20250129WA0022.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c8687dd57116683c7a73",
    "name": "externallmg_1738131559801_IMG20250129WA0023.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131559801_IMG20250129WA0023.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c8687dd57116683c7a74",
    "name": "externallmg_1738131559805_IMG20250129WA0024.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131559805_IMG20250129WA0024.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "6799c8687dd57116683c7a75",
  "name": "externalimg_1738131559831_IMG20250129WA0025.jpg",
  "path": "cases/6798a3362f3738a577c8d44b/
externalimg_1738131559831_IMG20250129WA0025.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6799c8687dd57116683c7a76",
  "name": "externalimg_1738131559848_IMG20250129WA0026.jpg",
  "path": "cases/6798a3362f3738a577c8d44b/
externalimg_1738131559848_IMG20250129WA0026.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6799c8687dd57116683c7a77",
  "name": "externalimg_1738131559853_IMG20250129WA0027.jpg",
  "path": "cases/6798a3362f3738a577c8d44b/
externalimg_1738131559853_IMG20250129WA0027.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6799c8687dd57116683c7a78",
  "name": "externalimg_1738131559893_IMG20250129WA0028.jpg",
  "path": "cases/6798a3362f3738a577c8d44b/
externalimg_1738131559893_IMG20250129WA0028.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "6799c8687dd57116683c7a79",
  "name": "externalimg_1738131559897_IMG20250129WA0029.jpg",
  "path": "cases/6798a3362f3738a577c8d44b/
externalimg_1738131559897_IMG20250129WA0029.jpg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
```

```
    "_id": "6799c875115bdf1669098b1d",
    "name": "externallmg_1738131573258_IMG20250129WA0030.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573258_IMG20250129WA0030.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b1e",
    "name": "externallmg_1738131573263_IMG20250129WA0031.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573263_IMG20250129WA0031.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b1f",
    "name": "externallmg_1738131573268_IMG20250129WA0032.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573268_IMG20250129WA0032.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b20",
    "name": "externallmg_1738131573296_IMG20250129WA0033.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573296_IMG20250129WA0033.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b21",
    "name": "externallmg_1738131573302_IMG20250129WA0034.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573302_IMG20250129WA0034.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b22",
```

```
    "name": "externallmg_1738131573332_IMG20250129WA0035.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573332_IMG20250129WA0035.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b23",
    "name": "externallmg_1738131573340_IMG20250129WA0036.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573340_IMG20250129WA0036.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b24",
    "name": "externallmg_1738131573374_IMG20250129WA0037.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573374_IMG20250129WA0037.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b25",
    "name": "externallmg_1738131573397_IMG20250129WA0040.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573397_IMG20250129WA0040.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b26",
    "name": "externallmg_1738131573404_IMG20250129WA0041.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573404_IMG20250129WA0041.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b27",
    "name": "externallmg_1738131573444_IMG20250129WA0042.jpg",
```

```
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573444_IMG20250129WA0042.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b28",
    "name": "externallmg_1738131573448_IMG20250129WA0043.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573448_IMG20250129WA0043.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b29",
    "name": "externallmg_1738131573472_IMG20250129WA0044.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573472_IMG20250129WA0044.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b2a",
    "name": "externallmg_1738131573475_IMG20250129WA0045.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573475_IMG20250129WA0045.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b2b",
    "name": "externallmg_1738131573498_IMG20250129WA0046.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573498_IMG20250129WA0046.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b2c",
    "name": "externallmg_1738131573520_IMG20250129WA0047.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externallmg_1738131573520_IMG20250129WA0047.jpg",
```



```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b2d",
    "name": "externalImg_1738131573526_IMG20250129WA0048.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externalImg_1738131573526_IMG20250129WA0048.jpg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b2e",
    "name": "externalImg_1738131573552_IMG20250129WA0049.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externalImg_1738131573552_IMG20250129WA0049.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b2f",
    "name": "externalImg_1738131573558_IMG20250129WA0050.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externalImg_1738131573558_IMG20250129WA0050.jpg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "6799c875115bdf1669098b30",
    "name": "externalImg_1738131573568_IMG20250129WA0051.jpg",
    "path": "cases/6798a3362f3738a577c8d44b/
externalImg_1738131573568_IMG20250129WA0051.jpg",
    "orientation": "portrait"
  }
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-28T09:28:22.065Z",
"updatedAt": "2025-01-29T06:19:33.820Z",
```

```

    "__v": 0,
    "assignmentType": {
      "value": "Retail",
      "label": "Retail"
    },
    "fullAddress": "Residential Flat No. A28, Ground Floor, Shree Ganesh CHSL, Plot No.
937, Sector 9, RSC 15, Village - Charkop, Kandivali West, Taluka - Borivali, Mumbai,
400067",
    "updatedBy": "6006d4ce5080a310ac1fd2",
    "addressForMap": "",
    "caseReferredBy": "659ccce98f39506e83489828",
    "contactPersonName": "MRS TAMUBAI KISHANLAL JOSHI AND MR KISHANLAL
NANALAL JOSHI",
    "email": "",
    "isExternal": "false",
    "isUrgent": "false",
    "ownershipShare": "",
    "proposePurchaserName": "",
    "purchaseValueAsPerDocument": "",
    "relationWithOwner": "self",
    "reald": "",
    "siteVisitContactNo": "9869901359"
  }

```

Name	Length	Width	Total
Composition :			
Other			
Composition :			