

```
{
  "typeOfReport": {
    "label": "Structural Report",
    "value": "Structural_Report"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "label": "Direct",
    "value": "Direct"
  },
  "purposeOfValuation": {
    "label": "Housing Loan",
    "value": "Housing_Loan"
  },
  "masterTypeOfPurpose": {
    "label": "Non SARFAESI",
    "value": "Non_SARFAESI"
  },
  "toAssess": {
    "label": "Fair Market Value",
    "value": "Fair_Market_Value"
  },
  "creditOfficer": {
    "branch": {
      "_id": "5fc6c33c74d12c494856ba7a"
    },
    "firstName": "Afrin",
    "type": "CREDITOFFICER",
    "_id": "65322d2e619c14402da74768",
    "lastName": "Shaikh",
    "mobileNo": "",
    "workMobileNo": "9819111447",
    "email": "1ubin0539287@unionbankofindia.bank"
  },
  "fees": {
    "type": "fixed",
    "propertyValue": "6000000",
    "discussWithPerson": "Afrin",
    "expectedFees": 3000,
    "quotedAmount": ""
  },
}
```

```
"organization": {
  "_id": "643a5702108b68389ed72f71",
  "name": "Mumbai",
  "shortName": "VCIPL/Mumbai",
  "email": "vastukalamumbai@vastukala.com",
  "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
  "city": "Mumbai"
},
"client": {
  "_id": "5fc6a0d8da3c631ed41d1828",
  "type": "BANK",
  "name": "Union Bank of India",
  "displayName": "Union Bank of India",
  "initial": "UBI",
  "remark": "Temp",
  "status": true
},
"branch": {
  "_id": "5fc6c33c74d12c494856ba7a",
  "branchCode": "000023",
  "type": "BRANCH",
  "name": "Bhayander (West) Branch",
  "email": "cbsbhayander@unionbankofindia.com",
  "mobileNo": "02228192334",
  "alternateMobileNo": "9137539280",
  "address": "Zainab Manzil, Ground Floor, Station Road Bhayander
(W)Thane-401101",
  "ledgerName": "",
  "fax": "02228190228",
  "sendStructuralCertificate": "0"
},
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": {
  "_id": "60f93be845132d6a6bdda676",
  "zoneName": "MUMBAI SOUTH"
},
"staff": {
  "pickupPerson": {
```

```
"type": "EMPLOYEE",
  "_id": "659ccce98f39506e83489828",
  "role": "DELIVERYPERSON",
  "firstName": "Amit",
  "email": "amitsalvi2909@gmail.com",
  "lastName": "Salvi",
  "mobileNo": "7499830659",
  "shortName": "Amit",
  "workWithDocumentMaker": "",
  "profilePhoto": "users/659ccce98f39506e83489828/
profilePhoto_1712385426269_image.jpeg"
},
"siteEngineer": {
  "type": "EMPLOYEE",
  "_id": "66850df5d9f18310ed2e5d98",
  "role": "SITEENGINEER",
  "firstName": "Krishna",
  "email": "krishnagawade9@gmail.com",
  "lastName": "Gawde",
  "mobileNo": "9821646373",
  "designation": "Site Engg",
  "shortName": "Krishna",
  "workWithDocumentMaker": "63fc575ece84bf289ba9e82d"
},
"rateVerifier": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"maker": {
  "type": "EMPLOYEE",
  "_id": "62fe044a48a26047e6552796",
  "role": "MAKER",
  "firstName": "Pradnya ",
  "email": "pradnya@vastukala.org",
  "lastName": "Rasam",
  "mobileNo": "9529385821",
```

```
"designation": "",
"shortName": "PR",
"workWithDocumentMaker": "60f9147bf3dd69653a591e8c",
"profilePhoto": "users/62fe044a48a26047e6552796/
profilePhoto_1668056250324_WhatsApp_Image_20221110_at_102500_AM.jpeg"
},
"checker": {
  "type": "EMPLOYEE",
  "_id": "64dc7184ccaf1e7b7f637f47",
  "role": "FRONTDESK",
  "firstName": "Binumon",
  "email": "binu@vastukala.org",
  "lastName": "Moozhickal",
  "mobileNo": "9930252906",
  "designation": "Back Office Team Leader",
  "shortName": "BS",
  "workWithDocumentMaker": "5ffe92d27737ca4d986b6453",
  "profilePhoto": "users/64dc7184ccaf1e7b7f637f47/
profilePhoto_1694780598179_60341cbfbaf74abfbe0c819dbff58c0f.jpg"
},
"valuers": [
  {
    "valuersRegistrationNumber": [
      {
        "value": "IBBI/RV/07/2018/10366",
        "label": "Registered Valuer"
      }
    ],
    "type": "EMPLOYEE",
    "_id": "5ffe92d27737ca4d986b6453",
    "role": "VALUER",
    "firstName": "Manoj",
    "email": "manoj@vastukala.org",
    "lastName": "Chalikwar",
    "mobileNo": "9819597579",
    "designation": "Registered Valuer",
    "registrationNo": [
      {
        "title": {
          "label": "IBBI"
        },
        "_id": "60af80072ffdf65bcd658651",
        "number": "IBBI/RV/07/2018/10366"
      }
    ],
    {
      "title": {
```

```
    "value": "FIIV",
    "label": "FIIV"
  },
  "_id": "60af80072ffdf65bcd658652",
  "number": "CAT-I-F-1763"
},
{
  "title": {
    "value": "Chartered_Engineer",
    "label": "Chartered Engineer"
  },
  "_id": "60af80072ffdf65bcd658653",
  "number": "AM161706-3"
},
{
  "title": {
    "value": "Registered_Valuer",
    "label": "Registered Valuer"
  },
  "_id": "60af80072ffdf65bcd658654",
  "number": "IBBI/RV/07/2018/10366"
}
],
"shortName": "MBC",
"workWithDocumentMaker": "",
"profilePhoto": "users\\5ffe92d27737ca4d986b6453\\
\\profilePhoto_1622114310919_Manoj C.jpeg",
"PANNo": "AERPC9086P",
"fatherName": "Baburao"
}
]
},
"clientType": {
  "label": "BANK",
  "value": "BANK"
},
"location": {
  "latitude": "19.294891244638336",
  "longitude": "72.85211838825192"
},
"geo": {
  "type": "Point",
  "coordinates": [
    72.85211838825192,
    19.294891244638336
  ]
}
```

```
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
    {
      "dateTime": "1/02/2025 12:00 am",
      "remark": ""
    }
  ],
  "visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Bhayander ",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "21",
```

```
"label": false
},
"buildingNo": {
  "status": false,
  "name": "Building No",
  "key": "buildingNo",
  "value": "",
  "label": true
},
"district": {
  "status": true,
  "name": "District",
  "key": "district",
  "value": "Thane",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": true,
  "name": "Taluka",
  "key": "taluka",
  "value": "Thane",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
```

```
"name": "Building Name",
"key": "buildingName",
"value": "Shree Agrawal Bhavan Co-Op. Hsg. Sco. Ltd.",
"label": false
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": true,
  "name": "Street 1",
  "key": "street1",
  "value": "Modi Patel Road",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": false,
  "name": "Project Name",
  "key": "projectName",
  "value": "",
  "label": false
}
```



```
},
"oldSurveyNumber": {
  "status": true,
  "name": "Old Survey No.",
  "key": "oldSurveyNumber",
  "value": "15, New Survey No. 351, Hissa No. 3(Part)",
  "label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hissaNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hissaNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "102",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
```

```
"key": "municipalityWardNo",
"value": "",
"label": true
},
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": true,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "PIN - 401101",
  "label": false
},
}
```

```
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
  "value": "Bhayander (West)",
  "label": false
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
```

```
"routeLat": "",
"routeLng": "",
"stationName": "",
"routeDistance": ""
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  }
}
```

```
},
"internalBrickWork": {
  "label": "Internal Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTillingKitchenPlatform": {
  "label": "Flooring, Tilling, Kitchen Platform",
  "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
}
```

```
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": true
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
```

```
"quantity": "0.00",
"ratePerUnit": "0.00",
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
```



```
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```

```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "RATEVERIFICATIONCOMPLETED",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "679cca077dd57116683e7c1d",
"ownerName": "MR CHANDRATAN MALCHAND AGARWAL / MR MAHESH
MALCHAND AGARWAL",
"ownerPhoneNo": "9892475780",
"appAddress": "FLAT NO 102 1ST FLOOR SHREE AGARWAL BHAVAN CHS LTD
MODI PATEL ROAD BHAYNDER WEST THANE 401101",
"remark": "Structral stability report",
"documents": [
  {
    "documentType": {
      "label": "Old Valution Report ",
      "value": "60ae1296aa6d152c1801b455"
    },
    "isHardCopy": false,
    "displayStatus": false,
    "path": "cases/679cca077dd57116683e7c1d/
document_1738328463426_1738328460990_DOC20241008WA0004.pdf",
    "fileName":
"document_1738328463426_1738328460990_DOC20241008WA0004.pdf",
    "id": "604954",
    "uploadedBy": "659ccce98f39506e83489828",
    "createdAt": "Fri Jan 31 2025 13:03:03 GMT+0000 (Coordinated Universal Time)"
  }
],
"caseNumber": "014060",
"createdBy": "659ccce98f39506e83489828",
"caseHistory": [
  {
    "id": "838149",
```

```
"title": "Create Lead",
"description": "Create Lead",
"datetime": "Fri Jan 31 2025 13:03:03 GMT+0000 (Coordinated Universal Time)"
}
],
"owners": [
{
"name": "MR CHANDRATAN MALCHAND AGARWAL / MR MAHESH MALCHAND
AGARWAL",
"phone": "9892475780",
"ownershipShare": "",
"email": "",
"id": "766078"
}
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "679db7fe7dd57116683ea767",
"name": "externalImg_1738389502004_externalImg_1728296319123_WhatsApp_I
mage_20241007_at_154358_1.jpeg",
"path": "cases/679cca077dd57116683e7c1d/externalImg_1738389502004_externalI
mg_1728296319123_WhatsApp_Image_20241007_at_154358_1.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
"status": false,
"_id": "679db7fe7dd57116683ea768",
"name": "externalImg_1738389502036_externalImg_1728296319125_WhatsApp_I
mage_20241007_at_154358_2.jpeg",
"path": "cases/679cca077dd57116683e7c1d/externalImg_1738389502036_externalI
mg_1728296319125_WhatsApp_Image_20241007_at_154358_2.jpeg",
"orientation": "portrait"
},
{
"type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "679db7fe7dd57116683ea769",
  "name": "externallmg_1738389502043_externallmg_1728296319128_WhatsApp_I
mage_20241007_at_154359_1.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389502043_externall
mg_1728296319128_WhatsApp_Image_20241007_at_154359_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db7fe7dd57116683ea76a",
  "name": "externallmg_1738389502088_externallmg_1728296319130_WhatsApp_I
mage_20241007_at_154359.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389502088_externall
mg_1728296319130_WhatsApp_Image_20241007_at_154359.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db7fe7dd57116683ea76b",
  "name": "externallmg_1738389502095_externallmg_1728296319132_WhatsApp_I
mage_20241007_at_154400_1.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389502095_externall
mg_1728296319132_WhatsApp_Image_20241007_at_154400_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db7fe7dd57116683ea76c",
  "name": "externallmg_1738389502140_externallmg_1728296319134_WhatsApp_I
mage_20241007_at_154400_2.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389502140_externall
mg_1728296319134_WhatsApp_Image_20241007_at_154400_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db7fe7dd57116683ea76d",
  "name": "externallmg_1738389502177_externallmg_1728296319136_WhatsApp_I
mage_20241007_at_154400.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389502177_externall
mg_1728296319136_WhatsApp_Image_20241007_at_154400.jpeg",
```

```
"orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db7fe7dd57116683ea76e",
  "name": "externallmg_1738389502185_externallmg_1728296319138_WhatsApp_I
mage_20241007_at_154401_1.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389502185_externall
mg_1728296319138_WhatsApp_Image_20241007_at_154401_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db7fe7dd57116683ea76f",
  "name": "externallmg_1738389502211_externallmg_1728296319141_WhatsApp_I
mage_20241007_at_154401_2.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389502211_externall
mg_1728296319141_WhatsApp_Image_20241007_at_154401_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db80bd6fb4a89a36789cb",
  "name": "externallmg_1738389515317_externallmg_1728296331024_WhatsApp_I
mage_20241007_at_154404_1.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389515317_externall
mg_1728296331024_WhatsApp_Image_20241007_at_154404_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db80bd6fb4a89a36789cc",
  "name": "externallmg_1738389515322_externallmg_1728296331025_WhatsApp_I
mage_20241007_at_154404.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389515322_externall
mg_1728296331025_WhatsApp_Image_20241007_at_154404.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db80bd6fb4a89a36789cd",
```

```
    "name": "externallmg_1738389515326_externallmg_1728296331025_WhatsApp_I
mage_20241007_at_154404_2.jpeg",
    "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389515326_externall
mg_1728296331025_WhatsApp_Image_20241007_at_154404_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679db80bd6fb4a89a36789ce",
    "name": "externallmg_1738389515345_externallmg_1728296331027_WhatsApp_I
mage_20241007_at_154405_1.jpeg",
    "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389515345_externall
mg_1728296331027_WhatsApp_Image_20241007_at_154405_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679db80bd6fb4a89a36789cf",
    "name": "externallmg_1738389515348_externallmg_1728296331028_WhatsApp_I
mage_20241007_at_154405.jpeg",
    "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389515348_externall
mg_1728296331028_WhatsApp_Image_20241007_at_154405.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679db80bd6fb4a89a36789d0",
    "name": "externallmg_1738389515368_externallmg_1728296331028_WhatsApp_I
mage_20241007_at_154405_2.jpeg",
    "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389515368_externall
mg_1728296331028_WhatsApp_Image_20241007_at_154405_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679db80bd6fb4a89a36789d1",
    "name": "externallmg_1738389515393_externallmg_1728296331029_WhatsApp_I
mage_20241007_at_154214.jpeg",
    "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389515393_externall
mg_1728296331029_WhatsApp_Image_20241007_at_154214.jpeg",
    "orientation": "portrait"
  },
  },
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db80bd6fb4a89a36789d2",
  "name": "externallmg_1738389515396_externallmg_1728296331032_WhatsApp_I
mage_20241007_at_154357_1.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389515396_externall
mg_1728296331032_WhatsApp_Image_20241007_at_154357_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db80bd6fb4a89a36789d3",
  "name": "externallmg_1738389515422_externallmg_1728296331034_WhatsApp_I
mage_20241007_at_154357.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389515422_externall
mg_1728296331034_WhatsApp_Image_20241007_at_154357.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db80bd6fb4a89a36789d4",
  "name": "externallmg_1738389515426_externallmg_1728296331037_WhatsApp_I
mage_20241007_at_154358.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389515426_externall
mg_1728296331037_WhatsApp_Image_20241007_at_154358.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db818d6fb4a89a3678a0e",
  "name": "externallmg_1738389528381_externallmg_1728296319138_WhatsApp_I
mage_20241007_at_154401_1.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389528381_externall
mg_1728296319138_WhatsApp_Image_20241007_at_154401_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db818d6fb4a89a3678a0f",
  "name": "externallmg_1738389528389_externallmg_1728296319141_WhatsApp_I
mage_20241007_at_154401_2.jpeg",
```

```
    "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389528389_externallmg_1728296319141_WhatsApp_Image_20241007_at_154401_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679db818d6fb4a89a3678a10",
    "name": "externallmg_1738389528407_externallmg_1728296331016_WhatsApp_Image_20241007_at_154401.jpeg",
    "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389528407_externallmg_1728296331016_WhatsApp_Image_20241007_at_154401.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679db818d6fb4a89a3678a11",
    "name": "externallmg_1738389528411_externallmg_1728296331018_WhatsApp_Image_20241007_at_154402_1.jpeg",
    "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389528411_externallmg_1728296331018_WhatsApp_Image_20241007_at_154402_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679db818d6fb4a89a3678a12",
    "name": "externallmg_1738389528436_externallmg_1728296331019_WhatsApp_Image_20241007_at_154402_2.jpeg",
    "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389528436_externallmg_1728296331019_WhatsApp_Image_20241007_at_154402_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "679db818d6fb4a89a3678a13",
    "name": "externallmg_1738389528439_externallmg_1728296331020_WhatsApp_Image_20241007_at_154402.jpeg",
    "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389528439_externallmg_1728296331020_WhatsApp_Image_20241007_at_154402.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "679db818d6fb4a89a3678a14",
  "name": "externallmg_1738389528475_externallmg_1728296331021_WhatsApp_I
mage_20241007_at_154403_1.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389528475_externall
mg_1728296331021_WhatsApp_Image_20241007_at_154403_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db818d6fb4a89a3678a15",
  "name": "externallmg_1738389528479_externallmg_1728296331022_WhatsApp_I
mage_20241007_at_154403_2.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389528479_externall
mg_1728296331022_WhatsApp_Image_20241007_at_154403_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "679db818d6fb4a89a3678a16",
  "name": "externallmg_1738389528500_externallmg_1728296331023_WhatsApp_I
mage_20241007_at_154403.jpeg",
  "path": "cases/679cca077dd57116683e7c1d/externallmg_1738389528500_externall
mg_1728296331023_WhatsApp_Image_20241007_at_154403.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [
  {
    "originalname": "Chandratan Malchand Agarwal.docx",
    "filename": "1738389483468_Chandratan_Malchand_Agarwal.docx",
    "path": "cases/679cca077dd57116683e7c1d/
processingDocuments/1738389483468_Chandratan_Malchand_Agarwal.docx",
    "size": "877845",
    "createdAt": "Sat Feb 01 2025 05:58:04 GMT+0000 (Coordinated Universal Time)",
    "uploadedBy": "62fe044a48a26047e6552796"
  },
  {
    "originalname": "UBI - Shri. Chandratan Malchand Agarwal & Shri. Mahesh
Malchand Agarwal.pdf",
    "filename": "1738389483500_UBI__Shri_Chandratan_Malchand_Agarwal__Shri_M
ahesh_Malchand_Agarwal.pdf",
    "path": "cases/679cca077dd57116683e7c1d/processingDocuments/1738389483500
```

```

_UBI__Shri_Chandratan_Malchand_Agarwal__Shri_Mahesh_Malchand_Agarwal.pdf",
  "size": "8176030",
  "createdAt": "Sat Feb 01 2025 05:58:04 GMT+0000 (Coordinated Universal Time)",
  "uploadedBy": "62fe044a48a26047e6552796"
}
],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-01-31T13:03:03.858Z",
"updatedAt": "2025-02-01T05:58:48.640Z",
"__v": 0,
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"fullAddress": "Residential Structural Report No. 102, 21st Floor, Shree Agrawal
Bhavan Co-Op. Hsg. Sco. Ltd., Old Survey No. 15, New Survey No. 351, Hissa No.
3(Part), Modi Patel Road, Village - Bhayander , Bhayander (West), Taluka - Thane,
District - Thane, PIN - 401101, State - Maharashtra, India",
"updatedBy": "62fe044a48a26047e6552796",
"addressForMap": "",
"caseReferredBy": "659ccce98f39506e83489828",
"contactPersonName": "MR CHANDRATAN MALCHAND AGARWAL / MR MAHESH
MALCHAND AGARWAL",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"reald": "",
"siteVisitContactNo": "9892475780"
}

```

Name	Length	Width	Total
Composition :			
Other Composition :			