

```
{
  "typeOfReport": {
    "value": "Capital_Gain",
    "label": "Capital Gain"
  },
  "reportInformation": {
    "amalgamated": false,
    "proposePurchaser": false,
    "RVDSValues": true,
    "proportionateValue": false
  },
  "leadFrom": {
    "value": "Direct",
    "label": "Direct"
  },
  "purposeOfValuation": {
    "value": "Capital_Gain",
    "label": "Capital Gain"
  },
  "masterTypeOfPurpose": {
    "value": "Capital_Gain",
    "label": "Capital Gain"
  },
  "toAssess": {
    "value": "Capital_Gain_2001",
    "label": "Capital Gain 2001"
  },
  "creditOfficer": "",
  "fees": {
    "type": "fixed",
    "propertyValue": "",
    "discussWithPerson": "",
    "expectedFees": null,
    "quotedAmount": ""
  },
  "organization": {
    "_id": "643a5702108b68389ed72f71",
    "name": "Mumbai",
    "shortName": "VCIPL/Mumbai",
    "email": "vastukalamumbai@vastukala.com",
    "address": "B1-001, U/B Floor, Boomerang, Chandivali Farm Road, Powai,
Andheri(East), Mumbai - 400 072. ",
    "city": "Mumbai"
  },
  "client": {
    "_id": "67aaeb9736a56c9b5f65535f",
```

```
"type": "PRIVATE_CLIENT",
"name": "Mr. S.Y. Raman",
"displayName": "Mr. S.Y. Raman",
"initial": "M"
},
"branch": "",
"assetsClass": {
  "value": "Land_&_Building_/_Immovable_Property",
  "label": "Land & Building / Immovable Property"
},
"propertyType": {
  "label": "Residential",
  "value": "Residential"
},
"zone": "",
"staff": {
  "pickupPerson": {
    "type": "EMPLOYEE",
    "_id": "62691c48afd7d55eddecfda3",
    "role": "ADMIN",
    "firstName": "Bhavika",
    "email": "bhavikachavan0102@gmail.com",
    "lastName": "chavan",
    "mobileNo": "8390804382",
    "shortName": "BH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
  },
  "siteEngineer": {
    "type": "EMPLOYEE",
    "_id": "62550ed0aba01e0af98f2f75",
    "role": "SITEENGINEER",
    "firstName": "Chandan",
    "email": "ck06806@gmail.com",
    "lastName": "Singh",
    "mobileNo": "8454863607",
    "designation": "",
    "shortName": "CH",
    "workWithDocumentMaker": "",
    "profilePhoto": "users/62550ed0aba01e0af98f2f75/
profilePhoto_1668057636003_WhatsApp_Image_20221110_at_104814_AM.jpeg"
  },
  "rateVerifier": {
    "type": "EMPLOYEE",
    "_id": "62691c48afd7d55eddecfda3",
```

```
"role": "ADMIN",
"firstName": "Bhavika",
"email": "bhavikachavan0102@gmail.com",
"lastName": "chavan",
"mobileNo": "8390804382",
"designation": "Site Engineer",
"shortName": "BH",
"workWithDocumentMaker": "",
"profilePhoto": "users/62691c48afd7d55eddecfda3/
profilePhoto_1668055228258_bhavika.jpeg"
},
"maker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"checker": {
"type": "EMPLOYEE",
"_id": "5fc78e26625ecd20ec1f88e9",
"role": "MAKER+CHECKER",
"firstName": "Vaishali",
"email": "v.sarmalkar@vastukala.org",
"lastName": "Sarmalkar",
"mobileNo": "9004437379",
"shortName": "VS",
"workWithDocumentMaker": "1",
"profilePhoto": "users\\5fc78e26625ecd20ec1f88e9\
\profilePhoto_1622369721406_Vaishali Sarmalkar Photo.jpg",
"designation": ""
},
"valuers": [
{
"valuersRegistrationNumber": [
{
"value": "[N]C.C.I.T/I -14/52/2008-09",
"label": "Wealth Tax"
}
}
]
```

```
],
  "type": "EMPLOYEE",
  "_id": "6084131a13f01f158c6ea1f3",
  "PANNo": "AEAPC7114Q",
  "role": "VALUER",
  "firstName": "Sharadkumar",
  "fatherName": "Baburao",
  "email": "cmd@vastukala.org",
  "lastName": "Chalikwar",
  "mobileNo": "9422171100",
  "designation": "CMD",
  "registrationNo": [
    {
      "title": {
        "value": "Wealth_Tax",
        "label": "Wealth Tax"
      },
      "_id": "6084131a13f01f158c6ea1f4",
      "number": "[N]C.C.I.T/I -14/52/2008-09"
    }
  ],
  "shortName": "SBC",
  "workWithDocumentMaker": "",
  "profilePhoto": "users\\6084131a13f01f158c6ea1f3\\
\\profilePhoto_1622369528291_Sharad Chalikwar Photo.jpg"
}
]
},
"clientType": {
  "value": "PRIVATE_CLIENT",
  "label": "Private Clients"
},
"location": {
  "latitude": "19.07122539441429",
  "longitude": "72.89969987066536"
},
"geo": {
  "type": "Point",
  "coordinates": [
    0,
    0
  ]
},
"siteVisit": {
  "siteVisitStatus": false,
  "schedule": [
```

```
{
  "dateTime": "11/02/2025 12:00 pm",
  "remark": ""
}
],
"visitedDate": []
},
"marketAnalysisAndRemark": {
  "audioNotes": []
},
"externalReportDetails": {
  "finalAreaType": "Built_Up",
  "finalMeasurementType": "Sq. Ft.",
  "underConstruction": false
},
"address": {
  "state": {
    "status": true,
    "name": "State",
    "key": "state",
    "value": "Maharashtra",
    "label": true
  },
  "country": {
    "status": true,
    "name": "Country",
    "key": "country",
    "value": "India",
    "label": false
  },
  "village": {
    "status": true,
    "name": "Village",
    "key": "village",
    "value": "Chembur",
    "label": true
  },
  "floorNo": {
    "status": true,
    "name": "Floor No",
    "key": "floorNo",
    "value": "Ground",
    "label": false
  },
  "buildingNo": {
    "status": false,
```

```
"name": "Building No",
"key": "buildingNo",
"value": "",
"label": true
},
"district": {
  "status": false,
  "name": "District",
  "key": "district",
  "value": "",
  "label": true
},
"city": {
  "status": false,
  "name": "City",
  "key": "city",
  "value": "",
  "label": false
},
"tahasilNo": {
  "status": false,
  "name": "Tehsil",
  "key": "tahasilNo",
  "value": "",
  "label": true
},
"taluka": {
  "status": false,
  "name": "Taluka",
  "key": "taluka",
  "value": "",
  "label": true
},
"plotNo": {
  "status": false,
  "name": "Plot No.",
  "key": "plotNo",
  "value": "",
  "label": true
},
"buildingName": {
  "status": true,
  "name": "Building Name",
  "key": "buildingName",
  "value": "Tilak Vrindavan CHSL",
  "label": false
}
```

```
},
"selectArea": {
  "status": false,
  "name": "Sector",
  "key": "selectArea",
  "value": "",
  "label": true
},
"street1": {
  "status": false,
  "name": "Street 1",
  "key": "street1",
  "value": "",
  "label": false
},
"street2": {
  "status": false,
  "name": "Street 2",
  "key": "street2",
  "value": "",
  "label": false
},
"landmark": {
  "status": false,
  "name": "Landmark",
  "key": "landmark",
  "value": "",
  "label": false
},
"wing": {
  "status": false,
  "name": "Wing",
  "key": "wing",
  "value": "",
  "label": true
},
"projectName": {
  "status": true,
  "name": "Project Name",
  "key": "projectName",
  "value": "Bramhadev Society",
  "label": false
},
"oldSurveyNumber": {
  "status": false,
  "name": "Old Survey No.",
```

```
"key": "oldSurveyNumber",
"value": "",
"label": true
},
"newSurveyNumber": {
  "status": false,
  "name": "New/Current Survey No.",
  "key": "newSurveyNumber",
  "value": "",
  "label": true
},
"hisNo": {
  "status": false,
  "name": "Hissa No.",
  "key": "hisNo",
  "value": "",
  "label": true
},
"CTSNo": {
  "status": false,
  "name": "CTS No.",
  "key": "CTSNo",
  "value": "",
  "label": true
},
"blockNo": {
  "status": false,
  "name": "Block No",
  "key": "blockNo",
  "value": "",
  "label": true
},
"selectNo": {
  "status": true,
  "name": "Flat / Unit / Office / Gala No.",
  "key": "selectNo",
  "value": "Room No. L/6/42",
  "label": false
},
"municipalityWardNo": {
  "status": false,
  "name": "Municipality Ward No.",
  "key": "municipalityWardNo",
  "value": "",
  "label": true
},
}
```



```
"khataNo": {
  "status": false,
  "name": "Khata No",
  "key": "khataNo",
  "value": "",
  "label": false
},
"mouza": {
  "status": false,
  "name": "Mouza",
  "key": "mouza",
  "value": "",
  "label": true
},
"SRO": {
  "status": false,
  "name": "SRO",
  "key": "SRO",
  "value": "",
  "label": false
},
"policeStation": {
  "status": false,
  "name": "Police Station(P.S)",
  "key": "policeStation",
  "value": "",
  "label": false
},
"GUTNo": {
  "status": false,
  "name": "Gut No.",
  "key": "GUTNo",
  "value": "",
  "label": true
},
"postalCode": {
  "status": false,
  "name": "Postal Code",
  "key": "postalCode",
  "value": "",
  "label": false
},
"suburb": {
  "status": true,
  "name": "Suburb",
  "key": "suburb",
```

```
    "value": "Tilka Nagar",
    "label": false
  }
},
"general": {
  "unitBoundaries": {
    "isDisplay": false
  },
  "whichTheLocalityIsServed": {
    "buses": {
      "title": "Buses"
    },
    "taxies": {
      "title": "Taxies"
    },
    "auto": {
      "title": "Auto"
    },
    "privateCars": {
      "title": "Private Cars"
    }
  }
},
"apfDetails": {
  "buildings": [],
  "compositions": []
},
"igrFinalRate": {
  "floorRatePercentage": "0.00"
},
"outgoingDetail": {
  "monthlyRent": ""
},
"siteMeasurement": {
  "isSiteVisitAllowed": true
},
"finalPlinthArea": {
  "area": "0.00"
},
"routeMap": {
  "routeMapDetail": {
    "routeMapImg": "",
    "routeLat": "",
    "routeLng": "",
    "stationName": "",
    "routeDistance": ""
  }
}
```

```
},
"finalLatLng": {
  "coordinates": []
},
"locationMapImg": []
},
"valuation": {
  "fairMarketValue": {
    "costOfConstruction": "",
    "depreciationPercentage": "",
    "depreciatedCostOfConstruction": "",
    "totalFairMarketValue": ""
  }
},
"outward": {
  "status": false,
  "remark": "SYSTEM_GENERATED"
},
"rateVerify": {
  "status": false
},
"underConstruction": {
  "rccFootingFoundation": {
    "label": "RCC Footing/Foundation",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": true
  },
  "rccPlinth": {
    "label": "RCC Plinth",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "fullBuildingRcc": {
    "label": "Full Building Rcc",
    "floorsCompleted": "",
    "percentage": "0.00",
    "isHideFloor": false,
    "status": false
  },
  "internalBrickWork": {
    "label": "Internal Brick Work",
    "floorsCompleted": "",
```

```
"percentage": "0.00",
"isHideFloor": false,
"status": false
},
"externalBrickWork": {
  "label": "External Brick Work",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"internalPlastering": {
  "label": "Internal Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPlastering": {
  "label": "External Plastering",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"door": {
  "label": "Door",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"window": {
  "label": "Window",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"flooringTilingKitchenPlatform": {
  "label": "Flooring, Tiling, Kitchen Platform",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
}
```

```
"internalPainting": {
  "label": "Internal Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"externalPainting": {
  "label": "External Painting",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"electrificationPlumbingSanitaryInstallation": {
  "label": "Electrification, Plumbing, Sanitary Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"liftInstallation": {
  "label": "Lift Installation",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": false,
  "status": false
},
"passageStaircaseLobbyDevelopment": {
  "label": "Passage, Staircase & Lobby Development",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"externalDevelopmentFinalFinishing": {
  "label": "External Development & Final Finishing",
  "floorsCompleted": "",
  "percentage": "0.00",
  "isHideFloor": true,
  "status": false
},
"workCompleted": {
  "label": "Work Completed (%)",
  "floorsCompleted": "",
  "percentage": "0.00",
```

```
    "isHideFloor": true,
    "status": true
  }
},
"guidelineDetails": {
  "finalGuidelineValue": "0",
  "selectedBuildUpValue": "0",
  "selectedBuildUpMeasurementType": ""
},
"reportImages": {
  "frontPageImages": [],
  "selfieWithSiteVisitImages": [],
  "externalPhotos": [],
  "parkingImages": [],
  "societyNameBoardImage": [],
  "compositionImages": []
},
"indicatorRange": {
  "carpetRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "builtUpRateRange": {
    "min": "0.00",
    "max": "0.00"
  },
  "saleableRateRange": {
    "min": "0.00",
    "max": "0.00"
  }
},
"detailsOfValuation": {
  "presentValueOfFlat": {
    "title": "Present value of the flat (incl. car parking, if provided)",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
    "isEditable": false
  },
  "wardrobes": {
    "title": "Wardrobes",
    "quantity": "0.00",
    "ratePerUnit": "0.00",
    "estimatedValue": "0.00",
    "status": true,
  }
}
```

```
"isEditable": true
},
"showcases": {
  "title": "Showcases",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"kitchenArrangements": {
  "title": "Kitchen arrangements",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"superfineFinish": {
  "title": "Superfine finish",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"interiorDecorations": {
  "title": "Interior Decorations",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"electricityDeposits": {
  "title": "Electricity deposits / electrical fittings, etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"extraCollapsibleGates": {
  "title": "Extra collapsible gates / grill works etc",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
```

```
"estimatedValue": "0.00",
"status": true,
"isEditable": true
},
"potentialValue": {
  "title": "Potential value, if any",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"others": {
  "title": "Others / Car Parking",
  "quantity": "0.00",
  "ratePerUnit": "0.00",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": true
},
"totalValues": {
  "title": "Total",
  "quantity": "",
  "ratePerUnit": "",
  "estimatedValue": "0.00",
  "status": true,
  "isEditable": false
}
},
"factorFavoringValue": {
  "additionValueDetails": [],
  "lessValueDetails": []
},
"taskStatus": {
  "SITE_INSPECTION": false,
  "RATE_VERIFY": false,
  "MAKER": false,
  "CHECKER": false,
  "PREPARE_INVOICE": false,
  "PRINT": false,
  "SIGN": false,
  "SIGNED_REPORT_UPLOAD": false,
  "DELIVERY": false,
  "PAYMENT_COLLECT": false,
  "COMPLETED": false
},
```



```
"createCase": "false",
"type": "CASE",
"leadType": {
  "label": "Lead",
  "value": "LEAD"
},
"siteVisitType": "FULL",
"isExternalReport": false,
"isSiteMeasurementAllowed": true,
"finalValuationArea": "0",
"empanelmentNo": [],
"isAdvanceInvoice": false,
"status": true,
"caseStatus": "REMAININGSITEVISIT",
"paymentStatus": "NA",
"invoiceIds": [],
"paymentIds": [],
"_id": "67aaeb9836a56c9b5f655364",
"ownerName": "Mr. S.Y. Raman",
"ownerPhoneNo": "9820422251",
"fullAddress": "Residential Capital Gain No. Room No. L/6/42, Ground Floor, Tilak
Vrindavan CHSL, Bramhadev Society, Village - Chembur, Tilka Nagar",
"remark": "",
"documents": [],
"assignmentType": {
  "value": "Retail",
  "label": "Retail"
},
"caseNumber": "014236",
"createdBy": "62691c48afd7d55eddecfda3",
"caseHistory": [
  {
    "id": "823652",
    "title": "Create Lead",
    "description": "Create Lead",
    "datetime": "Tue Feb 11 2025 06:18:00 GMT+0000 (Coordinated Universal Time)"
  }
],
"owners": [
  {
    "name": "Mr. S.Y. Raman",
    "phone": "9820422251",
    "ownershipShare": "",
    "email": "",
    "id": "386175"
  }
]
```

```
],
"proposePurchasers": [],
"siteInspection": [],
"composition": [],
"otherComposition": [],
"externalReport": [],
"documentPerArea": [],
"images": [],
"indicatorArr": [],
"externalImages": [
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf526d716769af0d46633",
    "name":
"externallmg_1739257125998_WhatsApp_Image_20250211_at_90509_AM.jpeg",
    "path": "cases/67aaeb9836a56c9b5f655364/
externallmg_1739257125998_WhatsApp_Image_20250211_at_90509_AM.jpeg",
    "orientation": "landscape"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf526d716769af0d46634",
    "name":
"externallmg_1739257126009_WhatsApp_Image_20250211_at_90513_AM.jpeg",
    "path": "cases/67aaeb9836a56c9b5f655364/
externallmg_1739257126009_WhatsApp_Image_20250211_at_90513_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf526d716769af0d46635",
    "name":
"externallmg_1739257126024_WhatsApp_Image_20250211_at_90517_AM.jpeg",
    "path": "cases/67aaeb9836a56c9b5f655364/
externallmg_1739257126024_WhatsApp_Image_20250211_at_90517_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf526d716769af0d46636",
    "name":
"externallmg_1739257126070_WhatsApp_Image_20250211_at_90518_AM.jpeg",
```

```
    "path": "cases/67aaeb9836a56c9b5f655364/
externallmg_1739257126070_WhatsApp_Image_20250211_at_90518_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf526d716769af0d46637",
    "name":
"externallmg_1739257126110_WhatsApp_Image_20250211_at_90520_AM_1.jpeg",
    "path": "cases/67aaeb9836a56c9b5f655364/
externallmg_1739257126110_WhatsApp_Image_20250211_at_90520_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf526d716769af0d46638",
    "name":
"externallmg_1739257126131_WhatsApp_Image_20250211_at_90520_AM_2.jpeg",
    "path": "cases/67aaeb9836a56c9b5f655364/
externallmg_1739257126131_WhatsApp_Image_20250211_at_90520_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf526d716769af0d46639",
    "name":
"externallmg_1739257126141_WhatsApp_Image_20250211_at_90520_AM.jpeg",
    "path": "cases/67aaeb9836a56c9b5f655364/
externallmg_1739257126141_WhatsApp_Image_20250211_at_90520_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf526d716769af0d4663a",
    "name":
"externallmg_1739257126185_WhatsApp_Image_20250211_at_90522_AM_1.jpeg",
    "path": "cases/67aaeb9836a56c9b5f655364/
externallmg_1739257126185_WhatsApp_Image_20250211_at_90522_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```

```
"status": false,
  "_id": "67aaf526d716769af0d4663b",
  "name":
"externallmg_1739257126208_WhatsApp_Image_20250211_at_90522_AM.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257126208_WhatsApp_Image_20250211_at_90522_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67aaf526d716769af0d4663c",
  "name":
"externallmg_1739257126223_WhatsApp_Image_20250211_at_90526_AM_1.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257126223_WhatsApp_Image_20250211_at_90526_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67aaf526d716769af0d4663d",
  "name":
"externallmg_1739257126277_WhatsApp_Image_20250211_at_90526_AM.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257126277_WhatsApp_Image_20250211_at_90526_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67aaf526d716769af0d4663e",
  "name":
"externallmg_1739257126286_WhatsApp_Image_20250211_at_90527_AM.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257126286_WhatsApp_Image_20250211_at_90527_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67aaf526d716769af0d4663f",
  "name":
"externallmg_1739257126361_WhatsApp_Image_20250211_at_90528_AM_1.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257126361_WhatsApp_Image_20250211_at_90528_AM_1.jpeg",
```

```
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf526d716769af0d46640",
    "name":
"externallmg_1739257126377_WhatsApp_Image_20250211_at_90528_AM_2.jpeg",
    "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257126377_WhatsApp_Image_20250211_at_90528_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf526d716769af0d46641",
    "name":
"externallmg_1739257126451_WhatsApp_Image_20250211_at_90528_AM_3.jpeg",
    "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257126451_WhatsApp_Image_20250211_at_90528_AM_3.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf526d716769af0d46642",
    "name":
"externallmg_1739257126483_WhatsApp_Image_20250211_at_90528_AM.jpeg",
    "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257126483_WhatsApp_Image_20250211_at_90528_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf526d716769af0d46643",
    "name":
"externallmg_1739257126504_WhatsApp_Image_20250211_at_90531_AM_1.jpeg",
    "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257126504_WhatsApp_Image_20250211_at_90531_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf526d716769af0d46644",
```

```
    "name":
"externallmg_1739257126529_WhatsApp_Image_20250211_at_90531_AM_2.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257126529_WhatsApp_Image_20250211_at_90531_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67aaf526d716769af0d46645",
  "name":
"externallmg_1739257126571_WhatsApp_Image_20250211_at_90531_AM.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257126571_WhatsApp_Image_20250211_at_90531_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67aaf526d716769af0d46646",
  "name":
"externallmg_1739257126615_WhatsApp_Image_20250211_at_90532_AM_1.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257126615_WhatsApp_Image_20250211_at_90532_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67aaf53119ca979ae946fb50",
  "name":
"externallmg_1739257137823_WhatsApp_Image_20250211_at_90532_AM.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257137823_WhatsApp_Image_20250211_at_90532_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67aaf54f36a56c9b5f655f42",
  "name":
"externallmg_1739257167357_WhatsApp_Image_20250211_at_90534_AM_1.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257167357_WhatsApp_Image_20250211_at_90534_AM_1.jpeg",
  "orientation": "portrait"
},
}
```

```
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67aaf54f36a56c9b5f655f43",
  "name":
"externallmg_1739257167394_WhatsApp_Image_20250211_at_90534_AM_2.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257167394_WhatsApp_Image_20250211_at_90534_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67aaf54f36a56c9b5f655f44",
  "name":
"externallmg_1739257167435_WhatsApp_Image_20250211_at_90535_AM_1.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257167435_WhatsApp_Image_20250211_at_90535_AM_1.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67aaf54f36a56c9b5f655f45",
  "name":
"externallmg_1739257167442_WhatsApp_Image_20250211_at_90535_AM_2.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257167442_WhatsApp_Image_20250211_at_90535_AM_2.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67aaf54f36a56c9b5f655f46",
  "name":
"externallmg_1739257167476_WhatsApp_Image_20250211_at_90535_AM.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externallmg_1739257167476_WhatsApp_Image_20250211_at_90535_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67aaf54f36a56c9b5f655f47",
  "name":
"externallmg_1739257167484_WhatsApp_Image_20250211_at_90536_AM_1.jpeg",
```

```
    "path": "cases/67aaeb9836a56c9b5f655364/
externallmg_1739257167484_WhatsApp_Image_20250211_at_90536_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf54f36a56c9b5f655f48",
    "name":
"externallmg_1739257167518_WhatsApp_Image_20250211_at_90536_AM_2.jpeg",
    "path": "cases/67aaeb9836a56c9b5f655364/
externallmg_1739257167518_WhatsApp_Image_20250211_at_90536_AM_2.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf54f36a56c9b5f655f49",
    "name":
"externallmg_1739257167542_WhatsApp_Image_20250211_at_90536_AM.jpeg",
    "path": "cases/67aaeb9836a56c9b5f655364/
externallmg_1739257167542_WhatsApp_Image_20250211_at_90536_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf54f36a56c9b5f655f4a",
    "name":
"externallmg_1739257167564_WhatsApp_Image_20250211_at_90537_AM_1.jpeg",
    "path": "cases/67aaeb9836a56c9b5f655364/
externallmg_1739257167564_WhatsApp_Image_20250211_at_90537_AM_1.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
    "status": false,
    "_id": "67aaf54f36a56c9b5f655f4b",
    "name":
"externallmg_1739257167602_WhatsApp_Image_20250211_at_90537_AM.jpeg",
    "path": "cases/67aaeb9836a56c9b5f655364/
externallmg_1739257167602_WhatsApp_Image_20250211_at_90537_AM.jpeg",
    "orientation": "portrait"
  },
  {
    "type": "EXTERNAL_IMAGES",
```



```
"status": false,
  "_id": "67aaf54f36a56c9b5f655f4c",
  "name":
"externalImg_1739257167630_WhatsApp_Image_20250211_at_90532_AM.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externalImg_1739257167630_WhatsApp_Image_20250211_at_90532_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67aaf54f36a56c9b5f655f4d",
  "name":
"externalImg_1739257167647_WhatsApp_Image_20250211_at_90533_AM.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externalImg_1739257167647_WhatsApp_Image_20250211_at_90533_AM.jpeg",
  "orientation": "portrait"
},
{
  "type": "EXTERNAL_IMAGES",
  "status": false,
  "_id": "67aaf54f36a56c9b5f655f4e",
  "name":
"externalImg_1739257167651_WhatsApp_Image_20250211_at_90534_AM.jpeg",
  "path": "cases/67aueb9836a56c9b5f655364/
externalImg_1739257167651_WhatsApp_Image_20250211_at_90534_AM.jpeg",
  "orientation": "portrait"
}
],
"externalDocuments": [],
"processingDocuments": [],
"leadRemarks": [],
"audioRemarks": [],
"remarks": [],
"createdAt": "2025-02-11T06:18:00.264Z",
"updatedAt": "2025-02-11T06:59:27.865Z",
"__v": 0,
"updatedBy": "62691c48afd7d55eddecfda3",
"addressForMap": "",
"caseReferredBy": "6006d4ce5080a310ac1fdcf2",
"contactPersonName": "Mr. S.Y. Raman",
"email": "",
"isExternal": "false",
"isUrgent": "false",
"ownershipShare": "",
"proposePurchaserName": "",
```

"purchaseValueAsPerDocument": "",
"relationWithOwner": "self",
"rerald": "",
"siteVisitContactNo": "9820422251"

}

| Name | Length | Width | Total |
|---------------|---------------|--------------|--------------|
| <hr/> | | | |
| Composition : | | | |
| <hr/> | | | |
| Other | | | |
| Composition : | | | |
| <hr/> | | | |